



TRAXXAS Radio-Controlled Vehicles

Aspect	Details
<p>Images</p>	
<p>PSD Number</p>	<p>2407-0125</p>
<p>Product Type</p>	<p>Hobby / Sports Equipment – Radio-Controlled Vehicles</p>
<p>Product Identifiers</p>	<p>Affected models were sold between 1 January 2002 and 10 June 2024. A list of models, parts and serial numbers can be found in Annex A.</p>
<p>Product Description</p>	<p>TRAXXAS Nitro and electric radio-controlled (RC) vehicles slipper or brake pads. Metal parts in rebuild kits or sets approximately 15mm by 2mm by 10mm.</p>
<p>Country of Origin</p>	<p>China</p>
<p>Counterfeit</p>	<p>No</p>
<p>Risk Level</p>	<p>Not provided</p>
<p>Risk Type</p>	<p>Health</p>
<p>Risk Description</p>	<p>The slipper or brake pads sold as parts or sold installed in the affected radio-controlled vehicles contain chrysotile asbestos. Asbestos fibres may be released from the slipper pad in the vehicle through friction and users may be exposed to asbestos fibres if the vehicle is disassembled for repair or maintenance. If asbestos fibres are released into the air and breathed in, they can cause serious medical conditions, including asbestosis, lung cancer and mesothelioma. The product does not meet the requirements of the General Product Safety Regulations 2005.</p>



Corrective Measures	Consumers should not attempt to remove or replace the slipper or brake pads or disassemble the slipper assembly in affected vehicles. Consumers should stop using affected nitro powered (non-electric) vehicles immediately. Access the following page to access further information and complete the recall form: https://www.iperkins.com/recall/traxxas-slipper-pad-recall/
Online Marketplace	N/A
Notifier	Office for Product Safety and Standards

Annex A – Affected Products

The affected models and serial number range information (serial numbers lower than the number listed are in scope of the recall):

- **Traxxas 2wd Electric models with 5552X friction pads:** Bandit, 240XX; Stampede, 360XX; Rustler, 370XX; Slash, 580XX; Drag Slash, 94076-4
- **Traxxas 4wd Electric models with 5552X friction pads:** Stampede 4X4, 670XX (excludes Ruster 4X4, 67064 and 67076); Slash 4X4, 680XX; Rally VXL, 7407X; E-Revo and Summit, 560XX and 5610 (excludes E-Revo, 86086); E-Maxx, 390XX
- **Traxxas Electric models with 7152 slipper clutch pad:** 1/16 Slash 4X4, 700XX; 1/16 E-Revo, 710XX; 1/16 Summit, 720XX; 1/16 Rally, Mustang, Nastruck, Fiesta 73XX; Ford Fiesta ST Rally, 74054 and 74064; Telluride, 67044
- **Traxxas Nitro models with 5352X friction pads, 5365 brake pads, and/or 5564 brake disc:** Jato, 550XX and 5510; Slayer, 690XX; T-Maxx, 490XX; Revo, 530XX and 5310

Spare parts affected:

5352X	Rebuild kit, slipper clutch (steel disc/ friction pads (3)/ spring (1)/ 2x9.8mm pin/ 5x8mm MW/ 5.0mm NL (1)/ 4.0mm NL (1))
5552X	Rebuild kit, slipper clutch (steel disc/ friction pads (3)/ spring (2)/ pin/ 4.0mm NL (1)/ 5.0mm NL (1))
6878	Slipper clutch, complete (for Slash 4x4)
3695	Transmission, complete (fits 1/10-scale 2WD Rustler®, Bandit®, Stampede®, Slash®)
4983	Transmission, complete (fits T-Maxx® 3.3)
5491	Transmission, complete (fits Revo® 3.3)
5691	Transmission, complete (fits Summit (2-speed))
9495	Pro Series Magnum 272R, Transmission, complete (assembled) (fits 1/10-scale 2WD Rustler®, Brandit®, Stampede®, Slash®)
5351X	T-Maxx® Torque Control Slipper Upgrade Kit (fits first generation T-Maxx® transmission w/o Optidrive®) (patent pending)
5352	Rebuild kit, slipper clutch (steel disc/ friction pads(3)/ spring/ 2x9.8mm pin/ 5x8mm MW/ 5.0mm NL)
5552	Rebuild kit, slipper clutch (steel disc/ friction pads (3)/ spring/ pin/ 4.00mm NL)
7152	Slipper clutch, complete (includes slipper clutch hub, clutch pad, spring, 3.0mm NL, 1.5x6mm pin)
6766	Gear clutch, complete (high stall)
7095	Transmission, complete (fits 1/16-scale brushed models)

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <https://www.gov.uk/guidance/product-recalls-and-alerts>



7096	Transmission, complete (fits 1/16-scale VXL models)
5365	Brake pad set (inner and outer calipers with bonded friction material)
4983	Transmission, complete (fits T-Maxx® 3.3)
5491	Transmission, complete (fits Revo® 3.3)
5564	Brake disc (semi-metallic material)
5417	Brake kit (dual disc rear for Revo®) (Requires center differential kit, part 5414)