April 2025

HS2

Air Quality and Dust Monitoring Monthly Report - April 2025

Stratford-on-Avon District Council



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2025, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High-Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in Stratford-on-Avon District (SoADC) during April 2025.
- 1.1.2 Figure 1 in Appendix A present the current worksites together with the dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report monthly available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1, include:

Southam worksite


- Culvert poring protection slab;
- Southam culverts Phase 3 backfill;
- Mill pond embankment E&R transition/ pond 3 backfill;
- Pond 9 & 10 Stockpile relocation to land option 4;
- Ladbroke cutting Section 3 excavation;
- Windmill lane OB Haul road construction;
- Ladbroke Grove Embankment E&R excavation;
- Upper Radbourne Embankment E&R/ starter layer installation;
- Oxford Canal North Embankment Mainline UEF stabilisation works;
- Oxford Canal North Embankment Landscape embankment fill;
- Oxford Canal Viaduct Temporary 6N fill;
- Oxford Canal South Culvert Phase 1 backfill;
- Oxford Canal South Embankment Stockpile relocation to OCNE;
- A423 Ancillary culvert Ancillary Culvert Earthworks E&R backfill; and
- Oxford Canal Culvert Boddington utilities enabling works and southern bypass.
- 1.1.5 Two (2) dust monitors are installed around these worksites, where works are underway. These sites returned a medium dust risk rating.
- 1.1.6 The dust monitoring location and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor presented in Figure 2. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of

uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.

- 1.1.7 The trigger level for PM₁₀ concentrations of 190 μg/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.
- 1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (April 2025).
- 1.1.9 There were no (0) complaints received during the reporting period (April 2025).

Appendix A - Worksites and Monitoring Locations

Figure 1: Worksites and Monitoring Locations within SoADC



Appendix B - Dust Monitoring Results

Table 1: Dust Monitoring Locations and Results

| Monitoring site ID | Coordinates (X,Y) | Location description | Dust risk rating for site | Monitoring site active during period | Change to site since previous period report | Mean 1-hour PM10 concentration (µg/m3) | Minimum 1-hour PM10 concentration (µg/m3) | Maximum 1- hour PM10 concentration (µg/m3) | Number of 1- hour periods exceeding trigger level of 190 µg/m3 | Data capture (%) |
|---------------------|----------------------|---|------------------------------------|---|---|---|--|---|--|------------------------|
| Harp Farm- AQMP1 | 441738, 260075 | Site boundary adjacent property on Harp Farm | М | Yes | Yes | 10.4 | 1.0 | 53.0 | 0 | 100.0 |
| Kineton Rd | 441092, 260808 | Adjacent to Kineton Road roundabout | М | Yes | Yes | 13.0 | 1.0 | 101.0 | 0 | 100.0 |

Figure 2: Construction dust 1-hour mean indicative PM₁₀ concentration for all dust monitors

