

Notice of Authorized Amendment: NAA/25/39

RA(s) or Manual Chapter(s): RA 3536 - Domestic Helicopter Landing Site

NPA Reference(s): N/A

RFC Reference(s): MAA/RFC/2025/064, 2025/073

MAA Author

Post	Name	Rank	Signature
MAA Reg ATM Ad Infra	Redacted	Redacted	Electronic Signature above

MAA Supervisor

Post	Name	Rank	Signature
MAA Reg ATM	Redacted	Redacted	Electronic Signature above

MAA Independent

Post	Name	Rank	Signature
MAA Reg ATM 1	Redacted	Redacted	Redacted - Original Signed

MAA LegAd (if required)

Post	Name	Rank	Signature
N/A	N/A	N/A	Choose an item.

Amendment Classification: Minor Change

Publishing Requirements: Next regular release

Cross-references to Other Documents or Relevant Sources

Other MRP Amendments: N/A

Service Inquiry Recommendations: N/A

AAIB Recommendations: N/A

Other Investigation Recommendations: N/A

Any Other Document: N/A

Authorized Amendment

Summary / Overview of the amendment to explain/ensure that the reader understands: the rationale for the amendment; the major changes; and, importantly, the full context (including desired outcome) of the amendment.

The Regulated Community is reminded to check this amendment against any applicable AAMC, Waivers or Exemptions to ensure their ongoing validity.

Two RFCs were received to request clarification on elements of the recently released Issue 6 of RA 3536.

The changes that have been implemented as a result of these RFCs unlock flexibility for

HoE's in regard to who they could allocate in particular roles. Additionally it provides clarification on SQEP requirements and the courses available to train selected personnel.

Changes made:

RA 3536: Scope - Amendment made for clarity.
 RA 3536: Para 2 – Removal of abbreviation, not required.
 RA 3536: Para 5 – Removal of abbreviation, not required.
 RA 3536: Para 9 - Removal of abbreviation, not required.
 RA 3536: Para 19 – Insertion of new paragraph to clarify the HOE's discretion on selection of a custodian. New para numbers from this point for the remainder of the document.
 RA 3536: Para 21 – Insertion of abbreviation for grammatical accuracy.
 RA 3536: Para 23 – Textual change to improve clarity.
 RA 3536: Para 24 – Textual removal, superfluous words.
 RA 3536: Table 1, Group 2 – textual amendment to provide clarity on intent.
 RA 3536: Para 32 - Insertion of abbreviation for grammatical accuracy.
 RA 3536: Para 33, Sub-para f – Textual insertion for clarity on applicable RAs.
 RA 3536: Para 39, Sub-para a – Textual inclusion to include all aviation capable HM Ships
 RA 3536: Para 40 - Removal of abbreviation, not required.
 RA 3536: Para 43 – Included to provide clarity on available training courses.

Issue State Changes (if more lines required, contact the MRP Team)

Document Title	Previous Issue	New Issue
RA 3536 - Domestic Helicopter Landing Site	Issue 6 to	Issue 7

MAA Approval

Post	Name	Rank	Signature
MAA Dep Hd Regs	Redacted	Redacted	Redacted - Original Signed