July 2025



Air Quality and Dust Monitoring Monthly Report - July 2025

Stratford-on-Avon District Council



High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited, Two Snowhill Snow Hill Queensway Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2025, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/version/3 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High-Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in Stratford-on-Avon District (SoADC) during July 2025.
- 1.1.2 Figure 1 in Appendix A present the current worksites together with the dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report monthly available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1, include:


Southam worksite

- Water Management Monitoring only and Site Wide General maintenance
- Earthworks at: Oxford Canal North Embankment Upper Radbourne Embankment Ladbroke Grove Cutting Ladbroke Grove Embankment Ladbroke Cutting
- Works at Ancillary Culvert 124-AC1 Placement and Compaction works and Highways
- Oxford Canal North Embankment SAR and haul road repairs
- Windmill lane OB and A423 OB SAR works
- Lower Radborne North, A423 overbridge and oxford canal viaduct structures works.
- 1.1.5 Two (2) dust monitors are installed around these worksites, where works are underway. These sites returned a medium dust risk rating.
- 1.1.6 The dust monitoring location and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor presented in Figure 2. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM_{10} concentrations of 190 μ g/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites (October 2018)' has been applied.

- 1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (July 2025).
- 1.1.9 There were no (0) complaints received during the reporting period (July 2025).

Appendix A - Worksites and Monitoring Locations

Figure 1: Worksites and Monitoring Locations within SoADC



Appendix B - Dust Monitoring Results

Table 1: Dust Monitoring Locations and Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM10 concentration (µg/m3)	Minimum 1-hour PM10 concentration (µg/m3)	Maximum 1- hour PM10 concentration (µg/m3)	Number of 1- hour periods exceeding trigger level of 190 µg/m3	Data capture (%)
Harp Farm- AQMP1	441738, 260075	Site boundary adjacent property on Harp Farm	М	Yes	Yes	6.7	1.0	54.0	0	100.0
Kineton Rd	441092, 260808	Adjacent to Kineton Road roundabout	М	Yes	Yes	8.0	1.0	89.0	0	99.7

Figure 2: Construction dust 1-hour mean indicative PM₁₀ concentration for all dust monitors

