

Images from 25 October 2021 (02_26_1BH)



Pro DSS

25/10/21 11:15:14

90%

Run

Leg One Sample

12.2 °C

100.2 DO %L

8.87 DO $\frac{mg}{L}$

46542 SPG $\frac{US}{CM}$

30.16 SAL PSU

8.00 pH

74.25 NH-N $\frac{mg}{L}$

1.42 NH-N $\frac{mg}{L}$



Pro DSS

05/10/21 11:55:19

Ren

Log One Sample

12.1 °C

102.0 DO %L

8.81 DO $\frac{mg}{L}$

51956 SPC- $\frac{mg}{dm}$

34.09 SAL-PSU

8.05 pH

71.50 NH₄-N $\frac{mg}{L}$

1.50 NH₄-N $\frac{mg}{L}$

System

Probe

Calibration

File

Pro DSS

25/10/21 12:40:36

100%

Run

Log One Sample

12.8 °C

120.4 DO %L

10.41 DO $\frac{mg}{L}$

48760 SPC $\frac{1}{min}$

31.79 SAL-PSU

8.42 pH

65.03 NH₄-N $\frac{mg}{L}$

3.44 NH₃-N $\frac{mg}{L}$

System

Probe

Calibration

File



Cal







Pro DSS

25/10/21 13:54:06

89%

Run

Log One Sample

13.3 °C

100.9 DO %L

8.64 DO $\frac{\text{mg}}{\text{L}}$

48649 SPC $\frac{\text{US}}{\text{cm}}$

31.73 SAL-PSU

8.11 pH

65.43 $\text{NH}_3\text{-N}$ $\frac{\text{mg}}{\text{L}}$

1.73 $\text{NH}_3\text{-N}$ $\frac{\text{mg}}{\text{L}}$

