

HS2

November 2022

Air Quality and Dust Monitoring Monthly Report – November 2022

West Northamptonshire District Council



Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2021, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-government-licence/version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken in the West Northamptonshire (WNDC) during November 2022.
- 1.1.2 Figures 1 and 2 in Appendix A present the current worksites together with the dust monitoring locations for November 2022.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites as presented in Appendix A, Figures 1 and 2, include:

Twyford to Greatworth (T2G)

Radstone and Hall Farm:

- Topsoil stripping
- Bulk excavation – Cutting
- Stockpile management
- Site Access Road maintenance
- Compound maintenance
- Drainage, temporary ponds
- Utilisation of haulage road for moving material
- Structures Compound set-up and aggregate stockpiling.

Greatworth Hall:

- Topsoil stripping
- Bulk excavation – Cutting
- Stockpile management
- Site Access Road maintenance
- Drainage and temporary ponds
- Construction of landscape bunds (Brackley north Cutting)
- Utilisation of haulage road for moving material
- Compound maintenance
- Surfacing of Site Access Road (SAR).

Greatworth to Southam (G2S)

Chipping warden – Ramac:

- Topsoil stripping
- Chipping Warden green tunnel excavation
- Stockpile management
- Site Access Road maintenance
- Chipping Warden batching plant
- Compound maintenance
- Vegetation maintenance
- Utilisation of haulage road for moving material
- Appletree lane utility diversion

CW Village:

- A361 temporary overbridge
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Stockpile management
- Vegetation maintenance
- Site Access Road maintenance
- Compound maintenance

Lower Boddington:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Vegetation maintenance
- Highfurlong brook piling works
- Bulk excavation – cutting

Fir tree nursery:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Vegetation maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds

Greatworth Village:

- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds

Lower Thorpe:

- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds
- Lower Thorpe piling works

Backgrounds:


- Topsoil stripping
- Stockpile management
- Site Access Road maintenance
- Utilisation of haulage road for moving material
- Drainage and temporary ponds


- 1.1.5 Dust monitoring locations and results are presented in Appendix B, Table 1, together with a line chart of monthly data from the dust monitor presented in Figure 3. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.6 The trigger level for PM₁₀ concentrations of 190 µg/m³, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (October 2018)*' has been applied.
- 1.1.7 Ten (10) dust monitors are installed at worksites, where works are underway. These sites returned a medium dust risk rating.
- 1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (November 2022).
- 1.1.9 Data capture was below 90% for multiple monitors due to battery faults and power supply issues.
- 1.1.10 No (0) complaints were received during the reporting period (November 2022).

Appendix A -Monitoring Locations

Figures 1 and 2: Worksite and Monitoring locations within the WNDC







Legend

- Dust
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCan, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong). (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Monitoring Locations In WNDC (Sheet 2)

West Northamptonshire Council



HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway,
Birmingham B4 6GA.

© Crown copyright and database rights 2022.
Ordnance Survey Licence Number 100049190.

Doc Number:

Scale at A3: 1:24,000



Date: 31/10/22


Appendix B – Dust Monitoring Results

Table 1: Dust monitoring locations and November 2022 Results


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (µg/m ³)	Minimum 1-hour PM ₁₀ concentration (µg/m ³)	Maximum 1-hour PM ₁₀ concentration (µg/m ³)	Number of 1-hour periods exceeding trigger level of 190 µg/m ³	1-hour data capture (%)
Chipping Warden – RAMAC	449600, 249755	Chipping Warden, West Northamptonshire	M	Yes	Yes	6.5	1.0	49.0	0	54.7
CW Village	450000, 249367	Chipping Warden, West Northamptonshire	M	Yes	Yes	6.9	1.0	59.0	0	92.2
Lower Boddington	447997, 251865	Lower Boddington, West Northamptonshire	M	Yes	Yes	6.6	1.0	43.0	0	79.9
Fir Tree Nursery	447283 , 252421	Fire Tree Nursery, West Northamptonshire	M	Yes	Yes	6.7	1.0	45.0	0	97.8
Radstone	458712 , 240454	Radstone Road, Brackley, West Northamptonshire	M	Yes	Yes	7.3	1.0	77.0	0	9.6
Hall Farm	458734, 239823	Hall Farm, Radstone Road	M	Yes	Yes	6.8	1.0	60.0	0	59.9
Greatworth Village	455551, 242992	Greatworth Village, Helmdon Road,	M	Yes	Yes	6.8	1.0	46.0	0	78.5
Lower Thorpe	453553, 245334	Banbury Lane, Lower Thorpe	M	Yes	Yes	7.0	1.0	57.0	0	99.2
Greatworth Hall	456179, 242763	Greatworth Hall, Greatworth	M	Yes	Yes	6.7	1.0	49.0	0	79.7
Blackgrounds	450846, 248413	Blackgrounds, West Northamptonshire	M	Yes	Yes	7.0	1.0	42.0	0	55.1

Air Quality and Dust Monitoring Summary Report, November 2022
 West Northamptonshire Council

Figure 3: Continuous dust 1-hour mean indicative PM₁₀ concentration for all dust monitors



Air Quality and Dust Monitoring Summary Report, November 2022
 West Northamptonshire Council



Air Quality and Dust Monitoring Summary Report, November 2022
West Northamptonshire Council

