



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[Redacted]

email: [Redacted]

Our Reference:
FOI2023/05483
Date:
12 May 2023

Dear [Redacted]

I am writing about your email of 01 May 2023, requesting the following information:

Can you please send me the unit history and service history for a vehicle I have recently purchased.

land rover defender 90

Military registration number : LS 19 AA

Serial number: SALLDAAC7WA145970

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History (redacted)
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the Owner History (Annex A) relating to sensitive units with which this vehicle served has been redacted under the qualified exemptions S26(1)(a) (Defence) and Section 38(1)(a) (Health and Safety). In addition, commercially sensitive information in the Fault History (Annex B) of relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As these exemptions are qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the
Defence Equipment & Support

MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, releasing the information redacted under Sections 26 and 38 in the Owner History would divulge information that could be used to compromise the ability of UK Armed Forces to carry out operations safely by revealing information about capabilities and actions which would assist adversaries in planning attacks against personnel and equipment. This would endanger the lives of Armed Forces personnel and disrupt or limit military operations and capabilities. Reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LS19AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
25/03/1998	SALLDAA67WA145970	N/A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LS19AA	3		CA005A	JSCS ASHCHURCH		33048AA	25/03/1998	
LS19AA	4	16/07/1998	A0222A	32 REGT RA	40906A	62	27/08/1998	
LS19AA	4	19/03/1999	A0222C	32 REGT RA 22(GIBRALTAR) BTY RA	3DIV99	3DIV99	19/03/1999	
LS19AA	4	06/10/2003	A0222A	32 REGT RA	ECR	ECR	06/10/2003	
LS19AA	3	20/01/2011	A5969A	TFSU (UK)	45857	3845DD	11/02/2011	
LS19AA	4	16/08/2012	CB998C	DSG COLCHESTER PLANNED REPAIR	4704D	999	16/08/2012	
LS19AA	2	19/02/2013	A6205G	DSG VEHICLES LONGMOOR	L0002	164/12	27/03/2013	
LS19AA		08/02/2018		SEF (UK) ASHCHURCH			26/03/2018	
LS19AA		20/09/2018		BABCOCK DISPOSAL			20/09/2018	

Work Objects

Serial Number: LS19AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Work Fault Description	Work Status	Work Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A5BAC3		CARRY OUT MOD 46 WHEEL NUT INDICATORS	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Modification	TUL HS FFR HARD TOP			
000000-00A6998A		CARRY OUT FMT932W1 (RE-CERTIFICATION)	Closed	Non-Taskworthy	No	Level 2		26 Oct 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A6999B		CARRY OUT FMT933 INSPECTION	Closed	Taskworthy	No	Level 2		26 Oct 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A5BD40		CARRY OUT FULL ENGINE AND CHASSIS STEAM CLEAN	Closed	Fully Fit	No	Level 1		27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A5BD25		REPLACE DAMAGED FRONT BUMPER	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Damage	TUL HS FFR HARD TOP			
000000-00A5BC79		REPLACE CORRODED THROUGH REAR CROSS MEMBER	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A5BD2B		REC COOLANT WEEP AT TOP AND BOTTOM HOSES	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A5BC6D		REPLACE DAMAGED DRIVERS SEAT BELT	Closed	Non-Taskworthy	No	Level 2		27 Sep 2017	N/A	Damage	TUL HS FFR HARD TOP			
000000-00A5BC33		REPLACE WORN/SEPERATING N/S & O/S FRONT RADIUS ARM BUSHES	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A5BC66		REPLACE WORN N/S & O/S UPPER & LOWER FRONT DAMPER BUSHES	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A5BBF0		REPLACE KINKED N/S & O/S FRONT CALIPER BRAKE PIPES	Closed	Non-Taskworthy	No	Level 2		27 Sep 2017	N/A	Damage	TUL HS FFR HARD TOP			
000000-00A5BD22		TIGHTEN PASSENGER SEAT RUNNER MTG BOLTS	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A5BBEA		REPLACE BROKEN N/S & O/S REAR AXLE BRAKE PIPE CLIPS	Closed	Non-Taskworthy	No	Level 2		27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A5BBE2		REPLACE ENGINE BREATHER PIPES (LEAKING/SPLIT)	Closed	Fully Fit	No	Level 2		27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP			

000000-00A58BD5	RECTIFY DIESEL LEAK AT INJECTOR LEAK OFF PIPES	Closed	Non-Taskworthy	No	Level 2	27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A58BDF	INV/RECTIFY EXCESSIVE OIL LEAKS O/S OF ENGINE	Closed	Fully Fit	No	Level 2	27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A5BAD3	CARRY OUT 2 YEARLY SERVICE	Closed	Non-Taskworthy	No	Level 2	27 Sep 2017	N/A	Servicing	TUL HS FFR HARD TOP		
000000-00A5BAE1	CARRY OUT 5 YRLY SERVICING, CHANGE G/BOX OIL & COOLANT	Closed	Non-Taskworthy	No	Level 2	27 Sep 2017	N/A	Servicing	TUL HS FFR HARD TOP		
000000-00A5BD2F	REPLACE U/S X1 O/S HEAD LIGHT GRILL TURNKEY	Closed	Fully Fit	No	Level 2	27 Sep 2017	N/A	Failure	TUL HS FFR HARD TOP		
000000-00A5BBC1	INVESTIGATE/RECTIFY HEAVY CLUTCH PEDAL OPERATION	Closed	Fully Fit	No	Level 2	27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A5BBC9	RECTIFY CLUTCH PEDAL BITE AT TOP OF TRAVEL	Closed	Fully Fit	No	Level 2	27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A5BB07	RE-CONNECT CLUTCH PEDAL SPRING	Closed	Fully Fit	No	Level 2	27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A01815	REPLACE N/S/R TYRE (SIDE WALL CRACKING)	Closed	Non-Taskworthy	No	Level 2	15 Feb 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A5BAB9	SWOP O/S/R WHEEL WITH SPARE WHEEL	Closed	Fully Fit	No	Level 1	27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A0180A	REPLACE U/S BATTERIES	Closed	Non-Taskworthy	No	Level 1	15 Feb 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A5BAEA	CARRY OUT FMT932(W1) INSPECTION	Closed	Non-Taskworthy	No	Level 2	27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00A5BD3D	CARRY OUT FMT933 INSPECTION	Closed	Non-Taskworthy	No	Level 2	27 Sep 2017	N/A	Inspection	TUL HS FFR HARD TOP		
000000-0098985A	000000-00315F7F CARRY OUT IN-INSPECTION	Closed	Fully Fit	Yes	Level 2	000000-000035BC 19 Apr 2016	N/A	Closed No Action	TUL HS FFR HARD TOP	JES DET (W)	GREEN FLEET
000000-0097F8D1	REPLACE REAR CABIN SEAT BELTS X2	Closed	Fully Fit	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00971F58	CARRY OUT AF 6534 INSPECTION	Closed	Fully Fit	No	Level 2	22 Feb 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-00971F66	CARRY OUT 6 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM A)	Closed	Fully Fit	No	Level 1	22 Feb 2016	N/A	Servicing	TUL HS FFR HARD TOP		
000000-00971F7E	CARRY OUT 6 MTHLY (L 2 VM TASKS 2320-D-128-601 T 7 COLM A)	Closed	Fully Fit	No	Level 2	22 Feb 2016	N/A	Servicing	TUL HS FFR HARD TOP		
000000-0097F8C0	REPLACE STEERING DAMPER	Closed	Non-Taskworthy	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-0097F8C2	RESEAL ENGINE SUMP GASKET	Closed	Fully Fit	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-0097F8C9	TENSION FRONT BUMPER BOLTS	Closed	Fully Fit	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-0097F8D5	ADJUST COOLANT S.G TO -37 DEG. C. +/- 3 DEG. C	Closed	Fully Fit	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-0097F8D9	REPAIR INOP L/H DOOR LOCK	Closed	Limited Role	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		
000000-0097F8DD	REPLACE L/H SEAT BELT	Closed	Non-Taskworthy	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP		

000000-0097F8E0	RETIGHTEN L/H & R/H MIRRORS	Closed	Non-Taskworthy	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP	
000000-0097F8CC	BALANCE FRONT WHEELS	Closed	Fully Fit	No	Level 2	21 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00962291	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003210	20 Jan 2016	N/A	Closed No Action	TUL HS FFR HARD TOP
000000-00964256	TORQUE WHEEL NUTS 170nm (aesp 2320-d-128-601-table 3)	Closed	Fully Fit	No	Level 2	22 Jan 2016	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008D3639	CARRY OUT 1 YRLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM B)	Closed	Fully Fit	No	Level 1	29 Oct 2015	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008D3648	CARRY OUT 1 YRLY (L 2 VM TASK'S 2320-D-128-601 T 7 COLM B)	Closed	Fully Fit	No	Level 2	29 Oct 2015	N/A	Servicing Closed No Action	TUL HS FFR HARD TOP	
000000-00895987	Carry out MOD 42 spare wheel carrier	Closed	Fully Fit	No	Level 2	15 May 2015	N/A	Action	TUL HS FFR HARD TOP	
000000-008D3621	CARRY OUT ANNUAL (FMT 932 W1 INSPECTION)	Closed	Fully Fit	No	Level 2	29 Oct 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-008D362C	CARRY OUT ANNUAL (FMT 933 INSPECTION)	Closed	Fully Fit	No	Level 2	29 Oct 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-008D6F98	CONVOY LIGHT COVER SEIZED	Closed	Fully Fit	No	Level 1	09 Nov 2015	N/A	Failure	TUL HS FFR HARD TOP	
000000-008D6F9C	PICK AXE HEAD MISSING	Closed	Fully Fit	No	Level 1	09 Nov 2015	N/A	Non Specific	TUL HS FFR HARD TOP	
000000-00895979	Replace missing heater air intake dump valve	Closed	Fully Fit	No	Level 2	15 May 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-0089597F	Adjust fan belt	Closed	Fully Fit	No	Level 2	15 May 2015	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00895984	Rectify oil @ LH side of sump	Closed	Fully Fit	No	Level 2	15 May 2015	N/A	Servicing	TUL HS FFR HARD TOP	
000000-0089598E	Carry out, out inspection and certify completed work	Closed	Fully Fit	No	Level 2	15 May 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00890E32	CARRY OUT 6 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM A)	Closed	Fully Fit	No	Level 1	06 May 2015	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00890E35	CARRY OUT 6 MTHLY (L 2 VMS TASKS 2320-D-128-601 T 7 COLM A)	Closed	Fully Fit	No	Level 2	06 May 2015	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00895971	Renew RHF eyebrow split	Closed	Limited Role	No	Level 2	15 May 2015	N/A	Failure	TUL HS FFR HARD TOP	
000000-0089A22B	Torque wheel nuts to 170nm using wrench 182973 cal due 7/15	Closed	Fully Fit	No	Level 2	28 May 2015	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00854C17	Rectify oil leaks @ cyclonic valve and rocker breather pipe	Closed	Fully Fit	No	Level 2	18 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00890E2A	CARRY OUT AF 6534 INSPECTION	Closed	Fully Fit	No	Level 2	06 May 2015	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00808547	RENEW AIR INTAKE dump valve	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure Closed No Action	TUL HS FFR HARD TOP	
000000-00854BF5	Reconnect aux batteries and test charging rate	Closed	Limited Role	No	Level 2	18 Nov 2014	N/A	Action	TUL HS FFR HARD TOP	
000000-00854BFC	Adjust / renew LH door bottom hinge	Closed	Fully Fit	No	Level 2	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	

000000-00854C08	Replace missing battery box grommets	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854C10	RHR operators seat locating bar missing	Closed	Limited Role	No	Level 2	18 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00854C1E	Replace missing adjusting handle from drivers seat	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854C25	Renew RH headlight guard plastic hinge	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00854C29	Renew both radius arms bushes	Closed	Non- Taskworthy	No	Level 2	18 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00854C32	Renew steering damper bush	Closed	Non- Taskworthy	No	Level 2	18 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00854C39	Straighten or renew front diff bash protection plate	Closed	Fully Fit	No	Level 2	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854C47	Rectify oil leak @ sump and oil pressure switch	Closed	Fully Fit	No	Level 2	18 Nov 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00854C50	Carry out, out inspection and recertify 932w1 and 933 reports	Closed	Fully Fit	No	Level 2	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-008503A4	CARRY OUT 2 YRLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM C)	Closed	Non- Taskworthy	No	Level 1	06 Nov 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008503A8	CARRY OUT 2 YRLY (L 2 VMS TASKS 2320-D-128-601 T 7 COLM C)	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008503AD	CARRY OUT O.O.P.M. T5 SERIAL 1 (RENEW ENGINE OIL & FILTER)	Closed	Fully Fit	No	Level 2	06 Nov 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008503B3	CARRY OUT O.O.P.M. T5 SERIAL 4 (RENEW AIR FILTERS)	Closed	Fully Fit	No	Level 2	06 Nov 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008503BA	RENEW BRAKE FLUID (2 YRLY VMS TASK)	Closed	Fully Fit	No	Level 2	06 Nov 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-008503C0	RE-PACK F & R HUB BEARINGS (2 YRLY VMS TASK)	Closed	Fully Fit	No	Level 2	06 Nov 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-0085C61B	Torque wheel nuts to 175 nm using wrench 182973	Closed	Fully Fit	No	Level 2	08 Dec 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00850398	CARRY OUT ANNUAL FMT 932 (W 1 INSPECTION)	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-008503A2	CARRY OUT ANNUAL (FMT 933 INSPECTION)	Closed	Non- Taskworthy	No	Level 2	06 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854B9A	Replace missing vehicle jack	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854BA4	Refit LH seat belt protector correctly	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854BC4	Replace missing fire extinguisher	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-00854BCF	Refit rear view mirror	Closed	Fully Fit	No	Level 1	18 Nov 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-0084421D	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000- 00001F58	09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP
000000-008381F3	REQUIRES IN INSPECTION	Closed	Fully Fit	No	Level 2	15 Sep 2014	N/A	Inspection	TUL HS FFR HARD TOP	

000000-00789BDB	passengers side of windscreen glass scratched excessively renew	Closed	Non-Taskworthy	No	Level 2	15 May 2013	N/A	Damage	TUL HS FFR HARD TOP	000:00
000000-008085A4	RENEW WINDSCREEN	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Damage	TUL HS FFR HARD TOP	
000000-00808550	RENEW ALTERNATOR BELT	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808555	RENEW BONNET BUFFERS	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808559	RENEW WEAPON MOUNT PADS	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Damage	TUL HS FFR HARD TOP	
000000-0080857C	RENEW NO 2 BALL JOINT	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808584	RENEW R/H AND L/H RADIOUS ARM BUSHES	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808817	RENEW STEERING DAMPER BUSHES	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00806EFE	CARRY OUT 6 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM A)	Closed	Fully Fit	No	Level 1	02 May 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00806FOB	CARRY OUT 6 MTHLY L2 VMS TASKS (2320-D-128-601 T7 COLM A)	Closed	Fully Fit	No	Level 2	02 May 2014	N/A	Servicing	TUL HS FFR HARD TOP	
000000-00808494	TIGHTEN R/H STEERING GUARD BOLT	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-0080849D	RE-SEAT R/H FRONT SHOCKER TOP BUSH	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808560	STEAM CLEAN ENGINE	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808565	INVESTIGATE OIL CONTAMINATION IN INTER COOLER AND REPAIR	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-0080856D	REPAIR ENGINE BREATHER PIPE OIL LEAK	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808575	ADJUST ANTI-FREEZE S/G (TOO HIGH)	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00808592	L/H AND R/H FRONT BRAKE PIPES FOULING SUSPENSION	Closed	Non-Taskworthy	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-0080859A	INVESTIGATE AND REPAIR VACUUM PUMP OIL LEAK	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-008085AE	BALANCE FRONT WHEELS AND ROTATE WITH REAR WHEELS	Closed	Fully Fit	No	Level 2	07 May 2014	N/A	Failure	TUL HS FFR HARD TOP	
000000-00806EF7	CARRY OUT AF 6534 INSPECTION	Closed	Fully Fit	No	Level 2	02 May 2014	N/A	Inspection	TUL HS FFR HARD TOP	
000000-007C5733	CARRY OUT ANNUAL FMT 932 (W2 INSPECTION)	Closed	Fully Fit	No	Level 2	29 Oct 2013	N/A	Inspection	TUL HS FFR HARD TOP	
000000-007C5739	CARRY OUT 12 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM B)	Closed	Fully Fit	No	Level 1	29 Oct 2013	N/A	Servicing	TUL HS FFR HARD TOP	
000000-007C573C	CARRY OUT 12 MTHLY (L2 VMS TASKS 2320-D-128-601 T7 COLM B)	Closed	Fully Fit	No	Level 2	29 Oct 2013	N/A	Servicing	TUL HS FFR HARD TOP	
000000-007A312E	RECTIFY (NONE STARTER) RECOVERED IN BY A.A.	Closed	Limited Role	No	Level 2	17 Jul 2013	N/A	Failure	TUL HS FFR HARD TOP	

000000-007C5735	CARRY OUT ANNUAL FMT 933 (INSPECTION)	Closed	Fully Fit	No	Level 2		29 Oct 2013	N/A	Inspection	TUL HS FFR
000000-00798B19	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	HARD TOP TUL HS FFR
000000-0079BAF2	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	HARD TOP TUL HS FFR
000000-0079CD28	REPLACE L/H/R TYRE	Closed	Fully Fit	No	Level 1		27 Jun 2013	N/A	Failure	HARD TOP TUL HS FFR
000000-00782507	CARRY OUT AFB 6534 INSPECTION	Closed	Fully Fit	No	Level 2		24 Apr 2013	N/A	Inspection	HARD TOP
000000-00782526	CARRY OUT 6 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM A)	Closed	Fully Fit	No	Level 1		24 Apr 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00782535	CARRY OUT 6 MTHLY (L2 VMS TASKS 2320-D-128-601 T 7 COLM A)	Closed	Fully Fit	No	Level 2		24 Apr 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-0078253F	REPLACE RADIO OPERATORS R/H SEAT BRACKET MISSING	Closed	Fully Fit	No	Level 2		24 Apr 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B45	wheel nut torque checked	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B4E	anti-freeze weak	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B53	positive battery terminal missing	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B55	steering wheel alignment out	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B59	r/h/r metal brake pipe adrift	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B5E	screenwash jet aasy adrift	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789B62	both front door glass loose/rattles.	Closed	Fully Fit	No	Level 2		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789BB3	r/h front door pull loose	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789BBA	both front air vent flaps seized	Closed	Fully Fit	No	Level 2		15 May 2013	N/A	Servicing	TUL HS FFR HARD TOP
000000-00789BC4	keys missing from both front doors.	Closed	Fully Fit	No	Level 2		15 May 2013	N/A	Damage	TUL HS FFR HARD TOP
000000-00789BCC	drivers seat locating adaptor/lug missing	Closed	Fully Fit	No	Level 1		15 May 2013	N/A	Inspection	HARD TOP
000000-00608549	Incomplete Equipment Information	Closed	Non-Taskworthy	No	Level 1		23 May 2011	N/A	Closed No Action	TUL HS FFR HARD TOP
000000-006B0695	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-00000312	22 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
000000-00404843	Initial Maintenance	Closed	Fully Fit	No	Level 1		29 Mar 2009			TUL HS FFR HARD TOP
000000-0040483C	Initial Usage	Closed	Fully Fit	No	Level 1		29 Mar 2009			TUL HS FFR HARD TOP

Work Objects

Serial Number: LS19AA
 NSN: 2320998939742

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request		Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated	Working Organisation	Repair Section
	Escalate	Work						Repair Time		
000000-0048B6A0	No		MEI (2)	27 Sep 2018	Level 2			000:00		
000000-0045ADA3	No		First Parade Insp (AR)(1)		Level 1			000:00		
000000-005343BC	No		6 Monthly 6534 Insp	29 Mar 2018	Level 1			000:00		
000000-007A7DF7	No		MEI (2)	27 Sep 2018	Level 2			000:00		
000000-008A9150	No		MEI (2)	27 Sep 2018	Level 2			000:00		
000000-006231CF	No		MEI (2)	27 Sep 2018	Level 2			000:00		
000000-0033764B	No		MEI (2)	27 Sep 2018	Level 2			000:00		
000000-006231D0	No		6 Monthly 6534 Insp	29 Mar 2018	Level 1			000:00		
000000-007A7DFD	No		6 Monthly 6534 Insp	29 Mar 2018	Level 1			000:00		
000000-0066E4B6	No		6 Monthly 6534 Insp	29 Mar 2018	Level 1			000:00		
000000-0033764C	No		6 Monthly 6534 Insp	29 Mar 2018	Level 1			000:00		
000000-00241394	No		MEI (2)	27 Sep 2018	Level 2			000:00		
000000-0048B6A1	No		6 Monthly 6534 Insp	29 Mar 2018	Level 1			000:00		

000000-00241395	No	6 Monthly 6534 Insp	29 Mar 2018	Level 1	000:00
000000-0027AEF7	No	6 Monthly 6534 Insp	29 Mar 2018	Level 1	000:00
000000-003EE3CE	No	6 Monthly 6534 Insp	29 Mar 2018	Level 1	000:00
000000-008A9151	No	6 Monthly 6534 Insp	29 Mar 2018	Level 1	000:00

Work Objects

Serial Number: LS19AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment by Usage Target Date	Usage Counter Units	Fault State Non-Taskworthy	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00693421	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Taskworthy	CL	Level 2			000:00
		This instruction details the fitting of additional lashing eyes to the front bumper and to the rear chassis rail. This modification is only applicable to those units who would be considering transporting the equipment as internal load by Air.													
000000-00643A23	00040			No	3/A	Mod				Fully Fit					
		This instruction details the removal of the existing six way lighting switch and the fitting of a seven way lighting switch to all variants including winter water vehicles.													
000000-00643A21	00044			No	3/A	Mod				Fully Fit					
000000-0062693E	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit					
000000-0062693F	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL	Level 2			
000000-00626945	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Limited Role	CL	Level 2			
000000-0061BECE	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0061BEE4	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			
000000-0061BECF	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061BEE3	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Limited Role	CL	Level 2			
000000-0061BEE5	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			

000000-0061BECC	00017	Introduction of Battery Retention	No	1/A	UTI	Non-Taskworthy	CL	Level 2
000000-0061BF12	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME	No	-/-	RTI	Fully Fit	CL	Level 2
000000-0061BF0F	00030	Front Belt Protection Sleeves	No	1/A	UTI	Non-Taskworthy	CL	Level 2
000000-0061BEE6	00025	Fitting of Spare Wheel Lifting Aid Harness	No	1/A	UTI	Non-Taskworthy	CL	Level 2
000000-0061BECA	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/	RTI	Limited Role	CL	Level 2
000000-0061BEE1	00001	Radio Rack Fixings	No	-/	RTI	Limited Role	CL	Level 2
000000-0061BF11	00035	Fitting of Emergency Hammer	No	1/A	UTI	Non-Taskworthy	CL	Level 2

Work Objects

Serial Number: LS19AA
 NSN: 2320998939742

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-002413A2		No	6 Monthly/10000 Kms OOPS 2 Yearly/20000 Kms Drain	10 Apr 2018	Level 1			000:00		
000000-00250A68		No	Engine Oil And Filter Change (1) OOPS 6 Yearly/120000 Kms	09 Oct 2019	Level 1			000:00		
000000-0024138A		No	Camshaft Timing Belt (2)	09 Nov 2018	Level 2			000:00		
000000-00337667		No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00		
000000-00250A3E		No	Yearly/20000 Kms OOPS 2 Yearly/20000 Kms Drain	09 Oct 2018	Level 1			000:00		
000000-002413A1		No	Engine Oil And Filter Change (1) OOPS 2 Yearly/40000 Kms Replace	09 Oct 2019	Level 1			000:00		
000000-002413A0		No	Air Cleaner Element (1)	09 Oct 2019	Level 1			000:00		
000000-00250A69		No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00		
000000-00337666		No	Yearly/20000 Kms	09 Oct 2018	Level 1			000:00		

		OOPS 2 Yearly/20000 Kms Drain					
000000-00250A3C	No	Engine Oil And Filter Change (1)	09 Oct 2019	Level 1			000:00
000000-0049BC27	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00
		OOPS 2 Yearly/20000 Kms Drain					
000000-007A7E67	No	Engine Oil And Filter Change (1)	09 Oct 2019	Level 1			000:00
		OOPS 5 Yearly Drain/Flush And					
000000-008A9481	No	Replen Cooling System	08 Oct 2022	Level 1			000:00
000000-006231D8	No	Yearly/20000 Kms	09 Oct 2018	Level 1			000:00
000000-00241389	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1			000:00
		OOPS 5 Yearly Drain/Flush And					
000000-00250A3F	No	Replen Cooling System	08 Oct 2022	Level 1			000:00
000000-007A7E66	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00
000000-0027AEC3	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00
		OOPS 2 Yearly/40000 Kms Replace					
000000-00250A67	No	Air Cleaner Element (1)	09 Oct 2019	Level 1			000:00
000000-00250A66	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1			000:00
000000-00541EB6	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00
000000-00250ABC	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1	Fully Fit	CL	000:00
		OOPS 2 Yearly/20000 Kms Drain					
000000-0049BC26	No	Engine Oil And Filter Change (1)	09 Oct 2019	Level 1			000:00
000000-0066E4C3	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00
		OOPS 5 Yearly/155000 Kms Drain					
000000-0024138B	No	And Replen Gearbox Oil (2)	08 Oct 2022	Level 2			000:00
		OOPS 2 Yearly/40000 Kms Replace					
000000-008A9188	No	Air Cleaner Element (1)	09 Oct 2019	Level 1			000:00
000000-006231D9	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00
000000-007A7E65	No	Yearly/20000 Kms	09 Oct 2018	Level 1			000:00
		OOPS 2 Yearly/40000 Kms Replace					
000000-0049BC25	No	Air Cleaner Element (1)	09 Oct 2019	Level 1			000:00
000000-008A9187	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1			000:00
000000-003EE3EF	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1			000:00

		OOPS 2 Yearly/40000 Kms Replace			
000000-00250A3B	No	Air Cleaner Element (1)	09 Oct 2019	Level 1	000:00
000000-00250A38	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1	000:00
		OOPS 5 Yearly/155000 Kms Drain			
000000-008A9189	No	And Replen Gearbox Oil (2)	08 Oct 2022	Level 2	000:00
000000-00250A6A	No	Yearly/20000 Kms	09 Oct 2018	Level 1	000:00
000000-0045AD8E	No	Weekly (AR)(1)		Level 1	000:00
000000-00250A3D	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1	000:00
		OOPS 5 Yearly Drain/Flush And			
000000-002413A4	No	Replen Cooling System	08 Oct 2022	Level 1	000:00
		OOPS 6 Yearly/120000 Kms			
000000-00250A39	No	Camshaft Timing Belt (2)	09 Nov 2018	Level 2	000:00
000000-008A918B	No	Yearly/20000 Kms	09 Oct 2018	Level 1	000:00
		OOPS 5 Yearly/155000 Kms Drain			
000000-00250A3A	No	And Replen Gearbox Oil (2)	08 Oct 2022	Level 2	000:00
		OOPS 2 Yearly/20000 Kms Drain			
000000-008A918C	No	Engine Oil And Filter Change (1)	09 Oct 2019	Level 1	000:00
000000-0049BC24	No	Yearly/20000 Kms	09 Oct 2018	Level 1	000:00
000000-008A918A	No	6 Monthly/10000 Kms	10 Apr 2018	Level 1	000:00
000000-0049BC23	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1	000:00
000000-007A7E64	No	2 Yearly/40000 Kms	09 Oct 2019	Level 1	000:00
000000-002413A3	No	Yearly/20000 Kms	09 Oct 2018	Level 1	000:00