



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

---

[REDACTED]

email: [REDACTED]  
[REDACTED]

Our Reference:  
FOI2023/07401  
Date:  
22 June 2023

---

Dear [REDACTED]

I am writing about your email of 14 June 2023, requesting the following information:

*I am making this Freedom of Information Request to inquire whether you have any vehicle Merlin Reports, Vehicle Record Cards or any other service history on my Land Rover Defender 110 Wolf soft top.*

*I have checked the Merlin archives and a previous owners FOI request, but there isn't anything about Units it was posted to, or where the vehicle has previously served, and from a modification stance, it's history.*

*Army Reg no: ME66AA*

*Chassis no. : SALLDBA67WA147338*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOI Act).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. The information identified relating to this vehicle is attached, as follows:

- Annex A – Owner History
- Annex B – Fault History (redacted)
- Annex C – Inspection History
- Annex D – Modification History
- Annex E – Servicing History

It has proved necessary to withhold some information in accordance with qualified exemptions of the FOI Act. Some of the commercially sensitive information in the Fault History (Annex B) relates to contractor repair times, which have been withheld under qualified exemption Section 43(2) (Commercial Interests). Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

**Defence Equipment & Support**

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

You may wish to note that when the Management of Equipment, Resources, and Liabilities Information Network (MERLIN) database was archived into its current format some data may have been lost or corrupted. You should therefore be cautious that some of the owner history data may be inaccurate.

I can advise that no other information on this vehicle is held.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat

**VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
ME66AA	2320998939963	NB50103101	LV2A/088DUM	TRUCK UTY MED (TUM HS) 4X4 SOFT TOP LANDROVER 2.5LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
03/06/1998	SALLDBA67WA147338	25LO5320B		

**VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
ME66AA	3		CA005A	JSCS ASHCHURCH		35003AA	03/06/1998	
ME66AA	4	07/08/1998	A0512A	1 WG	41508A	309	24/08/1998	
ME66AA	4	25/02/1999	A0344A	BFPO	999	239N99	25/02/1999	
ME66AA	4	20/04/1999	A9049A	UK SP UNIT (ARRC)	160	0762A57	15/06/1999	
ME66AA	4	19/09/1999	A9046A	UK CSS BN (CSAT)	74	2177	29/10/1999	A81
ME66AA	4	30/03/2003	A0227A	40 REGT RA(THE LOWLAND GUNNERS)	1335	6333	15/05/2003	T81
ME66AA	4	07/07/2003	A9105A	ARTY BG	866	1	30/07/2003	H/T
ME66AA	4	28/10/2003	A0227A	40 REGT RA(THE LOWLAND GUNNERS)	112	6813	10/11/2003	H/T
ME66AA	4	01/03/2004	A0571A	1 MERCIAN	995	4174	18/03/2004	U68
ME66AA	4	24/08/2005	A2239A	4 RIFLES	N/K	N/K	24/08/2005	H/T
ME66AA	2	15/06/2009	A0573A	R WELSH CO ORD CELL	64242	58523	25/06/2009	A29

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
ME66AA		15/02/2012		19 CSS BN 10 BDE SP SQN			15/02/2012	
ME66AA		24/04/2012		1 R WELSH CIS PLATOON			24/04/2012	
ME66AA		08/05/2014		2 YORKS MT			19/05/2014	
ME66AA		27/11/2019		OSVP HOLDINGS			10/12/2019	
ME66AA		05/07/2021		2 YORKS			05/07/2021	

Work Objects

Serial Number: ME66AA  
 NSN: 2320998939963

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B7D9C9		INVESTIGATE VEHICLE PULLING LEFT UNDER ACCELERATION	Closed	Non-Taskworthy	No	Level 2		05 Nov 2019	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00B775D3		INVESTIGATE VEHICLE PULLING RIGHT UNDER BRAKING	Closed	Non-Taskworthy	No	Level 2		31 Oct 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B775D6		INVESTIGATE VEHICLE PULLING LEFT UNDER NORMAL DRIVING	Closed	Non-Taskworthy	No	Level 2		31 Oct 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B435F2		RENEW O/S PANHARD BUSH	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B43615		INVESTIGATE LEAK @ STEERING BOX	Closed	Fully Fit	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B4361B		INVESTIGATE LEAK @ ROCKER COVER	Closed	Fully Fit	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B43619		INVESTIGATE LEAK @ TRANSFER BOX	Closed	Fully Fit	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B43618		INVESTIGATE LEAK @ SUMP	Closed	Fully Fit	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B435F4		RENEW FRONT SHOCK BUSHES	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B435EE		RENEW A FRAME BALL JOINT	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Damage	TUM HS GS SOFT TOP			000:00
000000-00B435F0		RENEW BOTH TRACTA SEALS	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00B435ED		RENEW TBOX OUTPUT SEAL	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00B435E2		RENEW ALTERNATOR DUCTING HOSE	Closed	Fully Fit	No	Level 2		11 Jun 2019	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00B435E6		RENEW PARK BRAKE SHOES	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00B435E0		RENEW WATER PUMP	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00B435DD		RENEW FAN BELT TENSIONER	Closed	Non-Taskworthy	No	Level 2		11 Jun 2019	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00ADCB68		DRIVER SIDE DOOR LOCK FAULTY	Closed	Fully Fit	No	Level 2		14 Sep 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A60EBO		MAP LIGHT INOP	Closed	Fully Fit	No	Level 2		09 Oct 2017	N/A	Closed No Action	TUM HS GS SOFT TOP			

000000-00AA5029	DRIVER AND PASSENGER DOOR SEALS PERISHED	Closed	Fully Fit	No	Level 2	09 Apr 2018	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00B2355E	SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP	
000000-00B209E0	SNvE 377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP	
000000-00AF54ED	EXHAUST DOWN PIPE INSECURE	Closed	Non-Taskworthy	No	Level 2	15 Nov 2018	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00A432F7	Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment Instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role Non-Taskworthy	No	Level 2	31 Jul 2017	N/A	No Fault Found	TUM HS GS SOFT TOP	
000000-00AB6559	RENEW FUEL LIFT PUMP	Closed	Taskworthy	No	Level 2	25 May 2018	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-00AB6558	000000-00336D60 CLUTCH PEDAL NOT RETURNING	Closed	Fully Fit Non-Taskworthy	No	Level 2	25 May 2018	N/A	Failure Closed No Action	TUM HS GS SOFT TOP	000:00
000000-00AB0A47	RENEW VALVE ON SPARE WHEEL	Closed	Taskworthy Non-Taskworthy	No	Level 1	11 May 2018	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00AB0A45	RENEW TYRE	Closed	Taskworthy	No	Level 1	11 May 2018	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00A60EB5	DASH SIDE LIGHT TELL TALE LAMP INOP	Closed	Fully Fit	No	Level 2	09 Oct 2017	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00A60FDB	REQUIRES REME ROAD TEST	Closed	Fully Fit Non-Taskworthy	No	Level 2	09 Oct 2017	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00A5D104	RENEW ANTI ROLE BAR AND JOINTS	Closed	Taskworthy	No	Level 2	29 Sep 2017	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-00A50CF9	RENEW REAR PROP RENEW PARK BRAKE SHOES DUE TO CONTAMINATION FROM LEAK @ T'BOX OUTPUT SEAL	Closed	Fully Fit Non-Taskworthy	No	Level 2	07 Sep 2017	N/A	Failure Closed No Action	TUM HS GS SOFT TOP	
000000-00A02166	RENEW T,BOX OUTPUT SEAL	Closed	Taskworthy Non-Taskworthy	No	Level 2	16 Feb 2017	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-009FF303	INVESTIGATE CHIP IN WINDSCREEN	Closed	Fully Fit	No	Level 2	08 Feb 2017	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-009FF2FF	INVESTIGATE BACKLIGHT FOR SPEEDO INOP	Closed	Limited Role	No	Level 2	08 Feb 2017	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-009D2DFA	FUEL GAUGE INOP	Closed	Fully Fit	No	Level 2	14 Oct 2016	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-008BD24F	RENEW WINDSCREEN SEAL	Closed	Fully Fit	No	Level 2	04 Sep 2015	N/A	Closed No Action	TUM HS GS SOFT TOP	
000000-0097E300	VIN PLATE MISSING	Closed	Fully Fit	No	Level 2	17 Mar 2016	N/A	Inspection	TUM HS GS SOFT TOP	
000000-00A0215F	RENEW ALL WHEEL BEARINGS.	Closed	Fully Fit	No	Level 2	16 Feb 2017	N/A	Failure	TUM HS GS SOFT TOP	
000000-00A02155	RENEW NO2 BALL JOINT	Closed	Fully Fit	No	Level 2	16 Feb 2017	N/A	Failure	TUM HS GS SOFT TOP	
000000-00A0215D	RENEW ALL STUB AXLES DUE TO DAMAGE	Closed	Fully Fit	No	Level 2	15 Feb 2017	N/A	Failure	TUM HS GS SOFT TOP	
000000-009FF2FC	RENEW INDICATOR STALK	Closed	Fully Fit	No	Level 2	08 Feb 2017	N/A	Failure	TUM HS GS SOFT TOP	
000000-008E2EB7	Renew rear view mirror	Closed	Fully Fit	No	Level 1	07 Dec 2015	N/A	Damage	TUM HS GS SOFT TOP	

000000-008BD24E	DAMAGE TO PASSENGER DOOR POCKET	Closed	Fully Fit	No	Level 1	03 Sep 2015	N/A	Damage	TUM HS GS SOFT TOP
000000-009B6960	INVESTIGATE NON STARTER	Closed	Fully Fit	No	Level 2	28 Jul 2016	N/A	Failure	TUM HS GS SOFT TOP
000000-009602F8	INVESTIGATE FUEL GAUGE INOP	Closed	Limited Role	No	Level 2	18 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-0096A37D	please carry out mei once ntw jobs complete	Closed	Non- Taskworthy	No	Level 2	05 Feb 2016	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-008C75F0	RENEW CLUTCH DUE TO EXCESSIVE JUDDER	Closed	Fully Fit	No	Level 2	29 Sep 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-00963C7D	RENEW WATER PUMP	Closed	Fully Fit	No	Level 2	21 Jan 2016	N/A	Failure	TUM HS GS SOFT TOP
000000-00960D7D	Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non- Taskworthy	No	Level 2	000000- 000031EF 19 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-008EA71C	CARRY OUT SEFIT INSPECTION IN LINE WITH LE SNVE 00063	Closed	Non- Taskworthy	No	Level 2	17 Dec 2015	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-008C7F48	FUEL LEAK TO FUEL TANK	Closed	Fully Fit	No	Level 2	01 Oct 2015	N/A	No Fault Found	TUM HS GS SOFT TOP
000000-008C6772	INVESTIGATE FOR LACK OF CLUTCH FLUID	Closed	Fully Fit	No	Level 2	28 Sep 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008959EC	000000- 0030BA6B RENEW GEARBOX OIL COOLER PIPES	Closed	Fully Fit	No	Level 2	15 May 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008BD682	000000- 0030BA6B INVESTIGATE FUEL LEAK AT TANK	Closed	Non- Taskworthy	No	Level 2	07 Sep 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008ACEDB	000000- 0030BA6B TIGHTEN BOTH DOOR HINGES	Closed	Fully Fit	No	Level 2	17 Jul 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008ACECD	000000- 0030BA6B RENEW HEAD LIGHT GUARD	Closed	Fully Fit	No	Level 1	17 Jul 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008BCE85	000000- 0030B7C4 CARRY OUT 934 IAW JSP 930	Closed	Non- Taskworthy	No	Level 1	04 Sep 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008BCE82	000000- 0030B7C4 CARRY OUT 6M VM'S IAW 2320-D-128-601 TABLE 7	Closed	Non- Taskworthy	No	Level 2	04 Sep 2015	N/A	Servicing	TUM HS GS SOFT TOP
000000-008BCE7F	000000- 0030B7C4 CARRY OUT 6M SERVICE IAW 2320-D-128-601 TABLE 7	Closed	Non- Taskworthy	No	Level 1	04 Sep 2015	N/A	Servicing	TUM HS GS SOFT TOP
000000-008ACEE1	000000- 0030B7C4 REFIT GILLE	Closed	Fully Fit	No	Level 1	17 Jul 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008ACED8	000000- 0030B7C4 REFIT DASH	Closed	Fully Fit	No	Level 2	17 Jul 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008ACED6	000000- 0030B7C4 REFIT DRIVERS DOOR WINDOW SEAL	Closed	Fully Fit	No	Level 2	17 Jul 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-008ACED3	000000- 0030B7C4 REFIT GUN RACK PAD	Closed	Fully Fit	No	Level 1	17 Jul 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-00879C94	000000- 0030B7C4 RENEW AIR FILTER HOUSING GROMITS BROKE	Closed	Fully Fit	No	Level 1	26 Feb 2015	N/A	Inspection	TUM HS GS SOFT TOP
000000-008ACEC9	WASHERS INOP	Closed	Fully Fit	No	Level 2	17 Jul 2015	N/A	Failure No Fault Found	TUM HS GS SOFT TOP
000000-008ACEC7	COOLANT LEAK ON N/S BLOCK	Closed	Fully Fit	No	Level 2	17 Jul 2015	N/A	Failure No Fault Found	TUM HS GS SOFT TOP
000000-0089D44E	FUEL TANK LEAK	Closed	Fully Fit	No	Level 2	05 Jun 2015	N/A	Damage	TUM HS GS SOFT TOP
000000-0089D450	INVESTIGATE FUEL LEAK FROM AROUND TANK AREA	Closed	Non- Taskworthy	No	Level 2	05 Jun 2015	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-0089A289	SECURE WASHER PUMP	Closed	Limited Role	No	Level 2	28 May 2015	N/A	Closed No Action	TUM HS GS SOFT TOP

000000-0088FD79	000000-00305E4F	FUEL GAUGE ALWAYS READING FULL	Closed	Non-Taskworthy	No	Level 2	28 Apr 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-00841461		CARRY OUT MEI IAW JSP 930	Closed	Fully Fit	No	Level 2	07 Oct 2014	N/A	No Fault Found	TUM HS GS SOFT TOP
000000-0082FBEA		RENEW L/H/R ALIGNMENT ROD	Closed	Fully Fit	No	Level 2	20 Aug 2014	N/A	Damage	TUM HS GS SOFT TOP
000000-0084145A		CARRY OUT 6M SERVICE IAW 2320-D-128-601 TABLE 7	Closed	Fully Fit	No	Level 1	07 Oct 2014	N/A	Servicing	TUM HS GS SOFT TOP
000000-0086A6D1		RENEW EXHAUST COMPLETE	Closed	Fully Fit	No	Level 2	27 Jan 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-0086A6D4		RENEW WINDOW WIPER WHEEL BOXES (BOTH SIDES)	Closed	Fully Fit	No	Level 2	27 Jan 2015	N/A	Failure	TUM HS GS SOFT TOP
000000-0084F7C4		RENEW TOW PINTLE	Closed	Fully Fit	No	Level 2	13 Oct 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-0084145E		CARRY OUT 6M VM'S IAW 2320-D-128-601 TABLE 7	Closed	Fully Fit	No	Level 2	07 Oct 2014	N/A	Servicing	TUM HS GS SOFT TOP
000000-0084F3A2		RENEW TURBO EGR VALVE	Closed	Non-Taskworthy	No	Level 2	04 Nov 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-0084F3A0		RENEW TURBO LUBRICATION PIPE	Closed	Non-Taskworthy	No	Level 2	04 Nov 2014	N/A	Failure	TUM HS GS SOFT TOP
000000-0084F392		RENEW FAN BELT	Closed	Fully Fit	No	Level 2	04 Nov 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-0084F378		RENEW PANHARD ROD	Closed	Fully Fit	No	Level 2	04 Nov 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-0084BE6F		RENEW TURBO	Closed	Fully Fit	No	Level 2	27 Oct 2014	N/A	Failure	TUM HS GS SOFT TOP
000000-008447D4		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58 09 Oct 2014	Degraded	Inspection	TUM HS GS SOFT TOP
000000-00841455		REAR RIGHT CREW SEAT WON'T FOLD AWAY	Closed	Fully Fit	No	Level 1	07 Oct 2014	N/A	Damage	TUM HS GS SOFT TOP
000000-00841450		N/S CAM POLE HOLDER LOOSE	Closed	Fully Fit	No	Level 1	07 Oct 2014	N/A	Damage	TUM HS GS SOFT TOP
000000-0084144E		DRIVERS DOOR NOT CLOSING FULLY	Closed	Non-Taskworthy	No	Level 2	07 Oct 2014	N/A	Failure	TUM HS GS SOFT TOP
000000-00841449		HORN INOP	Closed	Non-Taskworthy	No	Level 2	07 Oct 2014	N/A	Failure	TUM HS GS SOFT TOP
000000-00841447		REAR DOOR CABLE SNAPPED	Closed	Fully Fit	No	Level 1	07 Oct 2014	N/A	Damage	TUM HS GS SOFT TOP
000000-0081430F	000000-002FD91E	SECURE SLAVE SOCKET COVER	Closed	Fully Fit	No	Level 2	29 May 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-00814307	000000-002FD91E	REPLACE BONNET STAY CLIP	Closed	Fully Fit	No	Level 2	29 May 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-00814302	000000-002FD91E	REPLACE MISSING BATTERY CLAMP BOLT	Closed	Fully Fit	No	Level 2	29 May 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-008142FA	000000-002FD91E	REPLACE MISSING DASH BLANKING PLUG	Closed	Fully Fit	No	Level 2	29 May 2014	N/A	Inspection	TUM HS GS SOFT TOP
000000-00838F4B	000000-002FC8A8	HORN INOP	Closed	Non-Taskworthy	No	Level 1	19 Sep 2014	N/A	Failure	TUM HS GS SOFT TOP
000000-0082FBE9	000000-002FC66B	RENEW PANHARD ROD	Closed	Non-Taskworthy	No	Level 2	21 Aug 2014	N/A	Damage	TUM HS GS SOFT TOP
000000-00814314	000000-002F9BAF	REPLACE FOAM PADS ON WEAPON STOWAGE SYSTEM	Closed	Fully Fit	No	Level 2	29 May 2014	N/A	Inspection	TUM HS GS SOFT TOP



000000-007BDEFC	000000-002F9279	RENEW 5X TYRES(DMDD IN ERROR FOR ME89AA)	Closed	Limited Role	No	Level 1	07 Oct 2013	N/A	Failure	TUM HS GS			
000000-008140FA	000000-002F9272	REPLACE HEATER FAN	Closed	Non-Taskworthy	No	Level 2	29 May 2014	N/A	Inspection	SOFT TOP			
000000-00814A27		RECTIFY STOP LIGHTS	Closed	Non-Taskworthy	No	Level 2	29 May 2014	N/A	Closed No Action	TUM HS GS			
000000-0080E152	000000-002F7A2F	CARRY OUT MEI IAW JSP 930	Closed	Non-Taskworthy	No	Level 2	21 May 2014	N/A	Inspection	SOFT TOP	2 YORKS LIGHT AID	USA LAD	
000000-0080E13C	000000-002F7A2F	CARRY OUT 1 YEARLY VM'S IAW 2320-D-128-601	Closed	Non-Taskworthy	No	Level 2	21 May 2014	N/A	Servicing	SOFT TOP	2 YORKS LIGHT AID	USA LAD	
000000-0080E137	000000-002F7A2F	CARRY OUT 1 YEARLY SERVICE IAW 2320-D-128-601	Closed	Non-Taskworthy	No	Level 1	21 May 2014	N/A	Servicing	SOFT TOP	2 YORKS LIGHT AID	USA LAD	
000000-008064FF		CARRY OUT 5 YRLY OOP (GEARBOX OIL)	Closed	Non-Taskworthy	No	Level 1	30 Apr 2014	N/A	Closed No Action	TUM HS GS			
000000-008064F9		CARRY OUT 5 YRLY OOP (COOLING SYSTEM)	Closed	Non-Taskworthy	No	Level 1	30 Apr 2014	N/A	Closed No Action	SOFT TOP			
000000-008014F3	000000-002F5AE6	RENEW VEHICLE BATTERIES	Closed	Non-Taskworthy	No	Level 1	11 Apr 2014	N/A	Failure	TUM HS GS			
000000-007D0E2C	000000-002F5993	RENEW FUEL LIFT PUMP	Closed	Fully Fit	No	Level 2	28 Nov 2013	N/A	Failure	SOFT TOP			
000000-007C849F	000000-002F5993	EXCESSIVE LEAK @ F/L TRACTA SEAL	Closed	Non-Fully Fit	No	Level 2	05 Nov 2013	N/A	Inspection	TUM HS GS			
000000-007DF9DE	000000-002F5993	OOPM IAW 2320-D-128-601 T5 TIMING BELT	Closed	Non-Taskworthy	No	Level 2	22 Jan 2014	N/A	Servicing	SOFT TOP			
000000-007C84A5		FIT RIFLE STOWAGE BUMPERS	Closed	Fully Fit	No	Level 2	05 Nov 2013	N/A	Inspection	TUM HS GS			
000000-007BACFB		RENEW 2 X WHEEL STUDS @ F/L HUB	Closed	Non-Taskworthy	No	Level 2	29 Sep 2013	N/A	Damage	SOFT TOP			
000000-0078D00F		REPAIR/RENEW FUEL FILTER STAP	Closed	Fully Fit	No	Level 2	23 May 2013	N/A	Inspection	TUM HS GS			
000000-0078D00B		RENEW REAR EXHAUST SECTION	Closed	Fully Fit	No	Level 2	23 May 2013	N/A	Inspection	SOFT TOP			
000000-00786B14		RENEW PASSANGER WINDOW	Closed	Fully Fit	No	Level 2	06 May 2013	N/A	Damage	TUM HS GS			
000000-007C160C		SPARE TYRE	Closed	Non-Taskworthy	No	Level 2	17 Oct 2013	N/A	Closed No Action	SOFT TOP			
000000-0079EF67		RENEW R/R TIRE	Closed	Non-Taskworthy	No	Level 1	04 Jul 2013	N/A	Failure	TUM HS GS			
000000-007A0177		RENEW FRONT LEFT BRAKE PIPE	Closed	Non-Taskworthy	No	Level 2	09 Jul 2013	N/A	Damage	SOFT TOP			
000000-0078D00D	000000-002E5D57	RECT HORN INOP	Closed	Non-Taskworthy	No	Level 2	24 May 2013	N/A	Inspection	TUM HS GS			
000000-0078D00A	000000-002E5D57	RECT SEEPAGE AT F/L TRACTOR SEAL	Closed	Fully Fit	No	Level 2	24 May 2013	N/A	Inspection	SOFT TOP			
000000-00785D56	000000-002E5D57	RENEW GRILLE	Closed	Fully Fit	No	Level 2	03 May 2013	N/A	Damage	TUM HS GS			000:00
000000-00785D52	000000-002E5D57	BOTH FRONT WING PANNELS DISTORTED AFFECTING HEADLIGHT AIM	Closed	Non-Taskworthy	No	Level 2	03 May 2013	N/A	Damage	SOFT TOP			000:00
000000-00782089	000000-002E5D57	RENEW BOTH FRONT WINGS	Closed	Non-Taskworthy	No	Level 2	23 Apr 2013	N/A	Failure	TUM HS GS			000:00
000000-00785D59		RENEW GRILLE SURROUND	Closed	Fully Fit	No	Level 1	03 May 2013	N/A	Damage	SOFT TOP			000:00
000000-0079C04F		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUM HS GS		

000000-007990A1		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUM HS GS SOFT TOP	
000000-00785D54	000000-002E5D57	RENEW REAR AXLE	Closed	Fully Fit	No	Level 2		03 May 2013	N/A	Damage	TUM HS GS SOFT TOP	000:00
000000-00782090		CARRY OUT DAMAGE REPORT FOR RTA INSP	Closed	Non-Taskworthy	No	Level 2		23 Apr 2013	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00762A0B		NOCKING NOISE ON FLH WHEEL	Closed	Fully Fit	No	Level 1		30 Jan 2013	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-0071A1FA	000000-002DA67F	CARRY OUT ANNUAL MEI IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2		03 Jun 2012	N/A	Inspection	TUM HS GS SOFT TOP	
000000-0071A067	000000-002DA67F	CARRY OUT L2 TASKS IAW AESP 2320-D-128-601 T7 COL B (1 YRLY VMs)	Closed	Non-Taskworthy	No	Level 2		01 Jun 2012	N/A	Servicing	TUM HS GS SOFT TOP	
000000-0071A066	000000-002DA67F	CARRY OUT L1 TASKS IAW AESP 2320-D-128-601 T7 COL B (1 YRLY)	Closed	Non-Taskworthy	No	Level 1		01 Jun 2012	N/A	Servicing	TUM HS GS SOFT TOP	
000000-007412CB	000000-002DA67F	RECT INSECURE BONNET	Closed	Non-Taskworthy	No	Level 2		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412D9	000000-002DA67F	CORRECT ENGINE COOLANT SG READING (CURRENTLY -24)	Closed	Non-Taskworthy	No	Level 1		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007448C8	000000-002DA67F	RNW RADIATOR ASSY	Closed	Non-Taskworthy	No	Level 2		16 Oct 2012	N/A	Refurbishment	TUM HS GS SOFT TOP	
000000-007412DD	000000-002DA67F	FIT DIFFY SPACER/WASHERS TO FRONT LASH DOWN POINTS	Closed	Limited Role	No	Level 1		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412DB	000000-002DA67F	RNW 1 X REAR SEAT ASSY (R/R/H)	Closed	Limited Role	No	Level 1		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412D3	000000-002DA67F	INV TURBO LEAKING OIL (NEW TURBO FITTED)	Closed	Non-Taskworthy	No	Level 2		08 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412D1	000000-002DA67F	RECT EXHAUST MANIFOLD BLOWING	Closed	Non-Taskworthy	No	Level 2		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412CE	000000-002DA67F	INV POOR CLUTCH OPERATION	Closed	Non-Taskworthy	No	Level 2		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412CA	000000-002DA67F	RNW SPARE TYRE & R/R/H TYRES (CLOSE TO WEAR LIMIT)	Closed	Fully Fit	No	Level 1		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412C6	000000-002DA67F	RNW L/H TUAAM MNT (ACCESS DOOR DIFFY)	Closed	Fully Fit	No	Level 2		09 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP	
000000-007412C5	000000-002DA67F	CARRY OUT MOD IAW AESP 2320-D-128-811-0037 - GLOW PLUG HARNESS	Closed	Non-Taskworthy	No	Level 2		09 Oct 2012	N/A	Modification	TUM HS GS SOFT TOP	
000000-007412C2	000000-002DA67F	CARRY OUT GI 17 IAW AESP 2320-D-128-821 - TAILGATE STRAPS	Closed	Fully Fit	No	Level 2		09 Oct 2012	N/A	Modification	TUM HS GS SOFT TOP	
000000-0071ECFA	000000-002DA67F	RNW CANOPY - TORN	Closed	Limited Role	No	Level 1		20 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-0071ECF3	000000-002DA67F	CARRY OUT IAW AESP 2320-D-128-811-0039 - MOD 39 - PROJECT REMUS 1	Closed	Fully Fit	No	Level 3		19 Jun 2012	N/A	Modification	TUM HS GS SOFT TOP	000:00
000000-0060DBD5	000000-002DA67F	renew front left (passenger side) recovery shackle	Closed	Fully Fit	No	Level 1		09 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-0060DBD0	000000-002DA67F	fit diffy passengeer side front air ducting	Closed	Fully Fit	No	Level 2		09 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-00379215	000000-002DA67F	RECTIFY CAB HEATER SWITCH INOP ( PART ON DEMAND )	Closed	Fully Fit	No	Level 2		12 Jan 2009	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-0060DBD1	000000-002DA67F	renew air filter bracket	Closed	Fully Fit	No	Level 1		09 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-005CFAB9	000000-002DA67F	front left wing damaged	Closed	Fully Fit	No	Level 2		11 Jan 2011	N/A	Damage	TUM HS GS SOFT TOP	000:00

000000-0060DBCE	000000-002DA67F	renew heater switch	Closed	Fully Fit	No	Level 2	09 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-004BDECE	000000-002DA67F	NO HEATING ON THE SIDE OF DASUBOARD	Closed	Fully Fit	No	Level 2	21 Jan 2010	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-006E2DAB		6 Monthly VM'S	Closed	Non-Taskworthy	No	Level 2	01 Dec 2011	N/A	Servicing	TUM HS GS SOFT TOP	000:00
000000-006E2DA8		6 Monthly SER	Closed	Non-Taskworthy	No	Level 1	01 Dec 2011	N/A	Servicing	TUM HS GS SOFT TOP	000:00
000000-006CA231		cluch	Closed	Non-Taskworthy	No	Level 3	15 Sep 2011	N/A	Damage	TUM HS GS SOFT TOP	000:00
000000-0060DC57		renew rear wheel bearings	Closed	Non-Taskworthy	No	Level 2	09 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	
000000-006B0B3C		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-0000031B 22 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	
000000-0061791C		steering drop arm insp	Closed	Fully Fit	No	Level 2	16 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-0060D78E		MEI	Closed	Non-Taskworthy	No	Level 2	09 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP	000:00
000000-005E271C		STARTER MOTOR U/S	Closed	Non-Taskworthy	No	Level 2	02 Mar 2011	N/A	Inspection	TUM HS GS SOFT TOP	
000000-005D2A65		EXIESS NOISE FROM ENGINE	Closed	Non-Taskworthy	No	Level 2	18 Jan 2011	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-005D2A59		EXNAUST MANIFOLD BLOWING	Closed	Non-Taskworthy	No	Level 2	18 Jan 2011	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-005D29DA		RENEW RADIATOR	Closed	Non-Taskworthy	No	Level 2	18 Jan 2011	N/A	Failure	TUM HS GS SOFT TOP	000:00
000000-005CFA28		wheels new ones x3	Closed	Fully Fit	No	Level 1	11 Jan 2011	N/A	Servicing	TUM HS GS SOFT TOP	
000000-0051F103	000000-002B8533	Map light inop	Closed	Fully Fit	No	Level 1	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051EC87	000000-002B802B	MEI	Closed	Non-Taskworthy	No	Level 2	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F13C	000000-002B8536	Renew steering damper	Closed	Non-Taskworthy	No	Level 2	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F13B	000000-002B8536	Renew steering box lower bracket	Closed	Non-Taskworthy	No	Level 2	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F136	000000-002B8536	Renew steering box drop arm	Closed	Non-Taskworthy	No	Level 2	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F12F	000000-002B8536	Renew front brake discs and pads	Closed	Non-Taskworthy	No	Level 2	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F12D	000000-002B8536	Renew L/H/R Panhard rod	Closed	Non-Taskworthy	No	Level 2	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051E19E	000000-002B7E5E	KNOCKING WHEN STEERING	Closed	Non-Taskworthy	No	Level 2	09 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F13F	000000-002B8533	Free off front tie down points	Closed	Fully Fit	No	Level 1	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F11E	000000-002B8533	Rectify incorrect milage on JAMES	Closed	Fully Fit	No	Level 1	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F11C	000000-002B8533	Fit missing screw to R/H/R brake light	Closed	Fully Fit	No	Level 1	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F11B	000000-002B8533	Clean paint from 24v sign at NATO socket	Closed	Fully Fit	No	Level 1	16 Jun 2010			TUM HS GS SOFT TOP	
000000-0051F10E	000000-002B8533	Renew number plate light cover	Closed	Fully Fit	No	Level 1	16 Jun 2010			TUM HS GS SOFT TOP	

000000-0051F10B	000000-002B8533	Stencil 'Acid splash' warning on battery cover	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051F107	000000-002B8533	Secure lower air vent in passenger footwell	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051FOFF	000000-002B8533	Secure passenger side wing mirror	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051FOFA	000000-002B8533	Stencil tyre pressures at all wheel stations	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051FOE9	000000-002B8533	Coolant overfilled	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051FOE8	000000-002B8533	Renew bonnet CES securing straps	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051F0D8	000000-002B8533	Adjust washer jets	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0051F0D6	000000-002B8533	Clean out interior of vehicle	Closed	Fully Fit	No	Level 1	16 Jun 2010	TUM HS GS SOFT TOP
000000-0050D136	000000-002B4B5E	1YEARLY VMS ASPER AESP TABLE 7 2320-D-128-601	Closed	Fully Fit	No	Level 2	24 May 2010	TUM HS GS SOFT TOP
000000-0050D131	000000-002B4B5E	1YEARLY SERVICE ASPER AESP TABLE 7 2320-D-128-601	Closed	Fully Fit	No	Level 1	24 May 2010	TUM HS GS SOFT TOP
000000-004FCD27	000000-002B0D9C	6 monthly VMS carried out as per aesp 2320-d-128-601 table 7 column a	Closed	Fully Fit	No	Level 2	27 Apr 2010	TUM HS GS SOFT TOP
000000-004FCD24	000000-002B0D9C	6 monthly service carried out as per aesp 2320-d-128-601 table 7 column a	Closed	Fully Fit	No	Level 1	27 Apr 2010	TUM HS GS SOFT TOP
000000-004BDEB7	000000-002A4B0C	WHEELS NEED TO BE BALANCEING	Closed	Limited Role	No	Level 1	21 Jan 2010	TUM HS GS SOFT TOP
000000-0049DA17	000000-0029EA03	6 MONTHLY VM TASKS AS PER AESP 601 TABLE 7	Closed	Non-Taskworthy	No	Level 2	18 Nov 2009	TUM HS GS SOFT TOP
000000-0049DA14	000000-0029EA03	6 MONTHLY SERVICE AS PER AESP 601 TABLE 7	Closed	Non-Taskworthy	No	Level 1	18 Nov 2009	TUM HS GS SOFT TOP
000000-00469B4B	000000-00295037	ALTERNATOR U/S	Closed	Taskworthy	No	Level 2	05 Aug 2009	TUM HS GS SOFT TOP
000000-004263B4		Carry out 5 yrl oopm table 5 ser 2.1 gear box drain and replen ( to be carried out by 20/05/14 )	Closed	Fully Fit	No	Level 1	21 May 2009	TUM HS GS SOFT TOP
000000-004263BD		Carry out 5 yrl oopm table 5 ser 3 drain, flush and re-fill cooling system ( to be carried out by 20/05/14 )	Closed	Fully Fit	No	Level 1	21 May 2009	TUM HS GS SOFT TOP
000000-0041EA28	000000-0028CE5F	CARRY OUT MEI ( RETEST )	Closed	Non-Taskworthy	No	Level 2	08 May 2009	TUM HS GS SOFT TOP
000000-0037FCCF	000000-00275A44	PLEASE CARRY OUT ANNUAL MEI	Closed	Non-Taskworthy	No	Level 2	14 Jan 2009	TUM HS GS SOFT TOP
000000-002157AE	000000-0027E83C	PLEASE INSPECT AND REPAIR REAR EXHAUST BRACKET	Closed	Non-Taskworthy	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-00424CE7	000000-0028DFB2	TABLE 5 SER 2.1 GEAR BOX DRAIN AND REPLEN	Closed	Non-Taskworthy	No	Level 1	20 May 2009	TUM HS GS SOFT TOP
000000-00424CDD	000000-0028DFB2	TABLE 5 SER 3 COOLING SYSTEM DRAIN, FLUSH AND REPLEN	Closed	Non-Taskworthy	No	Level 1	20 May 2009	TUM HS GS SOFT TOP
000000-00424CDC	000000-0028DFB2	TABLE 5 SER 4 AIR FILTER CHANGE	Closed	Non-Taskworthy	No	Level 1	20 May 2009	TUM HS GS SOFT TOP
000000-00424CD7	000000-0028DFB2	TABLE 5 SER 1 ENGINE OIL DRAIN AND REPLEN	Closed	Non-Taskworthy	No	Level 1	20 May 2009	TUM HS GS SOFT TOP
000000-00424B20	000000-0028DF71	CARRY OUT 2 YEARLY VM'S	Closed	Non-Taskworthy	No	Level 2	20 May 2009	TUM HS GS SOFT TOP

000000-00424B1E	000000-0028DF71	CARRY OUT 2 YEAR SERVICE	Closed	Non-Taskworthy	No	Level 1	20 May 2009	TUM HS GS SOFT TOP
000000-003D3E7C	000000-0028DF59	PLEASE CARRY OUT 1 YEAR VM'S PLEASE CARRY OUT 1 YEAR SERVICE (	Closed	Non-Taskworthy	No	Level 2	18 Feb 2009	TUM HS GS SOFT TOP
000000-003D3E7A	000000-0028DF59	AWAITING LEVEL 2 PARTS TO BE FITTED TO COMPLETE SERVICE	Closed	Non-Taskworthy	No	Level 1	18 Feb 2009	TUM HS GS SOFT TOP
000000-003791DD	000000-0028DF59	REPLACE SPARE WHEEL	Closed	Limited Role	No	Level 1	12 Jan 2009	TUM HS GS SOFT TOP
000000-0037922A	000000-0028CAC7	CARRY OUT RBT WHEN STEERING BOX REPAIRED	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-0037921F	000000-0028CAC7	CARRY OUT EMISSIONS TEST WHEN EXHAUST REPAIRED	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-00379210	000000-0028CAC7	RECTIFY EXHAUST BLOWING AT MANIFOLD AND DOWNPIPE ( PART ON DEMAND )	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-003791EE	000000-0028CAC7	RECTIFY EXCESSIVE PLAY IN R/H/R WHEEL BEARINGS ( PART ON DEMAND )	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-00379217	000000-00275A69	RECTIFY REVERSING LIGHT INOP	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-00379214	000000-00275A69	RECTIFY CAB HEATER CONTROL INOP	Closed	Fully Fit	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-003791F4	000000-00275A69	RECTIFY EXCESSIVE PLAY IN FRONT WHEEL BEARINGS	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-003791EA	000000-00275A69	RECTIFY EXCESSIVE PLAY IN DROP ARM BALL JOINT	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-003791E8	000000-00275A69	RECTIFY EXCESSIVE PLAY IN STEERING BOX	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-003791E4	000000-00275A69	RENEW BONNET CATCH	Closed	Limited Role	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-003791E0	000000-00275A69	REFIT HEADLIGHTS	Closed	Non-Taskworthy	No	Level 2	12 Jan 2009	TUM HS GS SOFT TOP
000000-002157B7	000000-0027E83C	PLEASE INSPECT AND REPAIR BRAKE WARNING LIGHT IS IN OP	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-001F1262	000000-0027E83C	RENEW HEADLIGHT GUARD SECURING CLIPS	Closed	Fully Fit	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP
000000-001F13DD	000000-0027E83C	RENEW BOTH BOTTOM DOOR HINGES	Closed	Fully Fit	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP
000000-001F17DB	000000-0027E83C	RENEW FAN	Closed	Fully Fit	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP
000000-002157B4	000000-0027E83C	PLEASE INSPECT AND REPAIR SEPAGE FROM FRONT DAMPNER	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-002157BB	000000-0027E83C	PLEASE INSPECT AND REPAIR HAND BRAKE IS VERY SLACK	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-002157C3	000000-0027E83C	PLEASE INSPECT AND REPAIR BRAKE ARE VERY SLOW TO ENGAGE TO STOP VEHICLE	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-002E1AAC	000000-00283B1A	PLEASE CARRY OUT 6 MONTHLY VM'S	Closed	Non-Taskworthy	No	Level 2	30 Oct 2008	TUM HS GS SOFT TOP
000000-0020084C	000000-0027E064	12 MONTHLY VM	Closed	Fully Fit	No	Level 2	10 Jul 2008	TUM HS GS SOFT TOP
000000-003348B3	000000-0028555D	PLEASE CARRY OUT 1 YEAR SERVICE	Closed	Non-Taskworthy	No	Level 1	24 Nov 2008	TUM HS GS SOFT TOP
000000-001F1275	000000-0027E83C	RENEW HEADLIGHT GUARD SECURING CLIPS	Closed	Fully Fit	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP

000000-0020084A	000000-0027E064	12 MONTHLY SERVIC	Closed	Non-Taskworthy	No	Level 1	10 Jul 2008	TUM HS GS SOFT TOP
000000-002E1A9C	000000-00283B1A	PLEASE CARRY OUT 6 MONTHLY SERVICE	Closed	Non-Taskworthy	No	Level 1	30 Oct 2008	TUM HS GS SOFT TOP
000000-002157AC	000000-0027E83C	PLEASE INSPECT AND REPAIR REAR ENG MOUNT BELL HOUSING	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-002157B0	000000-0027E83C	PLEASE INSPECT AND REPAIR BUSH ON REAR LEFT STEERING ROD PERRISHED	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUM HS GS SOFT TOP
000000-001F11FC		RENEW HEATER CONTROL ASSEM	Closed	Fully Fit	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP
000000-001F123A		RENEW HEADLIGHT GUARD SECURING CLIPS	Closed	Non-Taskworthy	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP
000000-001F133E		RENEW HEADLIGHT GUARD SECURING CLIPS	Closed	Fully Fit	No	Level 2	02 Jul 2008	TUM HS GS SOFT TOP
000000-00094415		NON STARTER BATTERIES STARTER MOTOR	Closed	Non-Taskworthy	No	Level 1	16 Oct 2007	TUM HS GS SOFT TOP
000000-0009D319		RENEW VISCOUS FAN	Closed	Fully Fit	No	Level 2	14 Nov 2007	TUM HS GS SOFT TOP
000000-0009D31A		RENEW SPARE WHEEL	Closed	Fully Fit	No	Level 1	14 Nov 2007	TUM HS GS SOFT TOP
000000-0007591B	000000-00271ADC	RENEW SHOCK ABS BUSHES	Closed	Non-Taskworthy	No	Level 2	27 Jun 2007	TUM HS GS SOFT TOP
000000-00075920	000000-00271ADC	REAR AXLE TIE RODS EXCESIVE PLAY IN BUSHES	Closed	Non-Taskworthy	No	Level 2	27 Jun 2007	TUM HS GS SOFT TOP
000000-00046FB1	000000-0026AECD	STEERING PUMP U/S	Closed	Non-Taskworthy	No	Level 2	18 Jan 2007	TUM HS GS SOFT TOP
000000-00046FB4	000000-0026AECD	FAN BELT SNAPPED	Closed	Non-Taskworthy	No	Level 2	18 Jan 2007	TUM HS GS SOFT TOP
000000-000400AA		EXHAUST MOUNTS	Closed	Non-Taskworthy	No	Level 2	07 Dec 2006	TUM HS GS SOFT TOP
000000-0003E44C		Initial Usage	Closed	Fully Fit	No	Level 1	02 Dec 2006	TUM HS GS SOFT TOP
000000-0003E452		Initial Maintenance	Closed	Fully Fit	No	Level 1	02 Dec 2006	TUM HS GS SOFT TOP

Work Objects

Serial Number: ME66AA  
 NSN: 2320998939963

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request		Maintenance Event Name	Next Due Date	Repair		Work Status	Estimated	Working Organisation	Repair Section
	Escalate Work	ID			Level	Fault State		Repair Time		
000000-003EE193	No		MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-007A2750	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00A61F24	No		Annual Brake Test (2) FMT933 (W) Role Equipment	08 Feb 2020	Level 2	Fully Fit	CL	000:00		
000000-00B60457	No		(2)*	26 Aug 2020	Level 2	Limited Role	CL	000:00		
000000-00238A7E	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-0094D7B0	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-004EA6E4	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-00A61F1F	No		Annual Headlight Alignment Check (2)	08 Feb 2020	Level 2	Fully Fit	CL	000:00		
000000-0031B31B	No		MEI (2)		Level 2	Non-Taskworthy	CL	000:00		

000000-00A62151	No	FMT934 Functional Check (1)*	26 Feb 2020	Level 1	Fully Fit	CL	000:00
000000-0059F30B	No	6 Monthly 6534 Insp FMT932 (W) 6 Monthly Safety		Level 1			000:00
000000-00B60456	No	Inspection (2)	26 Feb 2020	Level 2	Fully Fit	CL	000:00
000000-003D56BE	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-00238A7D	No	First Parade Insp (AR)(1)		Level 1			000:00
					Non-		
000000-0031D3F1	No	6 Monthly 6534 Insp		Level 1	Taskworthy	CL	000:00
000000-00A61EC1	No	FMT932 (W) 6 Monthly Safety	26 Feb 2020	Level 2	Fully Fit	CL	000:00
000000-006831F3	No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-00A62203	No	FMT930 Landworthiness (AR)		Level 1	Fully Fit	CL	000:00
000000-006831F5	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-0008FE88	No	MEI (2)		Level 2		CL	000:00
000000-000AD91D	No	MEI (2)		Level 2		CL	000:00
000000-00013500	No	MEI (2)		Level 2		CL	000:00
000000-0005428F	No	MEI (2)		Level 2		CL	000:00
000000-000544C7	No	MEI (2)		Level 2		CL	000:00
000000-00238A7C	No	MEI (2)		Level 2			000:00
000000-008958D5	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-00B6108D	No	FMT934 Functional Check (1)* FMT932 (W) Mandatory	26 Feb 2020	Level 1	Limited Role	CL	000:00
000000-00A61E17	No	Equipment Inspection (2)*	09 Jan 2020	Level 2	Fully Fit	CL	000:00
000000-00A61F64	No	FMT933 (W) Role Equipment	26 Aug 2020	Level 2	Fully Fit	CL	000:00
000000-00163EB2	No	6 Monthly 6534 Insp		Level 1		WiP	000:00
000000-00163E05	No	MEI (2)		Level 2			000:00
000000-00A61F29	No	Annual Smoke Emissions	08 Feb 2020	Level 2	Fully Fit	CL	000:00
000000-004E0C01	No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-0071715F	No	6 Monthly 6534 Insp		Level 1			000:00
000000-001A2F1A	No	6 Monthly 6534 Insp		Level 1			000:00



Work Objects

Serial Number: ME66AA  
 NSN: 2320998939963

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request		Maintenance Event Name	Next Due Date	Repair		Work Status	Estimated	Working Organisation	Repair Section
	Escalate Work	ID			Level	Fault State		Repair Time		
000000-003EE193	No		MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-007A2750	No		MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00A61F24	No		Annual Brake Test (2) FMT933 (W) Role Equipment	08 Feb 2020	Level 2	Fully Fit	CL	000:00		
000000-00B60457	No		(2)*	26 Aug 2020	Level 2	Limited Role	CL	000:00		
000000-00238A7E	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-0094D7B0	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-004EA6E4	No		6 Monthly 6534 Insp		Level 1			000:00		
000000-00A61F1F	No		Annual Headlight Alignment Check (2)	08 Feb 2020	Level 2	Fully Fit	CL	000:00		
000000-0031B31B	No		MEI (2)		Level 2	Non-Taskworthy	CL	000:00		

000000-00A62151	No	FMT934 Functional Check (1)*	26 Feb 2020	Level 1	Fully Fit	CL	000:00
000000-0059F30B	No	6 Monthly 6534 Insp FMT932 (W) 6 Monthly Safety		Level 1			000:00
000000-00B60456	No	Inspection (2)	26 Feb 2020	Level 2	Fully Fit	CL	000:00
000000-003D56BE	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-00238A7D	No	First Parade Insp (AR)(1)		Level 1			000:00
					Non-		
000000-0031D3F1	No	6 Monthly 6534 Insp		Level 1	Taskworthy	CL	000:00
000000-00A61EC1	No	FMT932 (W) 6 Monthly Safety	26 Feb 2020	Level 2	Fully Fit	CL	000:00
000000-006831F3	No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-00A62203	No	FMT930 Landworthiness (AR)		Level 1	Fully Fit	CL	000:00
000000-006831F5	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-0008FE88	No	MEI (2)		Level 2		CL	000:00
000000-000AD91D	No	MEI (2)		Level 2		CL	000:00
000000-00013500	No	MEI (2)		Level 2		CL	000:00
000000-0005428F	No	MEI (2)		Level 2		CL	000:00
000000-000544C7	No	MEI (2)		Level 2		CL	000:00
000000-00238A7C	No	MEI (2)		Level 2			000:00
000000-008958D5	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00
000000-00B6108D	No	FMT934 Functional Check (1)* FMT932 (W) Mandatory	26 Feb 2020	Level 1	Limited Role	CL	000:00
000000-00A61E17	No	Equipment Inspection (2)*	09 Jan 2020	Level 2	Fully Fit	CL	000:00
000000-00A61F64	No	FMT933 (W) Role Equipment	26 Aug 2020	Level 2	Fully Fit	CL	000:00
000000-00163EB2	No	6 Monthly 6534 Insp		Level 1		WiP	000:00
000000-00163E05	No	MEI (2)		Level 2			000:00
000000-00A61F29	No	Annual Smoke Emissions	08 Feb 2020	Level 2	Fully Fit	CL	000:00
000000-004E0C01	No	MEI (2)		Level 2	Fully Fit	CL	000:00
000000-0071715F	No	6 Monthly 6534 Insp		Level 1			000:00
000000-001A2F1A	No	6 Monthly 6534 Insp		Level 1			000:00

Work Objects

Serial Number: ME66AA  
 NSN: 2320998939963

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0069246E	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00627041	00038	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit					
000000-00627040	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit					
000000-0062703F	00032	Project SHOEHORN Revised Weight Data Plate		No	-/	UTI				Fully Fit	CL				
000000-0062702C	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants)		No	-/-	UTI				Fully Fit					
000000-0062702B	00028	FITTING OF REAR ANTI-ROLL BAR (RARB) Input/Output Porthole for		No	-/	UTI				Fully Fit	CL				
000000-0062703E	00027	Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL				
000000-0062702A	00016	Radio Battery Isolation Switch and Power Import / Export System		No	-/	RTI				Fully Fit	CL				
000000-00627028	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Fully Fit					
000000-00627026	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL				
000000-00627025	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL				
000000-00627024	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL				
000000-00627058	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-00627051	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00

000000-00627031	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME	No	-/-	RTI	Fully Fit	CL	Level 2	000:00
000000-00627059	00024	Fitting of Trailer Breakaway Attachment Plate	No	-/	UTI	Fully Fit	CL	Level 2	000:00
000000-0062704D	00037	Fitting Glow Plug Timer Interface Harness	No	-/	UTI	Fully Fit	CL	Level 2	000:00
000000-00627037	00019	Blackout Cover for Warning Light Panel	No	-/-	UTI	Fully Fit	CL	Level 2	000:00
000000-00627056	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation	No	-/-	UTI	Fully Fit	CL	Level 2	000:00
000000-000247B8	00017	Introduction of Battery Retention	No	1/A	UTI	Fully Fit	CL		
000000-00025657	00014	Fitting of Showerproof Dash Cover	No	-/-	RTI	Fully Fit	CL		
000000-0001AB19	00004	Fitting Emergency Lights, Siren and Harness	No	-/-	RTI	Fully Fit	CL		
000000-000216B8	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/	RTI	Fully Fit	CL		

Work Objects

Serial Number: ME66AA  
 NSN: 2320998939963

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00B14C91		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	02 Jun 2024	Level 2	Fully Fit	CL	000:00		
000000-008958BF		No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00		
000000-006831F1		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-003D56AE		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-0023355C		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	02 Jun 2024	Level 2			000:00		
000000-00161E7F		No	Yearly/20000 Kms	21 Oct 2020	Level 1		WiP	000:00		
000000-004B9250		No	2 Yearly/40000 Kms	19 Sep 2021	Level 1	Fully Fit	CL	000:00		
000000-0027F80A		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	22 Sep 2021	Level 1	Fully Fit	CL	000:00		
000000-00A0F415		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-007A2742		No	2 Yearly/40000 Kms	19 Sep 2021	Level 1	Fully Fit	CL	000:00		
000000-006831FF		No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00		
000000-00B7DE77		No	2 Yearly/40000 Kms	19 Sep 2021	Level 1	Fully Fit	CL	000:00		
000000-0027F7BD		No	2 Yearly/40000 Kms	19 Sep 2021	Level 1	Fully Fit	CL	000:00		
000000-001A2F16		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1			000:00		
000000-00233544		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	14 Feb 2021	Level 1			000:00		
000000-001DFBCB		No	Yearly/20000 Kms	21 Oct 2020	Level 1		WiP	000:00		
000000-00161E80		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		WiP	000:00		
000000-003CDCB8		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	07 Apr 2020	Level 2	Non-Taskworthy	CL	000:00		
000000-00A0022A		No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00		
000000-0023356E		No	Weekly (AR)(1)		Level 1		WiP	000:00		
000000-00AD74A2		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Limited Role	CL	000:00		
000000-0071715C		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-00B7F1FD		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00		
000000-0027FADC		No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00		
000000-003EE18F		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	02 Jun 2024	Level 1	Non-Taskworthy	CL	000:00		
000000-0059F308		No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Non-Taskworthy	CL	000:00		

000000-003EE192	No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00
000000-008958BE	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-004EA6BD	No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00
000000-00942DBD	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-0023355D	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	02 Jun 2024	Level 1			000:00
000000-0027F7BB	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	14 Feb 2021	Level 1	Fully Fit	CL	000:00
000000-0027FADB	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-0031AB1C	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Non-Taskworthy	CL	000:00
000000-00233529	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	07 Apr 2020	Level 2		WiP	000:00
000000-000CD019	No	Weekly (AR)(1)		Level 1		CL	000:00
000000-000B31CE	No	2 Yearly/40000 Kms	19 Sep 2021	Level 1		CL	000:00
000000-000DD521	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-000B31CF	No	Yearly/20000 Kms	21 Oct 2020	Level 1		CL	000:00
000000-0008270B	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-0008270C	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-0008270D	No	Yearly/20000 Kms	21 Oct 2020	Level 1		CL	000:00
000000-0008270E	No	2 Yearly/40000 Kms	19 Sep 2021	Level 1		CL	000:00
000000-0008270F	No	Weekly (AR)(1)		Level 1		CL	000:00
000000-000BD6FB	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-00090130	No	Yearly/20000 Kms	21 Oct 2020	Level 1		CL	000:00
000000-00090131	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-000F5564	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00
000000-0008F67E	No	Yearly/20000 Kms	21 Oct 2020	Level 1		CL	000:00
000000-0008F67F	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-000DFA92	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-0000DC90	No	2 Yearly/40000 Kms	19 Sep 2021	Level 1		CL	000:00
000000-0000DC91	No	Yearly/20000 Kms	21 Oct 2020	Level 1		CL	000:00
000000-0000DC92	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-0000DC93	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-0002D56A	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-0004972C	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		CL	000:00
000000-0004F8AF	No	Yearly/20000 Kms	21 Oct 2020	Level 1		CL	000:00
000000-007A2743	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	14 Feb 2021	Level 1	Fully Fit	CL	000:00
000000-003EE171	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	02 Jun 2024	Level 2	Fully Fit	CL	000:00
000000-00A937B7	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	14 Feb 2021	Level 1	Fully Fit	CL	000:00
000000-0023356F	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		WiP	000:00
000000-004E0C00	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	22 Sep 2021	Level 1	Fully Fit	CL	000:00
000000-0023356D	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	22 Sep 2021	Level 1			000:00
000000-00159C5D	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1		WiP	000:00
000000-004E0BFF	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	14 Feb 2021	Level 1	Fully Fit	CL	000:00
000000-00BA4ED4	No	Yearly/20000 Kms	21 Oct 2020	Level 1	Fully Fit	CL	000:00
000000-004E085C	No	6 Monthly/10000 Kms	20 Mar 2020	Level 1	Fully Fit	CL	000:00
000000-00161E77	No	2 Yearly/40000 Kms	19 Sep 2021	Level 1		WiP	000:00
000000-00B14CB8	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	02 Jun 2024	Level 1	Fully Fit	CL	000:00
000000-00B7DE92	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	22 Sep 2021	Level 1	Fully Fit	CL	000:00

000000-007A274E

No

OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)

22 Sep 2021

Level 1 Fully Fit

CL

000:00