



# Sewage-related contaminants in Isles of Scilly groundwater: concentrations, spatial distribution, sources and risk

Project ENVRESW001361

September 2016

Part 3 of 4







Figure 12: St Agnes sampling sites  
November 2015 - January 2016






Figure 13: Tresco and Bryher sampling sites  
November 2015 - January 2016





Figure 14: Isles of Scilly Council nitrate data, December 2015






Figure 15: Isles of Scilly Council ammonium data, December 2015






Figure 16: Isles of Scilly Council e-coli data  
December 2015






Figure 17: Duchy e-coli data, December 2015










Figure 18b: Duchy Nitrate data 2013






Figure 19: Carrs Well, St Mary's nitrate and ammonium concentrations




Figure 20: Hales, St Mary's nitrate and ammonium concentrations






Figure 21: Joaney's Well, St Mary's nitrate and ammonium concentrations







Figure 22: Rocky Hill, St Mary's nitrate and ammonium concentrations










**Figure 25: Bryher Borehole 2 nitrate and ammonium concentrations**



**Figure 26: Bryher Well nitrate and ammonium concentrations**










Figure 29: Joaney's, St Mary's e-coli count




Figure 30: Rocky Hill, St Mary's e-coli count










Figure 33: Bryher Borehole 2 e-coli count




Figure 34: Bryher Well e-coli count

