







# G-BCRU

## Tail Rotor Blade Pocket

Recovered from Oil Rig "Forties Charlie"



# Tail Rotor and Gearbox of Sikorsky S58ET



Denotes failure line.....>---<

Denotes portion  
detached.....  
↑

# G-BCRU Tail Rotor Gearbox

(Showing fractured intermediate casing)

