





G-BCRU

Tail Rotor Blade Pocket

Recovered from Oil Rig "Forties Charlie"



Tail Rotor and Gearbox of Sikorsky S58ET



Denotes failure line.....>---<

Denotes portion
detached.....

G-BCRU Tail Rotor Gearbox

(Showing fractured intermediate casing)

