











DATE:	05.04.17	INSPECTORS:	[REDACTED]			ROUTE:	B401
VEHICLE:	[REDACTED]	START TIME:	08:30		FINISH TIME:	14:30	
ROAD	LINK & SECTION	CARRIAGEWAY	LANE	MARKER POST	DEFECT	ACTION TAKEN	
A120	NA	EB ✓	L1	49/2	Numerous Potholes in lane 1		
A120	NA	EB ✓	L1	300m prior to crossing	Pavement		
A120	NA	EB ✓	L2	415	incur Pavement		
A120	NA	EB ✓	L1	marks reg 28B	Numerous pavement defects		
A120	NA	WB ✓		55/1	uneven RD	uneven RD signs to be erected	
A120	NA	WB ✓	L2	34/5	uneven RD	" "	
A120	NA	WB ✓	L2	27/3	3x Potholes		
A120	NA	WB ✓	L2	22/4	2x Potholes		
<del>A120</del>	<del>NA</del>	WB	L2	41/5	depression Bridge		
A120	NA	WB ✓	L1	27/2	multiple 2x Potholes		
[REDACTED]							

✓  
 ✓  
 ✓  
 ✗  
 ✗  
 ✓  
 ✓  
 ✓  
 ✗  
 ✓  
 ✓  
 ✗

LUM 15 29

[REDACTED]

DATE:	05.04.17	INSPECTORS:	[REDACTED]		ROUTE:	BHOI
VEHICLE:	[REDACTED]	START TIME:	08:30	FINISH TIME:	14:30	
ROAD	LINK & SECTION	CARRIAGEWAY	LANE	MARKER POST	DEFECT	ACTION TAKEN
A120	NA	EB	L1	49/2	NUMEROUS POTHOLES IN LANE 1	PASSED TO DEPOT
A120	NA	EB	L1	COGGESHAL CROSSING	NUMEROUS POTHOLES	PASSED TO DEPOT
A120	NA	EB	L1	500m PRIOR TO RAJ INDIAN	NUMEROUS PAVEMENT DEFECTS	PASSED TO DEPOT
A120	NA	EB	L1	MARKS TEY RAB	NUMEROUS PAVEMENT DEFECTS	PASSED TO DEPOT
A120	NA	WB	L1	55/1	SURFACE DEFORMATION	UNEVEN RD SIGNS TO BE ERECTED.
A120	NA	WB	L1	34/5	" "	" "
A120	NA	WB	L1	27/3	3 x POTHOLES	PASSED TO DEPOT
A120	NA	WB	L2	22/4	2 x POTHOLES	PASSED TO DEPOT
A120	NA	WB	L1	27/2	NUMEROUS POTHOLES	PASSED TO DEPOT