

job_notes	job_location	feature_location	log_effective_date	site_code	job_type_name	Completed date
Main Carriageway Defect - large pothole (Enquiry 41072) Located pothole requires filling (Blacktop : potholes)	M66 NB J1 Mp 5/7 lane 1	4200M66/37 - NB 5/8 4/6 (start of J1 exit)	07/03/2016 00:20	M66	Blacktop : potholes	07/03/2016 00:23
Potholes require filling ( passed to UU17 ) (Blacktop : potholes)	M66 N/B 5/8+60 to 5/7+70 J2 to J1 ( CL1 )	RS: 4200M66/42, CL1, 14., 1389.	07/01/2016 11:06	M66	Blacktop : potholes	08/01/2016 02:33
Large pothole in lane 1 (Blacktop : potholes)	M66 N/B 5/8+50	VG: 4200M66/37, L1, 100., 150.	03/03/2016 15:15	M66	Blacktop : potholes	04/03/2016 04:29
Pothole requires filling with Viafix. (Blacktop : fretting)	M66 N/B. MP 7/8 CL1.	RS: 4200M66/51, LH, 1055., 1083.	25/02/2016 09:32	M66	Blacktop : fretting	25/02/2016 16:40
x 2 sections of c/w requires filling with Viafix. (Blacktop : fretting)	M66 N/B. MP 6/3, 6/2+ 70	LL: 4200M66/41, CL1, 0, 18.	25/02/2016 09:44	M66	Blacktop : fretting	26/02/2016 05:33

