

M25 Events - Detailed Defect Report

DEFECT DETAILS		
Defect Ref		Status
10084563		CLOSED
Road No	Section	Direction
A1089	Main Carriageway	B
Junction From	Junction To	Marker Post
A13	A126	11/0
Location	1/4 mile passed ASDA store.	
Description	Cat 1 pothole, Essex Police ref 258, 1/4 mile passed ASDA store.-All work complete: Pothole [1] 600 x 300 x 200mm 2 x Tubs of viafix used. Pothole [2] 600 x 300 x 200mm.2 x Tubs of viafix used. Pothole [3] 300 x 800 x 100mm. 2 X Tubs of viafix used.	
Call Date/Time		
27 May 2017 07:54:33		
Additional Details		
Reported By	Name	Contact Number
Connect Plus	HU31	[REDACTED]
Defect Category	Sub Category	Depot
Carriageway or Footway	Pothole	Blunts Farm
Immediate Response Req	Confirmed CAT1	
No	Yes	
Response Time (mins)	Chart Section	Paymech Section
120	1500A1089/106	A1089 IB 1-2
Closure Information		
Structure/Column ID	RSBS Ref	External Ref
		291
Confirm WO	Follow up	Paymech Cost
ERP Cost		
Response Times		
Site Response Required By	Made Safe Required by	Restore Service Required by
27 May 2017 09:54:33		
Actual Site Response	Actual Made Safe	Actual Restore Service
27 May 2017 07:54:53	27 May 2017 08:30:00	27 May 2017 08:30
Time Closed Location		
Footway	Verge	Hardshoulder
No	No	No
Lane 1	Lane 2	Lane 3
Yes	No	No
Lane 4	Lane 5	Lane 6
No	No	No
Central Reservation		
No		
Gang Assignment		
Gang Assignment: 1		
Secondary Response	Gang Name	

M25 Events - Detailed Defect Report

Gang Assignment

Gang Assignment: 1		
	ISU 7 - Blunts Farm HU31	
Assigned Date/Time	ETA Date/Time	Required Response
27 May 2017 07:54:51	27 May 2017 07:54:52	
Assign Notes		

Works		
Arrival Date/Time	Hazards covered by RAs/Method Statements	If NO, control with DRA
27 May 2017 07:54:53	Yes	
DRA Notes		
Made Safe Date/Time	Depart Date/Time	Cancel Date/Time
27 May 2017 08:30:00	27 May 2017 08:30:17	
Cancellation Notes		
Follow up Work Required	Follow up Works	

Yes

1/4 mile passed ASDA store. All work complete: Pothole [1] 600 x 300 x 200mm 2 x Tubs of viafix used. Pothole [2] 600 x 300 x 200mm. 2 x Tubs of viafix used. Pothole [3] 300 x 800 x 100mm. 2 X Tubs of viafix used.

Additional Information

Expected Delay:	Traffic Management:	Nature of Works:
Temporary Speed Limit:	Narrow Lanes:	No Of Narrow Lanes:
Works Flag:	Summary/Detail:	Hardshoulder Only:
Closed Lanes:	Added Lanes:	

Action Log

Date Created	Log Type	Details
27-MAY-2017 07:55	Call Received	HU 31 called to report a cat 1 defect and request a RRB to deal.
27-MAY-2017 07:56	Outgoing call	Requested a RRB from ERCC who will pass to Essex Police to attend. ERCC gave Police ref 258.
27-MAY-2017 08:36	Call Received	Potholes filled crew state 2
27-MAY-2017 09:17	Hazard Mitigation	ISU fill pothole
27-MAY-2017 09:18	Defect Closed	Defect by user [REDACTED] at 27/05/2017 09:18:01.