

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAI v4.7 0.3

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: VRS - Maintenance Insp Length: Roadstud Type:

Defect Type: Damaged/deformed Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
VRS_RE_00C	Vehicle Restraint System - Repair (d	1.00			1.00	LIN M	1.00	1.00

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@iamisprtdpprdeixdb01 MAIv4.7.0.3

Defect Id: 8460638 Order By: Defect Id (Desc) Navigator

Asset: [Empty] View Asset

Road Section: 0400M1/350 XSP 4 Start Chain 123 Inspector: RHB Inspection Batch: 17197

Road Desc: MP 880 TO MP 900 Initiation Type: MRP Inspection Id: 3780780

Location: M1 MP 88/1 N/B L1 P1 POTH Priority: SFTY SISS: ALL

Special Instr: [Empty] Superseded? N By: [Empty]

Activity: P1 Paved Areas - Maintenance Insp Depth (mm): [Empty] Roadstud Type: [Empty]

Defect Type: POTH Pothole Diameter(mm): [Empty] Co-ords X: 483559.0

Defect Desc: 1XPOTHOLE Step Chg(mm): [Empty] Y: 246108.0

Defect Status: INSTRUCTED Asset Modification: [Empty]

Recharge: [Empty] Date Inspected: 14-JAN-2015 09:43 Notice Printed: [Empty]

Notify: [Empty] Date Recorded: 14-JAN-2015 14:57 Notice Id: [Empty]

Repair

Category: Temporary Perm Imm Temp Date Repair Due: 15-JAN-2015 Work Status: INSTRUCTED

Repair Desc: MAKE SAFE Date Instructed: 14-JAN-2015 14:57 Work Order: A08/1992

Treatment: MS MAKE SAFE Target Complete: 15-JAN-2015 09:43 Work Sheet: [Empty]

Total Cost: 1.00 Date Completed: [Empty] Check Batch: [Empty]

BOQ Uplift Item: [Empty] Check Date: [Empty] Check Result: [Empty]

WOL Uplift Item: [Empty] Date Paid: [Empty] Payment Id: [Empty]

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe	1.00			1.00	SQ M	1.00	1.00

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@iamisprd.DPPRDEXDB01 MAIv4.7.0.3

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Superseded? By: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_MS00	Paved Areas - Make Safe					SQ M		

Defects - MAI3806 - AAMEY08DW@lamisprd.DPPRDEKDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset: View Asset

Road Section	<input type="text" value="0400M1/350"/>	XSP	LH	Start Chain	<input type="text" value="1927"/>	Inspector	<input type="text" value="RH8"/>	Inspection Batch	<input type="text" value="10577"/>
Road Desc	<input type="text" value="MP 880 TO MP 900"/>					Initiation Type	<input type="text" value="MRP"/>	Inspection Id	<input type="text" value="3722352"/>
Location	<input type="text" value="M1 MP 89/9 N/B SP DBHS"/>					Priority	<input type="text" value="SFTY"/>	SISS	<input type="text" value="ALL"/>
Special Instr	<input type="text"/>					Superseded ?	<input type="text" value="N"/>	By	<input type="text"/>
Activity	<input type="text" value="SP"/>	<input type="text" value="Sweeping and Cleaning - Maintenance Insp"/>			Length (m)	<input type="text"/>	Roadstud Type	<input type="text"/>	
Defect Type	<input type="text" value="DBHS"/>	<input type="text" value="Debris in hard shoulder"/>			Area (m2)	<input type="text"/>	Co-ords X	<input type="text" value="482140.0"/>	
Defect Desc	<input type="text" value="FXF LORRY TYRE"/>						Y	<input type="text" value="247219.0"/>	
Defect Status	<input type="text" value="COMPLETED"/>					Asset Modification	<input type="text"/>		
Recharge	<input type="text"/>	<input type="text"/>			Date Inspected	<input type="text" value="05-NOV-2014"/>	<input type="text" value="10:20"/>	Notice Printed	<input type="text"/>
Notify	<input type="text"/>	<input type="text"/>			Date Recorded	<input type="text" value="05-NOV-2014"/>	<input type="text" value="16:04"/>	Notice Id	<input type="text"/>

Repair

Category	<input type="text" value="Permanent"/>	<input checked="" type="checkbox"/> Perm	<input type="checkbox"/> Imm	<input type="checkbox"/> Temp	Date Repair Due	<input type="text" value="03-DEC-2014"/>	Work Status	<input type="text"/>	
Repair Desc	<input type="text" value="REMOVED"/>				Date Instructed	<input type="text"/>	Work Order	<input type="text"/>	
Treatment	<input type="text" value="MS"/>	<input type="text" value="MAKE SAFE"/>			Target Complete	<input type="text"/>	Work Sheet	<input type="text"/>	
Total Cost	<input type="text"/>				Date Completed	<input type="text" value="05-NOV-2014"/>	<input type="text" value="10:21"/>	Check Batch	<input type="text"/>
BOQ Uplift Item	<input type="text"/>				Check Date	<input type="text"/>	Check Result	<input type="text"/>	
WOL Uplift Item	<input type="text"/>				Date Paid	<input type="text"/>	Payment Id	<input type="text"/>	

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Defects - MAI3806 - AAMEY08DW@jamisprl.DPPRDEXDB01 MAI v4.7.0.3

Defect Id: 3452396 Order By: Defect Id (Desc) Navigator

Asset: [Empty] View Asset

Road Section: 0400M1/350 XSP LH Start Chain: 1099 Inspector: RH8 Inspection Batch: 9651

Road Desc: MP 880 TO MP 900 Initiation Type: MRP Inspection Id: 3706987

Location: M1 MP 90/7 N/B SP LITB Priority: SFTY SISS: ALL

Special Instr: [Empty] Superseded?: N By: [Empty]

Activity: SP Sweeping and Cleaning - Maintenance Insp Area (m2): [Empty] Roadstud Type: [Empty]

Defect Type: LITB Litter Grade B Co-ords X: 482771.0

Defect Desc: FXF DEBRIE TYRE Y: 246683.0

Defect Status: COMPLETED Asset Modification: [Empty]

Recharge: [Empty] Date Inspected: 15-OCT-2014 10:11 Notice Printed: [Empty]

Notify: [Empty] Date Recorded: 15-OCT-2014 15:09 Notice Id: [Empty]

Repair

Category: Permanent Perm Imm Temp

Date Repair Due: 12-NOV-2014 Work Status: [Empty]

Repair Desc: REMOVED Date Instructed: [Empty] Work Order: [Empty]

Treatment: MS MAKE SAFE Target Complete: [Empty] Work Sheet: [Empty]

Total Cost: [Empty] Date Completed: 15-OCT-2014 10:12 Check Batch: [Empty]

BOQ Uplift Item: [Empty] Check Date: [Empty] Check Result: [Empty]

WOL Uplift Item: [Empty] Date Paid: [Empty] Payment Id: [Empty]

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@jamisprd.DFPRDEXDB01 MAI v4.7.0.3

Defect Id: 3449877 Order By: Defect Id (Desc) Navigator

View Asset

Asset

Road Section: 0400M1/350 XSP 4 Start Chain 1263 Inspector: RH8 Inspection Batch: 8070

Road Desc: MP 880 TO MP 900 Initiation Type: MRP Inspection Id: 3678958

Location: M1 MP86/4 L1 N/B P1 POTH Priority: SFTY SISS: ALL

Special Instr: Superseded?: N By: Depth (mm): Roadstud Type: Co-ords X: 482643.0

Activity: P1 Paved Areas - Maintenance Insp Diameter(mm): Y: 246786.0

Defect Type: POTH Pothole Step Chg(mm): Asset Modification: Defect Desc: POTHOLE

Defect Status: COMPLETED Date Inspected: 03-SEP-2014 11:03 Notice Printed: Date Recorded: 04-SEP-2014 15:29 Notice Id: Recharge: Notify: Repair

Category: Temporary Perm Imm Temp Date Repair Due: 04-SEP-2014 Work Status: Repair Desc: REPAIR Date Instructed: Work Order: Treatment: / REPAIR Target Complete: Work Sheet: Total Cost: Date Completed: 03-SEP-2014 11:04 Check Batch: BOQ Uplift Item: Check Date: Check Result: WOL Uplift Item: Date Paid: Payment Id: BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole					SQ M		

Summary Print Create WO Edit Defect

Defects - MAI3806 - AAMEY08DW@jamisprtd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Superseded? By:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole					SQ M		

Summary

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Roadstud Type:

Defect Type: Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Date Repair Due: Work Status:

Repair Desc: Date Instructed:

Treatment: Target Complete:

Total Cost: Date Completed: Work Order:

BOQ Uplift Item: Check Date: Work Sheet:

WOL Uplift Item: Date Paid: Check Batch:

Check Result: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEKDB01 MAI v4.7.0.3

Defect Id: Order By: Navigator

Asset:

Road Section: XSP Start Chain Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Length (m): Roadstud Type:

Defect Type: Area (m2): Co-ords X:

Defect Desc: Superseded? By:

Defect Status: Asset Modification:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost

Summary Create WO

Defect Id: Order By: Navigator

Asset:

Road Section: XSP Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr: Superseded? By:

Activity: Depth (mm):

Defect Type: Diameter(mm): Roadstud Type:

Defect Desc: Step Chg(mm): Co-ords X:

Defect Status: Asset Modification: Y:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp

Repair Desc: Date Repair Due: Work Status:

Treatment: Date Instructed: Work Order:

Total Cost: Target Complete: Work Sheet:

BOQ Uplift Item: Date Completed: Check Batch:

WOL Uplift Item: Check Date: Check Result:

Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
PAVE_RE00	Paved Areas - Patch Repair Pothole					SQ M		

Summary Create WO

Defects - MAI3806 - AAMEY08DW@jamisprd.DPPRDEXDB01 MAIv4.7 0.3

Defect Id: Order By: Navigator

Asset: View Asset

Road Section: XSP: Start Chain: Inspector: Inspection Batch:

Road Desc: Initiation Type: Inspection Id:

Location: Priority: SISS:

Special Instr:

Activity: Soft Estate - - Maintenance Insp. Roadstud Type:

Defect Type: Obstructed sign/lighting point, etc. Co-ords X:

Defect Desc: Y:

Defect Status: Asset Modification:

Superseded? By:

Recharge: Date Inspected: Notice Printed:

Notify: Date Recorded: Notice Id:

Repair

Category: Perm Imm Temp Date Repair Due: Work Status:

Repair Desc: Date Instructed: Work Order:

Treatment: REPAIR Target Complete: Work Sheet:

Total Cost: Date Completed: Check Batch:

BOQ Uplift Item: Check Date: Check Result:

WOL Uplift Item: Date Paid: Payment Id:

BOQ Items

Item Code	Description	Dim 1	Dim 2	Dim 3	Quantity	Unit	Rate	Cost
SEVC_00_00	Soft Estate - Visibility cuts					ITEM		

Summary Print Create WO Edit Defect