


6332	18293931	A27	A27 Devils Dyke	A27 Devils Dyke caller reporting that the area floods and asks what plans we have to remedy the situation	Customer Enquiries	██████████	Customer Enquiry	Flooding	FLO	23/11/2016 10:51	23/11/2016 11:26	Email
6444	email	A27	A27 devils Dyke - Flooding	customer has come back into us regarding flooding. ██████ has asked him for location	Undefined	██████████ ██████████	Customer Enquiry	Flooding	FLO	25/11/2016 16:39	07/12/2016 11:01	Email

158877	23/11/2015 12:29	Public	Email	Flooding	A27	<p>A27 Devil Dyke Road Brighton I own a farm bordering the A27 Brighton Bye Pass. In the past 5 years a drainage problem has occurred and is now causing major problems on my land. A grype has been dug which now allows standing water to exit the road carriageway and be diverted onto my soil. This each year erodes my topsoil and ends up in the very wet times as a lake. Under cross compliance rules with DEFRA this invalidates our Soil Protection Reveiw as well as destroying crops destined for the human food chain. No thought at all has been given to myself or how to work out this problem.</p> <p>I would like to request a meeting with yourself to sort an answer to the mess you are allowing to make of my farm and business.</p>	Observation	Complete - Written	26/11/2015 11:50	■
151130	06/03/2015 08:49	Public	Email	Flooding	A27	<p>A27 Hangleton</p> <p>Flooding on the carriageway</p>	Information	Complete	06/03/2015 09:38	■
150644	23/02/2015 15:09	HAIL	Email	Flooding	A27	<p>A27 Hangleton Link to Devils Dyke</p> <p>Appears to be no drainage and vehicle is prone to aquaplaning.</p>	Observation	Complete - Written	04/03/2015 14:29	■
150534	20/02/2015 17:45	Public	Email	Flooding	A27	<p>A27 Hangleton/Dyke Road</p> <p>Flooding concerns on carriageway</p>	Observation	Complete - Written	05/03/2015 08:37	■



Full Details Report Summary - A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accidents Found Date Range: 20/01/2013 - 05/10/2015

Grid Coordinate Range: 526920,107755-528607,108305

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

Accident Severity

	2013	2014	2015	Total
Serious	0	1	0	1
Slight	2	2	4	8
Total	2	3	4	9

Casualty Severity

	2013	2014	2015	Total
Serious	0	1	0	1
Slight	2	2	5	9
Total	2	3	5	10

Casualty KSI

	2013	2014	2015	Total
Adult KSI	0	1	0	1
Slight	2	2	5	9
Total	2	3	5	10

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1300354 Slight A27 Hove 280M West Of A2038 King George VI Avenue Accident 1 of 9
 Outside Lamp Post 718/04
 1.7 Date & 1.9 Time.....Sunday 20/01/2013 18:19 1.15 Speed limit.....70 Mph
 1.11 Grid co-ordinates.....528238/107976 1.14 Road type.....Dual c'way
 1.10 Local Authority.....Brighton and Hove 1.16 Junction detail.....Not at or within 20m of junction
 1.12/1.13 1st road identity..A27 1.17 Junction control.....
 1.18/1.19 2nd road identity.. 1.24 Special conditions...None
 1.22 Weather.....Snow 1.25 Carriageway hazards..Previous accident
 1.21 Light conditions.....Dark/lights lit 1.5 Number of vehicles...2
 1.20a Crossing(human).....No Human control within 50m 1.6 Number of casualties.1
 1.20b Crossing(physical).....No crossing facility within 5 1.23 Surface.....Ice

Contributory Factors

Slippery road due to weather (Road Environment Contrib)
 Travelling too fast for conditions (Driver/Rider - Injudicious)
 Loss of control (Driver/Rider - Error)
 Emergency vehicle on call (Special Codes)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Very likely	
Vehicle 001	Possible	
Vehicle 001	Very likely	Yes
Vehicle 002	Possible	

Accident Description

Marked Police Vehicle with Illuminated Flashing Warning Lights Stationary in Main Carriageway Protecting Previous Rtc Scene. V1 Westbound on Main Carriageway Reacted to Police Vehicle and Lost Control on Slippery Icy Road Surface. V1 Hit Central Armco Barrier then Slid Broadside into Rear of Police Vehicle.

2 Vehicles

2.4 Veh ref no.....1	2.16 First impact.....Nearside
2.17 Other vehicle.....2	2.12 Hit object in c'way..Parked vehicle unlit
2.5 Vehicle class.....Car	2.14 Hit object off c'way.Central crash barrier
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location..On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to....East West	2.22 Driver age.....32
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....Yes	2.24 Hit and Run.....No
2.13 Left c'way.....Left c'way offside onto central	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Other
2.28 Foreign vehicle.....Not foreign	

2.4 Veh ref no.....2	2.16 First impact.....Back
2.17 Other vehicle.....1	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location..On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to....Parked Parked	2.22 Driver age.....39
2.7 Manoeuvres.....Parked	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Did not leave c'way	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Journey as part of work
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Unknown
3.8 Age.....32	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1305935 Slight A27 Brighton 980M West Of A2038 Accident 2 of 9

1.7 Date & 1.9 Time.....Tuesday 05/11/2013 08:00	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....527470/107765	1.14 Road type.....Dual c'way
1.10 Local Authority.....Brighton and Hove	1.16 Junction detail.....Not at or within 20m of junction
1.12/1.13 1st road identity..A27	1.17 Junction control.....
1.18/1.19 2nd road identity..	1.24 Special conditions...None
1.22 Weather.....Rain	1.25 Carriageway hazards..None
1.21 Light conditions.....Daylight	1.5 Number of vehicles...3
1.20a Crossing(human).....No Human control within 50m	1.6 Number of casualties.1
1.20b Crossing(physical).....No crossing facility within 5	1.23 Surface.....Wet

Contributory Factors

Distraction in vehicle (Driver/Rider - Impairment)
 Following too close (Driver/Rider - Injudicious)
 Failed to look properly (Driver/Rider - Error)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Possible	
Vehicle 001	Possible	
Vehicle 001	Very likely	Yes

Accident Description

V1 Following V2. V2 Slowed for Traffic. V1 Collided with Rear of V2. V2 Lost Control and Collided with V3.

3 Vehicles

2.4 Veh ref no.....1	2.16 First impact.....Front
2.17 Other vehicle.....2	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to...West East	2.22 Driver age.....50
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Did not leave c'way	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Journey as part of work
2.28 Foreign vehicle.....Not foreign	

2.4 Veh ref no.....2	2.16 First impact.....Back
2.17 Other vehicle.....1	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to...West East	2.22 Driver age.....23
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Did not leave c'way	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Commuting to/from work
2.28 Foreign vehicle.....Not foreign	

2.4 Veh ref no.....3	2.16 First impact.....Offside
2.17 Other vehicle.....2	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to...West East	2.22 Driver age.....39
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Did not leave c'way	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Journey as part of work
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Unknown
3.8 Age.....23	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....2	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1406110 Slight A27 Brighton At Junction Of A27 Accident 3 of 9

1.7 Date & 1.9 Time.....Friday 17/10/2014 08:07 1.15 Speed limit.....70 Mph
 1.11 Grid co-ordinates.....528290/108062 1.14 Road type.....Dual c'way
 1.10 Local Authority.....Brighton and Hove 1.16 Junction detail.....Slip Road
 1.12/1.13 1st road identity..A27 1.17 Junction control.....Give way sign or uncontrolled
 1.18/1.19 2nd road identity..A27 1.24 Special conditions...None
 1.22 Weather.....Rain Wind 1.25 Carriageway hazards..None
 1.21 Light conditions.....Daylight 1.5 Number of vehicles...1
 1.20a Crossing(human).....No Human control within 50m 1.6 Number of casualties.1
 1.20b Crossing(physical).....No crossing facility within 5 1.23 Surface.....Wet

Contributory Factors

Inexperienced or learner driver/rider (Driver/Rider - Behaviour)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Possible	Yes

Accident Description

Vehicle One Travelling Eastbound in Lane Two of the A27. Sudden Gust of Wind Caused Car to Move Unexpectedly. Driver Attempted to Correct Steering but Lost Control and Went over Bank into off Slip which was at a Lower Lever Than Main Carriageway. Car Rolled Several Times Impacting with Road Furniture (Pole Holding Roundabout Sign) Eventually Landing on Offslip. Minor Injuries to Female Driver Consisting to Grazed Elbow.

1 Vehicle

2.4 Veh ref no.....1	2.16 First impact.....Nearside
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.Road sign or signal
2.10 Junction location...Cleared junction or parked at junc	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to...West North east	2.22 Driver age.....20
2.7 Manoeuvres.....Going ahead left hand bend	2.27 Driver postcode.....
2.11 Skidding.....Yes & Overturned	2.24 Hit and Run.....No
2.13 Left c'way.....Left c'way near-side	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Journey as part of work
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Unknown
3.8 Age.....20	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1406466 Serious A27 Hove At Junction Of A27 Devils Dyke Road Outside Accident 4 of 9
810/13
1.7 Date & 1.9 Time.....Monday 03/11/2014 18:16 1.15 Speed limit.....60 Mph
1.11 Grid co-ordinates.....528401/108181 1.14 Road type.....Slip road
1.10 Local Authority.....Brighton and Hove 1.16 Junction detail.....Slip Road
1.12/1.13 1st road identity..A27 1.17 Junction control.....Give way sign or uncontrolled
1.18/1.19 2nd road identity..A27 1.24 Special conditions...None
1.22 Weather.....Fine 1.25 Carriageway hazards..None
1.21 Light conditions.....Dark/lights lit 1.5 Number of vehicles...1
1.20a Crossing(human).....No Human control within 50m 1.6 Number of casualties.1
1.20b Crossing(physical).....No crossing facility within 5 1.23 Surface.....Wet

Contributory Factors

Loss of control (Driver/Rider - Error)

Participant

Vehicle 001

Confidence

Possible

Did a police officer attend?

Yes

Accident Description

V1 Travelling East on A27 off Slip Towards Devils Dyke Road. Stalls Vehicle in Lane Two in Queuing Traffic. Can't Get Vehicle to Restart So Opens Drivers Door Puts Foot on Road Surface and Tries to Push Vehicle Towards the Offside to Clear the Road. Loses Control of Vehicle on Steep Hill Vehicle Rolls Backwards Leading the Door into the Armco Barrier and in Turn Crushing Driver's right Leg and Comes to a Rest in Same Position.

1 Vehicle

2.4 Veh ref no.....1
2.17 Other vehicle.....0
2.5 Vehicle class.....Van/Goods < 3.5t 2.16 First impact.....Offside
2.10 Junction location...Approaching or parked on approach 2.12 Hit object in c'way..None
2.9 Restricted location.On main carriageway 2.14 Hit object off c'way.None
2.8 Movement from/to...West East 2.18 Parts damaged..... / /
2.7 Manoeuvres.....Waiting to go ahead but held up 2.21 Driver gender.....Male
2.11 Skidding.....No 2.22 Driver age.....52
2.13 Left c'way.....Did not leave c'way 2.27 Driver postcode.....
2.6 Towing.....No 2.24 Hit and Run.....No
2.28 Foreign vehicle.....Not foreign 2.23 Breath test.....Not provided
2.29 Journey purpose.....Unknown

1 Casualty

3.5 Cas ref no.....1 3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider 3.16 PSV passenger.....No
3.7 Gender.....Male 3.14 Seat belt usage.....Unknown
3.8 Age.....52 3.13 School pupil.....Other
3.18 Casualty postcode... (3.19 School)
3.9 Severity.....Serious 3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1 3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian 3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1406964 Slight A27 Hove 631M West Of U Devils Dyke Road Accident 5 of 9

1.7 Date & 1.9 Time.....Wednesday 26/11/2014 22:38	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....527781/107823	1.14 Road type.....Dual c'way
1.10 Local Authority.....Brighton and Hove	1.16 Junction detail.....Not at or within 20m of junction
1.12/1.13 1st road identity..A27	1.17 Junction control.....
1.18/1.19 2nd road identity..	1.24 Special conditions...None
1.22 Weather.....Rain	1.25 Carriageway hazards..None
1.21 Light conditions.....Dark/no lights	1.5 Number of vehicles...1
1.20a Crossing(human).....No Human control within 50m	1.6 Number of casualties.1
1.20b Crossing(physical).....No crossing facility within 5	1.23 Surface.....Wet

Contributory Factors

Careless/Reckless (Driver/Rider - Behaviour)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Possible	Yes

Accident Description

V1 Travelling East on A27 Hits Large Puddle of Water on Nearside Loses Control Leaves Carriageway to Near Side and Rolls on to Side Causing Damage and Slight Injury.

1 Vehicle

2.4 Veh ref no.....1	2.16 First impact.....Nearside
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Van/Goods < 3.5t	2.14 Hit object off c'way.
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to....West East	2.22 Driver age.....33
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....Overtuned	2.24 Hit and Run.....No
2.13 Left c'way.....Left c'way near-side	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Journey as part of work
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Unknown
3.8 Age.....33	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1500161 Slight A27 23 Hove 50M East Of U Mill Road Accident 6 of 9

1.7 Date & 1.9 Time.....Tuesday 06/01/2015 15:30	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....528607/108305	1.14 Road type.....Dual c'way
1.10 Local Authority.....Brighton and Hove	1.16 Junction detail.....Not at or within 20m of junction
1.12/1.13 1st road identity..A27	1.17 Junction control.....
1.18/1.19 2nd road identity..	1.24 Special conditions...None
1.22 Weather.....Fine	1.25 Carriageway hazards..None
1.21 Light conditions.....Daylight	1.5 Number of vehicles...2
1.20a Crossing(human).....No Human control within 50m	1.6 Number of casualties.1
1.20b Crossing(physical).....No crossing facility within 5	1.23 Surface.....Wet

Contributory Factors

Failed to look properly (Driver/Rider - Error)
 Travelling too fast for conditions (Driver/Rider - Injudicious)
 Dazzling sun (Driver/Rider - Vision Affected)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Possible	
Vehicle 001	Very likely	
Vehicle 001	Very likely	Yes

Accident Description

V2 Travelling Westbound Along A27 in Outside Lane Towards Having Passed A23 Junction. Traffic Slows in Front of V2 and V1 Drove into Back of V2

2 Vehicles

2.4 Veh ref no.....1	2.16 First impact.....Front
2.17 Other vehicle.....2	2.12 Hit object in c'way..None
2.5 Vehicle class.....Goods 3.5 - 7.5t	2.14 Hit object off c'way.None
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Male
2.8 Movement from/to....East West	2.22 Driver age.....34
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Did not leave c'way	2.23 Breath test.....Not contacted
2.6 Towing.....No	2.29 Journey purpose.....Unknown
2.28 Foreign vehicle.....Not foreign	

2.4 Veh ref no.....2	2.16 First impact.....Back
2.17 Other vehicle.....1	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.None
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to....East West	2.22 Driver age.....28
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Did not leave c'way	2.23 Breath test.....Not contacted
2.6 Towing.....No	2.29 Journey purpose.....Commuting to/from work
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Unknown
3.8 Age.....28	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....2	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1500905 Slight A27 Hove 1229M East Of A293 Accident 7 of 9

1.7 Date & 1.9 Time.....Friday 13/02/2015 12:22	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....527443/107755	1.14 Road type.....Dual c'way
1.10 Local Authority.....Brighton and Hove	1.16 Junction detail.....Not at or within 20m of junction
1.12/1.13 1st road identity..A27	1.17 Junction control.....
1.18/1.19 2nd road identity..	1.24 Special conditions...None
1.22 Weather.....Rain	1.25 Carriageway hazards..Other object
1.21 Light conditions.....Daylight	1.5 Number of vehicles...1
1.20a Crossing(human).....No Human control within 50m	1.6 Number of casualties.1
1.20b Crossing(physical).....No crossing facility within 5	1.23 Surface.....Wet

Contributory Factors

Swerved (Driver/Rider - Error)
 Animal or object in carriageway (Road Environment Contrib)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Very likely	Yes
Vehicle 001	Very likely	

Accident Description

V1 Travelling West on A27 Hove Between Junction for Dyke Road Avenue and A293 in Lane 2. Debris on the Carriageway Led to D1 Swerving to the Near Side to Avoid Hitting It. this in Turn Has Led D1 Losing Control of her Vehicle Colliding with an Armco Barrier to the Nearside and Rolling the Vehicle on to its Side.

1 Vehicle

2.4 Veh ref no.....1	2.16 First impact.....Nearside
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.Nearside/offside crash
2.10 Junction location...Not at junction	2.21 Driver gender.....Female
2.9 Restricted location.On main carriageway	2.22 Driver age.....23
2.8 Movement from/to....East West	2.27 Driver postcode.....[REDACTED]
2.7 Manoeuvres.....Going ahead other	2.24 Hit and Run.....No
2.11 Skidding.....Yes & Overturned	2.23 Breath test.....Negative
2.13 Left c'way.....Left c'way nearside & rebounded	2.29 Journey purpose.....Unknown
2.6 Towing.....No	
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Unknown
3.8 Age.....23	3.13 School pupil.....Other
3.18 Casualty postcode...[REDACTED]	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1501738 Slight A27 Hove 890M East Of A293 Accident 8 of 9

1.7 Date & 1.9 Time.....Sunday 29/03/2015 14:06	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....526920/107830	1.14 Road type.....Dual c'way
1.10 Local Authority.....Brighton and Hove	1.16 Junction detail.....Not at or within 20m of junction
1.12/1.13 1st road identity..A27	1.17 Junction control.....
1.18/1.19 2nd road identity..	1.24 Special conditions...None
1.22 Weather.....Rain	1.25 Carriageway hazards..None
1.21 Light conditions.....Daylight	1.5 Number of vehicles...1
1.20a Crossing(human).....No Human control within 50m	1.6 Number of casualties.1
1.20b Crossing(physical).....No crossing facility within 5	1.23 Surface.....Wet

Contributory Factors

Nervous/Uncertain (Driver/Rider - Behaviour)
Loss of control (Driver/Rider - Error)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Possible	
Vehicle 001	Possible	Yes

Accident Description

V1 Travelling East on A27. Begins to Move from Lane One to Lane Two. for Unknown Reasons Appears to Slightly Leave the Tarmac and Make Contact with Grass Verge. Vehicle then Continues to Drive on Grass Verge Before Hitting Temporary Road Sign and Spinning into Armco Barrier.

1 Vehicle

2.4 Veh ref no.....1	2.16 First impact.....Front
2.17 Other vehicle.....0	2.12 Hit object in c'way..None
2.5 Vehicle class.....Car	2.14 Hit object off c'way.Road sign or signal
2.10 Junction location...Not at junction	2.18 Parts damaged..... / /
2.9 Restricted location.On main carriageway	2.21 Driver gender.....Female
2.8 Movement from/to....West East	2.22 Driver age.....48
2.7 Manoeuvres.....Going ahead other	2.27 Driver postcode.....
2.11 Skidding.....No	2.24 Hit and Run.....No
2.13 Left c'way.....Left c'way nearside & rebounded	2.23 Breath test.....Negative
2.6 Towing.....No	2.29 Journey purpose.....Unknown
2.28 Foreign vehicle.....Not foreign	

1 Casualty

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Unknown
3.8 Age.....48	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School ..)
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....1	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

1.3 Accident Reference:1505803 Slight A27 Hove 520M West Of A2038 Devils Dyke Road Accident 9 of 9

1.7 Date & 1.9 Time.....Monday 05/10/2015 12:56	1.15 Speed limit.....70 Mph
1.11 Grid co-ordinates.....527624/107780	1.14 Road type.....Dual c'way
1.10 Local Authority.....Brighton and Hove	1.16 Junction detail.....Not at or within 20m of junction
1.12/1.13 1st road identity..A27	1.17 Junction control.....
1.18/1.19 2nd road identity..	1.24 Special conditions...None
1.22 Weather.....Rain	1.25 Carriageway hazards..None
1.21 Light conditions.....Daylight	1.5 Number of vehicles...2
1.20a Crossing(human).....No Human control within 50m	1.6 Number of casualties.2
1.20b Crossing(physical).....No crossing facility within 5	1.23 Surface.....Flood

Contributory Factors

Failed to judge other person's path/speed (Driver/Rider - Error)
 Nervous/Uncertain (Driver/Rider - Behaviour)
 Sudden braking (Driver/Rider - Error)
 Slippery road due to weather (Road Environment Contrib)

Participant	Confidence	Did a police officer attend?
Vehicle 001	Very likely	
Vehicle 002	Very likely	
Vehicle 002	Very likely	Yes
Vehicle 002	Very likely	

Accident Description

V1 Hgv Has Been Travelling Eb Behind V2. the Weather Conditions Were Heavy Rain and the Road at Intervals Had Standing Water. V2 Had Slowed for Standing Water in the Dip and on Exiting Has Applied Brakes to Check. V1 Has Seen this and Has Not Been Able to Adjust Speed Accordingly and Collided with V2. Speed is <30Mph and Damage Not Excessive. Passenger of V2 Has Sustained Whiplash and Driver Shock. Driver of V1 no Injury.

2 Vehicles

2.4 Veh ref no.....1	
2.17 Other vehicle.....2	
2.5 Vehicle class.....Goods > 7.5t	2.16 First impact.....Front
2.10 Junction location...Not at junction	2.12 Hit object in c'way..None
2.9 Restricted location.On main carriageway	2.14 Hit object off c'way.None
2.8 Movement from/to...West East	2.18 Parts damaged..... / /
2.7 Manoeuvres.....Going ahead other	2.21 Driver gender.....Male
2.11 Skidding.....No	2.22 Driver age.....49
2.13 Left c'way.....Did not leave c'way	2.27 Driver postcode.....
2.6 Towing.....No	2.24 Hit and Run.....No
2.28 Foreign vehicle.....Not foreign	2.23 Breath test.....Negative
	2.29 Journey purpose.....Journey as part of work

2.4 Veh ref no.....2	
2.17 Other vehicle.....1	
2.5 Vehicle class.....Car	2.16 First impact.....Back
2.10 Junction location...Not at junction	2.12 Hit object in c'way..None
2.9 Restricted location.On main carriageway	2.14 Hit object off c'way.None
2.8 Movement from/to...West East	2.18 Parts damaged..... / /
2.7 Manoeuvres.....Stopping	2.21 Driver gender.....Female
2.11 Skidding.....No	2.22 Driver age.....60
2.13 Left c'way.....Did not leave c'way	2.27 Driver postcode.....
2.6 Towing.....No	2.24 Hit and Run.....No
2.28 Foreign vehicle.....Not foreign	2.23 Breath test.....Negative
	2.29 Journey purpose.....Other

2 Casualties

3.5 Cas ref no.....1	3.15 Car passenger.....No
3.6 Casualty class.....Driver or Rider	3.16 PSV passenger.....No
3.7 Gender.....Female	3.14 Seat belt usage.....Unknown
3.8 Age.....60	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....2	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

3.5 Cas ref no.....2	3.15 Car passenger.....Front
3.6 Casualty class.....Passenger	3.16 PSV passenger.....No
3.7 Gender.....Male	3.14 Seat belt usage.....Unknown
3.8 Age.....60	3.13 School pupil.....Other
3.18 Casualty postcode...	(3.19 School
3.9 Severity.....Slight	3.10 Pedestrian location..Not a pedestrian
3.4 Vehicle no.....2	3.11 Pedestrian movement..Not a pedestrian
3.12 Ped Direction.....Not a pedestrian	3.19 Roadworker injured...No

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND
Road Surface IN LIST 2,3,4,5

ACCIDENT SEVERITY UPTO 2016

	2012	2013	2014	2015	2016	Total
Fatal	0	0	0	0	0	0
Serious	0	0	1	0	0	1
Slight	0	2	2	4	0	8
Damage	0	0	0	0	0	0
Total	0	2	3	4	0	9

ACCIDENTS BY MONTH AND YEAR UPTO 2016

	2012	2013	2014	2015	2016	Total
January	0	1	0	1	0	2
February	0	0	0	1	0	1
March	0	0	0	1	0	1
April	0	0	0	0	0	0
May	0	0	0	0	0	0
June	0	0	0	0	0	0
July	0	0	0	0	0	0
August	0	0	0	0	0	0
September	0	0	0	0	0	0
October	0	0	1	1	0	2
November	0	1	2	0	0	3
December	0	0	0	0	0	0
Total	0	2	3	4	0	9
%	0%	22%	33%	44%	0%	100%

ACCIDENTS BY DAY AND TIME

	Sun	Mon	Tue	Wed	Thu	Fri	Sat	Total
Midnight - 00:59	0	0	0	0	0	0	0	0
01:00 - 01:59	0	0	0	0	0	0	0	0
02:00 - 02:59	0	0	0	0	0	0	0	0
03:00 - 03:59	0	0	0	0	0	0	0	0
04:00 - 04:59	0	0	0	0	0	0	0	0
05:00 - 05:59	0	0	0	0	0	0	0	0
06:00 - 06:59	0	0	0	0	0	0	0	0
07:00 - 07:59	0	0	0	0	0	0	0	0
08:00 - 08:59	0	0	1	0	0	1	0	2
09:00 - 09:59	0	0	0	0	0	0	0	0
10:00 - 10:59	0	0	0	0	0	0	0	0
11:00 - 11:59	0	0	0	0	0	0	0	0
12:00 - 12:59	0	1	0	0	0	1	0	2
13:00 - 13:59	0	0	0	0	0	0	0	0
14:00 - 14:59	1	0	0	0	0	0	0	1
15:00 - 15:59	0	0	1	0	0	0	0	1
16:00 - 16:59	0	0	0	0	0	0	0	0
17:00 - 17:59	0	0	0	0	0	0	0	0
18:00 - 18:59	1	1	0	0	0	0	0	2
19:00 - 19:59	0	0	0	0	0	0	0	0
20:00 - 20:59	0	0	0	0	0	0	0	0
21:00 - 21:59	0	0	0	0	0	0	0	0
22:00 - 22:59	0	0	0	1	0	0	0	1
23:00 - 23:59	0	0	0	0	0	0	0	0
Total	2	2	2	1	0	2	0	9
%	22%	22%	22%	11%	0%	22%	0%	100%

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND Road Surface IN LIST 2,3,4,5

JUNCTION DETAIL		Number	%
SLIP ROAD		2	22
NOT AT JUNCTION		7	78
TOTAL		9	

JUNCTION CONTROLS		Number	%
GIVE WAY SIGN		2	22
NOT AT JUNCTION		7	78
TOTAL		9	

SPEED LIMIT		Number	%
60 MPH		1	11
70 MPH		8	89
TOTAL		9	

ROAD CLASS		Number	%
A		9	100
TOTAL		9	

NUMBER OF ACCIDENTS INVOLVING PEDESTRIANS		Number	%
		0	0

NUMBER OF ACCIDENTS INVOLVING SKIDDING		Number	%
		4	44

WEATHER		Number	%
FINE		2	22
RAIN		5	56
SNOW		1	11
RAIN WIND		1	11
TOTAL		9	

ROAD SURFACE		Number	%
WET		7	78
ICE		1	11
FLOOD		1	11
TOTAL		9	

LIGHT CONDITIONS		Number	%
Light		6	67
Dark		3	33
TOTAL		9	

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND
Road Surface IN LIST 2,3,4,5

CASUALTY SEVERITY UPTO 2016

	2012	2013	2014	2015	2016	Total
Fatal	0	0	0	0	0	0
Serious	0	0	1	0	0	1
Slight	0	2	2	5	0	9
Total	0	2	3	5	0	10
%	0%	20%	30%	50%	0%	100%

CASUALTIES BY MONTH AND YEAR UPTO 2016

	2012	2013	2014	2015	2016	Total
January	0	1	0	1	0	2
February	0	0	0	1	0	1
March	0	0	0	1	0	1
April	0	0	0	0	0	0
May	0	0	0	0	0	0
June	0	0	0	0	0	0
July	0	0	0	0	0	0
August	0	0	0	0	0	0
September	0	0	0	0	0	0
October	0	0	1	2	0	3
November	0	1	2	0	0	3
December	0	0	0	0	0	0
Total	0	2	3	5	0	10
%	0%	20%	30%	50%	0%	100%

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND
Road Surface IN LIST 2,3,4,5

CASUALTIES BY DAY AND TIME

	Sun	Mon	Tue	Wed	Thu	Fri	Sat	Total
Midnight - 00:59	0	0	0	0	0	0	0	0
01:00 - 01:59	0	0	0	0	0	0	0	0
02:00 - 02:59	0	0	0	0	0	0	0	0
03:00 - 03:59	0	0	0	0	0	0	0	0
04:00 - 04:59	0	0	0	0	0	0	0	0
05:00 - 05:59	0	0	0	0	0	0	0	0
06:00 - 06:59	0	0	0	0	0	0	0	0
07:00 - 07:59	0	0	0	0	0	0	0	0
08:00 - 08:59	0	0	1	0	0	1	0	2
09:00 - 09:59	0	0	0	0	0	0	0	0
10:00 - 10:59	0	0	0	0	0	0	0	0
11:00 - 11:59	0	0	0	0	0	0	0	0
12:00 - 12:59	0	2	0	0	0	1	0	3
13:00 - 13:59	0	0	0	0	0	0	0	0
14:00 - 14:59	1	0	0	0	0	0	0	1
15:00 - 15:59	0	0	1	0	0	0	0	1
16:00 - 16:59	0	0	0	0	0	0	0	0
17:00 - 17:59	0	0	0	0	0	0	0	0
18:00 - 18:59	1	1	0	0	0	0	0	2
19:00 - 19:59	0	0	0	0	0	0	0	0
20:00 - 20:59	0	0	0	0	0	0	0	0
21:00 - 21:59	0	0	0	0	0	0	0	0
22:00 - 22:59	0	0	0	1	0	0	0	1
23:00 - 23:59	0	0	0	0	0	0	0	0
Total	2	3	2	1	0	2	0	10
%	20%	30%	20%	10%	0%	20%	0%	100%

CASUALTIES BY TYPE AND AGE GROUPING

	Unknown Age	0 to 4	5 to 15	16 to 19	20 to 29	30 to 59	60 Plus	Total	%
Car Driver	0	0	0	0	4	2	1	7	70
Car Passenger	0	0	0	0	0	0	1	1	10
Goods Driver	0	0	0	0	0	2	0	2	20
TOTAL	0	0	0	0	4	4	2	10	
%	0	0	0	0	40	40	20		

Number of Casualties with unknown age: 0

VEHICLES INVOLVED BY TYPE AND AGE OF DRIVER

	0 to 15	16 to 19	20 to 29	30 to 59	60 Plus	Unknown	Total	%
Car	0	0	4	5	1	0	10	71
Goods < 3.5T	0	0	0	2	0	0	2	14
Goods > 3.5T	0	0	0	2	0	0	2	14
TOTAL	0	0	4	9	1	0	14	
%	0	0	29	64	7	0		

VEHICLE MANOEUVRES

	Number	%
GOING AHEAD LEFT HAND BEND	1	7
GOING AHEAD OTHER	10	71
PARKED	1	7
STOPPING	1	7
WAITING TO GO AHEAD BUT HELD UP	1	7
TOTAL	14	

A27 BH (Between Hangleton and Devils Dyke Road) -Wet collision Data

Accident Date BETWEEN '01-Jan-2012' AND '31-Dec-2016' AND Accident Severity < 4 AND
Road Surface IN LIST 2,3,4,5

BREATH TEST

	Number	%
NEGATIVE	11	79
DRIVER NOT CONTACTED	2	14
MEDICAL REASONS	1	7
TOTAL	14	