

TOP 5 DEFECTS FOR PRS RESULTS ONLY BY CALENDAR YEAR 2009-2010 and January 2011- 30 September 2011

H00033

GRANTHAM Rank	MOTOR VEHICLE				
	1	2	3	4	5
DEFECTION Description	Aim of headlamps	Lamps	Glass and view of the road	Brake systems and components	Suspension
DEFECTION ITEM No.	67	63	23	59	48
2009	415	90	37	35	30
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Glass and view of the road	Oil leaks
DEFECTION ITEM No.	67	63	59	23	44
2010	324	75	34	30	21
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Suspension	Steering mechanism
DEFECTION ITEM No.	67	63	59	48	54
Jan 2011-Sep 2011	181	64	27	17	16

GRANTHAM Rank	TRAILERS				
	1	2	3	4	5
DEFECTION Description	Lamps	Reflectors and rear markings	Brake systems and components	Direction indicators and hazard warning lamps	Service brake operation
DEFECTION ITEM No.	63	62	59	66	38
2009	44	10	9	9	4
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Road wheels and hubs	Suspension
DEFECTION ITEM No.	63	59	62	6	48
2010	30	14	9	8	5
DEFECTION Description	Lamps	Suspension	Brake systems and components	Reflectors and rear markings	Direction indicators and hazard warning lamps
DEFECTION ITEM No.	63	48	59	62	66
Jan 2011-Sep 2011	24	11	8	6	6

GRANTHAM Rank	PSV				
	1	2	3	4	5
DEFECTION Description	Aim of headlamps	Brake systems and components	Seat belts	Electrical wiring and equipment	Oil and waste leaks
DEFECTION ITEM No.	67	59	3	42	44
2009	43	9	4	4	4
DEFECTION Description	Aim of headlamps	Interior of body passenger entrance, exit steps & platforms	Passenger doors, driver's doors and emergency exits	Oil and waste leaks	Exhaust and waste systems
DEFECTION ITEM No.	67	21	16	44	46
2010	27	5	4	3	3
DEFECTION Description	Aim of headlamps	Brake systems and components	Seat belts	Interior of body passenger entrance, exit steps & platforms	Lamps
DEFECTION ITEM No.	67	59	3	21	63
Jan 2011-Sep 2011	28	8	7	7	6

H00042

BEVERLEY Rank	MOTOR VEHICLE				
	1	2	3	4	5
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Condition of tyres	Mirrors
DEFECTION ITEM No.	67	63	59	8	22
2009	302	114	28	15	15
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Direction indicators and hazard warning lamps	Suspension
DEFECTION ITEM No.	67	63	59	66	48
2010	197	74	36	19	18
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Reflectors and rear markings	Condition of tyres
DEFECTION ITEM No.	67	63	59	62	8
Jan 2011-Sep 2011	127	58	17	17	14

BEVERLEY Rank	TRAILERS				
	1	2	3	4	5
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Suspension	Road wheels and hubs
DEFECTION ITEM No.	63	59	62	48	6
2009	77	31	23	22	12
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Road wheels and hubs	Suspension
DEFECTION ITEM No.	63	59	62	6	48
2010	56	26	15	13	8
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Road wheels and hubs	Suspension
DEFECTION ITEM No.	63	59	62	6	48
Jan 2011-Sep 2011	36	13	10	8	7

BEVERLEY Rank	PSV				
	1	2	3	4	5
DEFECTION Description	Aim of headlamps	Oil and waste leaks	Lamps	Passenger doors, driver's doors and emergency exits	Interior of body passenger entrance, exit steps & platforms
DEFECTION ITEM No.	67	44	63	16	21
2009	15	4	4	3	3
DEFECTION Description	Aim of headlamps	Lamps	Oil and waste leaks	Passenger doors, driver's doors and emergency exits	Interior of body passenger entrance, exit steps & platforms
DEFECTION ITEM No.	67	63	44	16	21
2010	24	8	7	6	4
DEFECTION Description	Aim of headlamps	Lamps	Passenger doors, driver's doors and emergency exits	Direction indicators and hazard warning lamps	Oil and waste leaks
DEFECTION ITEM No.	67	63	16	66	44
Jan 2011-Sep 2011	16	10	6	4	3

H00045

GRIMSBY Rank	MOTOR VEHICLE				
	1	2	3	4	5
DEFECTION Description	Aim of headlamps	Lamps	Steering mechanism	Brake systems and components	Condition of tyres
DEFECTION ITEM No.	67	63	54	59	8
2009	193	83	30	29	27
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Steering mechanism	Oil leaks
DEFECTION ITEM No.	67	63	59	54	44
2010	164	59	29	27	21
DEFECTION Description	Aim of headlamps	Lamps	Brake systems and components	Steering mechanism	Oil leaks
DEFECTION ITEM No.	67	63	59	54	44
Jan 2011-Sep 2011	100	52	20	18	15

GRIMSBY Rank	TRAILERS				
	1	2	3	4	5
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Road wheels and hubs	Condition of tyres
DEFECTION ITEM No.	63	59	62	6	8
2009	58	27	26	13	8
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Suspension	Road wheels and hubs
DEFECTION ITEM No.	63	59	62	48	6
2010	40	24	20	11	9
DEFECTION Description	Lamps	Brake systems and components	Reflectors and rear markings	Road wheels and hubs	Suspension
DEFECTION ITEM No.	63	59	62	6	48
Jan 2011-Sep 2011	28	18	18	8	7

GRIMSBY Rank	PSV				
	1	2	3	4	5
DEFECTION Description	Aim of headlamps	Lamps	Passenger doors, driver's doors and emergency exits	Oil and waste leaks	Seat belts
DEFECTION ITEM No.	67	63	16	44	3
2009	18	7	4	3	2
DEFECTION Description	Aim of headlamps	Steering mechanism	Lamps	Interior of body passenger entrance, exit steps & platforms	Glass and view of the road
DEFECTION ITEM No.	67	54	63	21	23
2010	25	6	6	4	4
DEFECTION Description	Aim of headlamps	Glass and view of the road	Brake systems and components	Seat belts	Road wheels and hubs
DEFECTION ITEM No.	67	23	59	3	6
Jan 2011-Sep 2011	6	3	3	2	2