

**PATH HEAD – OCTOBER 2016**



**Cohesive sealing layer  
being progressively  
applied in advance of  
further capping works**



**Tanker removing  
water from surface  
water lagoon**



**Surface water  
drainage ditch**



**Tanker removing water  
from surface water  
lagoon. Some water in  
lagoon following  
recent rainfall, though  
level is low.**





**Cohesive cover  
material in use**



Key infrastructure (such as leachate wells) checked for H<sub>2</sub>S emissions



*Jerome* H<sub>2</sub>S monitor in use on the site (reading displayed is 8.67 ppb [parts per billion] which is very low.