



**Clay capped area of cell 3
– looking northwest
towards the ‘mound’**



**Sealed gas extraction
well (within cell 3)**



**Clay capped area of cell 3
– looking east towards
site lagoon and Hexham
Old Road**



**Clay capping work being
undertaken (looking from
Stargate)**

Images from January (pre-works)



**Ponding leachate in
centre of cell 3 – in
January (prior to
remedial works)**



**Flooded lagoon
from cell 3 –
looking east
(January)**