

Road Name	Network Element Id	Network Element Ref	Network Element Description	Location Description	Inspection Id	Date Inspected	Defect Description	Defect Type Description	Activity Description
A11	1477344	2600A11/364	Heathersett - opp.C182 to Ketteringham Lane overbridge	A11 S/B SLIP OFF TO STATION LANE HEATHERSET JUNC. PLAIN FACE BOLLARD ON SPLITTER ISLAND 2 X GLASDON PEDESTRIAN BOLLARDS ON THE C/RES	3752309	11-Dec-14	A11 HEATHERSET SB BOLLARDS	Accident damage	Road Traffic Signs - Face/Structures/Fixings
A11	1477344	2600A11/364	Heathersett - opp.C182 to Ketteringham Lane overbridge	A11 S/B KETTERINGHAM BETWEEN THICKHORN AND WYMONDHAM	3769192	28-Dec-14	12X 3.2 TCB + 7 X DRIVEN POSTS	Accident damage	VRS - Maintenance Insp
A11	1477344	2600A11/364	Heathersett - opp.C182 to Ketteringham Lane overbridge	A11 MP 65/4 S/B POTH	3737496	28-Nov-14	LANE 1 POTHOLE S/B	Pothole	Paved Areas - Maintenance Insp
A11	1477344	2600A11/364	Heathersett - opp.C182 to Ketteringham Lane overbridge	A11 S/B NEXT TO KETTERINGHAM ON SLIP LANE 1 2 X POTHLES FILLD	3717991	29-Oct-14	F+FPOTH A11 S/B NEXT TO KETTERINGHAM SLIP	Pothole	Paved Areas - Maintenance Insp
A11	1477354	2600A11/355	Heathersett - Ketteringham Lane overbridge to Tourist sign (Wymondham)	A11 MP 64/1 S/B L/1 X 2 POTH	3737497	28-Nov-14	LANE 1 POTHOLE X 2 S/B	Pothole	Paved Areas - Maintenance Insp
A11	1477354	2600A11/355	Heathersett - Ketteringham Lane overbridge to Tourist sign (Wymondham)		3611130	31-May-14	FDFDFD	Safety Defect	Technology - Safety
A11	1478805	2600A11/382	Heathersett - Start PQC Thickthorn Hall to opp.C182	A11 S/B MP 69/5 IN LAYBY	3673774	27-Aug-14	F+F A11 S/B MP 69/5 REFIX 1 KERB	Kerb: Loose/rocking	Paved Areas - Maintenance Insp