


Safety Alert



Cracks to Crash Cushion Frames

Over the last few weeks Area 3 have found cracks in 2 different types of crash cushions. At the moment SHB are inspecting the damaged cushions to ascertain the causes of these failures, once complete they will forward their report.

In the meantime, until a plan can be formalised, can you all make sure extra care is taken when drivers daily walk around checks are carried out.

If any cushions are found to be defective, please remove from use and quarantine and contact your area transport manager ASAP.

