

L.A.Code	Activity	Factor Add	Client Target Du	Section Reference	Chainage	XSP	Location	Originated	Description	Client Reference	Defect	Stage	Completed	Order No.	Action
44708	MC	CHM/1	08/10/2016	3100M40/302	785	CL1	Jct 10 Exit	08/07/2016	Patch required to fill pothole in lane 1. Patch size 1m x 1m. This pothole is located at the end of the slip road.	AE	POTH	COMPLETED	24/11/2016 07:13	24758	D22