

Date	Defect Location	Defect Description
04/09/2016 10:51	M6 N/B 291/6 to 291/8	Blocked gullys risk of flooding in this area Vegetation on top of the gully. Tops
04/09/2016 11:02	M6 N/B 292/3	Pot hole in lane 1 and along the rib line
11/09/2016 17:12	M6 N/B 289/7	Failed patch leaving a large / deep pot hole in lane 1
22/09/2016 01:50	M6 SB link to m56 wb	Litterpick where strimmed
28/09/2016 03:06	M6 n/b 291/5	Pothole lane 1
28/09/2016 16:58	M6 Northbound, J19	Main Carriageway Defect - Pothole in lane 1. (Enquiry 46733)
07/10/2016 09:57	M6 SB MP 295/5	Debris in Road - Tyre debris for routine collection (Enquiry 46986)
09/10/2016 09:36	M6 n/b m/p 291/6-291/9	Blocked gully tops
10/10/2016 14:43	M6 n/b 291/2-291/5	Sweep hard shoulder
15/10/2016 03:34	M6 n/b 291/5 to 291/7	Clear gully tops
19/10/2016 10:39	M6 N/B M/P 290/6 - 291/5	25 X gullies blocked by leaves
19/10/2016 21:36	M6 NB between J19 to J20	Debris in Road - Insulation (Enquiry 47257)
25/10/2016 10:38	M6 n/b m/p294/3+70	Broken fence rail
25/10/2016 10:42	M6 n/b m/p 295/4-295/7	Blocked gully tops
25/10/2016 15:28	NB J20 exit to m56 w/b	Traffic Management - TM Sign left after works (Enquiry 47377)
26/10/2016 00:04	M6 NB J19 opp exit slip	Spillage - Derv spill 400 ltrs aprox from Tanker - (Enquiry 47387)
07/11/2016 04:08	M6 S/B 18 exit	Litter picking
10/11/2016 18:49	SB Just prior to J19, 291/3	Spillage - Fuel Spill - HGV ruptured tank (Enquiry 47780)
15/11/2016 00:56	M6 n/b jct 19 access slip	Blocked gully tops
15/11/2016 16:11	m6 nb j19 between slips	Road Traffic Collision - overturned vehicle - secondary response request. (Enquiry 47883)
22/11/2016 11:51	M6 n/b 290/6 - 291/5	Blocked gully tops (approx 20) passed to uu15
24/11/2016 12:18	M6 north jct20 to m56	Cleared culvert
07/12/2016 09:52	M6 NB 290/7 to 293/0 nearside	Slips Soft Estate (NS) Grade C
14/12/2016 18:08	M6, s/b, Junc 19/18, MP	Boundary Fence Damage - Boundary fence damage, livestock in the field = 12 to 14 ft damaged (Enquiry 48756)
15/12/2016 02:08	M6 S/B Jct 19-18 M/P 288.9	Road Traffic Collision - RTC - Closure Overlay (Enquiry 48763)
15/12/2016 10:40	M6 N/B 294/0	Marker post sign facing the wrong way

20/12/2016 09:35	M6 N/B 290/4	Sweep hard shoulder
23/12/2016 12:13	M6 n/b 292/3	Pothole in lane 1 passed to uu15
24/12/2016 05:20	M6 SB 289/1	Spillage - Spillage across 3 lanes (Enquiry 48964)
25/12/2016 10:45	M6 NB J19-20 MP 291/6	Animal in Road - Dead Cat (Bagged by HATO) (Enquiry 48981)
30/12/2016 09:08	M6 NB 293/8+90	Pothole CL1
30/12/2016 09:11	M6 NB 293/9	Wood debris and Blocked gullies X 6
30/12/2016 10:05	M6 N/B 293/0	Large piece of metal approx 12 feet long in central res Need to be removed for safety to road users
01/01/2017 02:24	M6 N/B 295/8	Sweep hard shoulder
07/01/2017 01:23	M6 N/B Jn 19 Exit Slip	Litterpicking
08/01/2017 09:05	M6 s/b jct 18 exit slip	Gully clearing
08/01/2017 15:00	M6 n/b 291/4	Pot hole lane 1
09/01/2017 10:41	M6 S/B 294/4 50	Pothole to be filled CL1
14/01/2017 21:28	M6 NB MP 286/4	Main Carriageway Defect - Pothole Lane 2 (Enquiry 49383)
15/01/2017 14:31	M6 SB sign 293/0	Sign facing the wrong way
17/01/2017 15:35	M6 NB 292/8	Main Carriageway Defect - Pothole in lane 1 (Enquiry 49463)
17/01/2017 15:35	M6 NB 292/8	Main Carriageway Defect - Pothole in lane 1 (Enquiry 49463)
20/01/2017 03:14	M6A J19-20 MP 292/7 Lane 1	Main Carriageway Defect - Pothole in lane 1 (Enquiry 49531)
24/01/2017 08:18	M6 s/b 291/9 to 291/5	Block gullys
24/01/2017 10:26	M6 s/b 293/1	Damaged kerb line
24/01/2017 15:27	SB 291/9	Road Traffic Collision - HGV - L3 & 4 Closed (Enquiry 48854)
29/01/2017 13:31	M6. MP 293/4 n/b	Vegetation - overgrowth (Enquiry 49705)
31/01/2017 18:48	M6 Northbound, J20	Vehicle Fire - Milk Tanker fire (Enquiry 49844)
04/02/2017 17:01	M6 n/b m/p 277/5-278/0 .. N/s	Flooding inspection . Hotspot number 1702
05/02/2017 12:02	M6, n/b, Junc 19/20, MP 290/5	Spillage - Oil Spill on h/s (Enquiry 49971)
05/02/2017 20:44	M6 NB J19/20 293.3	Main Carriageway Defect - Pothole in lane 1 (Enquiry 49976)
08/02/2017 17:57	M6 NB J19-20 MP 295/2A	Electrical Defects - Electric box broken into (Enquiry 50060)
09/02/2017 11:41	M6 s/b 296/3 - 296/0	Blocked gully tops
10/02/2017 16:22	M6 n/b 295/0 - 295/2	Blocked gully tops

17/02/2017 13:16	M6 NB J19 Exit Slip	Spillage - HGV Tanker spillage - Hydrochloric acid (Enquiry 50307)
17/02/2017 15:35	M6 NB MP294/4 - MP294/5	Debris in Road - Tyre debris (Enquiry 50317)
18/02/2017 01:02	M6 n/b jct 19 access slip	Litter picking
20/02/2017 12:10	Litter pick 296/5 to 294/0 m6 sb	Litter pick area
21/02/2017 02:42	M6 n/b jct 19 exit offside	Strim all vegetation from offside barrier to Litterpick
21/02/2017 21:58	M6 S/B Jct 20-19 M/P 295.4	Barrier Damage - RTC with Nearside Barrier Damage (Enquiry 50411)
22/02/2017 01:59	M6 n/b jct 19 access slip offside	Strim off side barrier
22/02/2017 02:03	M6 n/b jct 19 access slip offside	Litterpick offside of access slip
22/02/2017 02:13	M6 n/b jct 19 access slip offside	Clear detritus and debris from kerb edge and in front of side entry drains
22/02/2017 03:03	M6 s/b jct19 access offside	Litterpick offside of slip
22/02/2017 03:05	M6 s/b jct19 access offside	Strim offside barrier
23/02/2017 22:54	M6 NB J19/20 296/4	Boundary Fence Damage - Damaged fencing from fallen tree (Live stock in field) (Enquiry 50477)
24/02/2017 08:24	M56 EB MP27/8	Large water bowser to be picked up
24/02/2017 11:57	m6 nb mp 298/5 J20-21	Other - Clearance request (Enquiry 50495)
24/02/2017 12:30	M6 NB MP 292/7 +30	Pothole to be filled CL1
02/03/2017 08:48	M6 n/b m/p 292/7 approx	Pothole in l/1