

ASC Area 6/8

Process: Deliver Service

Title: Electrical Scout Sheet

Methods	HA Process
Generic	HA4
Component Specific	
Guidance	

Works Order No.		c = consecutive	Direction	Position
Road:	All	S = Sequential	NB = North Bound, SB = South Bound	L1=Lane1, CR= Central reserve
Date:	26.1.16		EB = East Bound, WB West Bound	LV=Left Verge, RV=Right Verge
Name:				

COL Ref.	SIGN Bollard Ref.	MEWFP Y/N	C	S	MP	JCT	H/B	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct.	Repair Carried out					
											Lamp Type	Fuse	Ballast	Ignitor	Repair Date	Beyond Repair
	No Num								RV	Thurston West entry from Hekkerstr						
	"								RV	" " " "						
123	No Num							WD	RV	on RAD west side under A17 bridge						
	"								LV	East side RAD						
	"								RV	service rd junct						
	"								CR	" " "						
	"								LV	splitter island						
	"								RV	} Rd to Service						
	"								CR							
401			/						SB	RV	Turtles Lane					
899			/						"	"	on slip					
	No Num								WD	CR	next to 877					
	"								WD	RV	off slip					
09615									NB	RV	Spencer Row on slip					
09625									"	"	off slip					
	No Num								SB	RV	on slip next to 979					
	No Num										Athelburg's Steap - west side					
	No Num								WD	LV	on RAD North side					
	"								"	"	London Rd junct					
	No Num								EB		Stone cross 1st light					
	No Num								EB	LV	Weather Rd RAD splitter island R1 marker - bollard					
	"								WD	LV	" " " " weather side bollard					
	No Num								NB	CR	1" col leaving RAD					
	No Num										Mundford RD RAD					
	No Num								WB	LV	A1066 jct					
	73								WD	LV	last col A174					
	No Num								LV	RV	A1066 jct clearing sign					
	134								SB	CR	" " " "					
	No Num										last col south					
											all bollards out - DE illuminated?					
	No Num								SB	CR	Brandon RAD					
	No Num								LV	RV	1" col SB approach					
	"								LV	RV	Brandon RD approach					
	"								CR	RV	" " " "					
	"								CR	RV	A174 bollard splitter island					
	"								LV	RV	sig - splitter island					
	"								LV	RV	up lighter A174 side of RAD					
	"								RV	RV	clearing signs " " " "					
1719									RV	RV	" " " "					
											RAD North side					
Totals																

ASC Area 6/8

Process: Deliver Service
 Title: Electrical Scout Sheet

Mandatory	HA Process
Generic	
Priority Items	HA4
Challenges	

Works Order No.		c = consecutive	Direction	Position
Road:	All	S = Sequential	NB = North Bound, SB = South Bound	L = Lane, CR = Central reserve
Date:	27-11-15		EB = East Bound, WB = West Bound	LV = Left Verge, RV = Right Verge
Name:				

COL Ref:	SIGN Bollard Ref	REWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Slips, Jct to Jct, At Jct	Repair Carried out						
											Lamp Type	Fuse	Bollard	Ignitor	Repair Date	Beyond Repair	
	No Num			✓						Thick thorn							
	"			✓					LV	West entry from Hellenzett							
	"			✓					RV	"							
128	No Num							NB	RV	on RAB West Side							
	No Num									Under A17 Bridge							
	No Num								LV	East side RAB							
	"								RV	Service rd junction							
	"								CR	splitter island							
901			✓							Tutless lane							
894			✓					SB	RV								
	No Num							SB	RV								
	No Num							WB	CR	next to 877							
	No Num							NB	RV	off slip							
09613								NB	RV	Spoooner row							
09623								NB	RV	on slip							
	No Num							SB	RV	off slip							
	No Num							SB	RV	on slip							
	No Num									Athelborough - Stag RAB							
	"									on RAB West side							
No Num			✓					WB	LV	on RAB North side							
No Num			✓					"	"	London rd approach to RAB							
	No Num		✓					"	"								
No Num								EB		Stone cross - under pass							
										1st light							
No Num										Shelferton							
No Num								NB		on RAB East side							
No Num								NB	CR	splitter island NB on slip							
										bolton							
								EB		Walter rd RAB							
								WB		splitter island Tottenham bolton							
								WB		splitter island Walter side - bolton							
No Num										Mundford rd							
73								WB	LV	A1066 jct							
								WB	LV	last col A134							
	No Num							WB	LV	A1066 jct } clearing signs							
	134							WB	RV	"							
No Num								WB	CR	last col south							
										All bollards out - De-illuminated ???							
Totals																	

October 2015
Scouting

ASC Area 6/8

Process: Deliver Service
Title: Electrical Scout Sheet

HA Process	HA4
Generic	
Guidance	

Works Order No.		c = consecutive	Direction	Position
Road:	All	s = Sequential	NB = North Bound, SB = South Bound	L1 = Lane 1, CR = Central reserve
Date:			EB = East Bound, WB = West Bound	LV = Left Verge, RV = Right Verge
Name:				

COL Ref	SIGN Bollard Ref	MEWP Y/N	C	S	MP	JCT	H/S	Direction	Position	Comments and/or Additional Location: A Roads, Between Bllps, Jct to Jct, At Jct,	Repair Carried out					Beyond Repair	
											Lamp type	Fuse	Ballast	Ignitor	Repair Date		
	No Num		✓	✓						Thickthorn RAB 2x signs							
	No Num		✓	✓						Sign on west side of RAB							
128	No Num							NB	RV	under bridge							
	No Num								LV	off this side of RAB							
	No Num								RV	service road junction							
	No Num								CR	"							
	No Num								LV	on left verge from service rd							
	No Num								RV	under east side bridge							
										bottom of slip cutting line							
	236							SB	RV	Tullis Ln							
901+899	221		✓					SB	RV	off slip							
	No Num							WB	CR	RAB							
										on slip							
										opposite 877							
	304							SB	RV	Spencer Row							
	301							SB	RV	off slip							
09613								SB	RV	"							
0921								NB	RV	on slip							
09423								SB	RV	on slip							
								NB	RV	off slip							
	No Num									Atterborough Stn							
	No Num									RAB west rd side							
	No Num									RAB north side							
	No Num								LV	London rd junction							
	No Num									Stone cross							
	No Num									East side 2nd light							
	No Num									Shatterkin							
	No Num									on RAB of NB off slip							
	26							NB	LV	east and west sides							
										off after RAB							
	No Num									Loring							
	No Num									East side under bridge							
	No Num									Utter RAB							
										Spiker island towards Kilmston							
										ballard							
	No Num									Mumford RAB							
									WB	A1066 junction							
73	No Num								SB	lv	All ballasts out - De-illuminated?						
										Just col A1066							
	No Num									Drumton RAB							
	No Num		✓					SB	CR	1st col SB approach							
	No Num		✓						LV	Drumton road approach to RAB							
	No Num								RV	"							
	No Num								CR	Spiker island A1066 side							
	No Num								CR	Sign + ballard							
Totals																	