

Date	Defect Location	Defect Description
01/04/2014 15:43	M6 Northbound, 100m after J18.	Could see where water had built up in the poor weather, unblocked 8x gully tops
20/05/2014 13:43	M6 northbound junction 18	Gully checks all ok .
05/09/2014 14:11	M6 NB 277/8	M6 N/B 277/8 HGV strap collected debris
01/12/2014 14:38	M6 s/b 277/9	Tyre in c/r for night collection .
09/03/2015 13:15	M6 s/b 278/0	HGV mudguard on verge
12/03/2015 13:00	M6 n/b 273/8	HGV tyre to be removed
05/05/2015 16:57	M6 NB 278/0	Called to spillage leaking out of back of van after RTC
10/06/2015 09:37	M6 s/b 277/8	Metal debris
10/06/2015 15:44	M6 n/b 277/7	Wood debris
11/06/2015 16:04	M6 n/b 277/7+30	Strim sight line
20/06/2015 12:41	M6N/B 277/7	Large piece of wood , removed from hard shoulder
01/08/2015 11:52	J18 n/b entry	Side gullies on Dane bridge
04/08/2015 09:19	M6 S/B 277/5+ 40	Pot hole in lane 1
06/11/2015 08:22	M6 s/b m/p 277/7+70	Tyre in c/r for removal
09/11/2015 14:53	M6 NB jct 18 access to 278/0	Gullies blocked
17/12/2015 10:44	M6 277/6 to 279/0	Blocked gullies
14/01/2016 11:15	M6 N /B 277/6 HGV tyre	HGV tyre on hard shoulder to remove
22/01/2016 16:31	M6 N/B Jct 18-19 M/P 277.8	Removed
24/03/2014 05:06	M6 NB J18 to J19	Hgv strap for routine removal Unable to get strap due to hardshoulder closure, will have to be removed at another time
25/03/2014 22:44	M6 NB J18 to J19 MP 278/8	Can't access due to closure.
01/05/2014 11:13	M6 S/B 278/9	M6 S/B 278/9+50 and 278/9+90 Pot holes in lane 1
03/05/2014 11:09	M6 NB J18/19 278.2	M6 N/B 278/2 RTC 3 vehicle shunt in lane 3
11/05/2014 11:16	M6 n/b 279/4-279/5	Potholes require passing to uu19 night shift for filling and inspecting .
15/05/2014 18:02	M6 N/B J18-19 MP278/4	M6 N/B 278/4 Tyre collection debris removed
19/06/2014 16:45	M6 NB J18-19 MP 279/0	M6 N/B 279/0 Desil spillage on hard shoulder from broken down vehicle MRT arrived at scene and the vehicle has already been recovered Treated the spillage with 2 bags of granules
20/06/2014 15:22	M6 NB J18/19 278/.9	Large bag of hazardous waste on verge at marker post UNABLE TO REMOVE AS SPECIALIST REMOVAL NEEDS TO BE ARRANGED BY NCC
01/08/2014 10:58	M6n/b 278/7	Remove tyre debris from hard shoulder
03/09/2014 23:48	M6 Jct NB J18-19 MP 278/7A	Removed HGV strap .
21/10/2014 00:37	M6 Northbound, MP 278/3+50	4 x bags of bitmac used.
08/01/2015 12:53	M6 s/b 278/7+70	3 x potholes in lanes 2and 3 require passing to uu19 to fill on nights
13/02/2015 10:59	M6 s/b 278/5	HGV tyre collected from h/s
02/04/2015 10:46	M6 NB J18/19 Mp278/6	Met Ashley's tree specialist on M6 N/B 278/6 to inspect tree line ,
08/05/2015 03:11	M6 NB J18/19 btwn Mp278/0 - 280/5	Unable to get a heto block, there is a large number of potholes in various lanes. These require inspecting due to the sheer number and high traffic count
09/05/2015 03:39	M6 NB J18/19 btwn Mp278/0 - 280/5	Potholes In CL2/3 , Complete Upto 279/4 . 15 x Bitmac Used , NCC Informed
09/05/2015 12:07	M6 NB J18/19 btwn Mp278/0 - 280/5	Number of potholes in between m/p278/0-280/5 , locations and photos given for night shift to attend
10/05/2015 03:38	M6 NB J18/19 btwn Mp278/0 - 280/5	Various potholes between 279/4 and 280/3

14/05/2015 13:08	M6 NB J18-19 MP 278/5	Cardboard for removal
16/05/2015 09:55	M6 s/b 278/2 on h/s	Plastic drum
10/06/2015 11:05	M6 n/b 278/7	Tyre debris
02/07/2015 10:14	M6 S/B 278/0.+ 20 Lane two	Pot hole
03/07/2015 09:31	M6 S/B. 278 / 7. + 80. & . + 90.	2 x. Large pots. Filled numerous times . Causing uneven road service in lane 2
09/07/2015 10:19	M6 northbound 278/7+80 to 278/8	Potholes in lane 2/3
13/07/2015 10:02	Pothole in lane 3	268 /5 plus 80
23/07/2015 08:31	M6 S/B 278/8+10 and 278/8+60	Pot hole in lanes in lane 1
23/07/2015 08:34	M6 S/B 278/8+30	Large pot hole in lane 2
30/07/2015 10:19	M6 n/b 278/3+90	Pothole lane 2/3
30/07/2015 10:24	M6 n/b 278/4+50	Pothole lane 2/3
24/08/2015 09:08	M6 SB 267/8 + 60 CL2	Pothole
24/08/2015 09:13	M6 SB 278/8+50 cl1	X3 small pot holes
24/08/2015 09:18	M6 SB 278/7+ 70 under bridge	Large defective road surface, needs patching or complete resurfacing - potholes are appearing and need topping up, will need rolling block to complete and approximately 5 bags
04/09/2015 12:27	M6 S/B 278/8+30	3 x CL1 Potholes
07/09/2015 08:29	M6 S/B 278/8 +40	Pot hole lane 2
16/09/2015 12:35	M6 s/b 278/3+90	2 potholes in lane 2
13/10/2015 09:14	M6 s/b m/p 278/8+90	Pot hole needs topping up in l/1
20/10/2015 09:36	M6 N/B M/P 278/6	HGV tyre on verge
23/10/2015 12:14	M6 n/b 278/0-278/5	Several blocked gully tops require clearing on hard shoulder
28/10/2015 12:53	M6 n/b m/p 278/8+60	Damaged fence rail
12/11/2015 14:47	M6 N/B 278/3 to 278/9	Hgv tyre debris on hardshoulder from a blow out
17/11/2015 10:04	M6 northbound 278/6	Cone in c/r
19/11/2015 08:13	M6 southbound	Pothole in lane 2 at 278/8+50 Pothole in lane 1 at 278/8+30
25/11/2015 09:10	M6 s/b m/p 278/8 +40	Pothole in l/1
13/12/2015 11:28	M6 S/B 278/8 + 30	Pot holes
27/12/2015 09:06	M6 S/B 278/8+50 and 278/8+30	Pot holes in lane 1
31/12/2015 08:45	M6 S/B 278/8+30 Lane 1	Pot holes
18/01/2016 12:46	M6 s/b m/p 278/9+20	Pothole in l/2
18/01/2016 12:52	M6 s/b m/p 278/8+40	Pothole in l/1
10/02/2016 11:43	M6 s/b 278/8+50-278/8+40	1 x pothole in cl2 and 2 x potholes in cl1
01/06/2014 02:45	m6 nb j18-19 mpp279/5 cl2/3	Used 2x bags bitmac
26/08/2014 03:27	M6 NB J18-19 MP279/5	M6 N/B 279/5HGV brake down straddling hard shoulder and lane 1 MRT over layed H.As lane 1 MRTs lane 1 closure in place at 03:00MRTs
25/11/2014 13:06	M6 NB 279/4	Pothole Lane 3 (Enquiry 24705)
26/11/2014 01:18	M6 N/B Jct 18-19 m/p 279.4	Pothole (Enquiry 24700)
01/01/2015 22:50	M6 s/b 279/2+20	Pothole in cl2
05/02/2015 12:23	m6 m/p 279/5 NB just before 200m marker jct 18-19	
06/02/2015 15:30	M6, n/b, Junc 18/19, MP 279/2+70	C/Rbarrier damage 2 x socketed posts & 1 x OBB beam
16/02/2015 03:40	M6 NB 279/5	Fretting along line in lane 3
18/02/2015 15:54	M6, n/b, Junc 18/19, MP 279/5	

24/02/2015 14:30	m6 200 yds or so prior mp279/1+50 n/b cl2	Pothole filled under hato block
05/03/2015 02:24	M6 NB 1 mile North of J18 mp 279/0	Potholes x 3 to be filled
20/04/2015 15:31	M6, n/b, Junc 18/19, MP 279/9	Requested a rolling block.used 4 bags of viafix.
26/05/2015 12:14	280/0	Metal removed
30/05/2015 05:02	M6 N/B MP279/0 - 279/5	M6 N/B 297/8 to 297/1+70Filled numerous pot holes in lane 3 Used 7 bags of bit mac There is more pot holes from marker post 279/1+70 to 279/8 Job not complete please pass jol
02/06/2015 13:39	M6 N/B MP279/0 - 279/5	Several Potholes M6 N/B , 279/1 To 279/8 In CL3 , 279/1+80 , 279/3 , 279/3+30 , 279/3+90 Approx 5 Or 6 Potholes , 279/4+60 , 279/4+80 , 279/5+50 2 x Potholes , 279/7 ,
05/06/2015 01:39	M6 N/B MP279/0 - 279/5	4 bags of bitmac used between m/ps
03/07/2015 09:20	M6 S/B 279/1 + 10. Lane 2	Pot hole
08/07/2015 12:00	M6 N/B 279/9 + 60	Pot hole in lane 2 on a loop
15/07/2015 09:57	M6 n/b 279/4 plus 80	Pot hole in lane 3
23/07/2015 08:27	M6 S/B 279/0+50	Pot hole in lane 2
07/08/2015 08:17	M6 SB 279/8+50	
14/08/2015 12:32	M6 n/b 279/3	Pothole in lane3
14/08/2015 12:38	M6 n/b 279/4+50	Potholes lane 2/3
14/09/2015 09:23	M6 northbound 279/3	Cone for collection
15/09/2015 12:04	M6 s/b 279/8+50	Pothole lane 2/3
16/09/2015 20:18	M6 N/B Jct 18-19 M/P 279.6	M6 N/B RTC car vs central res barrier Damaging to barrier :- 12 TCB AND 6 socket posts and 1 adjuster Sprayed up job with yellow paint.
24/09/2015 14:27	M6 n/b 279/9+90	HGV tyre
01/11/2015 09:13	M6 n/b 279/0+ 50	Fence rail damaged.
01/11/2015 09:18	M6 n/b 280/0+60	Fence rail damaged.
08/12/2015 09:44	M6 n/b 279/8 to 280/0	Blocked gully's
29/12/2015 10:40	M6 N/B 279/7 to 281/0	Gully cleaning finished 280/0
28/01/2016 14:01	M6 s/b m/p 279/5+50	Pothole in l/2
01/02/2016 09:08	M6 S/B 279/8+50	Pot hole in lane 2
09/02/2016 09:58	M6 n/b 279/0+80	2 broken fence rails
09/02/2016 10:07	M6 n/b 279/0+80	2 broken fence rails
21/02/2016 13:25	M6NB Jct 18-19 MP 280/0	Debris in Road - Fibreglass car roof (Enquiry 40647)
09/04/2014 11:16	M6 s/b 280/5+10 lane 1	Pothole
19/05/2014 11:01	M6 southbound 280/5+10 lane 1	Pothole
19/05/2014 17:22	M6 N/B M/P 280.0 Jct 18-19	Asked to check location for pothole that possibly caused damage to vehicle Checked 500 metres either side of 280/0 and could not find any substantial potholes, we did find a few si stopped to fill. Locations are: 279/4+60, 279/5+50 and +60 , 279/6+30, 279/7, 279/7+30 and 280/1+90 all in lane 3 or centre line of lanes 2 and 3 Traffic count too high to get photos
28/05/2014 10:54	M6 n/b 279/4-279/5	4 x potholes in cl3 to be passed to nights
28/06/2014 15:42	M6 NB J18-19 MP280/5	Remove RTC debris from location given
25/07/2014 03:21	M6 NB J18-19 MP 280/5	HGV at mp for collection
02/09/2014 10:47	M6 n/b 273/5	HGV tyre on hardshoulder for removal
02/09/2014 11:23	M6 n/b 282/5	Metal debris on hardshoulder
21/09/2014 17:06	Nwrcc M6 NB 280/1	Bumper for routine collection (Enquiry 22743)
01/10/2014 11:02	M6 N/B M/P 280/1	Mudguard

10/12/2014 11:13	M6 S/B 280/5	Pot hole in lane 1 Contacted the H.A to put some signals on in the area to log:- 699 Filled pot hole with 1 bag of bit mac
13/02/2015 10:52	M6 S/B 280/2	HGV tyre debris on hard shoulder Collected
04/03/2015 02:14	m6 nb j18-19 mp 280/3	2 x areas of fretting found in lanes 1-2 and lane 2-3
11/05/2015 02:42	MP 280/3 M6 N/B	Large fretting and pothole, filled with x 3 bags of instamac
12/06/2015 09:28	M6 n/b 280/7+30	Strim round etb box
12/06/2015 09:39	M6 n/b 280/7+40	Blocked gully top
12/06/2015 09:44	M6 n/b 280/8	Blocked gully top
12/06/2015 09:54	M6 n/b 280/8+20	Gully top blocked
12/06/2015 10:01	M6n/b 280/8+70	Gully top blocked
12/06/2015 10:06	M6 n/b 280/8+95	Gully top blocked
12/06/2015 10:10	M6 n/b 280/9	Strim round marker post
12/06/2015 10:21	M6 n/b 280/9+30	Gully top blocked
12/06/2015 10:51	M6 n/b 280/9+60	Blocked gully top
13/06/2015 10:13	M6 north bound 280/9 +90	Clear gully top
13/06/2015 10:38	M6 north bound 281/0	Obstructed marker post
13/06/2015 11:18	M6 north bound 281/0 + 10	Coms box over grown foilage
27/06/2015 21:34	M6 S/B 280/2	Car tyre debris removed from centre res
07/08/2015 08:07	M6 SB 280/5+20	Pothole already filled but needs topping up as sunk
12/08/2015 10:22	M6 n/b 280/2	Fence rail damaged .
14/08/2015 11:20	M6 n/b 280/5 +10	Pothole lane 1
14/08/2015 17:12	M6NB J18-19 MP 208/1A	RTC barrier damage 2 beams + 3 posts
29/09/2015 14:18	M6 n/b m/p 280/0+30 n/s	1fence rail damaged
02/10/2015 09:52	M6s/b 280/2 +50	Pothole in lane 3
28/10/2015 11:16	M6 n/b m/p 280/5+80 in L/1	Pothole
06/11/2015 08:10	M6 s/b m/p 280/8+20 in c/r	Tyre in c/r for removal
01/12/2015 12:43	M6 S/B 280/5 + 30 Lane 1	Pot hole requires attention
11/12/2015 10:39	M6 N/B m/P-280/0+50 C/R	Barrier damage
15/12/2015 14:52	M6 N/B M/P-280/2	Contractor has put mud all over the had shoulder and gully tops requires a road sweeper to clear the hard shoulder.
21/01/2016 10:07	M6 n/b 280/7+30	2x fence rails need replacing
21/01/2016 10:10	M6 n/b 280/7+ 60 facing ETB box 6807	Fence rail needs replacing
08/02/2016 13:31	M6 n/b 282/9+80	Pothole lane 2
24/02/2016 09:44	M6n/b 282/2+50	Pothole in lane 2
26/02/2016 10:35	M6 n/b 280/2+70	Pothole in cl2
19/03/2014 11:59	M6 northbound 281/1+50	Small wooden trailer been dumped next to boundary fence with blown out tyreWill need removing with hi-ab so will need to be sent to depot for removal to be organised
24/05/2014 21:38	M6 S/B 282/1 +50	M6 S/B 282/1 +50 Pot hole in lane 2 Pot hole filled with 1 bag of bit mac
14/06/2014 12:58	M6 n/b 281/3	Car tyre
26/06/2014 16:07	Rob Lane	Oil spillage 5 bags granules used
17/10/2014 11:40	M6 Northbound, MP 281/5	C/R barrier damage
09/02/2015 14:01	M6 n/b 281/8 on h/s	Exhaust removed

23/02/2015 16:42	M6 n/b at 281/8 - 282/0	HGV tyre debris spread over 200m
14/05/2015 13:16	M6 n/b 281/1	Remove exhaust from hard shoulder
14/05/2015 13:19	M6 n/b 281/1	Exhaust for removal
13/06/2015 10:58	M6 north bound 281/0 +10	Blocked gully top
13/06/2015 11:46	M6 north bound 281/0 +50	Blocked gully top
13/06/2015 11:59	M6 north bound 281/0+80	Blocked gully top
13/06/2015 12:09	M6 north bound 281/1	Obstructed sight lines
13/06/2015 12:18	M6 northbound 281/1 +10	Blocked gully top
13/06/2015 12:31	M6 north bound 281/1 +50	Blocked gully tp
13/06/2015 12:40	MM6 north bound 281/1+80	Blocked gull top
13/06/2015 12:49	M6 northbound 281/2	Obstructed sight line
13/06/2015 12:58	M6 north bound 281/2 +30	Blocked gully top
13/06/2015 13:04	M6 north bound 281/2 +70	Blocked gully top
13/06/2015 13:11	M6 north bound 281/3	Blocked gully top
13/06/2015 14:43	M6 north bound 281/3+30	Blocked gully top
13/06/2015 14:48	M6 north bound 881/3 +50	Gully top blocked
13/06/2015 14:56	M6 north bound 281/3 +80	Gully top blocked
05/07/2015 10:22	M6 N/B 281/5 To. 281/9	10 blocked gullies
06/07/2015 11:21	M6 NB 281/6 +30	25litre plastic drum needs removing
09/07/2015 08:53	M6 southbound 281/8+40 and 281/8+50	Potholes in white lines between lanes 2 and 3
10/07/2015 08:19	M 6 s/b 381/5+30 to 281/3	Potholes in lane 3
19/07/2015 12:32	M6 S/B 281/5	CL2 Pothole
27/07/2015 08:04	M6 S/B 281/4+60 Lane 3	Pothole under bridge
28/07/2015 08:12	281/4 c/res	Barrier damage 2x18 posts behind OBB
29/07/2015 10:52	M6S/B 281/1	Over grown pathway to gantry
13/09/2015 12:03	M6 n/b 281/5+50	Cone
30/09/2015 08:04	M6 s/b 281/8-281/5	Blocked gullys
30/09/2015 09:43	M6n/b 281/5+30	Boundary fence damage 4 posts 8 rails
23/10/2015 10:48	M6 s/b 281/3	Pothole in cl3
01/11/2015 09:24	M6 n/b 281/4+90	Pothole in cl1
16/11/2015 14:58	M6 n/b m/p 281/5+20	Fence damage with live stock in field ,temp repair made but requires permanent repair
18/11/2015 09:30	M6 n/b 281/0+ 80	1 broken fence rail
23/11/2015 14:44	M6 n/b 281/0 - 281/5	Blocked gullys
04/12/2015 10:30	M6 n/b 281/4+90	Pothole in lane 1
10/12/2015 15:38	M6 N/B 279/7 To 281/3	Blocked Gullies
28/12/2015 10:16	M6 S/B 281/5 Lane 2/3 on white line	Pot hole
13/01/2016 09:44	M6 S/B 281/4	Pot hole in lane 2
13/01/2016 09:47	M6 S/B 281/3+90	Numerous pot holes in lane 3
02/02/2016 09:25	M6 southbound lane 3 281/3+70 to 281/3	Road surface breaking up
16/02/2016 13:40	M6 N/B 281/5	Pot hole in lane 1
23/02/2016 10:33	M6 n/b 281/7+50	1 broken fence rail
24/03/2014 05:11	M6 NB J18 to J19 MP 282/0	Pothole Unable to locate, pass to days to locate and indicate location
09/05/2014 03:16	M6 Northbound, J18 - 19. - 1/2 mile prior to	2 x potholes filled

12/12/2014 12:35	M6 N/B 281/8 to 282/2	Flooding on the hard shoulder due to blocked gullies Cleared 14 gully tops
17/03/2015 12:18	M6 N/B 282/5	RTC van vs car First on scene contacted the H.A for assistance Cleared up the RTC debris
14/05/2015 15:57	M6 n/b 280/0-281/9	7 x gullies cleared. We have reached our 15 min limit for hard shoulder works. There are more gullies requiring clearing at locations 280/7-281/9,283/1
22/06/2015 14:01	282/9. /. 284/4	Take photos of marker post after strimming / litter picking / and gully cleaning
09/07/2015 08:38	M6 southbound	Potholes 282/6+ 90 in lane 2/3 282/6+50 in lane 2/3
04/08/2015 11:48	M6 N/B M/P-282/9	
17/08/2015 09:26	M6s/b 282/6 + 20	Pot hole in lane3
14/09/2015 08:23	M6 southbound 282/8 hard shoulder	Tyre
17/09/2015 09:33	M6 s/b 282/1 lane 2	
25/09/2015 10:02	M6 NB 282/1	Potholes in lane 2 large needs rolling block and urgent repair
06/10/2015 14:19	M6 n/b m/p 282/9+60 on verge	Fence damage 1rail
29/10/2015 09:23	M6 n/b 282/5+50	3 X fence rails damaged
18/11/2015 09:37	M6 n/b 282/5 +90	2 broken fence rails
20/12/2015 23:36	M6 NB J18/19 Mp282/1	Pothole x3
29/12/2015 10:13	m6 nb j18-19 mp 282/2	Picked up HGV mud guard from verge
23/01/2016 11:42	M6 n/b 282/1	Large pothole in lane 2
12/02/2016 11:54	M6 n/b 282/3	Tyre on hard shoulder
25/02/2016 10:47	M6 n/b 282/7+70	1 broken fence rail
06/03/2014 22:09	M6 SN J18-19 MP 280/5	Loops pothole
07/05/2014 03:42	M6 NB J18-19	2 x potholes filled at mp 278/1+80 and 279/2+40 . No other issues found
12/07/2014 13:45	M6 NB J18-19 MP 283/2	Tyre debris for routine collection (Enquiry 20618)
12/07/2014 13:46	M6 NB J18-19 MP 283/2	Tyre debris for routine collection (Enquiry 20618)
25/08/2014 11:58	M6 NB J18 to J19 MP 284/0	8 beams and 8 posts marked up with a cone .
26/02/2015 15:36	M6 n/b 283/5	HGV tyre for removal
12/04/2015 06:20	M6 NB J18/19 283.4	Filled x2 bags instamac
17/06/2015 12:32	m6 nb j18-19 mp 283/5	Large Amount Of Nylon Twine covering 500 Mtr To 1000 Mtr Of Hardshoulder
22/06/2015 11:59	M6 northbound 284/4 to 285	Strim marker posts,signs and ETB's Litter pick strimmed area Clear gully tops
08/07/2015 12:09	M6 N/B 283/5 + 10 lane 1	Pot hole in lane on loop
20/07/2015 08:24	M6 S/B 283/2+70	CL3 Pothole
30/07/2015 08:37	M6 s/b 283/6 (no m/p)	Pothole lane 2/3
14/08/2015 11:04	M6n/b 283/7	Pothole lane 2/3
28/09/2015 09:46	M6 northbound 283/2+70	1x damaged fence rail
07/10/2015 16:20	M6 N/B 283/4+20	2 x Fence Rails Damaged
14/10/2015 11:00	M6 s/b m/p 283/4+80	Broken fence rail
16/10/2015 10:01	M6 n/b 283/2	Corrugated steel
04/11/2015 10:05	M6 n/b 283/4	Pothole lane 2/3
04/11/2015 10:10	M6 s/b 283/7+80	Broken fence rail
06/11/2015 10:49	M6 NB J18-19 281/5-281/6	100m of boundary fence has rotted and requires replacing so the farmer can put live stock in the field

13/11/2015 09:37	M6 n/b 283/1 to 283/5	Gullys require clearing.
13/11/2015 09:42	M6 n/b 283/5+70	Damaged fence rail.
18/11/2015 09:44	M6 n/b 283/6+70	Wheel on h/s
07/01/2016 10:37	M6 n/b 283/8+60	Tyre in c/res
27/01/2016 09:59	M6 n/b m/p 283/1to knutsford services	Blocked gully tops and h/s needs sweeping as photo shows
28/02/2016 09:19	M6 n/b 283/9 +90	Pothole in lane 2
28/02/2016 11:47	M6 n/b 283/9+70	Pothole in lane 2
27/03/2014 12:42	M6 NB J18 to J19 MP 284/1	Unable to check damage due to hard shoulder closure being work in
27/03/2014 22:08	M6 NB J18 to J19 MP 284/1	Can't access due to closure.
25/05/2014 15:48	M6, n/b, Junc 18/19, MP 284/3	5x gully tops blocked , require gully sucker M/P 284/2+90 - 284/3+50 Informed NCC
09/07/2015 08:25	M6 southbound 284/3 lane 1	Pothole and cracking in carriageway
30/07/2015 08:22	M6 s/b284/4 + 50	Pothole lane 2
12/08/2015 10:35	M6 n/b 284/9	HGV wheel in c/r
11/09/2015 15:10	M6, s/b, Junc 21/20, Mp 300/0 approx	RTC with c/res barrier damage (Enquiry 34430)
15/10/2015 13:48	M6 n/b m/p 284/7	Tyre moved to verge
28/10/2015 16:23	M6 S/B 284/3	Road surface is uneven in lane 1 due to two large pot holes Deployed a un even road sign to warn the traveling public Job number 32042
29/10/2015 09:30	M6 n/b 284/5+50	1 fence rail damaged.
29/10/2015 09:36	M6 n/b 284/7 to 284/9	10 gully tops need cleari
15/11/2015 03:55	M6 n/b 284/0-284/5	Blocked gully tops require clearing
15/11/2015 04:06	M6 N/B M/P-284/2-284/4	11 X blocked gullys requiring gully sucker causing flooding on hard shoulder
15/11/2015 09:20	M6 southbound 284/2 to 284/6	Gullys require clearing
27/01/2016 00:00	M6 NB J18-19 MP284/7	Removed
02/02/2016 09:15	M6 southbound 284/3 lane 1	Pothole needs topping up with bitmac
09/04/2014 15:15	M6 NB J18-19 MP 280/2 - Approx 5 miles af	Pothole along lane 2 and 3 join
16/07/2014 10:18	M6 s/b 285/2	Metal plates on hardshoulder
22/10/2014 09:44	M6 s/b 283/6	Remove plastic container
15/12/2014 03:28	M6 s/b mp 299/4-283/4	Removed large debris items from c/res ie tyres mudguards and damaged cones
23/03/2015 14:39	M6 NB J18-19 MP285/4	Removed damaged TM cone
04/04/2015 17:25	M6 NB J18-19 MP285/5	Insulation for routine removal REMOVED
17/06/2015 21:42	M6 Northbound, MP 285/0 to 286/0	HGV tyre and mudguard
19/06/2015 11:51	M6 north bound 281/9 to 282/9	Strumming all marker post + Clean and litter pick gulies
19/06/2015 18:24	M6 N/B 281/9 to 282/9	Strumming marker posts and large signs Cleaning gully tops .
07/07/2015 10:59	M6 N/B 285/7 to 285/8	Veruis debris on hard shoulder ie:- cone, plastic sign,plastic bumper and a cone lamp Requires picking up .
04/08/2015 10:56	M6 N/B 285/6+90 under the VMS sign	2 pot holes in lane 2
07/08/2015 07:55	M6 SB 285/9 centre res	Large piece of aluminium needs removing on nights
07/09/2015 10:50	M6 N/B 285/1 + 50	Large tree needs attention (dead) if collapses will encroach on to lane 1 of main carrageway
07/09/2015 11:01	M6 N/B 285/2	A number of large dead trees over 100 mtrs if collapses will encroach H/S + lane 1 of main carrageway
04/10/2015 09:09	M6 n/b 285/7	Over grown vegetation comms box

25/10/2015 02:38	M6 NB J18-19 MP 284/9	Barrier damage marked up 12 posts and 9 beams .removed debris from cl1 and h/s.
27/11/2015 15:35	m 6 N/B 285/4+50	HGV Tyre to remove
02/12/2015 18:31	m6 nb j20 -21	Sign with in the gantry on the wall had moved , engineer on his way out and stated there was no safety issues regarding it falling
10/12/2015 15:58	M6 N/B 284/5 To 284/9	Blocked Gullies
01/01/2016 09:41	m6 n/b m/p 285/4	Damaged cone moved to verge for removal
01/01/2016 09:45	M6 n/b m/p 285/4-285/7	Blocked gully tops
11/10/2014 13:52	M6 SB J19 to J18 m/p 286/9+60	Central reservation barrier damage 8x TCB beams and 10x socket posts (approx) marked with a cone to the nearside Needs close coning so needs sending to depot to be arranged
14/12/2014 15:58	M6 northbound 286/8+60	HGV tyre struck under central reservation barrier
10/06/2015 16:07	M6 n/b 286/8	Sign tiredness can kill (overgrown) needs cutting back
28/06/2015 16:25	M6 Jct18-19 M/P-287/0A O/S	Barrier damage
02/07/2015 09:37	M6 S/B 286/8	Pot hole in lane one
21/07/2015 11:32	M6 S/B 285/1 H/S	Strimming
02/08/2015 23:07	M6 NB 286/1+50	5 posts and 8 beams marked up
25/09/2015 10:19	M6 NB 285/3 + 50	Fence rail broken
28/09/2015 09:54	M6 northbound 286/3+50 boundary fence	1x damaged fence rail
29/09/2015 12:23	286/0+70	Fence damage 1rail
13/10/2015 10:51	M6 n/b m/p 286/0+30 on h/s	Have mudguard
18/01/2016 16:47	M6 SB J19-18 MP 286/9	C/r barrier damage
09/02/2016 10:19	M6 n/b 286/8+20	1 broken fence rail
15/02/2016 23:25	m6 nb j18-19 mp 286/6	Debris in Road - wood (Enquiry 40472)
16/03/2014 12:59	M6 Northbound, MP 287/6	Can't remove due to closure.
02/06/2014 00:37	M6, n/b, Junc 18/19 at MP 287/7 & 279/4	Potholes in CL2 &3 reported by the Police (Enquiry 19233)
12/06/2014 04:44	M6, MP 287/3	
25/07/2014 04:06	M6 NB J18-19 MP 287/7	Tyre Derbis - Request for removal (Enquiry 21010)
04/08/2014 17:22	M6. n/b, Junc 18/19, MP 287/5	
04/08/2014 22:00	M6. n/b, Junc 18/19, MP 287/5	Removed wheel arch from h/s
22/08/2014 13:34	M6 N/B 287/4	2 car tyres and a HGV mud gard debris on verge Debris collected
24/09/2014 02:01	M6 N/B M/P 287.5 jct 18-19	5 posts socketed 10 beams TCB
27/03/2015 11:50	M6 s/b 287/0	Remove HGV exhaust
10/06/2015 16:25	M6 n/b	Knutsford service 1/2 mile sign overgrown
06/07/2015 11:38	M6 NB 267/8 + 10	Carpet on HS needs removing.
16/07/2015 14:50	287/5	
05/08/2015 09:08	M6 N/B 287/0 to 288/0	Blocked gully tops require cleaning.
13/08/2015 09:46	M6 N/B M/P 287/5	Fence rail missing (possibly x 2)
05/09/2015 00:30	M6 NB J18-19 MP 287/6	Mud flap
20/09/2015 12:24	M6 n/b m/p 287/1+50	Fence rail
14/10/2015 11:19	M/6 n/b m/p 287/4 on h/s	Have strap for removal
02/11/2015 10:10	M6 n/b 287/7 opposite 200 count down ma	Hgv tyre
12/11/2015 15:02	M6 N/B 287/6	At the ETB box there is a hgv tyre for collection
18/11/2015 09:55	287/3+30 m6 n/b	1 broken fence rail
29/11/2015 16:40	M6 N/B prior to knutsford services 287/1	Fallen tree requires cutting back from protruding onto the hard shoulder

27/12/2015 08:48	M6 S/B 287/6	Car tyre with wheel debris on hardshoulder
07/02/2016 12:00	M6 N/B M/P 287/2 (M/P missing)	1 X broken fence rail
01/08/2014 11:15	M6, n/b, Junc 18/19, MP 288/0	Hgv tyre removed from hard shoulder
23/01/2015 12:50	M6 NB J18-19 no mp given	Numerous Potholes On M6 N/B Between Jn18 & Jn19 Locations , :
10/02/2015 15:23	Knutsford Sevices NB offslip to services.	Damaged sign,reported previously
20/05/2014 14:01	M6 n/b knutsford services exit slip	2x blocked gullys that need gully sucking.
20/05/2014 15:12	M6 NB exit slip to knutsford services	2 x blocked gullies (Enquiry 18895)
28/10/2014 02:43	M6 n/b access to knutsford services	Knutsford services sign damaged. One of the two posts holding the sign up is missing and the lighting post has been knocked over and may require inspection by a electrition
03/09/2015 12:03	M6 n/b 287/5+50	Missing fence rail requires replacing
28/09/2014 16:59	M6 N/B J19 MP288/4+90	Offside barrier damage (Enquiry 22915)
04/12/2014 13:41	M6 NB J18-19 MP288/6+20	Centre res. barrier damage 11 x socketed posts 4 x TCB beams 2 x OBB beams 2 x running rails 1 x transition joint 1 x middle DROBB beam
03/06/2015 17:54	M6NB MP288/6	RTC two vehicles HGV vs car Police put lane 1 out for 5 mins to put vehicles on hardshoulder No ha damage at the scene
04/07/2015 16:26	M6 N/B Knutsford Services Access	1 x Obscured M6 Sign
04/07/2015 16:29	M6 N/B Knutsford Services Access	2 x Gully Tops Require Clearing
20/07/2015 11:08	M6 N/B 288/1 To 2884 (Knutsford Services	20 x Blocked Gully Tops
23/07/2015 11:35	M6 N/B 288/5	Strimmed around gullys
30/09/2015 11:29	M6 Knutsford services entry slip	Litter picking required
07/11/2015 10:59	M6 n/b access from knutsford services	Blocked gully tops require clearing
04/12/2015 00:45	m6 nb knutsford services exit mp 289/7	Flooding on access slip requires gullies clearing
19/01/2016 10:04	M6 n/b 288/8+90 lane 1 290/2+60 lane 2	Potholes in roadworks so will need a block .no pictures because no were to stop.
18/02/2016 13:54	M6 N/B 288/6	HGV windscreen debris on verge
12/06/2014 04:45	M6, n/b, 200 mtrs prior to Knutsford services	
02/10/2014 15:08	M6 n/b 288/3	Remove metal debris
02/01/2015 00:21	M6 n/b 288/2+80 cl3	3 x potholes to be filled
04/03/2015 02:52	M6 NB Prior to Knutsford Services - 287/7	Nearside barrier damage found, DROBB system protecting gantry and bridge approach
29/04/2015 23:33	NB 288/2	M6 S/B 294/3 Tyre debris removed
14/07/2015 11:42	M6 Northbound exit to Knutsford services	Area requires strimming
21/07/2015 10:46	M6 N/B bowl at knutsford services	Blocked gully tops requires cleaning
18/08/2015 10:47	M6 s/b 287/9+50 access from services to m6	2 x damaged fence rails require replacing
11/11/2015 11:54	TEST... NO ACTION NEEDED	Test
11/11/2015 11:58	TEST... NO ACTION NEEDED	
22/01/2016 09:54	M6 n/b m/p 288/2	Tyre for removal
01/03/2016 09:56	M6 n/b , under the bowl at knutsford servic	Flooding
02/10/2014 15:32	M6 NB MP 289/0+10, +30 and +70	Report 3 x barrier strikes
18/04/2015 12:43	M6 N/B Jct18-19 M/P-288/6	oil spillage found by MRT on patrol (Enquiry 30426)

15/07/2015 10:30	M6 n/b 288/8 plus 50	Obscured sign / tatton park
15/07/2015 11:51	M6 sb mp 288/9 verge	Strim and cut back overgrown vegetation obscuring sigh
23/07/2015 12:01	M6 N/B 288/8 to 288/9	Strimming
23/07/2015 11:56	M6 N/B 288/4 TO 289/1	Strimming / gully cleaning / litter picking
06/10/2015 14:32	M6 n/b m/p 288/9+30	HGV tyre for removal
20/10/2015 09:59	M6 N/B M/P 288/9+70 Lane 1	Pothole
27/04/2014 15:35	M6 SB J19	Dead fox (Enquiry 18095)
10/07/2014 16:16	M6 NB 100yd countdown marker fro J19 Exi	Tyre debris
19/10/2014 16:48	M6 NB Just B4 J19 access slip	Report and mark up barrier damage, cone on nearside
17/05/2015 11:08	M6 n/b 289/2	Plastic debris
18/03/2014 01:46	M6 n/b 289.7+80 cl1	Pothole filled using 1 x bitmac
02/09/2014 03:52	M6 NB MP289/7 J19 Bowl	3 posts and 4 beams damaged and marked up with a cone .
11/09/2014 22:54	M6 NB 289/5 to 291/5 J19 near Knusford	Request for Sweeper for Scheme Works (Enquiry 22515)
24/07/2015 03:13	M6 n/b jct 19 exit slip	Litter picking
26/10/2015 22:45	M6 NB J19 Mp289/7	Barrier damage 4x 2 X post
02/02/2016 15:22	m6 nb j19 mp289/7	Road Traffic Collision - barrier damage (Enquiry 40000)
13/02/2016 13:59	M6 N/B Jn 19 Exit Slip	Felled Trees Overhanging N/S Barrier
04/03/2014 04:05	M6 NB J19 EXIT	2 x potholes filled using 1 x bitmac
04/03/2014 04:09	M6 NB J19 EXIT	2 x potholes filled using 1 x bitmac
28/06/2014 15:24	M6 NB J19 Exit Slip	O/side barrier damage ,marked up with a cone
16/10/2014 13:14	M6 N/B M/P 289/2	Large hose
30/05/2015 17:33	M6 nb j19 exit slip bullnose	Tyre debris
28/12/2015 02:57	M6 junction northbound 19 exit	Blocked gully tops
10/02/2016 13:02	M6 NB J19 Between the slips	HGV blocking main c/way and badly damaged bullnose barrier (Enquiry 40281)
09/12/2014 15:56	M6 N/B 290/5 to 291/1	Blocked gullys and risk of flooding in the area Cleared 16 gully tops
04/07/2015 16:43	M6 N/B Jn19 Access Slip (Offside)	Obscured P/T Traffic Lights Sign , CL2 Closure Required
14/07/2015 16:19	M6 290/1 - 289/4	Overgrown around maker post and gully tops
14/07/2015 16:49	M6 s/b jct 19 290/1 n/s	Sign requires vegetation cutting back
17/09/2015 10:10	M6 n/b. 290/0 +90 lane 1	Pot hole on loops lane 1
28/10/2015 14:48	M6 n/b jct19 a/s at comms box 290/0	Pothole on h/s
30/10/2015 10:47	M6 n/b jct 19 a/s prior to comms box 290/0	2 pot holes
19/02/2016 15:21	M6 n/b 288/8+80	Cl1 pothole at the beginning of the road works so no picture.
16/08/2014 09:59	NB 290/0	C/res barrier damage at location given , 7 x posts and 3 x beams , cone left on near side verge to locate
02/10/2014 22:23	M6 Northbound, MP 290/3	Removed wheel
02/11/2014 12:23	M6 NB J19 Access Slip o/s	3x blocked gully tops require clearing due to carriageway flooding
22/12/2014 11:26	M6 n/b jct 19 access	Metal pieces and plastic sheeting dumped behind barrier
30/04/2015 12:05	M6 NB J19 Mp289/5	HGV Tyre (Removed)
27/06/2015 17:49	M6 junction 19 access slip	Litterpick
04/07/2015 11:28	M6 S/B Jn19 Exit (Nearside)	1x Direction Sign obscured By Tree
08/07/2015 12:25	M6 N/B 290/0 blocked gullies	6 blocked gullies from 290/0 to The beginning of the hatched area
09/07/2015 11:02	M6 northbound 290/2+70 lane 1	Pothole
15/07/2015 08:25	M6s/b 290/1 at jct 19 bowl	Obscured sign
21/08/2015 10:01	M6 Jct 19 roundabout	Large amount of ragwort on roundabout

10/09/2015 08:08	M6 Northbound, MP 290/3+40	End of life central reserve barrier (Enquiry 35149)
10/09/2015 14:52	289/9 m6 NB	Pothole cl1
26/09/2015 10:29	M6 S/B jct 19 Exit top of slip	Gully top surround requires bit mac to repair
28/12/2015 03:33	M6 northbound junction 19 access slip	Blocked gully tops
18/01/2016 03:26	M6 NB j19 - 20 mp 290/2 h/s- cl1	Large pothole in between h/s and lane 1 filled with x3 bags of viafix under hato block
08/03/2014 15:14	M6 NB J19/20 Mp292/0	C/r barrier damage
27/03/2014 11:11	M6 s/b 290/8-290/7	6 x potholes filled
12/04/2014 15:46	M6 n/b 290/7+10	Pothole filled
01/09/2014 23:36	M6 s/b to m62 e/b	Gully hotspots .26 x gullys cleared
22/07/2015 10:29	M6 NB 291/0	Sign needs resetting and cleaning
19/08/2015 16:23	M6 NB MP 290/8	HGV mudguard for removal
20/08/2015 10:53	M6NB MP 290/5A	3 x Posts & 2 x OBB @ 290/3+60 , & 2 x Posts & 2 x OBB @ 290/3+80 Of Nearside Barrier Damage 2 x Bottom Rub Rail & 4 x Brackets Of R1 Barrier Damage , @ 290/4+90
01/10/2015 11:32	M6 N/B M/P 290/5 - 291/3	Blocked gullies between given location
29/10/2015 10:07	M6 n/b 290/6 to 291/0	Blocked gully tops.
02/02/2016 11:01	M6 northbound 292/3+90	Pothole in roadworks will require rolling block and be done on days
26/04/2014 09:14	M6 n/B J19-20a MP 291/8	RTC with boundary fence damage of approx 12 posts and 30 rails. Fencing team requested as there is livestock in the field.
18/10/2014 09:42	M6 NB J19-20 ERT 6920A	Mark up barrier damage
04/11/2014 12:24	M6 n/b 291/6 LH	Remove tyre and wooden debris
06/12/2014 10:04	M6 NB J19/20 292.0+50	Report and mark up barrier damage found on patrol. 5 x socket posts and 10 x TCB
25/12/2014 14:28	M6 NB J19/20 (N/S 291.3) O/S	RTC with C/res barrier damage (Enquiry 25933)
09/01/2015 13:13	M6 NB J19 MP 291/6+40	Report and mark up barrier damage
10/01/2015 09:49	M6 NB J19/20	Tree fell across H/S and C/way . Car hit C/Ress trying to avoid tree .
11/03/2015 10:00	M6 N/B jct 19-20 m/p-291/2+90	12 x Posts & 10 TCB N/ S Barrier Damage , M6 N/B 291/2+90 , Damage Sprayed
10/06/2015 17:14	M6 n/b 291/2	Obscured sign
06/07/2015 12:22	M6 NB 291/2	Barrier damage
01/10/2015 14:23	M6 N/B J19-20 MP291/2+10	6 beams TCB damaged and 4 posts
07/10/2015 16:43	M6 N/B 290/6 To 291/8	21 x Blocked Gullies
22/10/2015 12:25	M6 n/b 290/7+80	1 X damaged fence rail requires replacing
29/10/2015 13:32	M6 NB 19/20 291.3	Have strap
30/10/2015 09:39	M6 n/b m/p291/.1-291/4	Blocked gully tops
03/11/2015 09:26	M6 n/b 291/2+40	Mud guard on h/s
08/11/2015 16:58	M6 NB 291/2+70	Mark up barrier damage. RTC debris removed and mud cleared from hard shoulder.
24/02/2016 01:10	m6 nb hs j19-20 mp 291/8 and 291/7+50	Main Carriageway Defect - potholes (Enquiry 40713)
16/07/2014 09:34	M6 s/b 293/0	Metal plate and wagon tep on hardshoulder
31/07/2014 14:04	M6n/b 292/4-292/5	Remove plasterboard from hard shoulder
04/10/2014 09:37	M6 NB J19 - 20 MP 292/0	Blanket removed from hard shoulder
19/12/2014 09:19	M6 s/b 292/0	Blue plastic tub
25/02/2015 10:42	M6 s/b 292/9	HGV strap on hardshoulder for removal
01/05/2015 10:31	M6 n/b 292/1	Remove plastic container and HGV strap
06/05/2015 20:56	M6 NB J19/20 Mp292/7	Fire Debris Cleared ,No Damage To Overbridge , HardShoulder Requires Inspection
16/05/2015 14:51	M6 n/b 292/2	Pothole on rib line going into L/1
20/06/2015 09:17	M6 292/1	HGV Landing leg handle + tyre debris removed
20/06/2015 09:30	M6n/b	Metal debris on hard shoulder removed
21/06/2015 09:38	M6 /.NB 292/3	Exhaust box (removed)

21/07/2015 10:58	M6 N/B 292/4+50	Pot hole in lane 2
24/07/2015 08:47	M6 sb 292/7 + 50	Pothole lane 1
27/08/2015 11:39	M6 NB J19-20 MP292/4	HGV tyre
04/09/2015 08:21	M6 N/B Jct 19-20 M/P-274/7+60	Fence damage
15/11/2015 10:07	M6, n/b, Junc 19/20, MP 292/3	Removed
26/01/2016 12:37	M6 n/b 292/3+80 cl1	Pothole inside long term works that will require a rolling block
18/03/2014 02:12	M6 n/b 293.5+30 cl2	Pothole filled using 1 x bitmac
11/04/2014 23:01	m6 nb j19/20 mp293/6	Removed
03/05/2014 15:39	M6 NB J29 to J20 MP 293/3	M6 N/B 293/3 Mattress for collection Mattress collected
13/05/2014 09:49	M6 n/b jct 19-20 m/p 293.5+50	Fence damage approx 75-100m back from carriageway unsure if are responsibility ,requires sending to Preston brook o check and repair if required,as soon as possible
04/10/2014 09:52	M6 Jct 19-20 MP 293/5	Engineer required to inspect corrosion
14/01/2015 11:54	M6 northbound 293/8 to 294/1 hard should	Tyre dedris REMOVED
31/01/2015 02:45	M6, n/b, Junc 19/20, MP 293/5	Plastic Piping (No Trace)
31/01/2015 02:47	M6, n/b, Junc 19/20, MP 293/5	Plastic Piping (No Trace)
31/01/2015 02:49	M6, n/b, Junc 19/20, MP 293/5	Plastic Piping (No Trace)
31/01/2015 02:51	M6, n/b, Junc 19/20, MP 293/5	Plastic Piping (No Trace)
31/01/2015 11:06	M6 NB J19/20 293.5	Plastic pipes and debris on hard shoulder and verge REMOVED
23/02/2015 14:24	M6 s/b 293/7	Length of wood on hardshoulder
06/03/2015 02:55	M6 NB 293/8	Metal debris ,left for collection
15/03/2015 09:53	M6 S/B. 293/7	Large pot hole in lane 1 Filled pot hole under a HA RRB 2 bags of bit mac used HA log:- 206
01/05/2015 23:00	M6 N/B M/P 293/5+50	Pothole in lane 1 (unable to take photograph , unlit area)
08/05/2015 10:10	M6 NB 293/4	
04/06/2015 16:53	M6 N/B J19/20 Mp293/2	M6 N/ B 293/2 Tyre debris removed
21/06/2015 09:52	M6 NB 293/2	HGV tyre remove from hard shoulder
03/08/2015 11:10	Jct 19 roundabout	Broken gully top
18/10/2015 12:34	M6 n/b 293/5 - 293/6	Grass growing out of gully tops
25/10/2015 07:53	M6 sb 294/4+70	Pothole lane 3
19/04/2014 01:52	M6 s/b 294/8+70+80+90	3 x potholes filled
14/08/2014 11:40	M6 s/b mp 294/1	Tyre debris on hard shoulder
31/01/2015 10:43	M6 southbound 294/0 hard shoulder	Plastic debris
07/02/2015 12:53	M6 294/5 N/B H/S+Lane 1 Jct 19-20	CL1 Pothole , 1 x Bitmac Used
17/02/2015 01:56	M6 NB J19/20 (NO MP)	CL1 Pothole , M6 N/B 290/3+50. 2 x Bitmac Used
19/02/2015 14:53	M6N/B M/P 294/4	Metal debris for removal
23/02/2015 14:37	M6 n/b 294/4	HGV strap on hardshoulder
09/03/2015 12:11	M6 s/b jct 20-19 296/3 in cl1,	Areas of fretting requiring passing to uu19 on nights to fill

29/04/2015 22:35	M6 S/B 294/3	M6 S/B 294/3 2 pot holes in lane 1 Filled with 1 bag of bit mac
09/05/2015 23:52	M6 s/b 297/0-294/3 cl1	22 x potholes In various locations
06/06/2015 10:41	M6 N/B 294/9	M6 N/B 294/9 Over grown grass in central res approx 50 metres long Can't see barrier any more Requires strimming and N/B and S/B lane 3 closure
31/07/2015 10:20	M6 S/B M/P 294/6+90	Pothole lane 1
07/08/2015 07:41	M6 SB 294/2+70	Pothole vibra line sunken
07/08/2015 07:44	294/3+70 M6 SB	Pothole Vibra line
21/09/2015 11:47	M6 s/b m/p 294/5+60	Fly tipping 8-10 bags of waste
14/10/2015 08:41	M6 s/b m/p 294/8+60	Tyre on h/s
14/10/2015 08:49	M6 s/b m/p 294/7+90 in l/1 on white line	Pot hole
19/10/2015 10:03	M6 n/b 294/7	Hgv tyre
18/12/2015 10:45	M6 n/b 294/6	Cone
25/12/2015 16:58	M6 NB 294/3	
01/03/2014 14:20	M6 southbound 295/8 lane 1	Pothole in failed patch
10/03/2014 22:28	M6 s/b 295/8 lane 1 pothole	Used 1 tub
07/05/2014 21:56	M6 s/b 296/0	Lane 1 pothole .1 x bag used.
15/06/2014 15:14	M6 n/b 295/6	Metal bar on hardshoulder
15/07/2014 09:23	M6 NB J19/20 Mp295/5 - 295/8	Plastic mouldings removed
03/09/2014 13:25	M6 n/b 292/8	Remove HGV tyre
22/10/2014 12:23	m6 nb j19-20 mp 295/1 o/s	Report and mark up barrier damage
23/10/2014 11:53	m6 nb j19-20 mp	RTC damage
05/11/2014 13:29	M6 s/b 292/7	Piece of wood on hardshoulder
05/12/2014 14:41	M6n/b 300/6n/s	Wood encouching into lane 1
26/12/2014 10:09	M6 S/B 295/8	Pothole filled x1 bag instamac
14/02/2015 10:25	M6s/b 295/6	Remove car tyre debris
12/03/2015 11:29	m6 n/B 291/0 jct19-20	HGV strap to be removed under hato block
12/03/2015 11:35	M6 s/b 296/3,296/2+30,	Various potholes in cl1 to be passed to nights to fill
28/04/2015 09:51	M6 N/B 295/9	2 x damaged cones on hardshoulder
10/07/2015 10:18	M6 s/b 295/7 +30 verge	Damaged fence rail.
11/08/2015 11:47	M6 s/b 295/1+10	Cl1 pothole
08/09/2015 12:19	M6 SB 294/9+40	Pothole white line
20/09/2015 12:55	M6 n/b m/p 295/1+20	Pothole in l/1
20/09/2015 13:16	M6 s/b m/p 295/1+50	Pothole in l1-l/2
02/10/2015 10:22	M6 s/b 295/0+30	Pothole lane 1
25/10/2015 07:44	M6 sb 294/9+80	Pothole
25/10/2015 07:49	294/9 m6 sb	Pothole
06/11/2015 21:54	M6 NB J19 - 20 MP 295/2	Just a scuff no damage .
15/11/2015 20:23	M6 Northbound, MP 295/8	Road sign blown round (Enquiry 37151)
09/12/2015 09:34	M6 N/B J19-20	Sunken road surface

04/01/2016 09:25	M6 n/b 292/3+90	Lane 1 potholes in road works so will need a rolling block .no pictures due to no were to stop .
22/01/2016 10:39	M6 s/b m/p 295/9+80	Pothole in l/1
25/04/2014 13:29	M6 n/b 296/3 c/r	Rotten barrier in c/r (holes)
20/06/2014 10:29	M6 northbound 296/4	Tyre debris in hard shoulder
08/01/2015 12:21	M6 s/b at 296/5,296/3 and 296/2 in lane 1	Potholes found on patrol and require passing to uu19 (nights) to fill
09/06/2015 13:24	M6 N/B 296/0	x1 car tyre with rim on hardshoulder debris Removed
19/06/2015 14:02	296/2-40	Overgrown site line
08/12/2015 10:02	M6 n/b 296/2	Car tyre
08/12/2015 10:05	M6 n/b 296/2+20	Pot hole in lane 3
11/01/2016 08:24	M6 s/b m/p 296/2 in l/1	Pothole
23/07/2014 01:23	M6 SB link to M56 EB LC 8GR2	Length of wood on barrier for collection
27/11/2014 15:35	m6 sb lymm services split to m56 eb	No flooding at this location at present time, but we know it does flood here when there is a heavy downpour, this been reported numerous times for a permanent repair to be unde
22/08/2015 14:46	A50/M6 link to M56 opposite LC 8gr8	Pothole with road fretting and deterioration
27/09/2015 02:27	M6 SB Exit to M56 E/W Split (1st Parapet)	Pass to structure inspector
28/11/2015 20:59	M6 Jct 20 M slip from	1 gully top cleared
28/11/2015 21:15	M6 Jct 20 M slip from	.
10/12/2015 08:53	Slip from M6 SB Jct 20 Lymm services	Gully tops cleared , with assistance from a l/1 hato closure
21/12/2015 01:15	X2 potholes in SB link	Potholes
05/02/2016 09:22		
08/02/2016 03:52	M6 S/B Link to M56 E/B	Main Carriageway Defect - Report of Pothole. No lane or M/P given. (Enquiry 40173)
11/02/2016 10:22	M6 S/B link to M56 E/B	Main Carriageway Defect - Potholes on link (Enquiry 40317)
18/03/2014 02:40	M6 n/b 294.4+10 cl1	Pothole filled using 1 x bitmac
19/03/2014 01:17	M6 Southbound, MP 296/1	Dead owl removed from hardshoulder to embankment
01/12/2014 12:01	M6 S/B M/P 296/2	Polystyrene
12/03/2015 09:42	M6 n/b 295/4+60	Carriageway fretting to be filled
05/04/2015 09:42	M6 southbound lane 1	296/3-296/1 4x potholes USED 2x bags of viafix
06/05/2015 15:02	M6 Southbound, J20 - 19.	M6 S/B 298/6 RTC CAR VS HGV Car has came to rest on the hard shoulder striking the nearside barrier . Damage to the barrier :- 7 dig out posts and 8 TCB single sided Sprayed Job
04/06/2015 23:30	M6 s jct 20 acc	Litterpicking
04/06/2015 23:35	M6 s jct 20 acc	Litterpicking
19/06/2015 13:39	296/5-50	Site line over grown
07/08/2015 12:32	296/3+90 m6 NB	Broken fence rail
24/08/2015 08:48	M6 SB 296/2+90	Potholes spread over 50 metres
25/08/2015 10:58	M6SB MP 296/4B	Needs cutting back
12/04/2014 12:14	M6 SB J20/19 Mp295/2	RTC with barrier damage. Damage has occurred in same location as a previous strike
10/07/2014 00:59	M6 SB J20-19 MP 295/6 and MP 295/7	M6 S/B 295/7 and 295/6 3 tyres removed from both locations In total 6 tyres removed from verge
01/08/2014 15:25	M6s/b 295/6	Large metal box and tarpaulin removed
14/02/2015 10:36	M6 295/1	Tyre debris removed
07/05/2015 11:08	M6 SB 6959B Mp295/9	

12/05/2015 22:10	M6 Southbound, MP 296/0	Metal
26/06/2015 18:11	M6 Southbound, MP 295/9	Brush in live lane (Enquiry 32942)
10/07/2015 10:22	M6 s/b 295/0 h/s	Cone from repaired barrier damage .
20/07/2015 12:20	M6 S/B 295/0+70	CL2 Pothole
22/07/2015 08:20	295/6 + 50 M6 S/B	HGV tyre on hard shoulder (removed)
22/09/2015 14:02	M6 S/B 295/7	TM Frame (Removed D
20/10/2015 10:33	M6 S/B M/P 295/2 - 295/3	3 X gully top require cleaning
15/11/2015 20:31	M6 SB J20-19 MP 295/4	Tyre debris over approx 300 meters for routine collection (Enquiry 37148)
10/12/2015 14:19	M6 S/B 296/0 To 295/3	Blocked Gullies
24/02/2016 10:17	295/8 m6s/b	Pothole lane1
22/07/2014 08:35	M56 westbound 28/3	Plastic drum on hardouder
07/08/2014 21:33	M6 SB link to M56 WB MP 29/3 approx	Nearside barrier damage marked up with yellow spray
25/02/2015 02:15	SB link to M56 WB	Found pothole in lane1 just before slip road from a50 joins
25/02/2015 16:19	M6 s/b link to m56 w/b at LC 8GR30	Length of metal on hardshoulder
18/03/2015 02:58	N6 SB J20 Link to M56 WB - On the "bad ber	2 tubs bitmac used
03/04/2015 17:34	M56 w/b link at ETB 8277M	Road fretting, getting worse by the hour - attempted to fill with instamac x 3 bags approximately 80 metres in lane one needs resurfacing
11/05/2015 22:37	M6 N/B 297/3+80	Plaster board needs removing.
12/05/2015 06:33	M6 N/B 297/3+80	Plasterboard possibly containing asbestos (Enquiry 31351)
02/06/2015 15:46	M6 SB on the slip joining M56 WB -	Wagon Strap & Bucket (Removed)
08/08/2015 11:43	A50 to M56 EB - just after bridge pothole	Potholes
21/08/2015 03:03	M56 w/b j9 exit to m6 n/b o/s	Flirter sign requires strimming
22/08/2015 08:04	M56 EB 28/0+90	Pothole L3
17/10/2015 08:18	A50-m56 w/b	Lc 8gr29 small pothole lane 1
09/01/2016 11:59	M6 n/b link to m56 w/b lc1gv25	Damaged fence rail with live stock in the field
14/06/2014 09:51	M6 SB J20-19 MP 295/0+30	C/res barrier damage
21/06/2014 22:26	M6 SB J20-19 MP 294/9	Barrier damage C/R
25/07/2014 23:39	SB 294/3	Wooden pallet removed
14/08/2014 12:07	M6 s/b 276/0	Metal bar on hardshoulder
14/08/2014 15:10	M56 e/b 22/5	Tyre debris on hardshoulder
18/11/2014 10:14	M6 S/B 294/2	Remove damaged TM cone
13/12/2014 10:16	M6 SB Jct 19 MP 295/0+50 c/r	Central reservation barrier damage 2x socket posts 4x TCB beams Risk score 19=medium Marked with cone to nearside
13/12/2014 13:43	M6 SB Jct 19 MP 295/0+50	Central reservation barrier damage 2x socket posts 4x TCB beams Risk score 19=medium Marked with cone to nearside
15/12/2014 11:44	M6 n/ b m/ p 294/6	Car tyre removed
09/04/2015 09:25	M6 SB Mp295/0+30	C/r barrier damage 4 beams 2 posts
19/05/2015 16:40	M6 N/B 294/5+50	M6 N/B 294/5+50 Fence rail damaged on fence line Replaced fence rail with 1 rail and 6 nails
22/05/2015 02:30	M6 sb j20-19 mp 294/9	CI3 closure for RTC , barrier team requested

06/06/2015 10:36	M6 N/B 294/4	M6 N/B 294/4 Overgrown grass in the central res approx 50 metres long Can't see the central res barrier Requires strimming
10/07/2015 09:44	M6 n/b and s/b c/r junction 19 to 20 .	Overgrown vegetation in c/r and unable to see the barrier.
11/09/2015 10:04	M6 n/b 294/6+90	Car tyre
14/09/2015 15:42	m6 j20-19 mp 394/7	HGV strap
20/09/2015 13:20	M6 s/b m/p294/6+30	Pot hole on h/s rib line
30/10/2015 16:50	M6 Southbound, J20 - 19.	As reported multiple times there is ruts in the carriageway which are quite bad which could cause driver to possibly loose control,
06/01/2016 01:24	M6SB Jct 20-19	M6 S/B between junctions 20 to 19 Reports of a pot hole in this area .
17/02/2016 16:01	M6 SB J20/19 Mp294/7	Barrier Damage
15/06/2014 08:28	M56 jct 9acc from Lymm services at LC 5GR	Car wheel and tyre on offside rumble strip
18/08/2014 11:31	M56 e/b mp 29/1+70	Pothole to be passed to nights
12/07/2015 09:23	M56 w/b 27/3+10	Cl 2 potholes
05/09/2015 15:23	A50 Link To M56 E/B (Jn 20 Lymn)	12 x Blocked Gullies , (No Hardshoulder At Start Of Link) Hardshoulder Requires Sweeping
05/10/2015 11:07	M56 e/b m/p 27/5	HGV tyre
05/02/2016 09:13	M6 link to m56	Litter picking
05/02/2016 10:48	M6 m56 link from m6 SB to m56 wb	Litter
07/02/2016 08:07	M56 E/B JCT 9 Access M/P 27/7+50	1 X broken fence rail
14/06/2014 10:14	M6 SB J20 -19 MP 293/8+20	C/res barrier damage
23/06/2014 20:29	M6 s/b 293/4	Remove HGV mudguard from hardshoulder
08/07/2014 10:04	M6 SB J20 -19 MP293/9	Barrier damage (Enquiry 20454)
04/08/2014 17:11	M6 Southbound, MP 293/5	Bucket
20/08/2014 14:16		Main Paved Area (OS) Grade C
05/09/2014 13:15	M6 S/B J20-19 MP293/8	M6 S/B 293/8 Tyre debris collected from marker post
31/10/2014 09:39	M6 S/B M/P 294/7	HGV tyre for removal
05/11/2014 12:12	M6 n/b 294/1	Builders bucket on hardshoulder
12/12/2014 03:44	M6, s/b, Junc 20/19, MP 293/5	N/S barrier damage after RTC this morning (Enquiry 25229)
09/07/2015 19:44	m6 sb j20-19 mp 293/8	1 bag granules used
17/07/2015 15:55	M6 s/b 293/1	1 x fence post and 2 x rails damaged. Field is used for sheep but is empty at the moment
22/07/2015 08:40	293/3 M6 S/B to. 293/0	HGV tyre debris removed from H/S 300 mtrs
24/08/2015 23:55	M6 SB J20/19 293.4	Cracking on bridge joint will need bridge engineer to attend
20/09/2015 13:24	M6 s/b m/p 293/5+80	Pothole l/1
08/10/2015 01:45	M6SB Jct 19-20	Ruts in lane 1 signs to be put out
28/10/2015 14:59	M6 n/b m/p 293/5+30	Damaged fence rail
12/04/2014 16:00	M6 n/b 292/2+10	Pothole filled
23/06/2014 20:42	M6 n/b 292/4	Remove large builders bag from hardshoulder
17/08/2014 12:07	M6 n/b 291/9	Large wooden board on hardshoulder for removal
13/07/2015 10:37	M6 s/b 294/0-293/0	Numerous gullies need clearing
21/07/2015 11:02	M6 N/B 292/6+80	Pot hole in lane2
21/07/2015 11:05	M6 N/B 292/7+10	Pot hole in lane 1
16/08/2015 16:06	M6 n/b 298/6+80	Pothole in lane 1-2 passed to uu19
18/10/2015 08:52	M6 SB mp 292/9 verge	Strip comms boxes
18/10/2015 09:22	M6 SB mp 292/9 verge	Strim around comms boxes and access areas
18/10/2015 09:40	M6 S/B Jct 20-19 M/P 292.3	Debris removed

18/10/2015 10:30	M6 SB mp 292/5 verge	Strip around manhole access area
18/10/2015 11:38	M6 SB mp 292/2+50 verge	Strip access area for manhole cover
18/10/2015 12:08	M6 SB mp 292/1+30 verge	Strip around manhole access area
18/10/2015 14:20	M6 SB mp 292/0+40 verge	Strip and clear soil build up from around etb
18/10/2015 14:33	M6 SB mp 292/0+30 verge	Strim access area to manhole
16/11/2015 08:31	M6 Southbound, half mile marker for J19.	Fence rails require nailing back on
26/04/2014 12:29	M6 S/B J 19-20 MP 291/650	There are 2 strikes n/s and o/s . The o/s strike is 2 x TCB and 1 x post . N/s strike is 3 x obb and 5 x posts
11/05/2014 15:04	M6 NB J19-20 MP 291/2+60	C/res barrier damage
19/07/2014 10:55	M6 N/B from marker post 290/5 to. 291/7	M6 N/B from marker post 290/5 to. 291/7 Flooding Cleared 31 gullies At marker posts :- 290/8 291/1 to 291/2 blocked gullies requires a jetter to clear gullies
28/07/2014 11:07	m6 S/B M/P 291/8	Tyre debris
15/12/2014 11:35	M6 n/ b m/p 291/6	HGV mudguard removed
10/02/2015 10:31	m6 sb j20-19 mp 291/5	RTC with boundary fence damage,fence damage and RTC debris removed. 6x posts and 16 x rails damaged .
27/03/2015 11:27	M6, s/b, Junc 20/19, MP 291/2+30	Mark up barrier damage and remove damaged TM cones
28/04/2015 15:44	M6 s/b	HGV strap on hardshoulder
06/05/2015 20:25	M6 Southbound, MP 291/1	
07/05/2015 11:23	M6 SB 291/1 (site 6911B)	
26/05/2015 10:44	291/8	Strip of wood
30/05/2015 11:29	M6 n/b 291/8	Sand bar
28/06/2015 17:04	M6s/b 291/8	Tyre debris
01/07/2015 09:12	M6 s/b 290/5	HGV strap
05/07/2015 10:46	M6 N/B 290/4 + 90. To. 291/1	15 Blocked gullies
24/07/2015 08:52	M6 sb 291/2 to 290/5	X 19 gullies blocked
21/09/2015 12:00	M6 s/b m/p 291/8-291/5	Blocked gully tops
16/10/2015 10:44	M6 s/b 291/3+50	Tyre debris
18/10/2015 15:19	M6 SB mp 291/7+70 verge	Strim access steps to comms boxes
01/11/2015 10:38	M6 n/b 291/0 to 291/4	Gully tops need clearing.
02/11/2015 03:05	M6 S/B 300yd marker for J19	Large amount of wood and metal debris removed from the hard shoulder .
02/11/2015 03:09	M6 S/B 300yd marker for J19	Large amount of wood and metal Debris removed from hard shoulder.
14/04/2014 09:34	M6 S/B Jct 19 approx m/p 291.0	M6 S/B 290/8+10 and 290/8+80Central res barrier damage found from previous RTC Damage to central res :- 4 dig out posts and 8 TCB beams
31/08/2014 12:24	M6 n/b 291/0	Piece of ply wood on hardshoulder
07/02/2015 10:43	m6 sb j20-19 mp 290/7 n/s	RTC Barrier Damage M6 S/B 290/8+ 30, 8 x N/S Posts (Concrete) & 7 x N/S TCB Barrier Damage , damage Close Coned & Sprayed . RTC Debris Cleared
13/03/2015 15:57	m6 jct 20-19 290/7+60	Requested to check for barrier damage
24/06/2015 11:48	290/5 M6 N/B	Wood debris on hard shoulder removed
07/07/2015 20:09	M6 S/B approx 300 yards prior to J19	Barrier damage 3xpost 6x beams
09/07/2015 10:32	M6 northbound 291/0 lane 1	Pothole
28/07/2015 20:43	290/6	Tyre in hard shoulder
04/09/2015 15:22	M6 S/B 292/9 To 291/3	30 To 35 Blocked Gulley Tops
05/11/2015 13:28	M6 n/b m/p 290/8-291/2 on h/s	Blocked gully tops
05/11/2015 13:54	M6 s/b m/p 291/1-290/8	Blocked gully tops
10/03/2014 22:37	M6 s/b 290/3 lane 1 pothole	1 x tub used
25/04/2014 14:43	M6 s/b at 290/6 and 290/3+50	Potholes in lane1 requires passing to nights for filling

14/06/2014 11:19	M6 Southbound, MP 289/9+80	C/res barrier damage
22/08/2014 11:11	M6 Southbound, MP 290/0+10	M6 S/B 290/0.+10 Barrier damage found in central res Damage to barrier :- 1 TCB. 1 transition 2 dig out posts
15/01/2015 03:36	M6 SB J19 289.9	Ladders (Removed)
04/03/2015 03:01	M6 n/b cl1 290/4+50	2 x areas of fretting in lane 1
02/06/2015 09:55	M6 S/B 290/4	Metal And Fibreglass Debris (Removed)
04/06/2015 04:41	Jct 19 access n/b	Litter picking
02/07/2015 12:14	M6 N/B 292/2+80 lane one of main carriage	Pot holes
15/07/2015 16:17	M6 Jct 19 Southbound M/P 289.9	Barrier damage 1x box beam 1x post
08/08/2015 03:00	M6 n/b jct19 acc	Litter picking
14/09/2015 09:51	M6 southbound junction 19 exit 290/3 hard	Tyre for collection
29/04/2014 16:07	M6 SB J19 MP290/5	Removed debris
25/05/2014 10:14	M6 SB J19 MP293/+20	Marked up C/R barrier damage
30/10/2014 20:23	M6 Southbound, J19.	Take down out of date TM sign. There is no company logo on sign
09/12/2014 10:36	M6 S/B 290/0 to 289/5	Blocked gullies and risk of flooding Cleared 40 gully tops of top soil and debris
24/12/2014 11:59	SB J19 Exit 290/2	Rubber and plastic at location given for removal Joe Gunn crew member also not on system
05/11/2015 15:44	M6 s/b jct 19 top of exit slip	Gully requires filling around edges
06/11/2015 15:34	M6 S/B J19 exit	N/s barrier damage
06/11/2015 16:09	M6 S/B J19 exit	
07/06/2014 04:18	M6 Southbound, J19 Access slip.	Tyre removed
01/08/2014 23:29	M6 southbound junction 19 access	Check flooding hotspot 20x gully tops cleared
08/03/2015 03:25	A556 W/B designated lane to m6 S/B	2 large pot holes Filled pot holes with 2 bags of bit mac
13/04/2015 00:44	M6 J19-18 M/P 289/4 s/b	17 posts 80 rails and 40m sheep wire of boundary fence damage marked up .secured the fence
07/05/2015 11:39	m6 sb j19 entry slip mp289/6	
26/05/2015 12:39	M6 n/b 291/6	1 rail 6 nails used
13/06/2015 10:12	M6 S/B JCT 19 access slip offside	Old sign post leaning dangerously towards live traffic , requires cutting down with sthil saw ..
03/07/2015 11:58	M6 N/B 289/7 + 70 jct 19 bowl lane 1	Pot hole
15/07/2015 09:09	M6 jun 19 southbound entry slip	Strim around marker posts
15/07/2015 09:22	M6 sb mp 289/4 verge	Strim and clean grid tops
15/07/2015 09:48	M6 sb mp 289/2+20 verge	Strim grass and cut back vegetation obscuring sign
18/07/2015 10:10	M6 s/b jct 19 e/s at the top of slip	Pothole
18/07/2015 10:14	M6 s/b jct 19 a/s	Pot hole
27/07/2015 16:55	M6, s/b, Junc 19, MP 289/2+40	1no tcb beam
20/08/2015 10:25	M6 n/b 289/4+50-289/3+50	Approx 25 x fence posts and 60 rails require replacing. This is end of life damage to a stock field which is currently empty .
20/10/2015 08:25	M6 S/B Jct 19 access slip O/S (on chevrons)	2 X gullies require clearing , vegetation growing out of them
20/10/2015 10:05	M6 N/B Jct 19 exit (on point of chevrons)	Vegetation growing out of gully
15/11/2015 09:49	M6 southbound junction 19 access slip	Damaged fence rail.
22/10/2014 11:01	M6 n/b 289/7	Remove HGV tyre debris
19/11/2014 15:56	M6 s/b n289/5 - 285/8	Overgrown and blocked offside gully tops requiring digging out ,various locations between the 2 mp given ,requires doing on nights with a closure.
20/03/2015 12:17	M6 SB 289/8	8 posts and 6 beams damaged marked up with a cone on the n/b side due to closure on the s/b side .

04/04/2015 15:57	M6 Jct 19 R/B (manchester bound side)	Asked to check bridge parapet damage VEHICLE HAS MADE CONTACT WITH BRIDGE PARAPET IN 4 LOCATIONS CAUSING RAILS TO BEND, THIS NEEDS TO BE PASSED TO BRIDGE INSPECTOR ASAP
01/08/2014 23:39	M6 s/b 289/0 to 288/9	Gully hotspots 5 x gullys cleared.
08/04/2015 09:25	M6 S/B M/P 289/1	Tyre debris in lane 1
03/07/2015 08:18	M6 S/B. 288/9 +50	Obscured M6 road sign (large blue sign mileage information) requires strimming + small tree cutting
22/12/2015 04:38	M6 Southbound, MP 289/1.	Large pot hole in the hardshoulder in the major road works (hardshoulder running)
25/01/2016 11:04	M6 s/b 289/2-289/1 cl1	2 X potholes . These are inside long term works and will require a rolling block
29/02/2016 08:20	M6 s/b jct 19 access approx mp 289/0	Potholes inside road works no hard shoulder will need rollin block
24/06/2014 22:22	M6 S/B Jct 19-18 M/P 288.6	Removed branch
31/08/2014 11:20	M6 s/b 265/2	Tyre on hardshoulder
24/02/2015 14:48	M6 s/b 287/6	Remove HGV tyre and strap
08/05/2015 17:06	M6 lane 3, Jct19-18 S/B 289/0-284/0	Jon Lee Reports 20 blocked gullys for programming (Enquiry 31264)
12/06/2015 04:11	M6 S/B 288/6	Large pot hole n lane 1 Filled pot hole with 1 bag of bit mac
03/07/2015 08:34	M6 S/B prior to knutsford services 288/9 to	3 X knutsford services exit count down markers + services sign (requires strimming and tree cutting)
09/08/2015 10:58	M6 N/B 289/0	Car tyre for collection
30/09/2015 10:15	M6 s/b 289/9+49	Broken fence rail
30/09/2015 10:20	M6 s/b access to knutsford services	Scattered debris
06/01/2016 05:09	M6 SB 19-18 Just prior to Knutsford Services	Filled pot hole with 1 bag of bitmac
05/02/2016 11:52	m6 sb j19-18 MP288/9 C/R CL1	Road Traffic Collision - barrier damage (Enquiry 40072)
22/09/2014 11:31	M6 SB access slip from Knutsford S/A	Oil spill on H/S and S/B Exit slip used 1bag of granules on slip and two on H/S under broken down vehicle '
20/10/2014 15:40	M6 S/B under walkway from n/b to s/b at Kn	Bucket of rotten fish for removal
16/07/2015 11:40	288/3 s/b	Strim back vegetation for comms box
16/07/2015 11:57	288/2 s/b	Cut back and Strim vegation steps and comms box
01/08/2015 09:56	Knutsford serv. s/b entry	M6 sign
05/09/2015 09:35	M6 S/B Knutsford Services Access	Several Large Potholes On Hardshoulder
05/09/2015 09:51	M6 S/B Knutsford Services Access	2 x Blocked Gullies , Gulley Sucker Required
30/09/2015 11:17	M6 s/b Knutsford services exit slip	Litter needs clearing
02/10/2015 11:06	Knutsford services service road from depot t	Large pothole
20/05/2014 14:09	M6 n/b knutsford services access slip	Gully checks all ok.
16/07/2015 09:44	M6 s/b knutsford exit slip	Cut back vegation really needs doing with the strimmer blades for better finish as it is heavy brambles
16/07/2015 11:17	Knutsford exit services sign s/b	Strim vegation back
16/07/2015 11:21	288/4	Strim back vegetation
28/07/2015 16:57	M6,b. MP 288/5	Steps and comms box overgrown
20/10/2015 14:25	M6 SB J19-18 MP288/4	Barrier damage 11x post 11x beams signage damage also steps to comms box
04/07/2015 11:43	M6 S/B Knutsford Services Access (Nearside	2 x Signs
18/07/2015 10:51	M6 s/b jct 19 Sevices a/s	Pot hole on h/s
18/07/2015 12:31	M6 n/b jct 19 services e/s	Blocked gully tops
04/08/2015 08:55	M6 S/B knutsford services access	Blocked gullys requires cleaning the tops
04/09/2015 11:51	M6 S/B , 288/0+10 (Knutsford Services Acce	2 x Dead Trees
25/09/2015 08:15	M6 SB 287/9+40	Broken rail
28/11/2015 08:49	M6 S/B 288/0 to 287/9	Blocked bully's along the slip causing flooding
22/12/2015 08:54	M6 s/b knutsford services exit slip 287/9 +50	Broken fence rail plus possible fence line damage

15/02/2016 10:57	289/1 + 80 m6 s/b h/s cl1	Pothole on h/s running . Road block required for repair
28/06/2014 06:17	M6 jct 19-18 s/b 1/2 mile past knutsford ser	M6 S/B half a mile after knutsford services Strap and buckle to be collected debris NO TRACE
10/03/2015 15:43	M6 s/b 287/8 on h/s	Tyre debris removed
22/05/2015 21:49	0600M6/411 - SB Knutsford MSA entry slip	Check Litterpicking On Access Slip (4 x Additional Bags Removed , 16 Bags In Total)
24/07/2015 09:00	M6 sb 288/0	Marker post sign non visual from travel, bush needs cutting back
03/12/2015 21:46	M6, n/b, exit slip to m/way MP 277/5-277/	Clear 8 x blocked gully tops to clear flooding
11/03/2014 15:53	M6, n/b, Junc 18/19 mp 278.9	Fence damaged found at mp 278/9 (approx 6 x posts). No live stock in field but this is next to a farm.
10/07/2014 14:54	M6 SB J19-18 MP287/3	Tyre debris over 100m
10/07/2014 14:58	m6 sb j19-18 mp287/5 hs/	Collapsed gully top requires resetting
18/12/2014 13:03	M6 S/B knutsford services access slip	Flooding across h/s
24/01/2015 12:45	M6 SB J19-18 MP287/5+80	2 x Posts & 2 x DoubleSided TCB (4 x Beams)
24/01/2015 13:14	M6 SB J19-18 MP287/5+80	
16/06/2015 12:07	M6 N/B 285/0	Tyre (Removed)
22/06/2015 11:35	M6 N/B 287/3	Blown out tyre + wing and HGV bumper . Removed from hard shoulder
16/07/2015 15:16	287/5 +10	Comms box and steps strimmed
16/07/2015 15:18	287/5 +20	Services signs strimmed back
16/07/2015 15:42	287/3	Strim vegation from matrix
16/07/2015 21:13	M6S/B 287/5 + 20 To 286/5	Strim all marker post + signs . Litter pick and clean off all gullies tops , And strim round gulley tops , Finnish at M6 286/5
20/07/2015 10:57	M6 N/B 287/3+70	CL1 Pothole
26/07/2015 14:14	Rcc M6 SB 287/3	Bumper and exhaust (Enquiry 33855)
29/07/2015 09:16	M6 s/b 283/0+30	Lorry mud guard on h/s
19/08/2015 11:44	M6 n/b 286/8+10	1 x fence rail requires replacing
12/10/2015 01:52	M6 s/b 287/0 +70	Pothole lane2
12/11/2015 15:00	M6 N/B 287/3+50	Car tyre debris for collection
16/12/2015 07:58	M6 s/b 287/5+50 and 287/5+10	2 X HGV tyres and mudguards.
16/12/2015 08:01	M6 s/b 287/4 +10	HGV tyre
22/01/2016 09:50	M6 n/b m/p 287/3+40	Pothole in l/1
29/01/2016 08:53	M6 s/b 287/1	Plastic blowing around on hard shoulder.
09/02/2016 10:45	M6 n/b 287/0-288/0	Blocked gully tops
23/02/2016 08:23	M6 s/b 287/3+30	Pothole in lane 1
06/04/2014 17:24	M6 NB J18-19 MP 286/1	RTC with cen res barrier damage (Enquiry 13534)
01/09/2014 12:01	M6n/b 286/3	Remove HGV tyre
15/10/2014 05:40	m6 sb 1 mile or so from j18 in cl3	Location of pot hole :- M6 S/B marker post 280/3 in lane 3
05/11/2014 14:22	M6 n/b 286/5	HGV tyre for removal on hardshoulder
01/12/2014 14:23	M6 s/b 286/6+30	HGV tyre in c/r for night collection.
14/12/2014 12:39	M6 southbound 286/7+90 central reservatic	HGV tyre in central reservation
14/12/2014 15:52	M6 n/b 286/7+90	HGV in tyre in c/r for nights to remove.
16/04/2015 20:21	M6 SB 286/0	Fence damage stood fence up and sprayed
14/05/2015 16:08	M6 s/b 286/5-285/9 c/r	There are a number of blocked gullys in the c/r . This requires passing to the programming team as it requires a lane 3 closure
22/05/2015 19:28	M6 SB J19/18 Mp286/7	UU12 reported RTC with vehicle into CR barrier (Enquiry 31895)
01/06/2015 12:31	M6 N / B 279/2	Large pot hole in lane 3 approx 1 mtr long requested rolling block from HA
10/06/2015 16:01	M6 n/b 284/9	Large metal bolt

10/06/2015 16:18	M6 n/b 287/1	Matrix 6871a tree prior requires cutting back
19/06/2015 10:00	M6 S/B 286/8	Large pot hole in lane 1 found on patrol Pass to UU19
21/07/2015 11:56	M6 S/B 286/0 H/S	Strimming
08/08/2015 09:44	M6 S/B 286/2	HGV tyre on hardshoulder
14/08/2015 16:40	M6 n/b 277/3-288/5 various locations	Blocked gully's requiring a gully sucker
31/08/2015 08:10	M6 s/b 287/0-286/5	Numerous blocked gully tops
21/09/2015 14:01	M6 n/b m/p 286/4+50	Fence rail damaged (up embankment) marked on h/s so can be located
29/09/2015 14:30	M6 n/b m/p 286/0+90	Pot hole in l/1
18/12/2015 08:27	M6 s/b 286/0	Hgv mudguard
21/12/2015 15:55	M6 SB MP 286/0 - see attached map	Fence damage since April 15 x post approx 30 rails
10/08/2014 12:58	M6 SB J19-18 MP 285/8	Marked up barrier damage with a cone 6 posts and 12 beams damaged
01/09/2014 10:09	SB 285/7+50	Barrier damage reported and marked up
01/09/2014 10:27	M6 s/b 278/8+30	3 x potholes to be passed to nights
05/09/2014 14:22	M6 N/B 281/9 to 282/5	M6 N/B 281/9 to 282/5 HGV blow out Tyre debris and hag parts scattered between marker posts Collected debris
22/11/2014 00:35	M6 MP 285/7 SB J19-18	X 7 legs and 8 TCB of barrier damage.
31/01/2015 11:45	M6 SB Jct 19-18 MP 284/8+60	Central reservation barrier damage 3x socket posts 6x TCB beams approx Risk score 19 = medium Put cone out to nearside to mark
04/04/2015 10:55	M6 S/B Jct 19-18 m/p 285.5	Asked by NCC to check barrier Checked barrier and is marked from southbound side, asked for barrier crew to re inspect and score and assess if needs close coning or not
15/05/2015 02:15	M6 N/B	Large pot hole in lane 2 Filled pot hole with 2 bags of bit mac
15/05/2015 02:21	M6 S/B 285/9	Large pot hole in lane 2 Filled pot hole with 2 bags of bit mac
16/05/2015 04:30	M6 S/B 286/3+80	Pot hole in lane 2 Filled pot hole with 1 bag of bit mac
10/07/2015 15:56	M6 SB J19/18 Mp285/3	Tagged on verge
17/07/2015 15:12	M6 n/b 285/6+70+80	2 x potholes in cl2
21/07/2015 15:46	M6 S/B 285/8 H/S	Strimming
23/07/2015 08:18	M6 S/B 285/9	Pot hole in lane 1 on the the white line.
30/07/2015 08:12	M6 s/b 285/5 lane 1/2	Pothole
09/08/2015 10:45	M6 N/B. 285/5	HGV tyre on hardshoulder
19/08/2015 08:55	M6 SB J19-18 MP 285/2	Treat spillage on hardshoulder ,maincarriageway ok.
06/09/2015 14:18	M6 Southbound, MP 286/0+10	N/S RTC Barrier Damage ,2 x Socketed Posts & Brackets , 2 x Double Tier OBB , 1 x Rub Rail & Brackets . Damage Tagged
24/09/2015 09:18	M6 s/b 285/0+20	Table
24/09/2015 09:25	M6 s/b 285/0 to 284/7	Approx 8 gullies blocked .
02/10/2015 08:05	M6 s/b 285/3- 285/0	Numerous blocked gully tops
15/10/2015 12:02	M6 s/b m/p 285/4+ 90	Broken fence rail
25/10/2015 11:57	M6, n/b, Junc 18/19, MP 284/9	RTC van vs central res barrier damage Damage to barrier :- 6 posts and 12 beams
03/12/2015 21:10	M6 S/B J19-18 MP285/5	There are two blocked gullies at 285/6-285/5 that require a gully sucker. We also cleared 4 blocked gully tops in area

18/12/2015 08:32	M6 s/b 285/7 to 285/5	Tyre debris
27/12/2015 10:55	M6 S/B Jct19-18 M/P-285/9	Boundary fence down . We have propped it up to make safe.
23/01/2016 09:41	M6 s/b 285/9+50	Pothole in lane 3
27/01/2016 15:09	M6 SB J19/18 285/4	RTC with shed load. Overlay closure litter pick and remove debris
30/01/2016 10:55	M6 285/5 S/B	Blocked gullies
12/02/2016 10:32	M6 s/b 285/0	Blue plastic mesh
14/02/2016 08:25	M6 S/B 285/3	Flood due to blocked gullies x 6
11/07/2014 17:26	M6 SB MP284/3	Pothole in lane 1 (Enquiry 20604)
15/07/2014 10:38	M6, s.b, Junc 19/18, MP 284/3+40	Barrier damage reported and marked up with a cone
17/08/2014 08:40	M6 S/B J19-18 MP284/3-284/2	5x gullys overgrown ,vegetation removed but gully blocked and require a gully sucker to clear
18/11/2014 02:36	m6 sb j19-18 mp 284/5	POTHOLE (Enquiry 24460)
26/02/2015 13:36	M6 s/b 284/6	Car bumper and RTC debris for removal
27/02/2015 16:29	M6 S/B 284/3+50	Large pot hole in lane 1 There is 2 pot holes in this area and there is 2 large cracks across all3 lanes Filled the large pot hole at mp 284/3+50 with 6 bags of bit mac
20/05/2015 19:42	Barrier Crew M6 SB 284/8+90	CR barrier damage - marked with cone but no record for it (Enquiry 31588)
19/06/2015 10:11	M6 S/B 284/3 and 284/2+50	At marker post 284/3 the carrageway has cracked across all 3 lanes and in lane 1 the carrageway has cracked and sunk
02/07/2015 09:52	M6 S/B. 285. /3. To 284/7.	Blocked gullies
06/07/2015 08:28	M6 S/B 284/3 to 284/2	Block gullies full of silt needs gully sucker to cleanse.
09/07/2015 08:31	M6 s/b 284/3 to 284/0	Hard shoulder covered in debris and loose gravel
22/07/2015 09:24	M/6 S/B 284/4	Strimming VSM
12/08/2015 10:26	M6 n/b 280/1+50	3 x potholes cl2 an cl3
19/08/2015 10:18	M6 s/b 284/5	1 x fence rail requires replacing
06/09/2015 21:50	M6 S/B MP284/2+70	Large branches hanging in to hard shoulder NEEDS PASSING TO PLANNING TEAM TO ORGANISE ASHLEA'S TO ATTEND AND CUT TREES BACK
21/09/2015 12:17	M6 s/b m/p 284/8 approx no m/p	Bag removed on to verge
02/10/2015 10:25	M6 s/ b 285/2+90	1 x gully blocked requires a gully sucker to clear ,top cleared ,pot full with detritus
04/10/2015 09:03	M6 n/b 284/9	Comms box overgrown vegetation
26/10/2015 09:13	M6, s/b, Junc 19/18, MP 284/3	M6 S/B 284/5 2 vehicle RTC No HA damage found at scene Treated oil spillage in lanes 2 and 3 with 6 bags go granules The emergency services and HA attended .
28/10/2015 16:46	M6 S/B 284/3	Brocken fence rail
10/11/2015 15:38	M6 Jct19-18 S/B M/P-284/0 +284/1 H/S	M6 S/B MP 284/1 and 284/0 Picked up two metal bars
06/12/2015 09:19	M6 s/b 284/3 to 284/0	Needs sweeper at this location due gravel on h/s and mud
05/02/2016 08:38	M6 s/b m/p 284/0+50	HGV fuel tank
12/02/2016 17:45	M6 SB Jct 19-18 MP284/5+10	Barrier Damage - C/R barrier damage (Enquiry 40388)
12/02/2016 17:54	M6 SB Jct 19-18 MP284/4B	Barrier Damage - C/R barrier damage (Enquiry 40388)
12/03/2014 02:26	m6 sb j18-19 cl1	Pothole in lane 1 at marker post 281/1 1xTUB OF VIAFIX USED TO TEMP FILL POTHOLE
14/06/2014 11:42	M6 Southbound, MP 283/8+60	C/res barrier damage ,and RTC debris removed from nearside verge

13/07/2014 04:23	M6 SB J19-18 Mp282/8 to 282/7	M6 S/B 282/8 to 282/7 Pot holes in between the lanes of 1 and 2 Filled 6 pot holes in this area Used 9 bags of bit mac
03/12/2014 12:38	M6 S/B M/P 283/7	Plank of wood
06/12/2014 21:23	Rcc M6 SB 283/4	Glass on HS (Enquiry 25028)
10/02/2015 12:53	m6 sb j19-18 mp 283/2+60 o/s	Report and mark up barrier damage
18/02/2015 15:23	M6 Southbound, MP 283/8	4 beams tab 3 posts socketed
12/03/2015 12:05	M6 S/B M/P 283.6 Jct 19-18	Mark up barrier damage
28/03/2015 11:14	M6 Southbound, MP 283/1+30	C/res barrier damage found on safety patrol
17/07/2015 15:07	M6 n/b 283/3+50 cl2	Pothole in cl2
21/07/2015 10:35	M6 N/B 283/3+ 50	Pot home in lane 2
30/07/2015 14:45	M6 SB J19-18 MP 283/1	Gas canister for removal
17/08/2015 09:19	M6 s/b 283/2+60	Pot hole lane 3
24/09/2015 09:39	M6 s/b 283/2+50 to 282/9	Polystyrene
29/09/2015 08:31	M6 s/b 283/0	Metal
12/03/2014 12:14	M6 S/B 282/1+60	Pothole
10/04/2014 14:36	M6 s/b 282/+50	Pothole in cl1 filled
14/04/2014 02:50	M6 S/B J19-18 MP282/0	Pothole in lane 3 ,picture not taken due to poor light
19/05/2014 10:53	M6 southbound 282/8+30 (markerpost miss	Large pothole at each location for nights to complete
05/06/2014 00:23	282/5+20 lane 3	Pothole x 2
10/07/2014 01:28	M6 SB J19-18 MP 282/0	M6 S/B 282/0 Large pot hole in lane 3 Filled pot hole with 2 bags of bit mac Unable to take a photo. Due to no street lighting .
04/10/2014 10:20	M6 s/b 282/2	HGV mudguard and tyre debris removed from hard shoulder
02/01/2015 00:03	M6 n/b 282/1 cl2	2 x potholes to be filled
25/01/2015 15:08	M6 S/B Jct 19-8 MP 283/0+80	6 x Posts , 2 x OBB And 1 x TCB , R1 Barrier Damage . damage Marked With N/ S Cone
10/02/2015 13:07	M6 SB J19-18 MP283/0+30	Report and mark up barrier damage
19/02/2015 10:22	M6 S/B M/P 282/3	Plastic debris on hard shoulder
24/02/2015 15:01	M6 s/b 282/7,282/6+30,282/3+20,281/6,28	6 x potholes to be passed to nights for filling at locations M6 s/b 282/7,282/6+30,282/3+20,281/6,281/5+30,281/4+50
25/02/2015 10:58	M6 s/b at 282/5	Loose driver location sign
08/03/2015 03:24	M6 S/B Jct 19-18 H/S m/p 279.9	Broken down minibus with spillage (Enquiry 28713)
05/04/2015 10:18	M6 southbound 282/3+20 lane 3	Pothole
08/04/2015 09:36	M6 S/B M/P 283/0	Wood for removal
15/05/2015 10:43	M6 s/b 282/9	Metal debris
21/05/2015 11:14	M6 S/B 282/1	M6 S/B 282/1 Fence rail damaged Replaced the damaged rail with 1 rail ,6 nails and 6 clips
07/06/2015 15:27	M6 Northbound, MP282/2	RTC (Enquiry 32368)
12/06/2015 10:12	M6 s/b 282/7	Pot holes lanes 2 and 3
14/06/2015 01:44	M6 N/B 282/1	Large pot hole in lane 2 Filled pot hole with 2 bags of bit mac
14/06/2015 13:54	M6 s/b 282/1	Pot hole / needsfilling by nights
06/07/2015 08:45	M6 s/b 282/2 to 281/9	Potholes/cracking/deteriation on hard shoulder, will need approximately x15 bags+ of bitmac, with the distance, time needed and traffic count suggest to be done on nights

09/07/2015 08:47	M6 s/b 282/3 +20	Lane 3 pothole needs doing ASAP under a rolling block .
17/07/2015 13:09	M6 s/b 282/8+30	Pothole in cl2
22/07/2015 15:53	M6 S/B 284/5 TO 282/8	Strimming / gully cleaning 77 / litter picking
24/07/2015 09:15	M6 SB 282/8 +30	Pothole between lane 2/3
27/07/2015 22:47	M6, s/b, Junc 19/18, MP 282/2	
30/07/2015 08:47	M6 s/b 282/6+ 10	Pothole in lane 2/3
30/07/2015 08:57	M6s/b 282/0 +10	Pothole lane 2/3
16/08/2015 00:26	M6 NB 282/1	Pothole
28/08/2015 08:14	M6 s/b 282/6	Car bumper in centre res
28/08/2015 08:18	M6 s/b 282/2 to 282/0	Potholes/cracking on vibe line
31/08/2015 08:21	M6 s/b 282/6 +20	Pothole lane 2/3
02/09/2015 22:54	m6 sb j19-18 mp 282/2 c/r	X2 beams TCB double sided x 4 legs
08/09/2015 14:38	287/3 M6 s/b	Picked up from hard shoulder HGV wing
28/09/2015 09:44	M6 northbound 282/7+10 hard shoulder	Pothole
29/09/2015 18:06	M6 S/B Jct 19-18 M/P 282.2	Damaged barrier
06/10/2015 14:24	M6 n/b m/p 282/9+60	Pot hole in l/2
09/10/2015 10:18	M6 N/B 282/5	Broken glass on hardshoulder Needs sweeping up
15/10/2015 12:08	M6 s/b m/p282/8+30	Pothole in l2/3
20/10/2015 11:48	M6 SB J19-18 MP 282/7 C/R	1x post 1x beam barrier damage
02/11/2015 08:19	M6 s/b 282/4+90	Pothole lane2
04/11/2015 08:09	M6 s/b 282/6+20	Pothole lane 2/3
25/11/2015 08:56	M6 s/b m/p 282/7	Metal debris . Put on verge for removal
25/11/2015 09:00	M6 s/b m/p 282/6+60	Pothole in l/3
25/11/2015 10:54	M6 n/b m/p 282/1	Pothole in l/2
30/11/2015 14:18	M6 n/b m/p 282/1	Pothole in l/2
22/12/2015 09:06	M6 s/b 283/6 + 30 opp comms box no m/p	Pothole hole lane 2/3
05/01/2016 15:26	M6 SB J19/18 Mp282/4	Make safe boundary fence to stop sheep escaping onto carriageway
14/01/2016 09:07	M6 S/B 282/0+50 Lane 2	Pot holes
16/01/2016 12:55	M6 Jct- 19-18 M/P-282/8B	M6 S/B Between 19/18 Located sheep and put them back in to the field
02/02/2016 09:20	M6 southbound 282/2+20 h/s	Metal sign for routine collection
03/02/2016 08:25	M6 southbound 282/6+50 lane 2	Pothole
03/02/2016 08:31	M6 southbound 282/3+20 lane 3	Pothole
03/02/2016 09:37	M6 northbound 282/1 lane 2	Pothole
11/02/2016 09:54	M6 n/b m/p 282/5+80	Pothole in l/2
14/02/2016 08:34	M6 S/B 282/0+50	Pot hole lane 2
22/02/2016 08:14	M6 s/b 282/6+ 20	Pot hole 2/3
05/03/2014 08:39	M6 S/B MP281/9 - 281/8	4xpost 2x TCB beams
12/03/2014 01:37	m6 sb j19-18 mp281/5 b cl3	Pothole in lane 3 TEMP FILLED USING 4x TUBS OF VIAFIX
18/03/2014 21:23	M6 SB J19/18 Mp282/4	Car roof with windscreen and back window attached removed from hardshoulder
10/04/2014 12:29	M6 SB J19 - J18. 282/8-282/0	nights .
12/04/2014 01:04	M6 S/B MP281/5	4 x bags of ashphelt used.
12/04/2014 01:09	M6 Southbound, approx MP 281/4	4 x bags of ashphelt used.

10/07/2014 01:41	M6 SB J19-18 MP 281/1	M6 281/1 Pot holes in lane 1 Filled pot holes with 1 bag of bit mac
05/09/2014 13:44	M6 Southbound, MP 282/0	M6 S/B 282/0 Tyre debris collected from marker post
28/09/2014 21:50	SB 281/6	Removed tyre from marker post 281/6 M6 s/b
16/12/2014 08:57	M6 SB 281/3 +50m	O/S Barrier Damage (Enquiry 25431) 8x beams and 6x socket posts of damage
23/01/2015 11:34	M6 SB J19-18 MP281/3+70	M6 S/B , MP 281/3+70 , 2 x DoubleSided (4 x Beams) TCB & 2 x Socketed Posts Of R1 Barrier Damage , Damage Marked With N/S Cone
04/02/2015 22:54	M6 SB J19/18	RTC - HGV gone down the Embankment (Enquiry 27029)
02/07/2015 11:58	M6/ N/B. 281/5 to 281/8 + 50	Blocked gullies
06/07/2015 11:26	M6 NB 281/5 to 281/9	X 10 gullies need clearing of debris, silt etc
15/07/2015 08:42	M6 s/b 281/8 plus 20	Pot hole in lane 3
19/07/2015 12:28	M6 S/B 281/6	CL2 Pothole
20/07/2015 12:00	M6SB J19-18 MP 281/6	Damage to c/way , one bag of road repair used
24/07/2015 09:21	M6 SB 281/8 to 281/5	X7 Blocked gullies
24/07/2015 09:25	M6 SB 291/5+80	Pothole
29/07/2015 10:30	M6 S/B 281/2 +10	Strim grass around gully tops
03/08/2015 08:00	M6 s/b 281/5+80	Pothole lane2/3
04/08/2015 09:06	M6 S/B 281/4 to 281/3	Numerous pot holes in lane 3 and along the joint line for lanes 3 and 2
10/08/2015 12:02	M6 S/B 282/0. To. 281/9 tyre debris	Remove HGV wing + tyre debris
10/08/2015 12:12	281/6 M6 S/B	Car tyre on hard shoulder (removed)
14/08/2015 11:12	M6 n/b 281/3+10	Potholes lane lane 2/3
14/08/2015 11:15	M6 n/b 282/1+80	Pothole lane 2/3
22/08/2015 12:00	281/4+90	Pot hole on cl1 m6 n/b 281/4+90
30/08/2015 12:33	M6n/b 285/4+50	HGV tyre
10/09/2015 12:55	M6 SB 281/1+10	Pothole
18/09/2015 08:28	M6 s/b 281/9+10	Pothole lane 2
23/09/2015 08:28	M6 s/b 282/1-281/9	Large potholes on hard shoulder
16/10/2015 08:30	M6 s/b approximately 281/7	Pothole lane 2/3
19/10/2015 08:10	M6 s/b 281/3+70	3 potholes lane 2/3
28/10/2015 11:10	M6 s/b m/p 281/6+60	HGV battery cover
02/11/2015 08:29	M6 s/b 281/3+10	Pothole lane 3
23/11/2015 14:04	M6 s/b 281/8	Mudguard and tyre debris on h/s
27/11/2015 13:21	M6 S/B 281/3 +70	A number of pot holes in Lane 3 along white line .
08/12/2015 08:15	M6 s/b 281/9 to 281/6	Blocked gully's
10/12/2015 15:42	M6 N/B 281/9 To 281/3	Blocked Gullies
11/12/2015 12:18	M6 s/b 281/4	Pothole in lane 2/3
13/12/2015 11:19	M6 S/B 281/4 to 281/3 + 30	Pot holes in lane 2/3
14/12/2015 09:14	M6 S/B 281/3+70	Pot holes along whit line in lane 2/3 for approx 50 Mtrs
23/12/2015 10:55	M6 SB MP 281/8+20	Barrier damage 2x box beams 3x post
28/12/2015 10:33	M6 S\B 281/1+20	Pot hole in lane 1
03/01/2016 08:24	M6 southbound 281/1+10 lane 1	Pothole
07/01/2016 08:32	M6 s/b approximately 281/4 (under bridge)	Pothole lane 2/3
10/01/2016 13:55	M6 s/b 281/1+10 cl1	Pothole

13/01/2016 09:33	M6 S/B 281/5+30	Pot holes in lane 3
21/01/2016 08:37	M6 s/b 281/1+10	Pot hole lane1
30/01/2016 11:04	M6 S/B 281/1	Pot hole in lane 1
04/02/2016 12:41	M6 s/b m/p 281/1+20	Pothole in l/1
08/02/2016 12:27	M6 s/b 281/8+60	Broken fence rail
15/02/2016 11:19	281/1 +10 m6 s/b cl1	Pothole
23/02/2016 08:35	M6 s/b 281/1+10	Pothole in lane 1
03/05/2014 14:23	M6, s/b, Junc 19/18, MP 280/3	M6 S/B 280/3 Camping equipment debris collected from verge
27/05/2014 02:11	M6 SB J19-18 MP280/3	Filled pothole
03/06/2014 22:01	M6 Southbound, MP 280/9	Cut down and removed branches
05/08/2014 22:58	M6 Southbound, MP 280/2	2 tubs bitmac
14/08/2014 21:10	M6 SB - half a mile prior to J18 - MP 280/3	Not a pothole .40ft plus long surface corrosion in lane 3. Road surface end of life requires further inspection .at m/p 280/3 marked up with a cone due to m/p missing .
20/08/2014 16:39	M6 S/B J19/18 Mp aprox 281/1	Wind damaged tree split in two approx 10' above the ground
19/09/2014 03:26	M6, s/b, prior to Junc 18 in CL2 at MP 280/3	1bag of bitmac used.
18/10/2014 22:55	M6 SB J19/18 MP 281/1 to 280/9	Smashed polystyrene. Litter picked and removed at the request of the RCC due to high wind
04/11/2014 16:22	M6 SB J19 to J18 MP 280/3	There is a large area of carriageway erosion (approx 25m) at mp 280/3 in cl3 .
22/11/2014 15:14	M6 SB J19-18 MP280/3	Large area of carriageway surface has eroded an requires resurfacing
30/12/2014 10:14	M6 s/b 280/5	Pothole in lane 1.
13/02/2015 10:36	M6 S/B 280/5	Pot hole in lane 1 Filled pit hole with 1 bag of bit mac
14/03/2015 11:38	M6 n/b 280/2 on h/s	HGV mudguard removed
07/05/2015 10:53	M6 S/B lane 1 280/5 + 10	Large / deep pot hole in lane 1 , fill pot hole with 1 bag bit mac
07/05/2015 12:41	M6 Southbound, J19/18 MP 280/2	
27/06/2015 21:21	M6. S/B 280/6+50	Large pot hole in lane one (1 bag of bit mac used)
08/07/2015 10:11	M6 S/B 280/5+ 10	Pot hole in lane 1
20/07/2015 08:40	M6 S/B 280/5 To 280/3	Blocked Gulley Tops
29/07/2015 14:41	M6 s/b 280/5	Strimming around coms box
29/07/2015 20:45	M6 S/B 280/2 to 278/9	Strimming
30/07/2015 14:57	M6 Southbound, MP 280/9	Strap & buckle for removal
04/08/2015 09:14	M6 S/B 280/5+10	Pot hole hole in lane 1
07/08/2015 08:05	M6 SB 280/6	Pothole by cats eye between lane 1/2
07/08/2015 08:10	M6 SB 280/3	Pothole lane 1 start g to crack and sinking needs filling
08/08/2015 15:51	M6 SB J19-19 MP280/5	X1 air bed removed from barrier post
20/08/2015 10:42	M6 s/b 280/5 +30 cl1	Pothole in cl1
04/09/2015 12:13	M6 S/B 280/5+20	CL1 Pothole
07/09/2015 10:36	M6 N/B 280/2	Pot holes lane 2 / 3 start at location 280/2 for 50 mtrs requies top ups
13/09/2015 11:06	M6 s/b 280/5+20	Pothole cl1
09/10/2015 08:28	M6 S/B 280/5	Large pot hole in lane 1
14/10/2015 10:52	M6 n/b m/p 280/2+90	Pot hole in l/3
21/10/2015 11:47	M6 n/b 289/2+20-+40	Several potholes in cl2/3
01/11/2015 08:25	M6 s/b 285/0+20	Pothole in cl1
02/11/2015 08:36	M6 s/b 280/9	Tyre debris on h/s
03/11/2015 08:12	M6 s/b 280/5+30	Large pothole in lane 1

10/11/2015 16:37	M6 SB Mp280/5	Filled pit hole with 1 bag of bit mac
15/11/2015 08:11	M6 s/b 280/5+20	Pothole lane 1
30/11/2015 14:13	M6 n/b m/p 280/2+30	Pothole in l/2
08/12/2015 08:22	M6s/b 2807+80	Hgv tyre
09/12/2015 14:40	M6 S/B 281/3 To 280/8+50	Blocked Gulley Tops
12/12/2015 11:48	M6 S/B 280/6	Picked up strap from H/S
13/12/2015 12:56	M6 N/B 280/3	Pot hole in lane 2
14/12/2015 11:05	M6 N/B 280/2	Pot holes in lane 2/3 for approx 50 Mtrs
14/12/2015 11:17	M6 N/B 280/2+80	Pot hole in lane 2
13/01/2016 09:53	M6 S/B 280/5 +20	Pot hole in lane 1
19/01/2016 09:09	M6 n/b 280/2 +10 to 280/2+30	Potholes in lane 3
28/01/2016 15:19	M6 n/b m/p 280/3+30 in l/2	Pothole x2
07/02/2016 10:36	M6 M/P 280/5+20	Pothole in lane 1
08/02/2016 04:42	M6 SB J19/18 Mp280/2	Signage Issue - signage in CR leaning over. (Enquiry 40162)
09/02/2016 10:57	M6 SB MP280/8+90	Barrier Damage - C/res barrier damage (Enquiry 40241)
09/02/2016 10:57	M6 SB MP280/8+90	Barrier Damage - C/res barrier damage (Enquiry 40241)
17/02/2016 14:50	M6 S/B 280/5	Large pot hole in lane 1
22/02/2016 08:22	M6 s/b 280/5+20	Pot hole lane 1
26/03/2014 00:22	SB 280/0	1 tub used
12/04/2014 10:06	M6 SB J19/18 1.5 miles south of Knutsford S	Potholes located at 286/3+60 and 285/8+50 both in cl3 . These will need to be passed to nights .
18/04/2014 02:31	m6 sb cl3 about 2- 3 miles prior j18 mp 282/	Large pothole on line between lanes 2 and 3
01/05/2014 10:54	M6 S/B 279/9	M6 S/B 279/9 Pot hole in lane 1 Filled pot hole with 1 bag of bit mac
09/05/2014 01:36	M6 s/b 279/8+50	3 x potholes filled
27/05/2014 10:02	M6 s/b 282/8+80 to 282/5 in lanes 2/3	Carriageway fretting requires passing to nights to fill ,possibly require approx 10 bags of bitmac
05/06/2014 00:33	M6 S/B 279/9 lane 1	Pothole x 3
01/10/2014 09:55	M6 S/B M/P 279/7	Damaged TM cone
08/01/2015 12:44	M6 s/b 280/7	Green plastic container on harde shoulder for removal
11/02/2015 11:04	M6 S/B 279/5	3 large pit holes in lane 2 Contacted H.A and requested a RRB RRB l place at -: 11:15 RRB removed at:- 11:21 Used 2 bags of bitmac
21/03/2015 11:25	M6 n/b at 280/0 on h/s	HGV bumper
20/06/2015 10:54		Wood debris on hard shoulder removed
22/06/2015 11:55	M6 N/B	Metal back plate off HGV trailer (removed from hard shoulder)
27/06/2015 21:50	M6 S/B 279/6	Pot hole in lane 2 filled 1 bag of bitmac
02/07/2015 11:43	M6 N/B 279/3 to. 279/5	Numerous pot holes + extensive cracking causing uneven road service in 2 / 3
03/07/2015 09:16	M 6. S/B. 279/2 + 10	Pot hole in lane 2
08/07/2015 11:50	M6 N/B 279/7 lane 3 pot hole	Pot hole in lane 3 next to repair pach
20/07/2015 10:33	M6 N/B 279/2+90	CL3 Pothole
20/07/2015 10:38	M6 N/B 279/3+70	4 x CL3 Potholes
22/07/2015 12:31	M6 S/B 283/8	Strimming sign

27/07/2015 08:12	M6 S/B 279/7 to 279/8	4x potholes in lane 1
29/07/2015 21:28	M6 S/B 279/9	Strimming around coms box's
29/07/2015 23:11	M6 S/B 294/4	Strimmed around VMS pictures not very good at night complete on site
30/07/2015 01:30	M6 S/B 278/8	Strimmed around coms boxes pictures not very good at night on iPad
04/08/2015 10:47	M6 N/B 279/3 to 279/4	2 large pot holes n lane 3
07/08/2015 08:13	M 6 SB 279/8 +80	Potholes between L1+2
13/08/2015 08:38	M6 S/B M/P 279/1+70	Fence rail broken
14/08/2015 12:36	M6 n/n 279/4	Pothole lane 2/3
15/09/2015 11:58	M6 SB 279/9 +20	Pothole lane 2
27/10/2015 09:19	M6 S/B 279/3	Large piece of metal in lane 3 Collected debris under a HA RRB
18/11/2015 14:57	M6 S/B Jct 19-18 m/P-279/2+50	barrier damage found on safety patrol (Enquiry 37251) 1 post 1 beam in central reserve
11/12/2015 09:50	M6, s/b, MP 279/9, Junc 19/18	C/r barrier damage
16/12/2015 08:11	M6 s/b 278/9+80	Plastic
29/12/2015 09:30	M6 279/8 +50 also + 70 potholes lane 1/2	Pot holes
29/12/2015 09:40	M6 S\B 279/8 +50 lane 3	Pot hole
08/01/2016 08:20	M6 s/b 279/9+10	Pothole in lane 1
13/01/2016 09:59	M6S/B 279/5 +30	Pot hole in lane 2
17/01/2016 12:46	M6Sb Jct 19-18 MP 279/9+80	
09/02/2016 08:29	M6 s/b 279/2+30	Pothole in lane 1
14/02/2016 08:41	M6 S/B 279/5 +40	Pot hole in lane 2
14/02/2016 08:48	M6 S/B 277/1+ 90	A number of pot holes in lane 2
22/02/2016 08:29	M6 s/b 279/5+40	Pothole lane 2
23/02/2016 08:51	M6 s/b 279/9+10	Pothole in lane 1
29/03/2014 11:55	M6 n/b jct 18-19 278/2 and 280/3	Large pothole along road markings at 278/2 requires passing to nights to fill,also 280/3
19/04/2014 22:45	M6 Southbound, MP 279/0	Tyre debris for routine collection - removed
20/10/2014 11:49	M6 n/b 278/6+50 to 278/7+20	Potholes along line between lanes 2-3 require passing to uu19 nights
08/01/2015 10:02	M6 Jct 19-18 MP 278/9 - 279/8	Requested to attend a ha closure as there are lane 1 potholes that require filling, potholes filled using 1 x tub of bitmac (5 x potholes in total)
10/02/2015 13:21	m6 sb j19-18 mp 278/8	HGV strap removed
09/03/2015 12:39	M6 Southbound, MP 278/9 in lane 2	Large pothole in lane 2 requires filling ,requested hato block through ncc
16/03/2015 01:39	m6 sb j19-18 from 278/9 - 278/8+50	Filled pothole using 1x bitmac
17/03/2015 11:50	M6 SB J19-18 MP278/8	Large pot holes in lane 2
14/05/2015 11:36	M6 s/b 281/6-279/8 jct 19-18 c12/3	35 x fretting locations across two lanes. These require sending to programming team for resurface scheme work.
16/05/2015 10:01	M6 s/b	Blocked gully top
10/06/2015 15:32	M6 S/B Jct 18 m/p 278.5	Debris in c/r no trace
02/07/2015 10:09	M6 278/50	Lane 2 pot hole
02/07/2015 11:33	M6 N/B 278/6 lane two	Pot holes x 5
07/07/2015 09:10	M6 S/B 278/7	HGV mud wing and strap on hard shoulder for collection.
19/07/2015 15:14	M6 N/B 278/6 +30	3 x Potholes
19/07/2015 15:18	M6 N/B 278/8+80	2 x CL3 Potholes
20/07/2015 10:24	M6 N/B 278/3+90	2 x CL3 Potholes
22/07/2015 08:05	M6 S/B 278/1 to junction 18 exit slip	X20 gullies need tops cleaning and blocked gullies reporting for gully sucker
23/07/2015 08:39	M6 S/B 278/5 to 278/0	10 gully tops require cleaning .

24/07/2015 10:11	M6 southbound 282/2	Strim gullies, marker posts, signs, comms boxes and etbs Litter pick strimmed areas and clear gully tops
30/07/2015 10:12	278/9	VMS
30/07/2015 10:29	M6 n/b 278/5+90	Pothole lane2/3
30/07/2015 10:51	278/3	Coms
30/07/2015 13:38	278/3	Coms
03/08/2015 16:16	M6 Southbound, (app 278/9 to 278/7)	Fence is damaged
13/08/2015 15:42	M6 S/B J18 bowl MP 276/8+40 c/r	3x OBB beams, 1x adjuster beam and 5x socket posts Risk score =19 medium Marked on the nearside
29/08/2015 03:06	M6 Southbound, MP 278/2	Out of date to sign (chevron) dropped on to verge. Requires chevron TM to remove from site
09/10/2015 10:34	m6 j18 both sides of bridge	Graffiti on both sides of the bridge (railways) s/b andn/b
13/10/2015 09:09	M6 s/b m/p 278/9	Hgv strap +tyre debris
23/10/2015 12:04	M6 n/b 278/0+60	1 X fence rail requires replacing
06/11/2015 08:16	M6 s/b m/p 278/0+50 -277/8 on n/s	Blocked gully tops
08/11/2015 12:24	M6 S/B 278/8+50	3 pot holes in lane 1 and 1 large pot hole in lane 2
18/11/2015 08:15	278/8+30	Large pothole in lane 1
20/11/2015 14:48	M6 s/b 278/8+10	Pothole lane 1
26/11/2015 12:56	M6 S/B 278/8+30	Pot holes in lane 1 and 2
05/12/2015 15:48	M6 SB J19-18 MP 278/1	Removed
15/12/2015 13:20	M6 S/B 278/8+50	Pot hole in lane 1 and 2
20/12/2015 11:31	M6 s/b 278/3+80	Pothole in lane 2
22/12/2015 17:22	M6 SB J19-18 MP 278/9	Large metal lock for collection
23/12/2015 08:48	M6 s/b 278/8+30	Large pothole in lane 1
08/01/2016 08:26	M6 s/b 278/8+30	2 potholes in lane 1
21/01/2016 08:44	M6s/b 278/7+70	Pot hole lane2
21/01/2016 08:50	M6s/b 278/0 +50	Pot hole lane2
29/01/2016 09:09	M6 s/b 278/9	Pothole in lane 1
25/07/2014 03:03	M6 S/B Jct 19-18 m/p 277.8 L1	2 x potholes (fretting) in lane1 of jct 18 exit slip at 277/4
29/07/2014 15:30	Southbound M6 just above Junction 18 on l	1 rail 6 nails used
10/11/2014 10:42	M6 SB 2 to 1 miles Prior to J18 (mapped as	280/3- this has been reported on numerous occasions,
01/01/2015 23:02	M6 s/b 278/0+40	Pothole in cl2 to be filled
09/03/2015 13:04	M6 s/b 18-17	Locations are at 278/8+50 in cl2, 278/8+20 cl1, 278/7+80 x2 in cl2, and 278/0+40 in cl2
07/07/2015 09:16	M6 S/B 277/5+40 prior to junction 18	Pot hole in lane 1 (on the loops)
07/07/2015 09:21	M6 S/B 277/4+90	Large pot hole on hard shoulder at the bottom of junction 18 exit slip
21/07/2015 08:50	M6 S/B from junction 19 to 18	Numerous blocked gullies Requires an IPV , job is too big for an MRT crew
30/07/2015 15:09	277/9	Coms
30/07/2015 23:39	M6 S/B 277/6	Strimming around coms boxes
30/07/2015 22:16	M6 S/B 277/8 TO 276/8	Strimming / litter picking
01/08/2015 10:36	J18exit	Blocked side entry gullies
01/08/2015 10:44	Dane bridge deck	Pothole
09/09/2015 08:34	M6 S/B 277/6	100mtr count down marker missing (no post or sign found in verge)
09/09/2015 08:41	M6 S/B 277/5 + 50	Lane one pot holes x2

29/09/2015 12:40	M6 s/b m/p 277/8 n/s	Fence damage 1rail
14/10/2015 09:07	M6 s/b m/p 278/0 approx 200mtrs on h/s	Have tyre debris , mudguard
16/11/2015 08:13	M6 southbound 277/8 to 277/5	Blocked gully tops
11/12/2015 12:27	M6 s/b 277/8 +80	Tyre on hard shoulder
11/02/2016 08:23	M6 s/b m/p 277/5+50	Pothole in l/1
11/02/2016 11:19	M6 SB 277/5+70	Main Carriageway Defect - Potholes in lane 1 (Enquiry 40326)
15/12/2014 10:49	M6 s/b m/ p 277/2	HGV mudguard removed
15/01/2015 04:16	SB J18 exit slip 277/2	2 x barrier strikjes from earlier RTC marked up and risk score done
14/02/2015 14:00	Uu12M6 SB 277/2	Pothole in lane 2 (Enquiry 27734)
25/02/2015 11:22	M6 s/b 277/4+50 to 277/4+70 jct 18 exit slip	4 x areas of fretting on slip road between lanes 1-2
15/04/2015 05:19	m6 sb j18	RTC - HGV struck bridge , damage to bridge and C/R barrier
07/05/2015 11:59	M6 S.B Jct 19-18 m/p 277.1	
09/05/2015 11:19	M6 n/b 277/5 on the h/s	Plastic debris x2
14/05/2015 12:03	M6 s/b 277/2 jct 18 bowl	Remove wood and plastic debris from hard shoulder
27/05/2015 23:01	Junction 18 over bridge	All site lines cleared, strimmed, litter picked x 10 bags
04/07/2015 12:16	M6 S/B Jn18 Exit , Bottom of Slip Nearside)	1 x Blocked Gulley
04/07/2015 15:05	M6 N/B Jn 18 Access (Nearside)	4 x Gulley Tops Require Clearing
06/07/2015 09:14	M6 sb 277/2 + 50 -	From bullnose of the jct 18 bowl through to end of bowl all gullies need clearing x 20
09/07/2015 09:07	M6 southbound 277/2 lane 2	Potholes in lane 2 need refilling
17/07/2015 13:20	M6 s/b 277/0+40 cl2 and 277/1+10	Several potholes in cl2
18/07/2015 11:04	M6 s/b jct 18 e/s	Pothole in l/1
20/07/2015 08:51	M6 S/B 277/2 To 276//7	Blocked Gulley Tops x 8
20/07/2015 10:16	M6 N/B 276/7 To 277/1 , Jn 18 Bowl	Blocked Gulley Tops
31/07/2015 00:14	M6 S/B 277/1	Strimmed VMS
08/08/2015 09:16	M6 SB jct 18 277/4+90	Potholes h/s and Lane 1
31/08/2015 08:30	M6 s/b jct 18 bowl	Blocked gullys
28/09/2015 08:50	M6 southbound 277/1 under barrier	Builders bag
28/09/2015 09:31	M6 northbound 277/2 c/r	Metal ramp
13/10/2015 09:18	M6 s/b m/p 277/2+40	Pot hole in l/1 - h/s
30/10/2015 08:21	M6 s/b m/p 277/ 2-277/0	Blocked gully tops
24/11/2015 09:08	M6 s/b m/p 277/2-276/8	Blocked gully tops
04/12/2015 10:15	M6 SB J18 277.2	2x beams 1x post
14/12/2015 09:32	Jct 18 exit slip M6 SB	Pot holes
15/12/2015 13:33	M6 S/B 277/0+30	Pot holes in lane 1
29/12/2015 09:49	M6S/B 277/5+40 Lane 1	Pot hole
04/01/2016 08:10	M6 s/b 277/2 +10	Cl2 potholes
14/01/2016 09:30	M6 277/0+40 S/B Lane 2	Pot holes
29/01/2016 09:17	M6 s/b 277/0	Pothole in lane 3
24/02/2016 08:31	M6s/b 277/2	Pothole in lane 2
18/04/2014 23:54	M6 SB J19-18 MP 277/6	100m countdown marker with diversion sign attached knocked down in RTC . This is to big to be removed by MRT and will require larger vehicle .
10/08/2014 02:44	M6 SB J18 Exit Slip	Requested to check carriageway for damage and remove 4 x small yellow bags of debris and area of approx 3m x 2m requires inspection for possible repair
29/09/2014 14:58	M6 SB J18 EXIT	3 x 2 paving flag for replacement
20/03/2015 19:16	M6 Jct 18 S/B Exit slip approx 1/2 way down	Possible blocked gulleys/drainage (Enquiry 27320)
16/05/2015 04:47	M6 S/B277/5 bottom of jct 18 exit slip	Numerous pot holes filled with 1 bag of bit mac

16/05/2015 05:03	M6 S/B 277/3	2 pot holes filled with 1 bags of bit mac
04/07/2015 12:19	M6 S/B Jn 18 Exit , CL1	3 x Potholes
22/07/2015 08:16	M6 SB jct 18 exit (bridge over river)	Drainage full with vegetation, needs sweeping and cleaning.
22/07/2015 08:22	M6 SB 277/0 + 60	X2 potholes
30/07/2015 23:57	M6 S/B JCT 18 EXIT SLIP	Strimmed around A54 sign
		Strimmed around man hole
31/07/2015 00:09	M6 S/B 277/2	Pictures not very good on iPad at night
19/11/2015 22:48	M6 NB and SB 277/4	
09/12/2015 14:54	M6 S/B 278/5 To 277/4+80	Blocked Gulley Tops
29/12/2015 01:21	M6 s/b jct 18 exit	Litterpicking
02/01/2016 10:03	M6 s/b jct 18 e/s	Blocked gully tops
23/01/2016 09:54	M6 s/b 277/4+80	2 potholes in lane 1
13/02/2016 11:27	Jn18 Exit Slip , M6 S\B , 277/1	TM Cone & Metal Debris
20/02/2016 09:12	M6 s/b jct 18 exit slip	Blocked gully tops