



INSPECTION							MAKE SAFE / REPAIR		
DATE: 04/01/2018		INSPECTORS:			ROUTE: ARO2		CREW NAMES:		
VEHICLE:		START TIME: 08:00		FINISH TIME: 13:30					
ROAD	LINK & SECTION	CW	LANE	MP	LOCATION / DEFECT	ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF	
A120	1500A120/151	WB	1	1642	Pothole RWT Prior Horseley Cross Roundabout	Bumpy Road sign at MP 1646 WB			
A120	1500A120/151	WB	1	1642+10	Pothole RWT Prior Horseley Cross Roundabout	Bumpy Road Sign at MP 1646 WB			
A120	1500A120/151	WB	1	1642+20	Pothole RWT Prior Horseley Cross Roundabout	Bumpy Road Sign at MP 1646 WB			

DATE:18/01/18		INSPECTORS: [REDACTED]			ROUTE: AR02	
VEHICLE: [REDACTED]		START TIME: 08:00		FINISH TIME: 12:30pm		ACTION TAKEN
ROAD	LINK & SECTION	C/WAY	LANE	MP	LOCATION / DEFECT	






1

2

3

DATE:25/01/18		INSPECTORS			ROUTE: AR02	
VEHICLE:		START TIME: 10:30		FINISH TIME: 15:30		
ROAD	LINK & SECTION	C/WAY	LANE	MP	LOCATION / DEFECT	ACTION TAKEN
A120	1500A120/151	WB	1	1642	Pothole, LWT, Horseley Cross	





INSPECTION**MAKE SAFE / REPAIR**

DATE: 08/02/2018

INSPECTORS:

ROUTE: AR02 Main & Slips

CREW NAMES:

VEHICLE:

START TIME: 07.30

FINISH TIME: 13.30


ROAD LINK & SECTION CW LANE MP


LOCATION / DEFECT

ON-SITE ACTION TAKEN & MATERIALS USED

TIME ON

TIME OFF





A120	None	e/b	1	1701	Wix LWT Pothole						
			1								

