

Event Date	Event Ref	Status	Road Number	Direction	Chart Section	Marker Post	Category	Additional Information
Nov 24, 2017 4:40 AM	<a href="#">10089427</a>	CLOSED	A13	A	Main Carriageway	101/8	Carriageway or Footway	Pothole in Lane 2 - 300mm x 300mm
Sep 25, 2017 11:44 AM	<a href="#">10087522</a>	CLOSED	A13	B	Main Carriageway	102/5	Carriageway or Footway	Uneven road surface
Jul 9, 2017 11:14 AM	<a href="#">10085436</a>	CLOSED	A13	B	Main Carriageway	101/2	Carriageway or Footway	Pothole in Lane 1 - 500mm x 500mm
May 26, 2017 10:54 AM	<a href="#">10084546</a>	CLOSED	A13	A	Main Carriageway	102/1	Carriageway or Footway	Pothole in Lane 1 - 500mm x 500mm
Mar 17, 2017 11:23 AM	<a href="#">10083180</a>	CLOSED	A13	A	Main Carriageway	101/2	Carriageway or Footway	2 No. potholes in Lane 1 - 400mm x 400mm, 500mm x 400mm
Feb 10, 2017 12:18 PM	<a href="#">10082228</a>	CLOSED	A13	A	Main Carriageway	101/9	Carriageway or Footway	Pothole in Lane 1 - 300mm x 150mm
Feb 10, 2017 12:16 PM	<a href="#">10082227</a>	CLOSED	A13	B	Main Carriageway	101/5	Carriageway or Footway	Pothole in Lane 1 - 300mm x 150mm
Jan 8, 2017 4:50 AM	<a href="#">10081446</a>	CLOSED	A13	A	Main Carriageway	101/2	Carriageway or Footway	Pothole in Lane 1 - 400mm x 300mm
Jun 10, 2016 1:32 PM	<a href="#">10076726</a>	CLOSED	A13	A	Main Carriageway	102/0	Carriageway or Footway	Pothole in Lane 1 - 300mm x 300mm
Jun 1, 2016 9:58 AM	<a href="#">10076498</a>	CLOSED	A13	A	Main Carriageway	102/0	Carriageway or Footway	Surface delamination - loss of aggregate
May 18, 2016 11:36 AM	<a href="#">10076169</a>	CLOSED	A13	B	Main Carriageway	102/2	Carriageway or Footway	Pothole in Lane 1 - 200mm x 200mm