

Refusal of MOT test certificate

① Vehicle identification number

QQIDAAAAAAAA058568

②a) Registration number ②b) Country of registration

FE51OFA

GB

Make and model

DAF LF180

⑤ Vehicle category

N3

④ Odometer

73,341 miles



Driver & Vehicle
Standards
Agency

⑦ Fail

⑥ Do not drive until repaired (dangerous defects)



- Exhaust emits excessive smoke to an extent likely to obscure vision

⑥ Repair immediately (major defects)

- Engine MIL illuminated indicating a malfunction
- Clutch pedal anti-slip provision ineffective

⑥ Repair as soon as possible (minor defects)

- Required mirror with minor damage that does not obviously interfere with the view to the rear, nearside or front

③b) Date of the test

12.10.2017

③a) Location of the test

P12345, TransportMechs ATF, Lowdown Road, Anytown, AT1 1JP

⑨ Testing organisation and inspector

DVSA

A TESTER

Test number

180681400

For a retest, you must get the defects fixed and arrange to take the vehicle to a authorised testing facility within 14 working days of the date of this test, and pay the appropriate payment.

Further information can be found at www.gov.uk/getting-an-MOT

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 123 9000

Find out about the vehicle's MOT history at www.gov.uk/check-mot-history

Issuer's signature
