

Air Quality and Dust Monitoring Monthly Report – August 2019

London Borough of Hillingdon



SKANSKA



Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by Costain Skanska on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2019, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v2.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-government-licence/version/2 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Printed in Great Britain on paper containing at least 75% recycled fibre.

Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Hillingdon (LBH) during July 2019 and August 2019 respectively.
- 1.1.2 Figure 1 to Figure 4 in Appendix A indicate the current worksites, together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current phase of works commenced within the LBH during May 2018 and are expected to be completed by November 2019. The current worksites, as presented in Appendix A, Figure 1, include:
- 18' and 48' gas pipeline diversions, advanced planting and habitat creation, worksite ref. S002-WS05;
 - Merck Sharpe Dohme (MSD), demolition works and new access road construction, completed worksite ref. S002-WS03;
 - Utility diversions at Breakspear Road South; work sites ref. S002-WS07 and S002-WS08;
 - Utility diversions at Copthall North, worksite ref. S002-WS06 and South, worksite ref. S002-WS04; and
 - Haul Road construction and site compound and vegetation clearance at West Ruislip Golf Course site, worksite ref. S002-WS09.
- 1.1.5 Two (2) dust monitors were installed around worksite S002-WS03, where site establishment works are underway. This site returned a high dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1 together with line charts of monthly data from each dust monitor. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level of 190 µg/m³, over a 1-hour period, in accordance with the updated guidance document 'Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – October 2018' has been applied.
- 1.1.8 There were no (0) dust trigger alerts recorded during this monitoring period (August 2019).


- 1.1.9 Data capture for AQ033 and AQ034 were below 90% for the month of August 2019. Further to the recent completion of demolition works on the MSD site and following the completion of a further dust risk assessment (resulting in a classification of low risk during the current cease in works) the monitors were temporarily removed. These monitors will be reinstated prior to the commencement of any medium or high risk activities.
- 1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO₂) was undertaken at eleven (11) locations in July 2019, around highways within the LBH as part of the management of air quality where significant effects may occur as a result of the scheme.
- 1.1.11 Diffusion tube monitoring results are provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.12 NO₂ monitoring locations and results are presented in Appendix C, Table 2, together with the 2019 running mean.
- 1.1.13 Table 1 provides a summary of the complaint information related to dust or air quality received during the reporting period (August 2019), together with the findings of any related investigations.

Table 1: Summary of complaints received during August 2019 in LBH

Complaint Reference No.	Worksite Reference	Description of complaint	Results of investigation
HS2-19-07606-C	S002-WS03	A complaint was received on in relation to dust from dried construction mud on the road.	A response email was sent detailing the measures that the project undertaking to minimise its impact of dust. An on-site review of dust suppression techniques is being undertaken to ensure appropriate mitigation is in place.

Appendix A – Worksites and Monitoring Locations

Figure 1 to Figure 4: Worksites and monitoring locations within the LBH




- Legend**
- Route in tunnel
 - Route on surface
 - Dust monitoring location
 - Diffusion tube monitoring location
 - Trunk Main Diversion Route
 - West Ruislip Golf Course
 - Copthall North worksite
 - Copthall South worksite
 - 18' and 48' gas pipeline diversions
 - Merck Sharpe Dhome worksite
 - Utility Diversion worksite north
 - Utility Diversion worksite south

Figure Number	
Figure Name	Worksites and Monitoring locations in LBH (sheet 1)
London Borough of Hillingdon	

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Scale at A3: 10,000

© Crown copyright and database rights 2016. Ordnance Survey Licence Number 100049190.
 Map Number: 1EW02-CSJ-EV-REP-S000-000017_appA_fig1.pdf Date: 09/04/19




- Legend**
- Route in tunnel
 - Route on surface
 - Diffusion tube monitoring location

Figure Number
Figure Name Worksites and Monitoring locations in LBH (sheet 2)
London Borough of Hillingdon

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Scale at A3: 10,000

© Crown copyright and database rights 2016.
Ordnance Survey Licence Number 100049190.
Map Number: 1EW02-CSJ-EV-REP-S000-000017_appA_fig1.pdf **Date: 13/07/18**



Legend

- Route in tunnel
- Route on surface
- Diffusion tube monitoring location

Figure Number


Figure Name
Worksites and Monitoring locations in LBH (sheet 3)

London Borough of Hillingdon

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Scale at A3: 10,000

© Crown copyright and database rights 2016.
 Ordnance Survey Licence Number 100049190.
 Map Number: 1EW02-CSJ-EV-REP-S000-000017_appA_fig1.pdf **Date: 12/07/18**



- Legend**
-  Route in tunnel
 -  Route on surface
 -  Diffusion tube monitoring location

Figure Number
Figure Name Worksites and Monitoring locations in LBH (sheet 4)
London Borough of Hillingdon



HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.



Scale at A3: 10,000




Appendix B – Dust Monitoring Results

Table 1: Dust monitoring locations and July 2019 Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (µg/m ³)	Minimum 1-hour PM ₁₀ concentration (µg/m ³)	Maximum 1-hour PM ₁₀ concentration (µg/m ³)	Number of 1-hour periods exceeding trigger level of 190 µg/m ³	Data capture (%)
AQ033	507045, 187352	Merck Sharp Dohme, Building 24	H	Yes	N	9.9	2.8	33.8	0	40.3
AQ034	506832, 187425	Merck Sharpe Dohme Building 43	H	Yes	N	4.4	1.4	11.1	0	40.5

Figure 1: Construction dust 1-hour mean indicative PM₁₀ concentration for dust monitors



Appendix C – Air Quality Monitoring Results

Table 2: NO₂ monitoring locations around highways, NO₂ concentrations and monthly monitoring results with running mean for 2019 (µg/m³)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BNT	Lamp post on Pembroke Road	509678, 187214	34	41	28	26	20	23	17						27
HS2-000020BNU	Cowley Road sign post at junction with Hillingdon Road	505492, 183926	47	49	41	38	39	43	36						42
HS2-000020BNV	High Street sign post at junction with Pembroke Road	509439, 187117	46	47	38	45	27	39	34						40
HS2-000020BNW	Signpost on A4020 Uxbridge Road at junction with Long Lane	507365, 182687	54	47	41	50	38	41	36						44
HS2-000020BPK	Lamp post in crescent off Swakeleys Road	506542, 186037	45	48	39	31	33	28	34						37
HS2-000020BPL	Warren Road sign post on corner of Swakeleys Road and Warren Road	506240, 185660	43	61	Tube missing	30	37	36	38						41
HS2-000020BPN	Lamp post on B467	506767, 186224	39	No data	36	31	32	28	26						32
HS2-000020BQH	Lamp post on High Road Ickenham	508451, 186879	51	49	42	38	35	31	35						40
HS2-000020BQN	Lamp post on Park Road	506176, 185444	45	54	54	52	40	48	41						48

¹ Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹
HS2-000020BQP	Sign post on Long Lane	507614, 184663	43	47	43	48	38	45	38						43
HS2-000020BP8	Triplicate site at South Ruislip roadside automatic monitoring station	510858, 184916	46	44	34	36	29	37	Tubes missing						38