

Claim ref	Date	Route	Location	Description
RC 1941	02/09/2015	M25	M25 Jct 7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1945	09/09/2016	M25	M25 Jct 15	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1935	06/10/2016	M25	M25 Jct 10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1943	17/10/2016	M4	M4 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1951	24/10/2016	M25	M25 Jct 9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2021	09/11/2016	M4	M4 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1965	13/11/2016	M4	M4 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1975	20/11/2016	M25	M25 Jct 5/3	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1983	22/11/2016	M4	M4 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1981	22/11/2016	M4	M4 Jct 5-4 B	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 1996	04/12/2016	M25	M25 Jct 11	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2010	12/12/2016	M4	M4 Jct 5/4	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2014	21/12/2016	M25	M25 Jct 13	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2045	24/12/2016	M25	M25 Jct 13	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2055	31/12/2016	M25	M25 Jct 10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2050	15/01/2017	M4	M4 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2041	16/01/2017	M25	M25 Jct 12	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2042	16/01/2017	M25	M25 Jct 12	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2052	20/01/2017	M25	M25 Jct 6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2105	24/01/2017	M25	M25 Jct 7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2076	26/01/2017	M25	M25 Jct 10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2085	26/01/2017	M25	M25 Jct 9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2066	02/02/2017	M25	M25 Jct 12	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2089	20/02/2017	M25	M25 Jct 7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2086	23/02/2017	M25	M25 Jct 14	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2128	03/03/2017	M25	M25 Jct 9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2108	04/03/2017	M25	M25 Jct 9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2113	05/03/2017	M25	M25 Jct 8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2130	16/03/2017	M25	M25 Jct 14	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2153	27/03/2017	M25	M25 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2142	05/04/2017	M4	M4 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2190	03/06/2017	M25	M25 J 13	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2198	01/07/2017	M25	M25 5/6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2206	20/07/2017	M25	M25 J13/14	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2208	22/07/2017	M25	M25 j9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2247	30/07/2017	M25	M25 Jct 9-8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2233	09/08/2017	M4	M4 J5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2276	22/09/2017	M25	M25 J11	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2290	28/09/2017	M25	M25B just after Clackett Lane services	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2302	27/10/2017	M25	M25A middle land just before J10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2329	25/11/2017	M25	M25A Lane 1 MP 75/1A	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2359	13/12/2017	M25	M25B MP88/6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2429	05/01/2018	M25	M25 Jct 6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2446	21/01/2018	M25	M25 Jct 10-9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2451	01/02/2018	M25	M25 Jct 7-8 near Roe bridge railway bridge	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2821	01/02/2018	M4	M4 slip road as it joins the M25 southbound	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2487	27/02/2018	M25	M25 J8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2517	13/03/2018	M25	M25B between J14-13 Lane 3	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2583	15/03/2018	M25	M25 Jct 10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2542	19/03/2018	M25	M25 Jct 8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2591	21/03/2018	M25	M25 Jct 10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2585	23/03/2018	M25	M25 Jct 10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2719	28/03/2018	M25	M25 J8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2665	11/04/2018	M25	M25A between J5-J6 Lane 2	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2733	24/04/2018	M25	M25 Jct 8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2703	25/04/2018	M25	M25B between J14-13 lane 4	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2726	05/05/2018	M25	M25 Jct 7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2721	06/05/2018	M25	M25A J8	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2723	08/05/2018	M25	M25 Jct 7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2757	17/05/2018	M25	M25 79/2 B	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2782	17/05/2018	M25	M25 Jct 11	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2746	17/05/2018	M25	M25 Jct 11	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2759	30/05/2018	M25	M25 Jct 5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2788	01/06/2018	M25	M25 A3 Jct 10 slip	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3010	15/08/2018	M25	M25A between J8-J9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2840	29/08/2018	M25	M25 Jct 8-9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2850	31/08/2018	M25	M25 close to J7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2851	02/09/2018	M25	M25 just before Cobham services	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2846	08/09/2018	M25	M25A between J9-11 lane 3	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2861	08/09/2018	M25	M25B between J12-9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2853	19/09/2018	M25	M25 Jct 8-9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2856	21/09/2018	M25	M25 Jct 7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2855	23/09/2018	M25	M25 Jct 1 just before tunnel	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2880	08/10/2018	M25	M25A towards the M3	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2889	28/10/2018	M25	M25B between J10-9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2917	12/11/2018	M25	M25A between J6-J5	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2938	21/11/2018	M25	M25B between J9 and J10	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2940	23/11/2018	M25	M25B approaching Cobham Services L3	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2944	30/11/2018	M25	M25A between J9-J10 Lane 2	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2952	08/12/2018	M25	M25B between J12-J11 Lane 1	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC2967	17/12/2018	M25	M25A between J10-J11	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC 2525	24/12/2018	M25	M25B westbound to M40	Claimant alleges that they collided with a pothole resulting in vehicle damage

RC2998	31/12/2018	M25	M25A between J8-9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3016	22/01/2019	M25	M25A 1/2 mile before Cobham Services	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3031	27/01/2019	M25	M25 close to Juntion 11	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3053	04/02/2019	M25	M25B between J19-J18	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3082	08/02/2019	M25	M25A between J5-J6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3074	10/02/2019	M25	M25A between J9-J10 MP67/3	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3114	11/03/2019	M25	M25 J10/9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3103	11/03/2019	M25	M25B between J10-J9 Lane 1	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3138	11/03/2019	M25	M25B MP 70/6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3160	11/03/2019	M25	M25B MP 70/6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3118	18/03/2019	M25	M25 J6 exit slip	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3143	30/03/2019	M25	M25B between J8-J7	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3141	05/04/2019	M4	M4 at J4B/M25 slip	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3136	06/04/2019	M25	M25A midway between J9 and Cobham Services	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3153	26/04/2019	M25	M25A J6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3349	02/10/2019	M25	M25A J6	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3268	18/10/2019	M25	M25B between J13-J12 before M3 slip	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3284	25/10/2019	M25	M25B Lane 1 between J10 and Cobham Services	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3280	07/11/2019	M25	M25A exit slip to the M4	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3345	10/12/2019	M25	M25A J9	Claimant alleges that they collided with a pothole resulting in vehicle damage
RC3330	13/12/2019	M4	M4 Eastbound J5	Claimant alleges that they collided with a pothole resulting in vehicle damage