

ControlWorks Print - 672-200118**Primary Details**

Title	RTC
Description	OFF DUTY HATO 8125 - SEEN A CAR SOIN OUT AND HIT CENTRAL RES
Caller's Number	
Contact Origin	TRAFFIC OFFICER ROUTINE
Address-Location	P88/2A, J8A/9, AREA30, M40, THAM, XX999XX
Address-X	461801.0
Address-Y	213365.0
Address-URN	97004
Zone	0006 HERCC
Type	TC - TRAFFIC COLLISION
Grade	I - Immediate
Status	CL - Closed
Carriageway Status	Clear
Lead Organisation	Highways
Created	20/01/2018 13:39
Occurred From	20/01/2018 13:39
Occurred To	
Scheduled	
Control Groups	ESP
Access Classifications	Nothing to display

Closure Details

Is Closed	Yes
Closure Summary	
Closure Codes	TC - TRAFFIC COLLISION
Qualifier Codes	L13 - ROLLING CLOSURE SS1 - SIGNAL / SIGN SETTING V03 - CAR
Officer In Case	
Alarm Resolution	

Originator

Surname [REDACTED]
Forenames [REDACTED]
Date of Birth [REDACTED]
Contact Number [REDACTED]
Address [REDACTED]
Comments
Involvement
PNC ID
RMS ID
RMS URN

Linked People

Nothing to display

Linked Vehicles

RO08LVP

VRM [REDACTED]
VRM Match Status Untried VRM lookup
Details Confirmed
Involvement
Type
Colour SILVER/GREY
Make ALDI
Model A3
Variant
VIN / Chassis No.
Gear Type
Fuel Type
Drive Type
Max Authorised Mass (MAM)
MAM Classification
Marks
Comments
Safety Advice Given?
Recovery Status
VRT ID

Confidential

Location Along Road
Location in Road
If in a SMART motorway section, which type is it?
Additional Positioning Detail
Relative Location
CCTV Camera
Planned Arrangement
Recovery Organisation
Membership Details
Recovery Response
Recovery Reference
Driver Surname
Driver Forename
Driver Phone Number
Number of Persons
Particular Needs
Fault/Symptoms
Problem Detail
Upright
Substantially Damaged
Spare Usable
Wheels Free Rolling
Keys with Vehicle
Vehicle Locked
Towing
Towing Detail
Trailer Unit Detail
State of Load
Load Detail
Load Type
Hazchem Number
UN Number
Hazchem Breached
Haulier Name
Haulier Phone Number
unlabelled, hidden

Confidential

False

Additional Forms

Nothing to display

Parent/Child Events

Nothing to display


Other Linked Events

Incident 688-200118
Date/Time 20/01/2018 13:57:20
Type TC - TRAFFIC COLLISION
Title DUP OF 672
Location P88/2A, J8A/9, AREA30, M40, THAM, XX999XX
Grade I - Immediate
Qualifier Duplicate of

Incident 688-200118
Date/Time 20/01/2018 13:57:20
Type TC - TRAFFIC COLLISION
Title DUP OF 672
Location P88/2A, J8A/9, AREA30, M40, THAM, XX999XX
Grade I - Immediate
Qualifier Duplicate of

Log

No Log entries match the selected types



Daily Barrier Repair Report

M40-FORM-028

A&E No:	20958	Date:	1/2/18	Day:	Thursday		
Location:	135/1+30	A or B:	A	H/S or C/R:	C/R	Wet or Dry:	Dry
Materials Used	Ref. No	Qty	Internal Plant Used	Tick	Operatives		
T.C>B	C01	10	T.M. Lorry		[REDACTED]		
ADJ BEAM	C03	2	T.M. Lorry		[REDACTED]		
POSTS	A18	11	Barrier Rig bj04 vja	/	[REDACTED]		
SOCKETS	A70F	11	Tower Lights		[REDACTED]		
SOCKET CAPS	D231	11	Transit bf62 utm	/			
CONN STRAPS	C13	12	I.S.U bt11 ubm	/			
ADJ BRACKETS	C12	4					
ADJ BOLTS	F13	4					
LAP BOLTS	F07	112	External Plant Used	Tick			
POST BOLTS	F01	24	Coring Rig	/	2 X A.I		
RAPID SET	P02	26	T.M.Lorry				
			Mini Digger				
Length Repaired	L.M.	TCB/OBB	S.S/D.S	Temperature		Additional Post	
1. 19.2	/	tcb	SS	3	5	___No. at 1/2 spaced	
2.						___No. at 1/2 spaced	
Torque Wrench Ref:			Calibration Date:			___No. at Std spaced	

To Specification (TD19/85)	Yes	No	Traffic Management used for this repair
	/		
If no, please state reasons why:			
Erector responsible for repair:	(Print Name) [REDACTED]		
Signed	Start Time (am/pm)	Finish Time (am/pm)	
[REDACTED]	23:00	04:00	
Ref.No.	Date	A / B - VERGE / CENTER RESERVE	

