

Details for Enforcement Notice No. 33/2019

Notice Type	Improvement
Operator	Petrofac Facilities Management Limited
Address	Bridge View 1 North Esplanade West Aberdeen AB11 5QF
Details	At the non production installation, Transocean Leader, Petrofac Facilities Management Limited, as Well Operator, failed to implement the corporate major accident prevention policy and failed to set up appropriate monitoring arrangements to assure effectiveness of the policy.
Legislation	Regulation 7 of The Offshore Installations (Offshore Safety Directive) (Safety Case etc) Reg
Issue Date	19/12/2019