

Defence Equipment and Support Secretariat #2043 Maple 0a Ministry of Defence Abbey Wood Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

Email:

Our Reference: FOI2020/09255

Date:

7 September 2020

Dear

Thank you for your email of 16 August 2020, requesting the following information:

"I am making this Freedom of Information Request to inquire whether you have any vehicle Merlin Reports, Vehicle Record Cards or any other service history on my Land Rover Defender. Army Reg no: MB 00 AA."

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records, including the Merlin database, and it is confirmed that information is held within the scope of your request. This is provided in the attached Annexes, as follows:

Annex A - Transfer history

Annex B - Inspections history

Annex C - Service history

Annex D - Modifications history

Annex E - Faults history

Annex F - Usage history

However, some information contained within Annex A - Transfer history, has been withheld under Section 26(1)(a) and (b) (Defence) of the FOI Act. This exemption applies to information that if disclosed would or would likely prejudice the defence of the British Islands or any colony; and/or the capability, effectiveness or security of the Armed Forces of the Crown or any forces cooperating with them.

As a qualified exemption, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for public disclosure. This work concluded that some details for some military vehicles, when aggregated with others released under different FOI requests, would likely allow a picture to be formed of historic and current UK military land vehicle stock holdings, capabilities, locations, operational movements and actions for some specialist military units. If published, this information would likely benefit our adversaries and those wishing harm to Armed Forces personnel and equipment. I have set the level of prejudice against release of the exempted information at the higher level of "would" rather than "would be likely to".

Under Section 16 (Advice and Assistance) of the FOI Act, I can advise you that some of the information in the attached Annexes A to F is best viewed by using the zoom feature within the relevant software package on your computer.

Also, the Merlin archive was released as part of a previous FOI request and can be accessed through the Government publications website, at the following link:

https://www.gov.uk/government/publications/foi-responses-published-by-mod-week-commencing-09-july-2018

The published Merlin database is split into seven spreadsheets. The first has a list of vehicles, while sheets two through seven include the service histories. To search for a vehicle, you must press Ctrl + F on your computer keyboard, then select 'Options' and then select 'Workbook' from the 'Within' drop down list. Information relevant to your request can be found by typing the vehicle registration number and pressing 'enter'.

You may wish to note that when the Merlin database was archived into its current format some data may have been lost or corrupted. You should, therefore, be cautious that some of the data may be inaccurate.

You may also wish to contact the Royal Logistic Corps Museum who might be able to assist your research further. The contact details for the museum are below. It is, however, possible that the Museum may charge to use its services.

Royal Logistic Corps Museum The Princess Royal Barracks Deepcut Surrey GU16 6RW

Telephone: 01252 833371

Email: information@rlcmuseum.com

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at https://ico.org.uk/.

Yours sincerely

DE&S Secretariat

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number								
(a)	(b)	(c)	(d)	(e)	(f)						
				TRUCK UTY MED (HS) FFR HP 4X4 LAND ROVER 2.8 LTR	Sand Disruptive						
MB00AA	2320999087623	NB50323171	LV2A/088DUM	TURBO DSL AUTO TRANSMISSION RWMIK BOWMAN SH	Pattern						

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
19/02/1998	SALLDBA67WA141985	N/A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MB00AA	3		CA005A	JSCS ASHCHURCH		31816AA	19/02/1998	
MB00AA	4	31/03/1998	A0551A	1 SCOTS	38186A	1881	02/04/1998	
MB00AA	4	23/03/2000	A0577A	1 R IRISH	152	373	27/03/2000	R20
MB00AA	4	03/05/2006	CQ195B	RICARDO SPECIAL VEHICLES LTD	999999	DLOMISC	03/05/2006	
MB00AA	3	01/12/2006	CA005A	JSCS ASHCHURCH	999999	76089AA	01/12/2006	
MB00AA	4	15/02/2007	A8315A	TPS BASTION	82266A	13997	08/03/2007	
MB00AA	4	11/01/2008	A8313A	CF BURMA - (CSAT OP HERRICK)	MCR08	MCR08	11/01/2008	MCR
MB00AA	4	14/09/2008	A8315A	TPS BASTION	13155	78652	15/09/2008	Z57
MB00AA	3	01/04/2010	CA005A	JSCS ASHCHURCH	240442	93569AA	18/05/2010	
MB00AA	4	10/07/2010	CB998C	DSG COLCHESTER PLANNED REPAIR	100521	999	10/07/2010	

MB00AA	4	19/01/2011	CQ195B	RICARDO SPECIAL VEHICLES LTD	999	999	19/01/2011	B40
MB00AA	3	21/01/2011	CA005A	JSCS ASHCHURCH	999999	97567AA	21/01/2011	
MB00AA	2	12/12/2011	A2971A	BATUS QM(T)	109382	301816	19/03/2012	
MB00AA		04/11/2015	A0316A	36 ENGR REGT			04/11/2015	
MB00AA		16/11/2015	A0302F	36 ENGR REGT, 61 FD SQN			16/11/2015	
MB00AA		07/12/2015	A0316A	36 ENGR REGT			07/12/2015	
MB00AA		14/12/2015	A6205G	DSG LONGMOOR TUF			14/12/2015	
MB00AA		15/08/2016	A0864G	FTU			15/08/2016	
MB00AA		23/09/2016	A1990A	DSG WARMINSTER			23/09/2016	
MB00AA		07/10/2016	A0864G	FTU			07/10/2016	
MB00AA		29/11/2016	A6025G	DSG LONGMOOR TUF			29/11/2016	
MB00AA		05/04/2017	A0864G	FTU			05/04/2017	
MB00AA		18/07/2017	A6205G	DSG LONGMOOR TUF			18/07/2017	
MB00AA		04/10/2017	A1037A	DLS 25 REGT RLC			04/10/2017	
MB00AA		19/10/2017	A6205G	DSG LONGMOOR TUF			19/10/2017	
MB00AA		08/02/2018	A5969A	SEF (UK) ASHCHURCH			08/02/2018	
MB00AA		20/03/2018	CA005A	BABCOCK ASHCHURCH			20/03/2018	
MB00AA		27/03/2018	A5969A	SEF (UK) ASHCHURCH			27/03/2018	
MB00AA		24/09/2018	CA005A	BABCOCK DISPOSAL			24/09/2018	
MB00AA		14/02/2020	CA005A	BABCOCK ASHCHURCH			14/02/2020	
MB00AA		14/02/2020	D1832A	OSVP HOLDINGS				

Wall Object											
Work Objects											
Serial Number:	MB00AA										
NSN:	2320999087623										
NSIN.	2320333007023										
Criteria:											
Repair Level:	ALL										
•	Closed										
Mission Impact:	ALL										
Fault State:	ALL										
Escalate Work:	ALL										
Work Request ID:	•										
Assigned Work Status	ALL										
Working Organisation											
Repair Section:											
Maintenance Event II	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Leve	Fault State	Work Status	Estimated Repair Tim	Working Organisation	Repair Section	1
000000-00A973A2		No	FMT931 Weapons (2)*	21 Aug 2019	Level 2	Fully Fit	CL	000:00			
000000-00A97D92		No	FMT931 Comms (2)*	20 Aug 2019	Level 2	Limited Role	CL	000:00			
000000-00A97E4A		No	FMT932 (W) 6 Monthly Safety Inspection (2)	16 Aug 2019	Level 2	Fully Fit	CL	000:00			
000000-00A97E49		No	Annual Headlight Alignment Check (2)	16 Mar 2020	Level 2	Fully Fit	CL	000:00			
000000-00A97E48		No	Annual Brake Test (2)	16 Mar 2020	Level 2	Fully Fit	CL	000:00			
000000-00A97E47		No	Annual Smoke Emissions Test(2)	16 Mar 2020	Level 2	Fully Fit	CL	000:00			
000000-00A97DA5		No	FMT932 (W) Mandatory Equipment Inspection (2	15 Feb 2020	Level 2	Fully Fit	CL	000:00			
000000-00A97DA6		No	FMT930 Landworthiness (AR)		Level 1	Fully Fit	CL	000:00			
000000-00A97E84		No	FMT934 Functional Check (1)*	16 Aug 2019	Level 1	Fully Fit	CL	000:00			
000000-00A97DA3		No	FMT933 (W) Role Equipment (2)*	15 Feb 2020	Level 2	Fully Fit	CL	000:00			
000000-008EEF39		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00			
000000-008EEF5B		No	6 Monthly Safety Insp (2)		Level 2	Limited Role	CL	000:00			
000000-00840683	000000-00329964	No	6 Monthly Safety Insp (2)		Level 2	Non-Taskworthy	CL	000:00		LTF IBES	
000000-0076E994		No	6 Monthly Safety Insp (2)		Level 2			000:00			
000000-0076E993		No	Weekly Handbrake Inspection (2)		Level 2			000:00			
000000-0076E992		No	MEI (2)		Level 2			000:00			
000000-0071B7A7		No	6 Monthly Safety Insp (2)		Level 2	Limited Role	CL	000:00			
000000-0071B79E		No	Weekly Handbrake Inspection (2)		Level 2	Fully Fit	CL	000:00			
000000-0076BDF2		No	Weekly Handbrake Inspection (2)		Level 2	Non-Taskworthy	CL	000:00			
000000-0071B7A9		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00			
000000-005939D7		No	6 Monthly Safety Insp (2)		Level 2	Non-Taskworthy	CL	000:00			
000000-004FE311		No	6 Monthly Safety Insp (2)		Level 2			000:00			
000000-004FE310		No	MEI (2)		Level 2			000:00			
000000-001CEB80		No	Receipt Insp (AR)		Level 1			000:00			
000000-001CEB7F		No	6 Monthly Safety Insp (2)		Level 2			000:00			
000000-001CEB2E		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-001CEB2D		No	MEI (2)		Level 2			000:00			

Work Objects											
Serial Number:	MB00AA										
NSN:	2320999087623										
Criteria:											
Repair Level:	ALL										
Work Object Status:	Closed										
Mission Impact:	ALL										
Fault State:	ALL										
Escalate Work:	ALL										
Work Request ID:											
Assigned Work Status											
Working Organisation											
Repair Section:											
	W. J. B	F	Maintenance Event Name	Next Due Date	D	F II F		Estimated Repair Tim	W-1: 0	B	
000000-00A97E7C	work kequest ID		OOPS 2 Yearly/20000 Kms Replace Engine Oil And Filter					estimated kepair iim 000:00	Working Organisation	Repair Section	_
000000-00A97E50				19 Feb 2020	Level 2			000:00			
000000-00A97E30			2 Yearly/40000 Kms (2)					000:00			
000000 00A97E8A					Level 2			000:00			
000000 00157E01					Level 2			000:00			
000000-00A97E7E								000:00			
000000-00A97E7D			2 Yearly/40000 Kms Drain/Renew Brake Fluid (2)	18 Feb 2021	Level 2			000:00			
000000-0096C91D					Level 2			000:00			
000000-009361D0					Level 2			000:00			
000000-008ED6C9					Level 2	Non-Taskworthy		000:00			
000000-008ED6C8					Level 2	Non-Taskworthy	CL	000:00			
000000-008ED0AB		No	Yearly/20000 Kms (2)	19 Feb 2020	Level 2	Non-Taskworthy	CL	000:00			
000000-008ED0AA		No	OOPS Yearly/10000 Kms Gearbox Oil Change (2)	19 Feb 2020	Level 2	Non-Taskworthy	CL	000:00			
000000-00875ED8		No	3 Monthly/5000 Kms (2)		Level 2			000:00			
000000-00840684	000000-00329964	No	6 Monthly/10000 Kms (2)		Level 2	Non-Taskworthy		000:00		LTF IBES	
000000-00875EBA		No			Level 2			000:00			
000000-007AE491			2 Yearly/40000 Kms Drain/Renew Brake Fluid (2)	18 Feb 2021	Level 2	Non-Taskworthy		000:00			
000000-007AE49C			OOPS 2 Yearly/20000 Kms Replace Engine Oil And Filter		Level 2	Non-Taskworthy		000:00			
000000-007AE499			3 Monthly/5000 Kms (2)		Level 2	Non-Taskworthy		000:00			
000000-007B54A1					Level 2	Non-Taskworthy		000:00			
000000-007B54A0		No	Yearly/20000 Kms (2)	19 Feb 2020	Level 2	Non-Taskworthy		000:00			
000000-007B549F		No			Level 2	Non-Taskworthy		000:00			
000000-007B549E					Level 2	Non-Taskworthy		000:00			
000000-007B549D 000000-007AE49B			OOPS 2 Yearly/20000 Kms Replace Engine Oil And Filter 2 Yearly/40000 Kms (2)	18 Feb 2021	Level 2 Level 2	Non-Taskworthy Non-Taskworthy		000:00			
000000-007AE49B								000:00			
000000-0076E975					Level 2	Fully Fit		000:00			
000000-0071B7AA			OOPS Yearly Coolant Change (2) OOPS Yearly/10000 Kms Gearbox Oil Change (2)	19 Feb 2020	Level 2	Fully Fit		000:00			
000000-0071B7AA				11 Dec 2021				000:00			
000000 0071B7AB				19 Feb 2020	Level 2	Non-Taskworthy		000:00			
000000-0071B79E					Level 2	Non-Taskworthy		000:00			
000000-0071B7A8					Level 2	Non-Taskworthy		000:00			
000000-005939EA				21 May 2019	Level 2	Non-Taskworthy		000:00			
000000-0059894A		No			Level 2	Non-Taskworthy	CL	000:00			
000000-005939DB		No	6 Monthly/10000 Kms (2)	21 Aug 2019	Level 2	Non-Taskworthy	CL	000:00			
000000-0053B3DA		No	3 Monthly/5000 Kms (2)	21 May 2019	Level 2			000:00			
000000-004FE3B9					Level 2			000:00			
000000-004FE3B8		No	Yearly/20000 Kms (2)	19 Feb 2020	Level 2			000:00			
000000-004FE3B7					Level 2			000:00			
000000-004FE3B6			2 Yearly/40000 Kms Drain/Renew Brake Fluid (2)	18 Feb 2021	Level 2			000:00			
000000-004FE3B5			3 Monthly/5000 Kms (2)		Level 2			000:00			
000000-004FE3B4			OOPS 2 Yearly/20000 Kms Replace Engine Oil And Filter		Level 2			000:00			
000000-004FE3B3			2 Yearly/40000 Kms (2)	18 Feb 2021	Level 2			000:00			
000000-00268406			OOPS Yearly/10000 Kms Gearbox Oil Change (2)		Level 2			000:00			
000000-0026B405 000000-0026B404			6 Monthly/10000 Kms (2) 3 Monthly/5000 Kms (2)		Level 2 Level 2			000:00			
000000-0026B403 000000-0026B402			2 Yearly/40000 Kms Drain/Renew Brake Fluid (2) Yearly/20000 Kms (2)	18 Feb 2021 19 Feb 2020	Level 2 Level 2			000:00			
000000-0026B402 000000-0026B401					Level 2			000:00			
000000-0026B401 000000-0026B400			OOPS 2 Yearly/20000 Kms Replace Engine Oil And Filter 2 Yearly/40000 Kms (2)		Level 2 Level 2			000:00			
000000-00268400 000000-0020686B			OOPS First 1000 Kms (2)	201E0 2021	Level 2			000:00			
000000-0020686A			First 1600 Kms (2)		Level 2			000:00			
000000-0020686A 000000-001FA846			3 Monthly/5000 Kms (2)	21 May 2019	Level 2			000:00			
000000-001FA846			OOPS Yearly/10000 Kms Gearbox Oil Change (2)	19 Feb 2020	Level 2			000:00			
000000-001CEB73			3 Monthly/5000 Kms (2)	21 May 2019	Level 2			000:00			
000000-001CEB72					Level 2			000:00			
000000 001CEB70			Yearly/20000 Kms (2)	19 Feb 2020	Level 2			000:00			
000000-001CEB6C			2 Yearly/40000 Kms Drain/Renew Brake Fluid (2)		Level 2			000:00			
000000-001CEB6B		No	OOPS Yearly/10000 Kms Gearbox Oil Change (2)	19 Feb 2020	Level 2			000:00			
000000-001CEB6A					Level 2			000:00			
000000-001CEB69			Yearly/20000 Kms (2)	19 Feb 2020	Level 2			000:00			
000000-001CEB68			2 Yearly/40000 Kms (2)	18 Feb 2021	Level 2			000:00			
000000-001CEB67					Level 2			000:00			
000000-001CEB66				11 Dec 2021	Level 2			000:00			
000000-001CEB65			OOPS 2 Yearly/20000 Kms Replace Engine Oil And Filter		Level 2			000:00			
		No	OOPS 6 Yearly/120000 Kms Replace Cam Belt (2)	15 Jan 2023	Level 2			000:00			

Work Objects												
Serial Number:	MB00AA											
NSN:	2320999087623											
Criteria:												
Repair Level:	ALL											
Work Object Status	Closed											
Mission Impact:	ALL											
Fault State:	ALL											
Escalate Work:	ALL											
Work Request ID:												
Assigned Work Stat	us ALL											
Working Organisati	оп											
Repair Section:												
Modification Event	ID Modification Numb	Modification Description	Work Request ID Escalate Wo	rk Production Classification/In Service Classificat	ti Modification Type A	pply When Usage Equal Embody by Target Date	Usage Counter Unit: Fa	ult State Work Sta	tus Repair Leve	Working Organisatio Repair S	ction Estimated Repa	.ir Time
000000-006398A7	00009	Immediate Handbrake Assembly Modification	000000-00321225 No	1/A	Mod	08 Oct 2015	No	on-Taskworthy CL	Level 2	LTF IBES	003:00	
000000-0063FEB9	00007	Vehicle and Auxiliary Battery Isolation Switch Modification	000000-00321225 No	2/-	Mod	01 Jan 2015	Lin	mited Role CL	Level 2	LTF IBES		
000000-00646885	00010	Modification to rear view mirrors to increase spring back tension and to improve visibility on the Drivers side mirror only when carrying Short Gap Crossing	000000-00321225 No	1/A	Mod			on-Taskworthy CL	Level 2	LTF IBES		
000000-0063FFE5	00008	Modification to wheel arch armour to avoid contact with suspension forward swing arm	000000-00321225 No	2/B	Mod	31 Dec 2014		on-Taskworthy CL	Level 2	LTF IBES	003:00	
000000-0002B817	00001	Replacement Speedometer drive to improve the accuracy.	No	1/A	Mod	27 Sep 2012	No	on-Taskworthy CL	Level 2			
000000-0002CC9F	00004	Strengthening of front spring chassis mounting plate.	No	1/A	Mod	30 Oct 2012		on-Taskworthy CL	Level 2			
000000-0002CC27	00005	REVISED DIPSTICK SUPPORT BRACKET	No	3/B	Mod	30 Oct 2012		illy Fit CL	Level 2			
000000-0002CB79	00003	ITDU safety up grade, Cab netting, Ammunition box restraint assembly, Door handle assy LH & RH, Drvs & comds side step assy, Internal pannier lock release assy, Battery box net assy, Upper stowage net assy, Lower stowage net & side net	Strap kit assy. No	1/A	Mod			on-Taskworthy CL	Level 2			
000000-00610262	00006	RWMIK/RWMIK+ ENVIRONMENTAL PROTECTION COVER	No	3/C	Mod		Fu	illy Fit CL	Level 1		001:15	
000000-00028986	00002	Fit revised Mirror and Mirror Arms to improve visibility	No	2/A	Mod	27 Sep 2012	No	on-Taskworthy CL	Level 2		001:00	

Work Objects														
Serial Number:	MBOGAA													
NSN:	2320999087623													
Iriteria:														
lepair Level:	ALL													
	Closed													
	ALL													
Scalate Work:	ALL					_								
Work Request ID:	7													
Assigned Work Statu	ALL													
Working Organisation Repair Section:														
ault ID 000000-00812403	Work Request ID	Fault Description		s Fault State Non-Taskworthy	Escalate Worl	k Repair Lev Level 2	ve Batch Fault Group ID Numbe	Fault Occurrence Da 22 Feb 2019	Mission Impa N/A	Reason For Wo	rk Level 3 Description TUM HS RWMIK PLUS	Working Organisation	Repair Section	Estimated Repair Time
000000-008123F9		replace true timer cap replace true fires	Closed	Non-Taskworthy	No	Level 2		22 Feb 2019	N/A	Inspection	TUM HS RWWIK PLUS			000:00
02257-21BE0004		COMMS INOP	Closed		No	Level 2		19 Nov 2017	N/A	Failure	TUM HS RWMIK PLUS			000:00
000000-00AE3DC8 000000-00AE3DD2		INVESTIGATE GEARBOX U/S BRAZE FADAL MINSING	Closed	Fully Fit Fully Fit	No	Level 2 Level 2		01 Oct 2018 01 Oct 2018	N/A N/A	Inspection	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			000:00
00000-00AESDD2		BOARSE FROM MISSISSIAN BEAR SEA		Non-Taskworthy	No.	Level 2		05 Feb 2019	N/A	Inspection Servicing	TIM HS RWMIK PLUS			000:00
000000-00B0C26C		BAAN - 60 - 1200 - REMOVE AND REFIT TRANSFER BOX	Closed	Non-Taskworthy	No	Level 2		05 Feb 2019	N/A	Non Spec	TUM HS RWMIK PLUS			000:00
000000-00B0C25C 000000-00B0C255		BAAN = 0. 004-8 RNIV STST BAAN = 0. 014-8 RNIV SERVIC (AUTO)	Closed	Non-Taskworthy Non-Taskworthy		Level 2 Level 2		05 Feb 2019 05 Feb 2019	N/A N/A	Non Spec Non Spec	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			000:00
00000-00808969		BANDAT DE LOVER RESERVICION (RAUTO) REPAIR LACK OF DRIVE	Closed	Non-Taskworthy	No	Level 2		05 Feb 2019	N/A	Failure	TUM HS RWMIK PLUS			000:00
000000-00A85E9F		FUEL CAP DOESN'T LOCK	Closed	Fully Fit	No	Level 1		11 Jan 2018	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-00A7B882 000000-00A7B8A7		bonnet catch doesn't lock automatically in/s doer striker behen!	Closed		No	Level 2 Level 2		29 Nov 2017 29 Nov 2017	N/A N/A	Inspection	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			000:00
000000-00A758A7		PROPS NEED GREASING	Closed	Fully Fit	No No	Level 1		11 Jan 2018	N/A	Closed No Acti	or TUM HS RWMIK PLUS			000.00
000000-00A85E95		TOW PINTLE LOCKING PIN AND CLIP MISSING	Closed	Fully Fit	No	Level 1 Level 1		11 Jan 2018	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
06314-242C8000 03345-24194002		Inv lack of drive Inv lack of drive	Closed	Non-Taskworthy Non-Taskworthy		Level 2 Level 2		14 Jun 2018 08 Jun 2018	N/A N/A	Inspection Failure	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			000:00
06314-241C8000		INVERSE AT 190X	Closed	Non-Taskworthy	No	Level 2		09 Jun 2018	N/A	Failure	TUM HS RWMIK PLUS			000:00
06314-23FDE000		(Investigate) Lack of drive	Closed	Non-Taskworthy	No	Level 2		27 May 2018	N/A	Failure	TUM HS RWMIK PLUS			000:00
000000-00AA4643 000000-00AB4432		Instructs type scrub / uneven wear DIF foot live the sex excessive freeplay	Closed	Fully Fit Non-Taskworthy	No No	Level 2 Level 2		06 Apr 2018 21 May 2018	N/A No Effect		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			002:30
000000-00AB4431		investigate lack of drive	Closed	Non-Taskworthy	No	Level 2		21 May 2018	No Effect	Closed No Acti	OF TUM HS RWMIK PLUS			
000000-00AB4814		GEAR ISSUE - LAD TO INVESTIGATE	Closed	Non-Taskworthy		Level 2		22 May 2018	N/A		or TUM HS RWMIK PLUS			
000000-00A6195F 000000-00A7B8AE		BATTER MASTER SWITCH NOP WILL NOT CUT POWER IND that I plant the support of the s	Closed	Limited Role Non-Taskworthy	No No	Level 2 Level 2		10 Oct 2017 29 Nov 2017	N/A N/A	Closed No Acti Inspection	TUM HS RWWIK PLUS TUM HS RWWIK PLUS			000:00
000000-008/880ED		no suit joint woods	Closed		No	Level 2		29 Aug 2015	N/A N/A		or TUM HS RWMIK PLUS			www.
000000-00A3EC61	000000-00328CF9	Carry out work as per Armourers Report 857	Closed		No	Level 2		24 Jul 2017	N/A	Inspection	TUM HS RWMIK PLUS		LTF IBES	005:00
000000-00A4E979 000000-00A4E975	000000-00329964	Fit R dijg and lanyard to top the seatbelt mount Secure are done to the thing and the seatbelt mount Secure are done to the the seatbelt mount Secure are done to the thing and the seatbelt mount Secure are done to the s	Closed	Non-Taskworthy Fully Fit	No No	Level 2 Level 2		31 Aug 2017 31 Aug 2017	N/A N/A	Inspection	TUM HS RWMIK PLUS TUM HS RWMIK PLUS		LTF IBES LTF IBES	000:30 001:00
000000-00A4E971	000000 00329964	Renew floor plate at rear crew com	Closed	Limited Role	No	Level 2		31 Aug 2017	N/A	Inspection	TUM HS RWMIK PLUS			001:00
000000-00A4E96D	000000-00329964	Secure cable at RH radies arm	Closed		No	Level 2		31 Aug 2017	N/A	Inspection	TUM HS RWMIK PLUS		LTF IBES	001:00
000000-00971ADB 000000-008E12A8	000000-00329964	REPLACE FLAT SPARE WHEEL BELLYPLATE NOT PHITTED	Closed		No No	Level 1 Level 2		19 Feb 2016 02 Dec 2015	N/A N/A	Damage Non Spec	TUM HS RWMIK PLUS TUM HS RWMIK PLUS		LTF IBES	000:30 002:00
000000-0098298D		Inspect all times to ensure correct type as per SNyE 00101.	Closed		No	Level 1	000000-0000352D	30 Mar 2016	N/A	Inspection	TUM HS RWMIK PLUS			000:15
000000-0099DC85		Inspect all tyres to ensure correct type as per SNVE 00101. BDSG SERVICE AND INSPECTION	Closed	Non-Taskworthy		Level 2		30 Mar 2016 13 Jun 2016	N/A	Closed No Acti	or TUM HS RWMIK PLUS			000:15
000000-0088AD82 000000-00962F48		IRENEW PASSINGER DOOR LATCH AND STRIKER Integrating the confidence lever in encordance with SNVE 0069 issued by the PT	Closed	Fully Fit Fully Fit	No No	Level 2 Level 2		27 Aug 2015 20 Jan 2016	N/A		or TUM HS RWMIK PLUS or TUM HS RWMIK PLUS			000:30
000000-008DDFF7		Impect and pair damage to rear axie	Closed	Non-Taskworthy		Level 3		30 Oct 2015	N/A	Failure	TUM HS RWMIK PLUS			008:00
000000-0095F2F4		Inspect and repair damage to rear ade Check No2 ball joint torque dightness as per safety notice LE SNVE 00063	Closed	Non-Taskworthy	No	Level 3 Level 2		14 Jan 2016	N/A	Inspection Failure	TUM HS RWMIK PLUS			000:15
000000-00887030 000000-00882E65		INV ENGINE OVER HEATING REAR RIGHT HUB SEAL LEAK	Closed	Non-Taskworthy Non-Taskworthy		Level 2 Level 2		14 Aug 2015 31 Jul 2015	N/A N/A	Failure Failure	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			002:00 001:00
000000-007BC0B0		ESG-COMMS-B LINE-WRP14	Closed	Fully Fit	No	Level 2	000000-00000BCD	01 Oct 2013	N/A	Closed No Acti	OF TUM HS RWMIK PLUS			
000000-00757C28		REMABILITATE VEHICLE IN ACCORDANCE WITH STANDARD REPAIR ACTIONS LISTED IN BATUS WKSP SOP 4.22	Closed	Non-Taskworthy		Level 2	000000-0000059D	12 Dec 2012	N/A		or TUM HS RWMIK PLUS			000:30
000000-007C3SF4 000000-007C3DBC		Paint out all call signs/IAP numbers Require Later (vehicle batteries) fasteners, fasteners have been arc burned	Closed	Fully Fit Non-Taskworthy	Yes	Level 1		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWIMIK PLUS or TUM HS RWIMIK PLUS			
000000-007C3D77		Fit all un-embodied modifications	Closed	Limited Role	Yes	Level 2 Level 2		22 Oct 2013	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-007C3D11		Renew upper rear panel rubber lock strap	Closed	Fully Fit	Yes	Level 2		22 Oct 2013	N/A		or TUM HS RWMIK PLUS			
000000-007C3D25 000000-007C3D22		Reft under body amour paties Straighten under body amour unputing points	Closed	Limited Role Limited Role	Yes	Level 2 Level 2		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			
000000-007C3D17		Rectify failed RBT on service	Closed	Non-Taskworthy		Level 2		22 Oct 2013	N/A	Closed No Acti	OF TUM HS RWMIK PLUS			
000000-007C3D0C		Rectify T/box shifter inoperative	Closed	Limited Role	Yes	Level 2		22 Oct 2013	N/A		or TUM HS RWMIK PLUS			
000000-007C35F2 000000-007C35ED		Clean mouse next/faces out of rear of vehicle Carry out overdue 3 6 monthly service tasks	Closed	Fully Fit Non-Taskworthy	Yes	Level 1 Level 1		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			
000000-007C3SEB		Carry out overdue 3 and 6 monthly VM tasks	Closed	Non-Taskworthy		Level 2		22 Oct 2013	N/A	Closed No Acti	OF TUM HS RWIMIK PLUS			
000000-007C35EF		fit air cleaner housing cover correctly	Closed		Yes	Level 2		22 Oct 2013	N/A	Closed No Act	or TUM HS RWMIK PLUS			
000000-007C3SEA		Investigate/repair fust seepage at fuel tank Secure left, fower side of grill to to mudwing	Closed	Non-Taskworthy Fully Fit	Yes	Level 2 Level 2		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWMIK PLUS or TUM HS RWMIK PLUS			
000000-007C35E2		Secure front propellor shaft mounting fasteners	Closed	Limited Role	Yes	Level 2		22 Oct 2013	N/A	Closed No Acti	OF TUM HS RWIMIK PLUS			
000000-007C3SDD 000000-007C3SE1		differential locks (inoperative Remove twist from left from to base flex hose	Closed	Limited Role Non-Taskworthy	Yes	Level 2 Level 2		22 Oct 2013 22 Oct 2013	N/A N/A	Closed No Acti	OF TUM HS RWWIK PLUS OF TUM HS RWWIK PLUS			
000000-007C3SE1 000000-007C3SE7		Remove twist from left from brake flexi hose Rectly leaking supporting the properties of the propertie	Closed	Non-Taskworthy Limited Role	Yes	Level 2		22 Oct 2013 22 Oct 2013	N/A		or TUM HS RWMIK PLUS or TUM HS RWMIK PLUS			
000000-007C35E9		Fit lower link arm, front bushes correctly	Closed	Non-Taskworthy		Level 2		22 Oct 2013	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-007C3SE5 000000-007C3SE0		Refit front asle track rod protective plates	Closed	Limited Role Non-Taskworthy		Level 2 Level 2		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			
000000-007C3SE0 000000-007C3SDF		CORRECTLY lock tab steering drop arm retainer nut Secure ALL steering box mounting bolts	Closed	Non-Taskworthy Non-Taskworthy	Yes	Level 2		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWMIK PLUS or TUM HS RWMIK PLUS			
000000-007C3SD4		Renew diffy brake pedal anti-slip pad	Closed	Non-Taskworthy		Level 2		22 Oct 2013	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-007C3SD9		Rectify on board compressor inoperative Correctly secure 'Ploos shifter dask boot	Closed	Limited Role Limited Role	Yes	Level 2 Level 2		22 Oct 2013 22 Oct 2013	N/A N/A		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			
000000-007C35CE		Correctly mount shifter assembly	Closed	Non-Taskworthy	Yes	Level 2		22 Oct 2013	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-007A7842		RWMK+ Safety Notice Front Bulkhead/Chassis Dutrigger Inspection	Closed		No	Level 2	000000-000009CA	30 Jul 2013	N/A	Inspection	TUM HS RWMIK PLUS			001:00
000000-00840537 000000-0078C088		Towing Finite Assembly Sec COMM-8 BINE Ways 4	Closed	Limited Role Fully Fit	No No	Level 2 Level 2	000000-00001F35 000000-000008CE	07 Oct 2014 01 Oct 2013	Degraded N/A	Inspection Closed No Acti	TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			000:30
000000-0073E712		Comms WRP Inspection	Closed	Fully Fit	No	Level 2		28 Sep 2012	N/A	Inspection	TUM HS RWMIK PLUS	BATUS WKSP	ESG Comms L2	001:00
000000-00739836		Handback to BATUS inspisee inspiseet	Closed	Non-Taskworthy	No	Level 2		17 Sep 2012	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-00732AB5 000000-007082E6		ECM HORN SEMONED UNDER DIRECTION OF ARMY HID EQUIPMENT DIRECTORATE. TO BE REFITTED ONLY AS REQUIRED CARRY OUT MOD.	Closed	Fully Fit Fully Fit	No No	Level 2 Level 2	000000-000004E1	28 Aug 2012 03 Apr 2012	N/A N/A		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			
000000-007082E5		CARRY OUT MOD 1	Closed	Fully Fit	No	Level 2		03 Apr 2012	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-007082E4		CONNECT RADIO BATTS	Closed	Limited Role	No	Level 1		03 Apr 2012	N/A	Closed No Acti	ON TUM HS RWMIK PLUS			
000000-007082E3		FIT CORRECT HADUGHTS FOR CANADA FIT FOR AND REVISES LIGHTS CORRECTLY FOR CANADA	Closed	Limited Role Limited Role	No No	Level 2 Level 2		03 Apr 2012 03 Apr 2012	N/A N/A		or TUM HS RWWIK PLUS or TUM HS RWWIK PLUS			
000000-00704D65		INV MOVING SPARE WHEEL FROM L/H/S OF VEHICLE TO R/H/S	Closed	Fully Fit	No	Level 2		23 Mar 2012	N/A	Closed No Acti	or TUM HS RWMIK PLUS			
000000-00704D62		FIT PASSENGER SEAT WARNING STICKER (WINK ONLY MOD)	Closed	Fully Fit	No	Level 1		23 Mar 2012	N/A	Closed No Arti	OF THIM HS RWMIK PHUS			
000000-00704D5C 01387-086D0006		No JACK OR FIRE EXTINGUISHERS Into Year Or The Company of the Comp	Closed	Limited Role Non-Taskworthy	No.	Level 1 Level 2		23 Mar 2012 02 Sep 2012	N/A N/A	Closed No Acti Failure	TUM HS RWMIK PLUS			000:15
01387-086D0006		inv transterior do nop	Closed	Fully Fit	No	Level 1		02 Sep 2012	N/A	Inspection	TUM HS RWMIK PLUS			000:00
01387-0B6D0004		Tighten passenger mirror	Closed		No	Level 1		02 Sep 2012	N/A	Inspection	TUM HS RWMIK PLUS			000:00
01387-086D0003 01387-086D0002		Renew front shaddes	Closed	Fully Fit Fully Fit	No.	Level 1 Level 1		02 Sep 2012 02 Sep 2012	N/A N/A	Inspection	TUM HS RWWIK PLUS TUM HS RWWIK PLUS			000:00
01387-086D0002 01387-086D0001		Lyind pun missing Brake pedid cover	Closed	Fully Fit	No	Level 1		02 Sep 2012	N/A	Inspection	TUM HS RWMIK PLUS			000:00
01387-086D0000		Fuel tank damaged	Closed	Fully Fit	No	Level 2		02 Sep 2012	N/A	Inspection	TUM HS RWMIK PLUS			000:00
000000-0070A4C9	000000-00209210	BATUS comms in inspection WAP ARMS IN INSPECTION	Closed	Fully Fit Limited Role	No No	Level 2 Level 3		26 Mar 2012 27 Mar 2012	N/A N/A	Inspection	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			001:00 001:15
	002000086	INDEP AND INSPECTION. CARRY OUT RELEVANT SERVICING TASKS AND UPDATE JAMES	Closed	Non-Taskworthy	No	Level 1		27 Mar 2012 23 Mar 2012	N/A N/A	Inspection	TUM HS RWMIK PLUS			
000000-00705E0C 000000-00704D63		CARRY OUT RELEVANT MAINT TASKS AND UPDATE JAMES	Closed	Non-Taskworthy	No	Level 2		23 Mar 2012 23 Mar 2012	N/A	Inspection	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			
000000-00705E0C 000000-00704D63 000000-00704D58														
000000-00705E0C 000000-00704D63 000000-00704D58 000000-00704D5F		FIT WATER PROFF DASH COVER CORRECTLY	Closed	Fully Fit Limited Role	No No	Level 1		23 Mar 2012	N/A	Inspection				001:00
000000-00705E0C 000000-00704D63 000000-00704D58 000000-00704D5F 000000-00704D5E		FIT WATER PRIOFE DASH COVER, CORRECTLY CONVOIT USERT RICP GOANN AND FLUEN COLOURGE SYSTEM AND REFILL WITH CORRECT MOX OF AL39	Closed Closed Closed	Limited Role Non-Taskworthy		Level 1		23 Mar 2012 23 Mar 2012	N/A N/A	Inspection	TUM HS RWMIK PLUS TUM HS RWMIK PLUS			001:00 001:00
000000-00705E0C 000000-00704D63 000000-00704D58 000000-00704D5F 000000-00704D5E		FIT WATER PROFE DASH COVER CORRECTLY CONVOYUGHT INDOP	Closed	Limited Role Non-Taskworthy	No No No	Level 1		23 Mar 2012	N/A N/A N/A N/A	Inspection	TUM HS RWMIK PLUS			001:00

View Usage History			
Serial Number:	MB00AA		
NSN:	2320999087623		
Criteria:			
Usage Counter Type:			
Transaction Type:	ALL		
Start Date:			
End Date:			
Usage Type:			
Date and Time of Usage Readir			
28 Feb 2019 14:10	Usage Update		698.34 Fuel Drwn
28 Feb 2019 14:10	Usage Update		12037.00 Kilometres
22 Feb 2019 11:00	Usage Update		12035.00 Kilometres
19 Feb 2019 18:33	Usage Update	EQUIPMENT	11757.00 Kilometres
14 Feb 2019 10:37	Usage Update		698.34 Fuel Drwn
14 Feb 2019 10:37	Usage Update	EQUIPMENT	11162.00 Kilometres
27 Nov 2018 12:26	Usage Update	EQUIPMENT	698.34 Fuel Drwn
16 Nov 2018 09:17	Usage Update	EQUIPMENT	698.34 Fuel Drwn
16 Nov 2018 09:17	Usage Update	EQUIPMENT	11162.00 Kilometres
01 Oct 2018 13:49	Usage Update	EQUIPMENT	698.34 Fuel Drwn
01 Oct 2018 13:49	Usage Update	EQUIPMENT	11162.00 Kilometres
27 Sep 2018 19:52	Usage Update		698.34 Fuel Drwn
27 Sep 2018 19:52	Usage Update		11162.00 Kilometres
27 Sep 2018 19:21	Usage Update		698.34 Fuel Drwn
27 Sep 2018 19:21	Usage Update		11162.00 Kilometres
12 Sep 2018 12:16	Usage Update		698.34 Fuel Drwn
12 Sep 2018 12:16	Usage Update	-4-	11162.00 Kilometres
04 Jul 2018 12:02	Usage Update		698.34 Fuel Drwn
04 Jul 2018 12:02	Usage Update		11162.00 Kilometres
21 May 2018 15:47	Usage Update		698.34 Fuel Drwn
21 May 2018 15:47	Usage Update		11162.00 Kilometres
10 Apr 2018 14:01	Usage Update		698.34 Fuel Drwn
10 Apr 2018 14:01	Usage Update		11162.00 Kilometres
30 Mar 2018 18:18	Usage Update		698.34 Fuel Drwn
30 Mar 2018 18:18	Usage Update	-4-	11162.00 Kilometres
22 Mar 2018 23:37	Usage Update		557.66 Fuel Drwn
22 Mar 2018 23:37	Usage Update		10643.00 Kilometres
22 Mar 2018 23:37 14 Mar 2018 14:00	Usage Update		557.66 Fuel Drwn
14 Mar 2018 14:00 14 Mar 2018 12:40	Usage Update		557.66 Fuel Drwn
14 Mar 2018 12:40	Usage Update		10643.00 Kilometres
15 Jan 2018 16:52	Usage Update		364.07 Fuel Drwn
15 Jan 2018 16:52	Usage Update		9292.00 Kilometres
15 Jan 2018 16:52 11 Jan 2018 10:48		-4-	9292.00 Kilometres
11 Jan 2018 10:48 28 Nov 2017 14:49	Usage Update		
	Usage Update		364.07 Fuel Drwn
28 Nov 2017 14:49	Usage Update		9289.00 Kilometres
06 Nov 2017 10:57	Usage Update		264.00 Fuel Drwn
06 Nov 2017 10:57	Usage Update		8644.00 Kilometres
02 Mar 2017 14:12	Usage Update		8644.00 Kilometres
04 Oct 2016 16:32	Usage Update		8566.00 Kilometres
20 Nov 2015 09:59	Usage Update	-11-	8558.00 Kilometres
30 Aug 2015 08:27	Usage Update		8406.00 Kilometres
08 Apr 2015 10:00	Usage Update		7430.00 Kilometres
19 Jun 2014 11:58	Usage Update		264.00 Fuel Drwn
21 May 2013 21:34	Usage Update	-4-	132.00 Fuel Drwn
21 May 2013 21:34	Usage Update		7392.00 Kilometres
19 Feb 1998 00:00	Usage Update		132.00 Fuel Drwn
19 Feb 1998 00:00	Usage Update	FOUIPMENT	7392.00 Kilometres