



# Sewage-related contaminants in Isles of Scilly groundwater: concentrations, spatial distribution, sources and risk

Project ENVRESW001361

September 2016

Part 2 of 4

Figure 4a: St Mary's clostridium counts  
November 2015 - January 2016 sampling





Figure 4b: St Martin's clostridium counts  
November 2015 - January 2016 sampling





Figure 4c: St Agnes clostridium counts  
November 2015 - January 2016 sampling





Figure 4d: Tresco and Bryher clostridium counts November 2015 - January 2016 sampling







Figure 5: Isles of Scilly e-coli counts  
November 2015 - January 2016 sampling



Withdrawn 24 Nov 2020



Figure 5a: St Mary's e-coli counts  
November 2015 - January 2016 sampling





Figure 5b: St Martins e-coli counts  
November 2015 - January 2016 sampling





Figure 5c: St Agnes e-coli counts  
November 2015 - January 2016 sampling



Withdrawn 24 NOV 2020




Figure 5d: Tresco and Bryher e-coli counts  
November 2015 - January 2016 sampling





Figure 6: Isles of Scilly orthophosphate concentrations. November 2015 - January 2016 sampling



Withdrawn 24 Nov 2020



Figure 7: Isles of Scilly chloride concentrations  
November 2015 - January 2016 sampling






Figure 8: Isles of Scilly boron concentrations  
November 2015 - January 2016 sampling







Figure 9: Isles of Scilly dissolved oxygen percentages, November 2015 - January 2016 sampling



Withdrawn 24 Nov 2020