

Date - 2/10/2019	Inspector - [REDACTED]	
Chart section	Location- CW,MP,Lane,WT	Defect
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
[REDACTED]	[REDACTED]	[REDACTED]
1584A120/668	A120 WB MP 49/4 RWT	Pothole
1584A120/352	A120 WB MP 28/3 CRES	Blocked gully top

INSPECTION	HIGHWAYS ENGLAND						MAKE SAFE / REPAIR (RINGWAY)			
DATE: 18/12/2019		INSPECTORS: [REDACTED]				ROUTE: BH01		CREW NAMES:		
VEHICLE: [REDACTED]		START TIME: 07:00				FINISH TIME: 14:00				
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT	ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF	
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
[REDACTED]										
A120	1585A120/405	EB	30/8	Slip	RWT	Pothole - Dunmow south Entry slip Next to bull nose				
A120	1585A120/431	EB	39/6	1	LWT	Pothole				
A120	1585A120/638	EB	60/4			Pothole				
A120	1585A120/619	WB	54/0		RWT	Pothole - Opposite Ambridge road.				

