INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	06/01/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00		_	FINISH TIME:	14:00		_	
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							
				•							
				1							
				ı							
				ı							
				I							
A120	1585A129/311	EB	22/1	1	LWT	POTHOLE					

INSPECTION					HIGI	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	08/01/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00			_
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							
				ı							
				I							
A120	1585A120/602	ЕВ	48/1		LWT	Pothole					
A120	1585A120/602	EB	48/5		LWT	Pothole					

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	15/01/2019		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							
				•							
				•							
A120	1500A120/300	EB	20/3	1	RWT	Pothole					

INSPECTION					HIGH	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	22/01/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	13:00			_
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							
				ı							
				•							
				1							
				•							
				1							

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	29/01/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	13:00			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				ı							
				•							
				•							
				•							
				ı							
A120	1585A120/452	WB	37/1	1	RWT	Pothole					

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	05/02/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	13:00			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFEC	т		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/502	EB	39/7	1	LWT	Pothole					
A120	1585A120/473	WB				Dunmow south entry slip half w	ay up - Pothole				
A120	1585A120/473	WB				Dunmow south entry slip top o	f slip - Pothole				
A120	1585A120/384	WB	22/5+60	1	LWT	Pothole					

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	12/02/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							
				•							
				•							
A120	1585A120/668	WB	49/1		RWT	POTHOLE					
A120	1585AA120/384	WB	22/5	1	LWT	POTHOLE					

INSPECTION DATE:	19/02/2020		INSPECTORS:				ROUTE:	BH01	MAKE SAFE / REPAIR CREW NAMES:		
VEHICLE:	15, 02, 2020		START TIME:				FINISH TIME:	13:00	1		
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFEC			ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/580	W/B	400	2	RWT	Pothole					
A120	1585A120/384	W/B	225	1	C/ lane	Pothole					
		-									
			-								
			_								
			-								

INSPECTION					HIG	HWAYS ENGLAND	MAKE SAFE / REPAIR ( RINGWA	Y)
DATE:	26/02/2020		INSPECTORS:			ROUTE: BH01	CREW NAMES:	
VEHICLE:			START TIME:	07:00		FINISH TIME: 14:00		
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFECT	ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON TIME OFF
A120	1585A120/665	WB	50/6			Pothole (Large)- Ringway supervisor advised before midday that traffic lights required for this job		
A120	1585A120/668	WB	49/1			Multiple potholes.Ringway supervisor advised before midday that traffic lights required for this job		
				•				

INSPECTION					HIGI	HWAYS ENGLAND		MAKE SAFE / REPAIR ( RINGW	'AY)	
DATE:	04/03/2020		INSPECTORS:			ROUTE: BH01	CREW NA	AMES:		
VEHICLE:			START TIME:	07:00		FINISH TIME: 14:00				
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT	ON-SI	TE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•						
				•						
				ı						
				ı						
				I						
				1						
				•						
A120	1500M11/121	EB	20/3	1	RWT	Pothole				
A120	1585A120/502	EB	40/6	1	LWT	Pothole				
A120	1585A120/502	EB	47/4	1	LWT	Pothole- just prior to un-named track (first left turn after Marks farm RBT)				
A120	1585A120/602	EB	62/1	1/2		Pothole - approx 20m past Marks tey RBT				
A120	1585A120/467	WB	31/3	2	LWT	Potholes x 2				

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	11/03/2020		INSPECTORS:				ROUTE:	Bh01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00			
ROAD	LINK & SECTION	cw	МР	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
A120	1585A120/602	WB	48/6			Pothole - Gully Surr	ound				
A120	1585A120/602	WB	48/4		RWT	Pothole					
A120	1585A120/387	WB	21/8+50	1	RWT	Pothole					

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	18/03/2020		INSPECTORS:			ROUTE:		Bh01	CREW NAMES:		
VEHICLE:			START TIME:	07:00		FINISH TIM	ΛE:	14:00			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFECT			ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/568	WB				Panners exit slip - Pothole - 46013900	)				
A120	1585A120/586	WB				Felstead exit slip - Pothole - 4601390	7				
A120	1585A120/467	WB	31/9	1	LWT	Pothole - 46013906					
A120	1585A120/384	WB	22/2+80	1/2	CL	Pothole - Centre line - 46013899					
A120	1585A120/396	WB	19/9	3	RWT	Pothole - 46013903					
				•							
				•							

INSPECTION					HIGI	WAYS ENGLAND		MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	25/03/2020		INSPECTORS:			ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00		FINISH TIME:	14:00			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•						
A120	1585A120/632	EB	58/6			Very large pothole in Layby - 46038811				
A120	1585A120/643	EB	62/0+20	1	RWT	Pothole - 46038816				

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	01/04/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00		_	
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/396	WB	20/4+50	2	LWT	Pothole- 460675:	38				
A120	1585A120/200	WB	19/8	3	RWT	Pothole - 460675	72				
				•							

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	08/04/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:			08:30	FINISH TIME:	14:35			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	VAY)	
DATE:	15/04/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:		05:50		FINISH TIME:	13:17			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	CT		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				1							
				•							
				•							
				•							
				ı							
				1							
				•							
											<u> </u>

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	22/04/2020		INSPECTORS:		l		ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/302	EB	20/3	1	RWT	Pothole - 461316	60				
A120	1585A120/384	WB	22/4+50	1	RWT	Pothole - 46131659					
											1

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	29/04/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:			08:30	FINISH TIME:	14:30			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF	
A120	1585A120/580	WB	387	2	RWT	Pothole, lane 2 RWT Rayne					
A120	1585A120/464	WB	341	2	RWT	Pothole, lane 2 RWT Little Dunmow					
A120	1585A120/381	WB	237-50	1	LWT	Pothole, lane 1 LWT. Takeley					
A120	1585A120/381	WB	236-50	1	LWT	Pothole, lane 1 LWT. Takeley					
A120	1585A120/384	WB	231-90	1	RWT	Pothole, lane 1 RWT. Takeley					
				•							
				•							
				•							

								MAKE SAFE / REPAIR ( RING	NAY)	2
DATE:	06/05/2020		INSPECTORS:				ROUTE: BH01	CREWINANCA		
/EHICLE:			START TIME:			08:00	FINISH TIME: 14:35	•		
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	СТ	ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/384	WB	22. 9	1	LWT	Pothole, lane 1 LWT.	Takeley	1 × WAGIX	2030	2038
A120	1585A120/384	WB	22.3	2	LWT	Pothole, lane 2. Tal	reley	1 × VAFX	2040	204)
A120	1585A120/387	WB	21.8 +50	1	RWT	Pothole, lane 1 RWT. Takeley  Pothole, lane 2 LWT. Takeley		1 × VIAGIX 1 × VIAGIX 2 × VIAGIX 2 × VIAGIX	2050	2055
A120	1585A120/387	WB	21.5 + 50	2	LWT	Pothole, lane 2 LWT.	<b>Fakeley</b>	2 x varix	2055	2100
									:	

INSPECTION					HIGH	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	13/05/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	05:55			FINISH TIME:	13:06			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	т		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/617	WB	52/6	1	LWT	Pothole around twin Gully - J	ob 46188474				
A120	1585A120/387	WB	21/4+30	2	LWT	2 x Pothole - Job 4618	88475				
A120	1585A120/396	WB	20/0+90	1	LWT	Pothole - Job 46188	476				
A120	1500A120/200	WB	19/8	2	RWT	Pothole - Job 46188477					
A120	1500A120/200	WB	19/8+10	2	LWT	Pothole - Job 46188478					
A120	1500A120/200	WB	19/6	1	RWT	Pothole - Job 46188479					
A120	1500A120/200	WB	19/4+30	2	RWT	Pothole - Job 46188	480				
A120	1500A120/200	WB	19/2+40	2	RWT	Pothole - Job 46188	481				
A120	1500A120/200	WB	19/2+40	3	RWT	Pothole - Job 46188	482				
				•							
				•							
				1							
				•							
				•							
				•							

INSPECTION					HIGH	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	20/05/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	07:00	Track		FINISH TIME:	14:00			_
ROAD	LINK & SECTION	CW	MP	Lane	LWT	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1500A120/220	WB	18/9	1	LWT	Pothole - 462131	33				
				•							
											<u> </u>

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	27/05/2020		INSPECTORS:		1		ROUTE:	BH01 & AR03	CREW NAMES:		
VEHICLE:			START TIME:	07:00			FINISH TIME:	14:00			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
A120	1585A120/311	EB	22/6	1	Centre	Pothole - 462224	88				

INSPECTION					HIGH	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	03/06/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		06:40		FINISH TIME:	12:00		_	_
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	СТ		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/638	WB	61/6	1	LWT	Pothole Around Gully- job N	o. 46234430				
A120	1585A120/638	WB	61/2	1	LWT	Pothole Around Gully- job N	o. 46234433				
A120	1585A120/379	WB	23/8+50	2	LWT	Pothole- job No.46234434					
A120	1585A120/384	WB	22/2+90	1/2	Centreline	Pothole- job No.46234437					
A120	1585A120/113	EB	19/0+50	1	LWT	Pothole- job No.46234438					
A120	1585A120/113	EB	19/0+90	1	LWT	Pothole- job No.4623	4439				
A120	1585A120/220	EB	19/6	2	LWT	Pothole- job No.4623	4441				
A120	1585A120/311	EB	21/9+10	1	LWT	Pothole- job No.4623	4442				
A120	1585A120/311	EB	21/9+80	1	LWT	2 x Pothole - job No.46	234444				
A120	1585A120/326	EB	Exit slip	1	LWT	2 x Pothole - job No.46	234445				

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	10/06/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		05:50		FINISH TIME:	11:15		_	_
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/464	WB	34/2+20	1	LWT	Pothole - Job no. 462	41712				
A120	1585A120/384	WB	23/1+90	1	LWT	Pothole - Job no. 46241713					
A120	1585A120/384	WB	23/0+10	1	RWT	Pothole- Job no.46241714					
A120	1585A120/384	WB	22/2+80	1/2	Centreline	Pothole- Job no.46241715					
A120	1585A120/387	WB	21/5+20	2	RWT	Pothole- Job no.46241716					
A120	1500A120/200	WB	20/0+90	1	LWT	Pothole - Job no.4624	41717				
A120	1585A120/526	EB	46/3+50	1	LWT	2 x Potholes - Job no.46	5241718				
A120											
A120											
A120											

INSPECTION					HIGH	WAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	17/06/2020		INSPECTORS:				ROUTE:	AR03 & BH01	CREW NAMES:		
VEHICLE:			START TIME:		06:00		FINISH TIME:	13:15			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFEC	СТ		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/568	WB	Panners Exit Slip	1	Centre of lane & RWT	2 x Potholes- Job 4625	51188				
A120	1585A120/467	WB	32/7+80	1	LWT	Pothole- Job 46251	191				
A120	1500A120/376	WB	25/5+20	1	LWT	Pothole- Job 46251192					
A120	1500A120/220	WB	19/2+50	1 (Main Line)	RWT	Pothole- Job 46251193					
A120	1500A120/220	WB	19/1+80	1 (Main Line)	LWT	Pothole- Job 46251194					
A120	1500A120/220	WB	19/0+20	1 (Main Line)	LWT	Pothole- Job 46251	195				
	Line) BH01										
		•									
				İ							
				•							
		NB	44/0+50	1	LWT						

INSPECTION					HIGH	WAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	24/06/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		04.45		FINISH TIME:	10:35			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/635	WB	59/5	singles	LWT	Pothole - Job 46255	719				
A120	1585A120/662	WB	52/2	Layby	centre of Lane	Pothole - Job 46255	720				
A120	1585A120/473	WB	Dunmow South	On slip	RWT	Pothole - Job 46255	721				
A120	1585A120/411	EB	32/6+20	1	LWT	Pothole - Job 46255722					
A120	1585A120/632	EB	57/5	singles	LWT	Pothole - Job 46255723					
											<u> </u>
		<u> </u>									<u> </u>

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	01/07/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		<u>'</u>
VEHICLE:			START TIME:		05:55		FINISH TIME:	10:05			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/502	EB	39/8+50	1	LWT	Pothole - Job 46256	6682				
A120											
A120											
A120											
A120											
		•	•								
											<u> </u>
		+									
											<u> </u>

INSPECTION					HIGH	WAYS ENGLAND		MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	08/07/2020		INSPECTORS:			ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		07:00	FINISH TIME:	11:35			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/568	WB	Panners Exit slip	1	LWT & Centre of Lane	$2 \times Pothole 1 \times near top of slip LWT 1 \times near ADS sign centre of lane$	Job 46262156			
A120	1500A120/211	WB	19/6	1/2	centreline	2 x Potholes - Job 46262157				
A120	1585A120/379	ЕВ	23/6+90	2	centre of lane	Pothole - Job 46262158				
A120	1585A120/329	ЕВ	26/8+40	1	RWT	Pothole - Job 46262159				
A120										

INSPECTION					HIGH	WAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	/AY)	
DATE:	15/07/2020		INSPECTORS:			ROUTE:		AR03	CREW NAMES:		
VEHICLE:		_	START TIME:		07:30	FINISH TI	IME:	11:30			_
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFECT			ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/580	WB	38/8+50	1	LWT	Pothole - Job 46268360					
A120	1585A120/470	WB	30/9	1	LWT	Pothole - Job 46268362					
A120	1585A120/335	EB	27/6+70	1	LWT	Pothole - Job 46268366					
A120	1585A120/335	ЕВ	27/7+40	1	LWT & RWT	2 x Pothole - Job 46268367					
A120											
		_									
											1

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	22/07/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		05:30		FINISH TIME:	11:00			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFEC	CT .		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/373	WB	25/8	1	Rwt	2 x Pothole - Job 4627	5662				
A120	1500A120/50	WB	19/1+80	2	LWT	Pothole - Job 46275	663				
A120	1500A120/50	WB	19/0+30	2	LWT	Pothole - Job 46275	664				
A120	1500A120/50	WB	19/0+80	2	LWT	Pothole - Job 46275665					
A120	1585A120/632	EB	58/1	1	LWT	Pothole around gully - Job 46275666					
A120	1585A120/638	EB	60/2	1	LWT	Pothole around gully - Job 46275667					
											<u> </u>
											<u> </u>

INSPECTION					HIGH	WAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	VAY)	
DATE:	29/07/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:		_	START TIME:		07.15		FINISH TIME:	12:15			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	СТ		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/573	WB	See Attached map	1	Centre of lane	Pothole - Job 46276	985				
A120	1585A120/379	WB	23/8+20	Exit	in Layby	Pothole - Job 46276	986				
A120	1585A120/379	WB	23/8+30	2	LWT	Pothole - Job 46276	987				
											<u> </u>
											<u> </u>

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	05/08/2020		INSPECTORS:		1		ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	08:00			FINISH TIME:	12:00		_	
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
						No safety defects ra	ised.				

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	12/08/2020		INSPECTORS:				ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	08:00			FINISH TIME:	12:00			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
						No safety defects ra	ised.				

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	19/08/2020		INSPECTORS:		1		ROUTE:	BH01	CREW NAMES:		
VEHICLE:			START TIME:	08:00			FINISH TIME:	12:00			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				•							
				•							
				•							

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	26/08/2020		INSPECTORS:		<u> </u>		ROUTE:	BH01 & AR03	CREW NAMES:		
VEHICLE:			START TIME:	08:00			FINISH TIME:	14:30			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/379	WB	23/2+80	1	LWT	Pothole - 462836	600				

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	05/08/2020		INSPECTORS:			RO	OUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		05.45	FIN	NISH TIME:	09:15			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT			ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/638	WB	60/3	1	LWT	Pothole around Gully just before Bus stop/layby near I	Poplar nurserie	es - Job 46279921			
A120	1585A120/376	WB	25/4+60	1	LWT	Pothole - Job 46279923	3				
A120	1585A120/379	WB	24/2+10	1	RWT	Pothole - Job 46279924	4				
		+									

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	WAY)	
DATE:	12/08/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		06:00		FINISH TIME:	09:30			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				No defe	ects from today's	s inspection of AR03					
										†	
			-							+	<del>                                     </del>
											—

INSPECTION					HIGH	WAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	19/08/2020		INSPECTORS:			RC	OUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		05:50	FIN	NISH TIME:	09:15			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT			ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/638	WB	60/2	Singles	centre of Lane	Pothole around Manhole cover- jo	ob 46283308				
A120	1585A120/376	WB	25/4+70	1	LWT	Pothole - Job 4628331	.1				
A120	1585A120/384	WB	23/2+80	1	LWT	Pothole - Job 46283312					
A120	1585A120/387	WB	21/8+40	1	RWT	Pothole - Job 46283314					
A120	1585A120/308	EB	21/8+10	1	LWT	Pothole - Job 46283316					
A120	1585A120/329	EB	27/4+90	2	RWT	Pothole - Job 4628331	7				
A120											

INSPECTION					HIGI	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGW	/AY)	
DATE:	26/08/2020		INSPECTORS:		ı		ROUTE:	BH01 & AR03	CREW NAMES:		
VEHICLE:			START TIME:	08:00			FINISH TIME:	14:30			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/379	WB	23/2+80	1	LWT	Pothole - 462836	00				
											<u> </u>

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RING	WAY)	
DATE:	02/09/2020		INSPECTORS:			R	OUTE:	AR03 + BH01	CREW NAMES:		
VEHICLE:			START TIME:		05:50	F	INISH TIME:	14:45			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT	Г		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
					A120 No Defe	cts today.					
	•				M11						
				ı							
		•		•							
		•		1							
				•							
				•							
				ı							

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	VAY)	
DATE:	09/09/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		05:50		FINISH TIME:	10:00			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
				No defe	ects from today's	s inspection of AR03					
										†	
										$\vdash$	
										——	
										$oxed{oxed}$	

INSPECTION					HIGH	WAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	WAY)	
DATE:	16/09/2020		INSPECTORS:			RO	OUTE:	AR03	CREW NAMES:		
'EHICLE:			START TIME:		06:15	FIN	NISH TIME:	11:15			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT			ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OI
A120	1585A20/602	WB	48/1+60	1	LWT	Pothole around Gully- Job No.4	46284484				
A120	1585A20/602	WB	47/9	1	LWT	Pothole around Gully- Job No.4	46284485				
A120	1585A120/302	ЕВ	20/2+70	2	RWT	Pothole - Job No.46284486					
A120	1585A120/311	EB	22/7+70	1	LWT	Pothole - Job No.46284487					
A120	1585A120/311	ЕВ	22/8+60	1	LWT	Pothole - Job No.46284488					
A120	1585A120/323	ЕВ	24/9+20	2	RWT	Pothole - Job No.462844	491				
A120	1585A120/323	ЕВ	24/9+30	2	LWT	Pothole - Job No.462844	492				
A120	1585A120/323	EB	25/2+70	1/2	centreline	Pothole - Job No.462844	493				

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	WAY)	
DATE:	23/09/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		06:45	Weather :- wet Road :- wet	FINISH TIME:	10:15			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEF	ЕСТ		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/470	WB	30/5+20	1	RWT	Pothole- Job No.462	91604				
A120	1585A120/329	EB	26/9+20	1	LWT	Pothole- Job No.462	91606				

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	WAY)	
DATE:	30/09/2020		INSPECTORS:		J Ward		ROUTE:	AR03	CREW NAMES:		-
VEHICLE:	KV69VYY		START TIME:		06:45	Weather :- dry Road :- dry	FINISH TIME:	11:30			_
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFI	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/602	WB	48/0+50	1	LWT	Pothole Singles- Job No.	46291990				
A120	1585A120/470	WB	30/5+10	1	RWT	Pothole- Job No.462	91991				
A120	1585A120/329	EB	27/1+10	1	LWT	Pothole - Job No.46291992					
A120	1585A120/349	EB	Exit Slip	1	LWT	Dunmow South Exit Slip - Pothole- Job No. 46291994					

INSPECTION					HIG	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	VAY)	
OATE:	07/10/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
'EHICLE:		_	START TIME:		06:55	Weather :- dry Road :- dry	FINISH TIME:	11:15			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME O
A120	1585A120/635	WB	58/5+50	1	LWT	Pothole Singles - Job No.	46295851				
A120	1585A120/580	WB	40/1+40	2	RWT	Pothole- Job No.462	95852				
A120	1585A120/580	WB	39/9+10	2	LWT	Pothole - Job No.46295857					
A120	1585A120/580	WB	38/7+50	1	LWT	Pothole - Job No.46295858					
A120	1585A120/464	WB	34/2+20	1	LWT	Pothole - Job No.46295859					
A120	1585A120/352	WB	28/4+90	-	CRES	Clear CRES Gully top - Job N	lo.46295860				
A120	1585A120/396	WB	20/9+60	2	LWT	Pothole - Job No.462	95861				
A120	1585A120/396	WB	20/5+40	2	RWT	Pothole - Job No.462	95862				
A120	1585A120/396	WB	19/9+50	3	RWT	Pothole - Job No.462	95863				
A120	1585A120/396	WB	19/9+50	1	LWT	Pothole - Job No.462	95864				
A120	1585A120/502	EB	40/0+50	1	LWT	Pothole - Job No.462	95865				

INSPECTION					HIGH	HWAYS ENGLAND			MAKE SAFE / REPAIR ( RING)	VAY)	
DATE:	14/10/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		·
VEHICLE:			START TIME:		09:15	Weather :- cloudy/dry Road :- Wet	FINISH TIME:	12:35			_
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/464	WB	34/2+20	2	RWT	Pothole - Job 4629	5249				
A120	1585A120/411	EB	32/5	1	LWT	3 x Potholes within same patch	n- Job 46296250				
A120	1585A120/502	EB	39/8+60	1	LWT	Pothole - Job 46296251					
A120	1585A120/502	EB	40/4+20	2	Centerline	Pothole - Job 46296252					

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
ATE:	21/10/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
EHICLE:			START TIME:		07:27	Weather :- Heavy Rain Road :- Very wet	FINISH TIME:	11:35			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	СТ		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OF
A120	1585A120/308	ЕВ	21/5	2	LWT	Pothole - Job No.462	96592				
A120	1585A120/659	ЕВ	54/9	1	RWT	Pothole Singles - Job No.	46296593				
A120	1585A120/659	EB	55/2	1	Centre of Lane	Pothole Singles - Job No.	46296594				

INSPECTION					HIGH	IWAYS ENGLAND			MAKE SAFE / REPAIR ( RINGV	VAY)	
DATE:	28/10/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:		
VEHICLE:			START TIME:		06:45	Weather :- DRY Road :- wet	FINISH TIME:	10:30			
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	СТ		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
A120	1585A120/352	WB	28/4++80	2	CRES	2 x Gully tops please clear - Jo	No. 46296977				
A120	1585A120/384	WB	22/0+50	1	RWT	Pothole- Job No.4629	06979				
A120	1585A120/659	EB	54/9	1	RWT	Pothole Singles - Job No.46296980					
A120	1585A120/659	EB	55/2	1	Centre of Lane	e Pothole Singles - Job No.46296981					
		1									
											<u> </u>
		_									
											<u> </u>

INSPECTION				MAKE SAFE / REPAIR ( RINGWAY)							
DATE:	04/11/2020		INSPECTORS:			ROUTE: BH01		CREW NAMES:			
VEHICLE:			START TIME: 08:00			FINISH TIME: 14:00					
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFECT		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF	
A120	AR03					No safety defetcs found.					

INSPECTION					MAKE SAFE / REPAIR ( RINGWAY)						
DATE:	11/11/2020		INSPECTORS: ROUTE:					AR03	CREW NAMES:		
VEHICLE:			START TIME: 06:45 Weather :- Heavy Rain Road :- Very wet			Weather :- Heavy Rain Road :- Very wet	FINISH TIME:	11:35			
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF
											<u> </u>

INSPECTION	HIGHWAYS ENGLAND								MAKE SAFE / REPAIR ( RINGWAY)			
DATE:	18/11/2020		INSPECTORS:				ROUTE:	AR03	CREW NAMES:			
'EHICLE:			START TIME:		07:05	Weather :- Sunny Road :- Dry	FINISH TIME:	10:45				
ROAD	LINK & SECTION	CW	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OF	
A120	1585A120/602	WB	48/6+75	1	RWT	3 X Potholes- Job No.46299893						
A120	1585A120/602	WB	48/5+40	1	RWT	Pothole- Job No.46299894						
A120	1585A120/370	WB	25/8+60	1	RWT	2 x Potholes- Job No.46299895						
A120	1585A120/308	EB	21/4+30	2	LWT	Pothole- Job No.46299896						
A120	1585A120/402	ЕВ	30/3	1	LWT	Pothole- Job No.46299898						
A120	1585A120/502	EB	39/8+50	1	LWT	Pothole- Job No.46299899						
A120	1585A120/621	EB	55/2	1	Centre of Lane	Pothole- Job No.46299900						

INSPECTION					MAKE SAFE / REPAIR ( RINGWAY)							
DATE:	25/11/2020		INSPECTORS:				ROUTE: AR03	AR03	CREW NAMES:			
VEHICLE:			START TIME: 07:25 Weather :- Overcast Road :- Dry			Weather :- Overcast Road :- Dry	FINISH TIME:	10:35				
ROAD	LINK & SECTION	cw	MP	Lane	Track	LOCATION / DEFE	ст		ON-SITE ACTION TAKEN & MATERIALS USED	TIME ON	TIME OFF	
						No Defects Toda	<u>y.</u>					
											<u> </u>	
											<del>                                     </del>	
			-									
			-									