




Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

---



Our Reference:  
FOI2021/00221  
Date:  
2 March 2021

---

Dear 

I am writing about your email of 7 January 2021, requesting the following information:

***I would like to find the service history, for three vehicles that have recently left MOD service. Any other information on the regiments they served in etc would be gratefully appreciated.***

***-Land Rover Discovery chassis number SALLTGM97YA279195 civilian reg x966jke.  
-Yamaha Grizzly 450 PTL, chassis number 517238, in service reg number NA80AB  
-Land Rover Defender Wolf TUM HS GS chassis number SALLDBA67WA142125***

Your request has been handled in accordance with the Freedom of Information (FOI) Act 2000.

A search has been carried out of Ministry of Defence (MOD) records and unfortunately we do not hold any information for the Land Rover Discovery Reg X996JKE. However, it is confirmed that some information is held on the other two vehicles that can be released. This is enclosed, as follows:

Annex A - MB70AA TFR  
Annex B - MB70AA Fault History (redacted)  
Annex C - MB70AA Inspection History  
Annex D - MB70AA Modifications History (redacted)  
Annex E - MB70AA Service History  
Annex F - NA80AB Vehicle History (redacted)  
Annex G - NA80AB Fault History  
Annex H - NA80AB Inspection History  
Annex I - NA80AB Modifications History  
Annex J - NA80AB Service History

It has proved necessary to withhold some information related to your request. This is some of the NA80AB Vehicle Usage History (Annex F), relating to vehicle equipment which has been redacted under qualified exemptions Section 26(1)(a) and (b) (Defence) and Section 38(1)(a) and (b) (Health and Safety) of the FOI Act. Commercially sensitive information in the MB70AA Fault History (Annex B) and MB70AA Modifications History (Annex D), relating to contractor repair times, has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 26 applies to information that if disclosed would or would likely; prejudice the defence of the British Islands or any colony; and/or the capability, effectiveness or security of the Armed Forces of the Crown or any forces cooperating with them. Section 38 applies to information that if disclosed would or would likely; endanger the physical or mental health of any individual; or endanger the safety of any individual. Section 43 concerns information which if disclosed would or would likely; prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As these exemptions are qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release.

However, releasing the details of equipment fitted to NA80AB in the Vehicle Usage History (Annex F) would divulge information that could be used to compromise the ability of UK Armed Forces to carry out operations safely. Namely, by revealing information about vehicle modifications which could assist adversaries to plan attacks against equipment and endanger the lives of personnel.

The Fault History (Annex B) and Modifications History (Annex D) also provide details of the time taken by MOD contractors to rectify fault reports on MB70AA. This data, along with previously published information, could be used to make reasonable assumptions about hourly labour rates. As market sensitive information, this could then be exploited by commercial competitors to undercut the contractor when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld. The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail [CIO-FOI-IR@mod.gov.uk](mailto:CIO-FOI-IR@mod.gov.uk)). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely

DE&S Secretariat

## Equipment Transfer History

Report Date: 12 Jan 2021

Start Date

End Date

Equipment Description	ERM/Ser No.	UII	Holding Unit	Holding UIN	Days Held	Transfer IN Date	Reason for Transfer (IN)	Transfer Out Date	Reason for Transfer (Out)
TUM HS GS SOFT TOP	MB70AA		DMC (TFR)	Z0003Z		12 Mar 2019	000000-00082F59 TRANSFER		
TUM HS GS SOFT TOP	MB70AA		WSBA 2 YORK	A0567A	-6	19 Aug 2011	000000-00007A5E TRANSFER	12 Mar 2019	000000-00082F59 TRANSFER
			2 LANCS MT	A0558A				19 Aug 2011	000000-00007A5E TRANSFER

Total Transfers IN	2
Total Transfers OUT	2

Work Objects

Serial Number: MB7DAA  
NSN: 2320998939963

Criteria:  
Repair Level: ALL  
Work Object Status: Closed  
Mission Impact: ALL  
Fault State: ALL  
Escalate Work: ALL  
Work Request ID:  
Assigned Work Status: ALL  
Working Organisation:  
Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B20A6E		SNV 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00B235E9		SNV377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00ACBD88		MOD 30 (SEATBELT PROTECTION SLEEVES) NOT FITTED	Closed	Fully Fit	No	Level 1		23 Jul 2018	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00AEC252		BULK HEAD CORRODED	Closed	Non-Taskworthy	No	Level 2		23 Oct 2018	N/A	Failure	TUM HS GS SOFT TOP			
000000-00AB0C63		REPLACE CANOPY	Closed	Fully Fit	No	Level 1		13 May 2018	N/A	Damage	TUM HS GS SOFT TOP			000:00
000000-00AC8363		BOTH DOOR HANDLES MISSING	Closed	Fully Fit	No	Level 1		12 Jul 2018	N/A	Damage	TUM HS GS SOFT TOP			
000000-00AG5F12		mod 41	Closed	Fully Fit	No	Level 2		18 Oct 2017	N/A	Modification	TUM HS GS SOFT TOP			000:00
000000-0098A635		DVR DOOR TRIM DAMAGED	Closed	Fully Fit	No	Level 1		21 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			000:00
000000-00ACBD47		FRONT ANTI-ROLL BAR BALL JOINT BOOTS PERISHED	Closed	Fully Fit	No	Level 2		23 Jul 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00ACBD45		SEEPAGE @ POWER STEERING PUMP	Closed	Fully Fit	No	Level 2		23 Jul 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00AB2A86		NO 5 BALL JOINT DAMAGED.	Closed	Fully Fit	No	Level 2		16 May 2018	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00A9A48B		FRONT ANTI-ROLL BAR BUSHES PERISHED.	Closed	Fully Fit	No	Level 2		05 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00AB2A80		FRONT PROP HAS EXCESSIVE PLAY.	Closed	Non-Taskworthy	No	Level 2		16 May 2018	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00AB2A99		FRONT ANTI-ROLL BAR BUSHES DAMAGED.	Closed	Fully Fit	No	Level 2		16 May 2018	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00AA41E6		CALIPER BOLT DAMAGED.	Closed	Fully Fit	No	Level 2		04 Apr 2018	N/A	Failure	TUM HS GS SOFT TOP			000:00
000000-00A9A48B		BONNET RELEASE CATCH DAMAGED.	Closed	Fully Fit	No	Level 2		05 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A25129		TOWING PINTLE U/S	Closed	Limited Role	No	Level 2		16 May 2017	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A9A4A6		ALTERNATOR BREATHER MISSING.	Closed	Fully Fit	No	Level 2		05 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A9B9CB		FUEL LEAK AT ENGINE.	Closed	Non-Taskworthy	No	Level 2		07 Mar 2018	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0098A080		PIPE FROM BOTTOM OF VEH ALT NOT CONNECTED	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Non Specific	TUM HS GS SOFT TOP			000:00
000000-00A1A135		BONNET RELEASE CATCH DAMAGED	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-0098ABF0		MDDS 40, 41 & 29 NOT FITTED	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Modification	TUM HS GS SOFT TOP			000:00
000000-00A1A103		DVR DOOR EARTH STRAP SNAPPED	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-0098A738		PSGR DOOR LOCK INOP(DO NOT CARRY OUT Rep Act UNTIL DVRs DOOR HAS BEEN REPLACED)	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			000:00
000000-0098A68F		FRONT ROLL BAR BUSHES STARTING TO PERISH	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			000:00
000000-0098A566		RUBBER GROMMITS BATTERY BOX MISSING	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			000:00
000000-0097778E		OBS-DENT IN REAR L/H BUMPER	Closed	Fully Fit	Yes	Level 2		02 Mar 2016	N/A	Damage	TUM HS GS SOFT TOP			000:00
000000-0097718D		FUEL AND TEMP GUAGE LIGHTS U/S	Closed	Fully Fit	Yes	Level 2		02 Mar 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			000:00
000000-00A43234		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-00004550	30 Jul 2017	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00A56E72		INVESTIGATE INJECTOR PIPE LEAK AT FUEL PUMP LIFT	Closed	Non-Taskworthy	No	Level 2		14 Sep 2017	N/A	Damage	TUM HS GS SOFT TOP			
000000-00A1A104		REPLACE RADIATOR, 1/2 FINS MISSING	Closed	Limited Role	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-009851A3		OBS-REAR CANOPY WINDOW STARTING TO RIP	Closed	Fully Fit	No	Level 1		07 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0098A5FC		DASH TRIM DAMAGED	Closed	Fully Fit	No	Level 1		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A560		VEH BATTERY BOX SECURING CATCH U/S	Closed	Fully Fit	No	Level 1		20 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098ABEC		FIT SPARE TYRE EXTENSION VALVE /PART FITTED CANT CLOSE FAULT DUE TO LIVE DEMAND	Closed	Fully Fit	No	Level 1		19 Apr 2016	N/A	Modification	TUM HS GS SOFT TOP			
000000-008CB8C1		RUBBER COMING OFF FRONT AIRVENT UNDERNEATH WINDSCREEN	Closed	Fully Fit	No	Level 1		11 Oct 2015	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00A1A112		REAR SHOCKS LOOSE	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A10F		A-FRAME BJ BOOT SPLIT	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A10D		PLAY IN BOLT @ R/H TIE ROD	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A106		ND1 BJ BOOT SPLIT	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A114		PLAY IN REAR R/H SHOCK TOP BUSH	Closed	Non-Taskworthy	No	Level 2		20 Apr 2017	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00A1A115		EXCESSIVE PLAY IN FRONT LEFT HUB	Closed	Non-Taskworthy	No	Level 2		20 Apr 2017	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00A1A108		REAR PROP BOLTS LOOSE	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A10A		REPLACE FRONT SHOCK BUSHES	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A109		STEERING BOX MOUNTS LOOSE	Closed	Fully Fit	No	Level 2		20 Apr 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1A107		STEERING DROP ARM LOOSE	Closed	Non-Taskworthy	No	Level 2		20 Apr 2017	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00995B33		FIRE EXTINGUISHER OUT OF DATE	Closed	Limited Role	No	Level 1		22 May 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00995B33		REPLACE FIRE EXTINGUISHER (PAST SHELF LIFE)	Closed	Limited Role	No	Level 1		24 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-009E6384		OOPM TIMING BELT CHANGE	Closed	Fully Fit	No	Level 2		23 Nov 2016	N/A	Service	TUM HS GS SOFT TOP			
000000-0098A072		LH JERRYCAN SECURING STRAP SEIZED	Closed	Fully Fit	No	Level 1		19 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00A0B128		PLEASE CARRY OUT 2 YRLY OIL CHANGE AND OIL FILTER AND AIR FILTER CHANGE IAW 2320-D-128 TABLE S	Closed	Fully Fit	No	Level 1		12 Mar 2017	N/A	Service	TUM HS GS SOFT TOP			
000000-0098CA02	000000-003219C0	DRIVERS DOOR FRAME RUSTED THROUGH U/S	Closed	Fully Fit	No	Level 2		25 Apr 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-009E4CFA	000000-00320250	ACCELERATOR RETURN SPRING SNAPPED	Closed	Fully Fit	No	Level 2		21 Nov 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-00984DE3		BATTERIES FLAT/PARTS FITTED CANT CLOSE DUE TO LIVE DEMAND	Closed	Fully Fit	No	Level 1		24 Jul 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-0098AC07		TOW STROP REQ'S INSPECTING	Closed	Limited Role	No	Level 2		20 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0098A6DB		FIT HAMMER MOD	Closed	Fully Fit	No	Level 1		21 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00981828	000000-0031A57D	INVESTIGATE INSTRUMENT CLUSTER	Closed	Non-Taskworthy	No	Level 2		19 Jul 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-00981823	000000-0031A57D	INVESTIGATE LOSS OF POWER	Closed	Non-Taskworthy	No	Level 2		19 Jul 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-00977195		BOTH DVR AND PASSENGER DOOR HANDLES MISSING/PARTS FITTED (LIVE DEMAND STILL ON)	Closed	Fully Fit	No	Level 1		03 Mar 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-009A0025	000000-00318B1D	INVESTIGATE 6 WAY SWITCH U/S	Closed	Non-Taskworthy	No	Level 2		15 Jun 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00985194		DEMAND REAR CANOPY BUNGEE FASTENERS	Closed	Fully Fit	No	Level 1		07 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00985197		REPLACE REAR VIEW MIRROR	Closed	Fully Fit	No	Level 1		07 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00985190		REPLACE SEAT BACK COVER	Closed	Fully Fit	No	Level 1		07 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00982E68		FIT MISSING FUSE BOX LID SCREW	Closed	Fully Fit	No	Level 1		31 Mar 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098ABF9	000000-00317363	RE-CERT BY 19/05/2016 OR RE-ME1	Closed	Fully Fit	No	Level 2		20 Apr 2016	N/A	Inspection	TUM HS GS SOFT TOP			
000000-0098BD0E		DEMAND BATTERIES	Closed	Fully Fit	No	Level 1		20 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-00985192		REPLACE SEAT BASE COVER	Closed	Fully Fit	No	Level 1		07 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A07B		PASSENGER DOOR SEAL MISSING	Closed	Fully Fit	No	Level 1		20 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A6D1		FIT BONNET PROP BAR GROMMET	Closed	Fully Fit	No	Level 1		21 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A0AD	000000-0030D4EE	REAR BRAKE PADS LOW	Closed	Non-Taskworthy	No	Level 2		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A089	000000-0030D4EE	No 2 BALL JOINT BOOT SPLIT	Closed	Non-Taskworthy	No	Level 2		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-008CB888	000000-0030D4EE	OBSERVE OIL SEEPAGE AT BOTH TRACTA SEAL	Closed	Fully Fit	Yes	Level 2		11 Oct 2015	N/A	Failure	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET	
000000-0098A566		RH SPARE WHEEL ADAPTER PLATE NOT FITTED	Closed	Fully Fit	No	Level 2		20 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0098A592		FAN BELT WEARING MORE ONE SIDE	Closed	Non-Taskworthy	No	Level 2		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A5E6		AIR FILTER BRACKET LOOSE	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Refurbishment	TUM HS GS SOFT TOP			
000000-0098A56A		DIP BEAM LIGHTS INOP	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-0098A0B9		HEATER DOESNT BLOW ON MAX	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-0098A0B4		DASH LOOSE	Closed	Fully Fit	No	Level 2		19 Apr 2016	N/A	Non Specific	TUM HS GS SOFT TOP			
000000-0098A0A9		RH BOTTOM TOPLINK LOOSE	Closed	Non-Taskworthy	No	Level 2		20 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0098A080		INV OIL LEAK AT R/H/S OF ENGINE	Closed	Non-Taskworthy	No	Level 2		19 Apr 2016	N/A	Non Specific	TUM HS GS SOFT TOP			
000000-0098A068		DVR'S DOOR DOESNT CLOSE	Closed	Non-Taskworthy	No	Level 2		19 Apr 2016	N/A	Non Specific	TUM HS GS SOFT TOP			
000000-00977191	000000-00315157	DRIVER SEAT BELT BUCKLE OLTER COVER MISSING	Closed	Fully Fit	Yes	Level 2		02 Mar 2016	N/A	Refurbishment	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET	
000000-009769FD	000000-00315157	INVESTIGATE FRONT PROPSHAFT	Closed	Fully Fit	Yes									

00000-008A78E6	FIT MISSING DUST CAPS	Closed	Fully Fit	No	Level 1	05 Jul 2015	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-0095DDC0	REPAIR/REPLACE SPARE TYRE	Closed	Limited Role	No	Level 1	13 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-009491CD	RENEW FRONT LEFT TYRE, TYRE FITTED, CANT CLOSE DUE TO LIVE DEMAND STILL ON	Closed	Fully Fit	No	Level 1	04 Jan 2016	N/A	Inspection	TUM HS GS SOFT TOP		
00000-00968CE4	Clutch release bearing seized	Closed	Fully Fit	No	Level 2	02 Feb 2016	N/A	Failure	TUM HS GS SOFT TOP		
00000-00960C7F	Check No2 ball joint torque tightness as per safety notice LE SNVE 00063	Closed	Non-Taskworthy	No	Level 2	19 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-009491E2	NO SPARE WHEEL FITTED	Closed	Limited Role	No	Level 1	04 Jan 2016	N/A	Inspection	TUM HS GS SOFT TOP		
00000-008E3A9F	RAIUS ARM BUSHES PERISHED	Closed	Fully Fit	No	Level 2	08 Dec 2015	N/A	Failure	TUM HS GS SOFT TOP		
00000-008E3A8B	RENEW PANARD ROD	Closed	Fully Fit	No	Level 2	08 Dec 2015	N/A	Failure	TUM HS GS SOFT TOP		
00000-008E3272	RENEW STEERING DAMPER	Closed	Fully Fit	Yes	Level 2	07 Dec 2015	N/A	Failure	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET
00000-008DBADE	REPLACE FRONT LEFT TYRE	Closed	Non-Taskworthy	No	Level 1	11 Nov 2015	N/A	Refurbishment	TUM HS GS SOFT TOP		
00000-008DBA14	INVESTIGATE TRACKING, SEVERE WHEEL VIBRATION WHEN DRIVEN AT 50KPH	Closed	Fully Fit	Yes	Level 2	11 Nov 2015	N/A	Failure	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET
00000-008D38C6	L/H SIDE LIGHT U/S	Closed	Non-Taskworthy	No	Level 1	29 Oct 2015	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-008D2BFF	INVESTIGATE VIBRATION WHILE DRIVING	Closed	Fully Fit	Yes	Level 2	27 Oct 2015	N/A	Failure	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET
00000-008D2C02	INVESTIGATE KNOCKING NOISE WHEN BRAKING	Closed	Fully Fit	Yes	Level 2	27 Oct 2015	N/A	Failure	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET
00000-008CB8B4	FRONT RIGHT HUB SEAL MISSING	Closed	Fully Fit	No	Level 1	11 Oct 2015	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-008CB6C9	carry out 6534	Closed	Fully Fit	No	Level 1	11 Oct 2015	N/A	Inspection	TUM HS GS SOFT TOP		
00000-008CA58	REPLACE TAILGATE WIRE	Closed	Fully Fit	No	Level 1	20 Sep 2015	N/A	Refurbishment	TUM HS GS SOFT TOP		
00000-008A78EC	DRIVERS DOOR HANDLE MISSING	Closed	Fully Fit	No	Level 1	05 Jul 2015	N/A	Servicing	TUM HS GS SOFT TOP		
00000-008A78E4	FIT MISSING TOW PIN	Closed	Fully Fit	No	Level 1	05 Jul 2015	N/A	Servicing	TUM HS GS SOFT TOP		
00000-00893E86	please investigate steering box leak	Closed	Fully Fit	Yes	Level 2	12 May 2015	N/A	Failure	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET
00000-008880C2	PLEASE INSPECT BOTH ANTI ROLL BAR BUSHES	Closed	Fully Fit	No	Level 2	08 Apr 2015	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-00866968	Please rectify relays overheating fault	Closed	Fully Fit	Yes	Level 2	15 Jan 2015	N/A	Non Specific	TUM HS GS SOFT TOP	JES DET (W)	GREEN FLEET
00000-0083C1FB	PLEASE RNEW F/L/H PLASTIC WHEEL ARCH EXTENSION	Closed	Fully Fit	No	Level 2	25 Sep 2014	N/A	Damage	TUM HS GS SOFT TOP		
00000-0079AA66	RE-FIT NEAR SIDE BODY SKIRT	Closed	Fully Fit	No	Level 2	25 Sep 2013	N/A	Damage	TUM HS GS SOFT TOP		
00000-007DD938	HAND BRAKE WARNING LIGHT INOP	Closed	Fully Fit	No	Level 2	15 Jan 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-0083C1F6	PLEASE FIT MISSING SERVO VACUUM PIPE	Closed	Fully Fit	No	Level 2	24 Sep 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-0084DC09	RENEW RADIUS ARM BUSHES	Closed	Fully Fit	No	Level 2	29 Oct 2014	N/A	Inspection	TUM HS GS SOFT TOP		
00000-0083C1E7	PLEASE REPLACE ALTERNATOR	Closed	Fully Fit	No	Level 2	24 Sep 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-00844864	Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	09 Oct 2014	Degraded	Inspection	TUM HS GS SOFT TOP		
00000-0083C1ED	PLEASE REPLACE R/H HEADLAMP GAURD	Closed	Fully Fit	No	Level 2	25 Sep 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-007C9B00	REPLACE ROCKER COVER SEAL	Closed	Fully Fit	No	Level 2	31 Oct 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-00789A9D	SEVERIAL DASH WARNING LIGHTS INTERMITTEN	Closed	Fully Fit	No	Level 2	25 Sep 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-00789A45	FIT MISSING DOOR CARD ON DRV SIDE	Closed	Fully Fit	No	Level 2	25 Sep 2013	N/A	No Fault Found	TUM HS GS SOFT TOP		000:00
00000-00789A9A	FREE OFF FAN CONTROLS	Closed	Fully Fit	No	Level 2	25 Sep 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-00789A93	LEFT HAND SIDE OF FRONT BUMPER BENT	Closed	Fully Fit	No	Level 2	25 Sep 2013	N/A	Damage	TUM HS GS SOFT TOP		
00000-007E6925	vehicle btys are us dmd	Closed	Fully Fit	No	Level 2	06 Feb 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-007DD956	RENEW BOTH FRONT SEAT BELTS VERY CLOSE TO FAILURE	Closed	Fully Fit	No	Level 2	15 Jan 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-007DD93E	SIDE LIGHT WARNING LIGHT INOP	Closed	Fully Fit	No	Level 2	15 Jan 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-007DD934	REFIT INSIDE L/H DOOR HANDLE	Closed	Fully Fit	No	Level 2	15 Jan 2014	N/A	Failure	TUM HS GS SOFT TOP		
00000-007C9AFA	VEHICLE HORN INOP	Closed	Non-Taskworthy	No	Level 2	31 Oct 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-007C9AF8	MAIN LIGHT ON VEHICLE ARE INOP (FUSE CHECKED)	Closed	Non-Taskworthy	No	Level 2	31 Oct 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-007C9AFD	REPLACE FRONT LEFT TRACTER SEAL	Closed	Non-Taskworthy	No	Level 2	31 Oct 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-007C8152	PLEASE FIX OR REPLACE SPARE TYRE	Closed	Non-Taskworthy	No	Level 2	31 Oct 2013	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-007889E6	PLEASE CARRY OUT YEARLY SERVICE IAW AESP 2320-D-128-601	Closed	Non-Taskworthy	No	Level 2	12 Nov 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-007889E7	PLEASE CARRY OUT YEARLY VM TASKS IAW AESP 2320-D-128-601	Closed	Fully Fit	No	Level 1	24 Sep 2013	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-007889E4	PLEASE CARRY OUT MEI IAW AESP 2300-A-050-013	Closed	Fully Fit	No	Level 1	24 Sep 2013	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-007855C1	Replace Component	Closed	Fully Fit	No	Level 1	24 Sep 2013	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-00785387	REPLACE NUMBER PLATE LIGHT COMPLETE	Closed	Fully Fit	No	Level 2	13 Sep 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0078538D	REPLACE SPEEDO AS THE LIGHT FITTINGS ARE BROKEN	Closed	Fully Fit	No	Level 2	13 Sep 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0079EACD	PLEASE INVESTIGATE BLACK SMOKE WHILE DRIVING	Closed	Fully Fit	No	Level 2	04 Jul 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00793A95	PLEASE INVESTIGATE STEERING NOT SELF CENTERING	Closed	Fully Fit	No	Level 2	13 Jun 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00799130	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	23 Jun 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-0079C0D8	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	25 Jun 2013	N/A	Inspection	TUM HS GS SOFT TOP		
00000-007687CD	PLEASE CARRY OUT REMUS MOD 39	Closed	Fully Fit	No	Level 2	19 Feb 2013	N/A	Closed No Action	TUM HS GS SOFT TOP		
00000-00784E2C	PLEASE INVESTIGATE STEERING	Closed	Fully Fit	No	Level 2	01 May 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00786427	PLEASE REPLACE F/R TYRE	Closed	Non-Taskworthy	No	Level 2	06 May 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-00784E43	PLEASE REPLACE THE SPARE TYRE	Closed	Non-Taskworthy	No	Level 2	30 Apr 2013	N/A	Failure	TUM HS GS SOFT TOP		
00000-0077E83D	PLEASE REPLACE 4X TYRES	Closed	Fully Fit	No	Level 2	14 Apr 2013	N/A	Inspection	TUM HS GS SOFT TOP		
00000-0077CCE9	VEH DOES NOT SELECT 3RD GEAR	Closed	Fully Fit	No	Level 2	09 Apr 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0077CCE9	RENEW BOTH TRACTA SEALS	Closed	Fully Fit	No	Level 2	09 Apr 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0077CCF3	RENEW ALL BRAKE PADS	Closed	Fully Fit	No	Level 2	09 Apr 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0077841C	PLEASE CARRY OUT 6MTHLY SERVICE IAW AESP 2320-D-128-601 TABLE 7	Closed	Fully Fit	No	Level 1	22 Mar 2013	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-0077841E	PLEASE CARRY OUT 6534 INSP IAW AESP 2320-D-128-601	Closed	Fully Fit	No	Level 1	22 Mar 2013	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-00778421	PLEASE CARRY OUT 6MTHLY VM TASKS IAW AESP 2320-D-128-601 TABLE 7	Closed	Fully Fit	No	Level 2	22 Mar 2013	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-00768FB6	PLEASE INVESTIGATE SLOW STARTER	Closed	Fully Fit	No	Level 2	14 Feb 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00745A80	INV OIL AT OIL PRESSURE SWITCH	Closed	Fully Fit	No	Level 2	22 Oct 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0075C348	PLEASE REPLACE ALTERNATOR	Closed	Fully Fit	No	Level 2	14 Jan 2013	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00745A7C	REPAIR TAIL GATE	Closed	Fully Fit	No	Level 1	22 Oct 2012	N/A	Damage	TUM HS GS SOFT TOP		000:00
00000-00745A83	DIFF LOCK WARNING LIGHT INOP	Closed	Fully Fit	No	Level 1	22 Oct 2012	N/A	No Fault Found	TUM HS GS SOFT TOP		000:00
00000-0074A779	PLEASE REPLACE FUEL SENDER UNIT	Closed	Fully Fit	No	Level 2	05 Nov 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0074A782	PLEASE REPLACE FUEL BEED PIPE	Closed	Non-Taskworthy	No	Level 2	05 Nov 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-0074A771	PLEASE REPAIR AIR FILTER BRACKET	Closed	Fully Fit	No	Level 2	05 Nov 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00738830	PLEASE CARRY OUT MEI	Closed	Fully Fit	No	Level 2	14 Sep 2012	N/A	Inspection	TUM HS GS SOFT TOP		000:00
00000-006FA56A	bonnet straps sheared replace and repair	Closed	Fully Fit	No	Level 1	27 Feb 2012	N/A	Damage	TUM HS GS SOFT TOP		000:00
00000-00738828	PLEASE CARRY OUT 2YEARLY SERVICE IAW AESP 601	Closed	Non-Taskworthy	No	Level 1	14 Sep 2012	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-0073882C	PLEASE CARRY OUT 2YEARLY OOPM AIR ELEMENT IAW AESP 601	Closed	Non-Taskworthy	No	Level 1	14 Sep 2012	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-0073882E	PLEASE CARRY OUT 2YEARLY OOPM OIL DRAIN IAW AESP 601	Closed	Non-Taskworthy	No	Level 1	14 Sep 2012	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-0073882F	PLEASE CARRY OUT 2YEARLY VM TASKS IAW AESP 601	Closed	Non-Taskworthy	No	Level 2	14 Sep 2012	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-00731548	PLEASE CARRY OUT OOPM 6 YEARLY CAMSHAFT TIMING BELT (2)	Closed	Fully Fit	No	Level 2	22 Aug 2012	N/A	Servicing	TUM HS GS SOFT TOP		000:00
00000-00713460	adjust wheel bearings	Closed	Non-Taskworthy	No	Level 2	14 May 2012	N/A	Failure	TUM HS GS SOFT TOP		
00000-0071345D	renew panhard rod	Closed	Non-Taskworthy	No	Level 2	14 May 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-00711554	please inspect, repair after rti and report any faults	Closed	Non-Taskworthy	No	Level 2	08 May 2012	N/A	Inspection	TUM HS GS SOFT TOP		000:00
00000-00701C1F	investigate batteries	Closed	Fully Fit	No	Level 1	16 Mar 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-006FA592	battery fault , observe power	Closed	Non-Taskworthy	No	Level 2	27 Feb 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-006FA58E	fuel tank dented	Closed	Non-Taskworthy	No	Level 2	27 Feb 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-006FA589	steering fault when turning right vehicle will not do full lock	Closed	Non-Taskworthy	No	Level 2	27 Feb 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-006FA57F	rear axle dented	Closed	Non-Taskworthy	No	Level 2	27 Feb 2012	N/A	Damage	TUM HS GS SOFT TOP		000:00
00000-006FA57B	replace seal on tailgate	Closed	Fully Fit	No	Level 2	27 Feb 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-006FA570	side skirt bent on drivers side	Closed	Fully Fit	No	Level 1	27 Feb 2012	N/A	Damage	TUM HS GS SOFT TOP		000:00
00000-006FA56E	replace rubber on drivers pedal	Closed	Non-Taskworthy	No	Level 1	27 Feb 2012	N/A	Failure	TUM HS GS SOFT TOP		000:00
00000-006F0374	carry out off boot inspection	Closed	Fully Fit	No	Level 2	27 Jan 2012	N/A	Inspection	TUM HS GS SOFT TOP		000:00
00000-006F0371	in inspection after exercise in Jordan	Closed	Fully Fit	No	Level 2	27 Jan 2012	N/A	Inspection	TUM HS GS SOFT TOP		000:00
00000-006B0B7A	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	22 Jun 2011	N/A	Inspection	TUM HS GS SOFT TOP		
00000-006C7192	replace spare tyre	Closed	Limited Role	No	Level 1	06 Sep 2011	N/A	Damage	TUM HS GS SOFT TOP		000:00
00000-006C7197	repare damage to rear r/h bumper	Closed	Limited Role	No	Level 2	06 Sep 2011	N/A	Damage	TUM HS GS SOFT TOP		000:00
00000-006C719C	confirm vehicle limited role status	Closed	Non-Taskworthy	No	Level 2	06 Sep 2011	N/A	Accident	TUM HS GS SOFT TOP		
00000-00568D26	Carry out 932 MEI	Closed	Non-Taskworthy	No	Level 2	07 Sep 2010	N/A		TUM HS GS SOFT TOP		

Work Objects											
Serial Number:	MB70AA										
NSN:	2320998939963										
Criteria:											
Repair Level:	ALL										
Work Object Status:	Closed										
Mission Impact:	ALL										
Fault State:	ALL										
Escalate Work:	ALL										
Work Request ID:											
Assigned Work Status	ALL										
Working Organisation											
Repair Section:											
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section	
000000-0097147F		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1		AL	000:00			
000000-00220B4C		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-008BD0BA		No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	AL	000:00			
000000-000C5A5B		No	MEI (2)	24 Jul 2019	Level 2		CL	000:00			
000000-00107011		No	First Parade Insp (AR)(1)		Level 1		CL	000:00			
000000-00107012		No	MEI (2)	24 Jul 2019	Level 2		CL	000:00			
000000-002F2C2A		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-00220B4B		No	MEI (2)	24 Jul 2019	Level 2			000:00			
000000-009B948C		No	MEI (2)	24 Jul 2019	Level 2	Non-Taskworthy	CL	000:00			
000000-005C1FA9		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-0050F789		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	WIP	000:00			
000000-007CE55B	000000-00324D42	No	MEI (2)	24 Jul 2019	Level 2	Fully Fit	CL	000:00			
000000-00220B4D		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-002F2C29		No	MEI (2)	24 Jul 2019	Level 2			000:00			
000000-007307A9		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-00698C80	000000-003152F7	Yes	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	CL	000:00	JES DET (W)	INSPECTIONS	
000000-002F2C2B		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-001903D4		No	MEI (2)	24 Jul 2019	Level 2			000:00			
000000-009BC341		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	CL	000:00			
000000-008BCE55		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	AL	000:00			
000000-00266C1B		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-001903D5		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-002E1487		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-007307AA		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-0007210C		No	First Parade Insp (AR)(1)		Level 1		CL	000:00			
000000-0050D705	000000-00304D32	No	MEI (2)	24 Jul 2019	Level 2	Fully Fit	CL	000:00			
000000-001BEF12		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1		WIP	000:00			
000000-005C1FA8		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-0080AC69	000000-00324D42	No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Fully Fit	CL	000:00			
000000-0066B752	000000-003152F7	Yes	MEI (2)	24 Jul 2019	Level 2	Non-Taskworthy	CL	000:00	JES DET (W)	INSPECTIONS	

Work Objects

Serial Number: MB70AA  
 NSN: 2320998939963

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00693A95	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS	No	1/A		Mod				Non-Taskworthy	CL	Level 2			000:00
000000-0064268E	00044	This instruction details the removal of the existing six way lighting switch and the fitting of a seven way lighting switch to all variants including winter water vehicles.	No	3/A		Mod				Fully Fit	CL	Level 2			
000000-0064415D	00039	TUM (HS) REMUS 1 - SAFETY AND COMPLIANCE PROGRAMME	No	-/-		RTI				Fully Fit	CL	Level 2			
000000-0064415B	00024	Fitting of Trailer Breakaway Attachment Plate	No	-/-		UTI				Fully Fit	CL	Level 2			
000000-00026010	00019	Blackout Cover for Warning Light Panel	No	-/-		UTI				Fully Fit	CL	Level 2			
000000-000260E3	00037	Fitting Glow Plug Timer Interface Harness	No	-/-		UTI				Fully Fit	CL	Level 2			
000000-00024367	00025	Fitting of Spare Wheel Lifting Aid Harness	No	1/A		UTI				Non-Taskworthy	CL	Level 2			
000000-00023012	00030	Front Belt Protection Sleeves	No	1/A		UTI				Non-Taskworthy	CL	Level 1			
000000-00024158	00017	Introduction of Battery Retention	No	1/A		UTI				Non-Taskworthy	CL	Level 2			
000000-0001048B	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants	No	-/-		UTI				Fully Fit	CL				
000000-00014309	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation	No	-/-		UTI				Fully Fit	CL				
000000-00020B93	00014	Fitting of Showerproof Dash Cover	No	-/-		RTI				Fully Fit	CL				
000000-00018211	00004	Fitting Emergency Lights, Siren and Harness	No	-/-		RTI				Fully Fit	CL				
000000-0000A0F5	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension	No	-/-		RTI				Fully Fit	CL				

Work Objects											
Serial Number:	MB70AA										
NSN:	2320998939963										
Criteria:											
Repair Level:	ALL										
Work Object Status:	Closed										
Mission Impact:	ALL										
Fault State:	ALL										
Escalate Work:	ALL										
Work Request ID:											
Assigned Work Status	ALL										
Working Organisation											
Repair Section:											
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section	
000000-0097147F		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1		AL	000:00			
000000-00220B4C		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-008BD0BA		No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	AL	000:00			
000000-000C5A5B		No	MEI (2)	24 Jul 2019	Level 2		CL	000:00			
000000-00107011		No	First Parade Insp (AR)(1)		Level 1		CL	000:00			
000000-00107012		No	MEI (2)	24 Jul 2019	Level 2		CL	000:00			
000000-002F2C2A		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-00220B4B		No	MEI (2)	24 Jul 2019	Level 2			000:00			
000000-009B948C		No	MEI (2)	24 Jul 2019	Level 2	Non-Taskworthy	CL	000:00			
000000-005C1FA9		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-0050F789		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	WiP	000:00			
000000-007CE55B	000000-00324D42	No	MEI (2)	24 Jul 2019	Level 2	Fully Fit	CL	000:00			
000000-00220B4D		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-002F2C29		No	MEI (2)	24 Jul 2019	Level 2			000:00			
000000-007307A9		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-00698C80	000000-003152F7	Yes	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	CL	000:00	JES DET (W)	INSPECTIONS	
000000-002F2C2B		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-001903D4		No	MEI (2)	24 Jul 2019	Level 2			000:00			
000000-009BC341		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	CL	000:00			
000000-008BCE55		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Non-Taskworthy	AL	000:00			
000000-00266C1B		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-001903D5		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-002E1487		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-007307AA		No	First Parade Insp (AR)(1)		Level 1			000:00			
000000-0007210C		No	First Parade Insp (AR)(1)		Level 1		CL	000:00			
000000-0050D705	000000-00304D32	No	MEI (2)	24 Jul 2019	Level 2	Fully Fit	CL	000:00			
000000-001BEF12		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1		WiP	000:00			
000000-005C1FA8		No	6 Monthly 6534 Insp	22 Jan 2019	Level 1			000:00			
000000-0080AC69	000000-00324D42	No	6 Monthly 6534 Insp	22 Jan 2019	Level 1	Fully Fit	CL	000:00			
000000-0066B752	000000-003152F7	Yes	MEI (2)	24 Jul 2019	Level 2	Non-Taskworthy	CL	000:00	JES DET (W)	INSPECTIONS	



VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
NA80AB	2340999087737	NB12084108	GSV/55/55	QUADBIKE 4X4 ATV PTL GRIZZLY 450 YAMAHA	Sand Infra Red Reflecting

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
09/06/2011	517238	N/A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
NA80AB			CA005A	JSCS ASHCHURCH		128AA	09/06/2011	
NA80AB	2	06/12/2011	A0551A	1 SCOTS	109283	92624	09/01/2012	
NA80AB		08/11/2012	A1990A	DSG STIRLING			08/11/2012	
NA80AB		15/11/2012	A0551A	1 SCOTS LADS			15/11/2012	
NA80AB		04/12/2012	A0551A	1 SCOTS			04/12/2012	
NA80AB		16/07/2013	A5969D	DSG STIRLING TUF			16/07/2013	
NA80AB		16/07/2013	A1990A	DSG STIRLING			16/07/2013	
NA80AB		29/07/2013	A0551A	1 SCOTS			29/07/2013	
NA80AB		11/09/2013	A1990A	DSG STIRLING			11/09/2013	
NA80AB		14/10/2013	A0551A	1 SCOTS			14/10/2013	
NA80AB		07/11/2013	A1990A	DSG STIRLING			07/11/2013	

NA80AB		26/11/2013	A0551A	1 SCOTS			26/11/2013	
NA80AB		09/01/2014	A1990A	DSG STIRLING			09/01/2014	
NA80AB		21/01/2014	A0551A	1 SCOTS			21/01/2014	
NA80AB		24/01/2014	A0305A	21 ENGR REGT			24/01/2014	
NA80AB		05/02/2014	A0305K	21 ENGR REGT 7 (HQ) SQN			05/02/2014	
NA80AB		20/03/2014	A0305C	21 ENGR REGT 1 FD SQN			20/03/2014	
NA80AB		06/11/2014	A0305E	21 ENGR REGT 4 FD SQN			06/11/2014	
NA80AB		29/11/2014	A0305C	21 ENGR REGT 1 FD SQN			29/11/2014	
NA80AB		21/07/2015	A0305E	21 ENGR REGT 4 FD SQN			21/07/2015	
NA80AB		01/07/2016	A0305A	21 ENGR REGT			01/07/2016	
NA80AB		07/07/2016	A9016B	OP TRENTON			07/07/2016	
NA80AB		17/07/2016	Z0003Z	DMC (TFR)			17/07/2016	
NA80AB		28/08/2016	A9016B	OP TRENTON			28/08/2016	

Repair Action ID	System	Sub System	Repair Action Type	RAC Description	Repair Action State	Repair Action Condition	Non Specified Repair Lev	Repair Action Completion Date	Repair Trade Required
000000-004D2DE3	Common	N/A	Fault	Carry out	Fully Fit	CL		12 Mar 2012	Unspec
000000-0051906E	Common	N/A	Fault	CARRY OUT MEI IAW AESP 2300-A-050-013	Non-Taskworthy	CL		21 Aug 2012	Unspec
000000-00519073	Common	N/A	Fault	CARRY OUT 12 MTH/3200 MILES/320HRS MAINT IAW AESP 2340-R-105-601 TABLE 7 COL	Non-Taskworthy	CL		21 Aug 2012	Unspec
000000-005B4242	Common	N/A	Fault	OOPS YEARLY ENGINE OIL STRAINER L2 CHANGE	Non-Taskworthy	CL		06 Nov 2012	Unspec
000000-004F50A5	Common	N/A	Fault	CARRY OUT CHASSIS INSPECTION	Fully Fit	CL		16 May 2012	Unspec
000000-005B4252	Common	N/A	Fault	CARRY OUT ANNUAL WINCH TEST	Non-Taskworthy	CL		05 Nov 2012	Unspec
000000-005668D2	Common	N/A	Fault	CARRY OUT 12 MTH/3200 MILES/320HRS MAINT IAW AESP 2340-R-105-601 TABLE 7 COL B	Fully Fit	CL		18 Oct 2012	Unspec
000000-005B425C	Common	N/A	Fault	CARRY OUT 6 MTH/1600 MILES/160HRS MAINT IAW AESP 2340-R-105-601 TABLE 7 COL A	Non-Taskworthy	CL		06 Nov 2012	Unspec
000000-00B4B77F	Common	N/A	Fault	CARRY OUT AFB 6534 INSPECTION REPORT	Fully Fit	CL		13 Jan 2014	Unspec
000000-00B4B780	Common	N/A	Fault	CARRY OUT 6 MTH/1600 MILES/160HRS MAINT IAW AESP 2340-R-105-601 TABLE 7 COL A	Fully Fit	CL		13 Jan 2014	Unspec
000000-00B949AA	Common	N/A	Fault	Self Recovery Winch Annual WLL Test (2)	Limited Role	CL		27 May 2013	Unspec
000000-00BD7949	Common	N/A	Fault	Yearly/5120 Kms/320 Hrs	Fully Fit	CL		08 Oct 2013	Unspec
000000-00C1305B	Common	N/A	Fault	CARRY OUT ANNUAL WINCH TEST	Fully Fit	CL		25 Nov 2013	Unspec
000000-00C2BC10	Common		Fault	RENEW BOTH REAR WHEELS	Fully Fit	CL		18 Mar 2014	Unspec
000000-00CF9553	Common		Fault	CARRY OUT L2 1 YEARLY VMS	Non-Taskworthy	CL		01 Oct 2014	VM B
000000-00CC306E	Common		Fault	CARRY OUT L1 1 YEARLY MAINT IN ACCORDANCE WITH AESP 2340-R-105-601 TABLE 6	Fully Fit	CL		24 Jul 2014	Unspec
000000-00CC305C	Common		Fault	CARRY OUT L1 1 YEARLY MAINT IN ACCORDANCE WITH AESP 2340-R-105-601 TABLE 6	Fully Fit	CL		23 Jul 2014	Unspec
000000-00D2AE29	Common		Fault	L2 1 YEARLY VMS	Fully Fit	CL		11 Nov 2014	VM B
000000-00D25223	Common		Fault	L1 1 YEARLY MAINT	Fully Fit	CL		06 Nov 2014	Unspec
000000-00DA0407	Common		Fault	Carry out 6534	Limited Role	CL		26 Mar 2015	Unspec
000000-00DC258F	Common		Fault	carry out 6m vms l2	Fully Fit	CL		13 May 2015	VM B
000000-00DC09AF	Common		Fault	CARRY OUT 6M MAINT L1	Fully Fit	CL		12 May 2015	Unspec
000000-00F611A9	Survivability		Fault	CLEAN AIR FILTER	Fully Fit	CL		18 May 2016	Unspec
000000-00F6118D	Outfit, Furnishing, Stowage and Utility Spaces		Fault	MISSING DUST CAPS	Fully Fit	CL		18 May 2016	Unspec
000000-00F7F236	Electrical Systems		Fault	Replace Battery	Limited Role	CL		22 Jun 2016	ME Combat
000000-01195507	Survivability		Fault	OOPS 2 Yearly Coolant Change when coolant is available	Fully Fit	CL		12 Mar 2018	Unspec
000000-0138EE36	Common		Fault	CHANGE BRAKE FLUID	Fully Fit	CL		17 Nov 2019	VM B
000000-01212BA8	Structure		Fault	Out of Phase Maintenance	Limited Role	CL		21 Aug 2018	Unspec
000000-0117C43B	Common		Fault	REPLACE CARBURETTOR	Fully Fit	CL		07 Feb 2018	VM B
000000-011BB1DE	Common	N/A	Fault	REPAIRED WIRING LOOM	Non-Taskworthy	CL		28 Apr 2018	Unspec
000000-011C14D7	Common	N/A	Fault	CONDUCT ISI	Fully Fit	CL		05 May 2018	Unspec
000000-0139607F	Common		Fault	replaced fuel filter	Fully Fit	CL		26 Nov 2019	ME Ftr Gen

Work Objects										
Serial Number:	NA80AB									
NSN:	2340999087737									
Criteria:										
Repair Level:	ALL									
Work Object Status:	Closed									
Mission Impact:	ALL									
Fault State:	ALL									
Escalate Work:	ALL									
Work Request ID:										
Assigned Work Status	ALL									
Working Organisation										
Repair Section:										
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-003060DE		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2			000:00		
000000-002B9EA5		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-001BDFC2		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-0050652E		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-002C04AF		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2			000:00		
000000-005B5E80		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2			000:00		
000000-00368FC1		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2			000:00		
000000-0088C0F7		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2	Fully Fit	CL	000:00		OP Trenton LAD
000000-001C5332		No	Initial Quad Bike Chassis Insp (2)		Level 2			000:00		
000000-005B5E83		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2			000:00		
000000-002053E3		No	MEI (2)		Level 2			000:00		
000000-00369065		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2			000:00		
000000-0094B00C		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2	Fully Fit	CL	000:00		
000000-0094AFF1		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2	Limited Role	CL	000:00		
000000-00465C5D		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-002B9EA4		No	MEI (2)		Level 2			000:00		
000000-002C04B6		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2			000:00		
000000-005DFE91		No	MEI (2)		Level 2			000:00		
000000-002053E4		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00BC3EAC		No	MEI (2)		Level 2	Limited Role	CL	000:00		
000000-003060B1		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2			000:00		
000000-007D2952		No	6 Monthly 6534 Insp		Level 1	Limited Role	CL	000:00		
000000-0069B205		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-0086F56A		No	6 Monthly 6534 Insp		Level 1	Limited Role	CL	000:00		
000000-0033811A		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2			000:00		
000000-0094B5A5		No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-005DFE87		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-007CEDB2		No	MEI (2)		Level 2	Limited Role	CL	000:00		
000000-00338118		No	Self Recovery Winch Annual WLL Test (2)	04 Apr 2019	Level 2			000:00		
000000-00463340		No	MEI (2)		Level 2			000:00		
000000-0088C149		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2	Fully Fit	CL	000:00		OP Trenton LAD
000000-00A00E17		No	6 Monthly 6534 Insp		Level 1	Limited Role	CL	000:00		
000000-00933EA2		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-00A5BF0A		No	Self Recovery Winch Rope 6 Monthly Inspection	21 Apr 2019	Level 2	Limited Role	CL	000:00		
000000-00368FC0		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00BC5AFC		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		

Work Objects																			
Serial Number:	NA80AB																		
NSN:	2340999087737																		
Criteria:																			
Repair Level:	ALL																		
Work Object Status:	Closed																		
Mission Impact:	ALL																		
Fault State:	ALL																		
Escalate Work:	ALL																		
Work Request ID:																			
Assigned Work Status:	ALL																		
Working Organisation:																			
Repair Section:																			
Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equal	Embodied by Target Date	Usage Counter Unit	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time				
000000-0061764C	00001	Fitment of an in-line fuel filter		No	3/C	Mod				Non-Taskworthy	CL	Level 2			000:00				
000000-0061764D	00003	ECM Suppression Pack Fitment		No	3/C	Mod				Non-Taskworthy	CL	Level 2			000:00				
000000-0061763B	00002	Fitment of a Left Hand Throttle		No	3/C	Mod				Non-Taskworthy	CL	Level 2			000:00				
000000-0061763C	00004	Autojaw R Clip replacement		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00				

Work Objects										
Serial Number:	NA80AB									
NSN:	23409998737									
Criteria:										
Repair Level:	ALL									
Work Object Status:	Closed									
Mission Impact:	ALL									
Fault State:	ALL									
Escalate Work:	ALL									
Work Request ID:										
Assigned Work Status:	ALL									
Work ing Organisation:										
Repair Section:										
Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Work ing Organisation	Repair Section
000000	00285C96	No	OOPS 2 Yearly Renew Brake Fluid	16 Nov 2021	Level 2			000.00		
000000	00460F99	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Non Taskworthy	WIP	000.00		
000000	00863ED1	No	OOPS 2 Yearly Change Rear Axle Differential at Gear Oil	16 Nov 2021	Level 2	Limited Role	CL	000.00		
000000	00460F2	No	OOPS Yearly Engine Oil Stra ner (2)	04 Apr 2019	Level 2			000.00		
000000	00285C98	No	OOPS 2 Yearly Change Rear Axle Differential at Gear Oil	16 Nov 2021	Level 2			000.00		
000000	008C3BD4	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Limited Role	CL	000.00		
000000	00306C3	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	00285C94	No	OOPS 2 Yearly Change Differential Gear Oil (2)	16 Nov 2021	Level 2			000.00		
000000	00A0E04	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Limited Role	CL	000.00		
000000	0058E24	No	OOPS 2 Yearly Change Differential Gear Oil (2)	16 Nov 2021	Level 2			000.00		
000000	00285C92	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	0036902	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	0058E27	No	OOPS 2 Yearly Renew Brake Master Cyl Parts	16 Nov 2021	Level 2			000.00		
000000	00874DAD	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Fully Fit	CL	000.00		
000000	00306C4	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Limited Role	CL	000.00		
000000	008C3ED5	No	OOPS 2 Yearly Renew Brake Fluid	16 Nov 2021	Level 2			000.00		
000000	00285C93	No	OOPS 2 Yearly Renew Brake Master Cyl Parts	16 Nov 2021	Level 2			000.00		
000000	00863ED4	No	OOPS 2 Yearly Renew Brake Caliper Parts	16 Nov 2021	Level 2	Limited Role	CL	000.00		
000000	00875535	No	OOPS 2 Yearly Renew Brake Fluid	16 Nov 2021	Level 2	Fully Fit	CL	000.00		
000000	00460F0	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	008C3BD0	No	OOPS 4 Yearly Renew Brake Hoses	23 Nov 2023	Level 2	Limited Role	CL	000.00		
000000	00460E6	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Non Taskworthy	WIP	000.00		
000000	00871B30	No	OOPS 2 Yearly Change Differential Gear Oil (2)	16 Nov 2021	Level 2	Fully Fit	CL	000.00		
000000	0085D62	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Fully Fit	CL	000.00		
000000	0038F4E	No	OOPS Yearly Engine Oil Stra ner (2)	04 Apr 2019	Level 2			000.00		
000000	00584398	No	OOPS 2 Yearly Renew Brake Hoses	23 Nov 2023	Level 2			000.00		
000000	008C3ED7	No	OOPS 2 Yearly Renew Brake Master Cyl Parts	16 Nov 2021	Level 2	Limited Role	CL	000.00		
000000	002203E8	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	00285F3	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	00227A8B	No	OOPS Yearly Engine Oil Stra ner (2)	04 Apr 2019	Level 2			000.00		
000000	0018DFD9	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	0058E25	No	OOPS 2 Yearly Renew Brake Fluid	16 Nov 2021	Level 2			000.00		
000000	007D293F	No	OOPS Yearly Engine Oil Stra ner (2)	04 Apr 2019	Level 2	Fully Fit	CL	000.00		
000000	0058E26	No	OOPS Yearly Engine Oil Stra ner (2)	04 Apr 2019	Level 2			000.00		
000000	00461604	No	Monthly/320 Km/20 Hrs(AR)		Level 2			000.00		
000000	00871BF3	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Non Taskworthy	CL	000.00		
000000	0036903	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	0058E2A	No	OOPS 2 Yearly Change Rear Axle Differential at Gear Oil	16 Nov 2021	Level 2			000.00		
000000	00285F4	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	0052790	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	00698E1E	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	002203E9	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	00460F1	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	00948C50	No	OOPS Yearly Engine Oil Stra ner (2)	04 Apr 2019	Level 2	Fully Fit	CL	000.00		
000000	0058E28	No	OOPS 2 Yearly Renew Brake Caliper Parts	16 Nov 2021	Level 2			000.00		
000000	00875536	No	OOPS 2 Yearly Renew Brake Master Cyl Parts	16 Nov 2021	Level 2	Fully Fit	CL	000.00		
000000	009C6427	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Limited Role	CL	000.00		
000000	00285C85	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	008C3BD0E	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Limited Role	CL	000.00		
000000	0068B9FC	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Fully Fit	CL	000.00		
000000	00875539	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Fully Fit	CL	000.00		
000000	00285C97	No	OOPS 2 Yearly Coolant Change (2)	16 Nov 2021	Level 2			000.00		
000000	008C09F8	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Limited Role	CL	000.00		
000000	00227A82	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	0058E29	No	OOPS 2 Yearly Coolant Change (2)	16 Nov 2021	Level 2			000.00		
000000	00871B78	No	OOPS 2 Yearly Change Rear Axle Differential at Gear Oil	16 Nov 2021	Level 2	Fully Fit	CL	000.00		
000000	008C3BD0F	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Limited Role	CL	000.00		
000000	00481602	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	007D006E	No	Monthly/320 Km/20 Hrs(AR)		Level 2	Fully Fit	CL	000.00		
000000	00875534	No	OOPS 2 Yearly Renew Brake Caliper Parts	16 Nov 2021	Level 2	Fully Fit	CL	000.00		
000000	007CE0AA	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2	Fully Fit	CL	000.00		
000000	008C3ECE	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Non Taskworthy	CL	000.00		
000000	005F6732	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	00285C95	No	OOPS 2 Yearly Renew Brake Caliper Parts	16 Nov 2021	Level 2			000.00		
000000	00875533	No	OOPS 2 Yearly Coolant Change (2)	16 Nov 2021	Level 2	Fully Fit	CL	000.00		
000000	00481603	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	007D006F	No	After Use (AR)(1)		Level 1	Fully Fit	CL	000.00		
000000	0048160E	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		
000000	00835C38	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Fully Fit	CL	000.00		
000000	00874E42	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Fully Fit	CL	000.00		
000000	0048160F	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	0037153D	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2			000.00		
000000	007D006D	No	6 Monthly/2560 Kms/160 Hrs (2)	24 May 2020	Level 2	Fully Fit	CL	000.00		
000000	008C3BD3	No	OOPS 2 Yearly Change Differential Gear Oil (2)	16 Nov 2021	Level 2	Limited Role	CL	000.00		
000000	008C3BD6	No	OOPS 2 Yearly Coolant Change (2)	16 Nov 2021	Level 2	Limited Role	CL	000.00		
000000	005F6731	No	Yearly/5120 Kms/320 Hrs (2)	23 Nov 2020	Level 2			000.00		