



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk



Our Reference:
FOI2021/06301
Date:
24 June 2021

Dear 

I am writing about your email of 12 June 2021, requesting the following information:

Can you please send me the service history of the Ex MoD Land Rover 86KE41?

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Fault History (redacted)
Annex B – Inspection History
Annex C - Modification History
Annex D – Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex A), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

Defence Equipment & Support

However, the information about your vehicle history has previously been published and Section 21(1) of the FOI Act provides that information is exempt if it is reasonably available by other means. The Merlin archive was released as part of a previous FOI request and can be accessed at the Government publications website, at the following:

<https://www.gov.uk/government/publications/foi-responses-published-by-mod-week-commencing-09-july-2018>

Under Section 16 (Advice and Assistance) of the FOI Act, I can advise you that the Merlin database in the above link is split into seven spreadsheets. The first has a list of vehicles, while sheets two through seven include the service histories. To search for a vehicle, you must press Ctrl + F on your computer keyboard, then select 'Options' and then select 'Workbook' from the 'Within' drop down list. Information relevant to your request can be found by typing the vehicle registration number (86KE41) and pressing 'enter'.

You may wish to note that when the Merlin database was archived into its current format some data may have been lost or corrupted. You should, therefore, be cautious that some of the data may be inaccurate.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

Work Objects

Serial Number: 86KE41
 NSN: 2320998937004

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-005E8286		BATTERIES REQUIRE INSPECTION/ CHARGING	Closed	Non-Taskworthy	No	Level 1		17 Mar 2011	N/A	Inspection	TUM GS SOFT TOP			
000000-005CDE58		Renew Drivers Seat.	Closed	Fully Fit	No	Level 2		05 Jan 2011	N/A	Refurbishment	TUM GS SOFT TOP			
000000-005CDE2F		PLEASE CARRY OUT ANNUAL MEI INSPECTION	Closed	Non-Taskworthy	No	Level 2		05 Jan 2011	N/A	Inspection	TUM GS SOFT TOP			
000000-005CDE29		PLEASE CARRY OUT 1 YEARLY VM TASKS	Closed	Non-Taskworthy	No	Level 2		05 Jan 2011	N/A	Inspection	TUM GS SOFT TOP			
000000-005CDE25		PLEASE CARRY OUT 1 YEARLY SERVICE	Closed	Non-Taskworthy	No	Level 2		05 Jan 2011	N/A	Servicing	TUM GS SOFT TOP			
000000-005CDE62		secure Drivers side window Slide.	Closed	Fully Fit	No	Level 2		05 Jan 2011	N/A	Refurbishment	TUM GS SOFT TOP			000:00
000000-0052BB92	000000-002BD8F6	Stamp V.R.N. to Vehicle Jack.	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-002688C4		ENG OIL & FILTER CHANGE NEXT DUE 106236KM (OOPM)	Closed	Fully Fit	No	Level 1		03 Sep 2008			TUM GS SOFT TOP			
000000-00528DDC	000000-002B9E2E	PLEASE CARRY OUT MEI	Closed	Non-Taskworthy	No	Level 2		29 Jun 2010			TUM GS SOFT TOP			
000000-0052BC15	000000-002BA865	Please Carry out a 6 Monthly Service.	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BBA9	000000-002BA83B	Secure Passenger Side Air Vent Shelf. (R.D.I.)	Closed	Fully Fit	No	Level 2		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BBA4	000000-002BA83B	Check L.H. Main Beam and adjust H/Lights. (R.D.I.)	Closed	Fully Fit	No	Level 2		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB96	000000-002BA83B	Adjust Handbrake. (R.D.I.)	Closed	Fully Fit	No	Level 2		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB8E	000000-002BA83B	renew Clutch Pedal Rubber. (R.D.I.)	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB8B	000000-002BA83B	Rectify Convoy light Inop. (R.D.I.)	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB7F	000000-002BA83B	Fit R Clips to Stowage Bin Lids. (R.D.I.)	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB71	000000-002BA83B	Fit Fuel/ Water Warning Labels to Stowage Bins. (R.D.I.)	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB6B	000000-002BA83B	Fit Diesel only Label to Filler Cap. (R.D.I.)	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-0052BB4B	000000-002BA83B	Renew Rear Tow Pintle R Clip (R.D.I.)	Closed	Fully Fit	No	Level 1		05 Jul 2010			TUM GS SOFT TOP			
000000-004712F9	000000-002A5B11	REQUIRES 80,000KM SERVICE (TIMING BELT)	Closed	Non-Taskworthy	No	Level 2		01 Sep 2009			TUM GS SOFT TOP			
000000-004DEC6A	000000-002AB0DF	ACCELERATOR CABLE BROKEN	Closed	Non-Taskworthy	No	Level 2		09 Mar 2010			TUM GS SOFT TOP			
000000-00479FDC	000000-00297F79	Rectify Clutch inop (Clutch Slave Cylinder Leaking) Renew Clutch Slave Cyl. (R.D.I.)	Closed	Non-Taskworthy	No	Level 2		17 Sep 2009			TUM GS SOFT TOP			
000000-00477D62	000000-002978D9	Renew rear brake adjuster / Brake plate. (R.D.I.)	Closed	Non-Taskworthy	No	Level 2		14 Sep 2009			TUM GS SOFT TOP			
000000-00471CBF	000000-002978D9	Drain and Replenish Brake Fluid (Part of 2Yearly V.M.Tasks) (R.D.I.)	Closed	Fully Fit	No	Level 2		02 Sep 2009			TUM GS SOFT TOP			
000000-00471CB8	000000-002978D9	Strip and Examine / adjust Transmission Brake (Part of 2Yearly V.M.Tasks) (R.D.I.)	Closed	Fully Fit	No	Level 2		02 Sep 2009			TUM GS SOFT TOP			
000000-00471CB4	000000-002978D9	Strip and Examine / adjust Transmission Brake (Part of 2Yearly V.M.Tasks) (R.D.I.)	Closed	Fully Fit	No	Level 2		02 Sep 2009			TUM GS SOFT TOP			
000000-00471CB3	000000-002978D9	Strip and Examine Brakes (Part of 2 Yearly V.M.Tasks) (R.D.I.)	Closed	Fully Fit	No	Level 2		02 Sep 2009			TUM GS SOFT TOP			
000000-00471CAD	000000-002978D9	Renew Rear Brake Shoes. (R.D.I.)	Closed	Non-Taskworthy	No	Level 2		02 Sep 2009			TUM GS SOFT TOP			
000000-004C2B86	000000-002A594B	tighten Passenger side Top Window Frame (x2 Bolts Loose) (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B80	000000-002A594B	Rectify Passenger Seat not adjusting foward. (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B79	000000-002A594B	tighten Drivers Mirror Arm on top Hinge. (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B47	000000-002A594B	Re-Fit Drivers side Seat Belt Protection Sleeve. (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B3B	000000-002A594B	Tighten rear Tank Bolts. (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B2E	000000-002A594B	Tighten Steering Wheel. (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B2A	000000-002A594B	rectify Blower Motor Inop. (R.D.I.)	Closed	Fully Fit	No	Level 2		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B24	000000-002A594B	Mark Battery Cover " Danger Acid Splash" (R.D.I.)	Closed	Fully Fit	No	Level 1		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B1A	000000-002A594B	Fit Battery Protection Covers +ve/-ve. (R.D.I.)	Closed	Fully Fit	No	Level 1		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B10	000000-002A594B	Stencil Tyre Pressures to Wings. (R.D.I.)	Closed	Fully Fit	No	Level 1		28 Jan 2010			TUM GS SOFT TOP			
000000-004C2B0B	000000-002A594B	Fit Grommet To Passenger side Air Vent (R.D.I.)	Closed	Fully Fit	No	Level 1		28 Jan 2010			TUM GS SOFT TOP			
000000-004712F5	000000-00296576	REQUIRES MEI INSPECTION	Closed	Fully Fit	No	Level 2		01 Sep 2009			TUM GS SOFT TOP			
000000-004712F2	000000-00296576	REQUIRES 2 YRLY VM TASKS	Closed	Fully Fit	No	Level 2		01 Sep 2009			TUM GS SOFT TOP			
000000-004712F1	000000-00296576	REQUIRES BRAKE FLUID CHANGE	Closed	Fully Fit	No	Level 1		01 Sep 2009			TUM GS SOFT TOP			
000000-004712F0	000000-00296576	REQUIRES 2 YRLY SERVICE	Closed	Fully Fit	No	Level 1		01 Sep 2009			TUM GS SOFT TOP			
000000-0040EB45	000000-0028ACFB	Adjust valve clearances	Closed	Fully Fit	No	Level 2		01 Apr 2009			TUM GS SOFT TOP			
000000-0040EB40	000000-0028ACFB	Clean paint from brake fluid resevoir RDI	Closed	Fully Fit	No	Level 1		01 Apr 2009			TUM GS SOFT TOP			
000000-0040EB43	000000-0028ACFB	Secure rh front headlight and adjust beam RDI	Closed	Fully Fit	No	Level 2		01 Apr 2009			TUM GS SOFT TOP			
000000-0040EB3E	000000-0028ACFB	Refit battery clamp correctly RDI	Closed	Fully Fit	No	Level 1		01 Apr 2009			TUM GS SOFT TOP			
000000-003F6E1D	000000-0028A3F7	FUEL GAUGE NOT WORKING	Closed	Fully Fit	No	Level 2		24 Mar 2009			TUM GS SOFT TOP			

000000-003F5AAA	000000-0028A2EA	rectify ignition warning light inop	Closed	Non-Taskworthy	No	Level 2	24 Mar 2009	TUM GS SOFT TOP
000000-003F5A9D	000000-0028A2EA	renew speedo cable	Closed	Non-Taskworthy	No	Level 2	24 Mar 2009	TUM GS SOFT TOP
000000-003F5A91	000000-0028A2EA	rectify fuel gauge inop	Closed	Non-Taskworthy	No	Level 2	24 Mar 2009	TUM GS SOFT TOP
000000-00269A93		MEI/6MSI FAIL JOBS COMPLETE WITHIN 28DAYS (932 B RE-CERTIFIED)	Closed	Non-Taskworthy	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-0035ED75		Fit Correct Battery And Clamp	Closed	Non-Taskworthy	No	Level 1	11 Dec 2008	TUM GS SOFT TOP
000000-0035ED99	000000-00286A93	Rectify Excessive Engine noise (Knocking, Suspect F.I.P. incorrectly Timed)	Closed	Non-Taskworthy	No	Level 2	11 Dec 2008	TUM GS SOFT TOP
000000-00357A68		convoy light wiring	Closed	Fully Fit	No	Level 2	09 Dec 2008	TUM GS SOFT TOP
000000-00087749		Renew front No plate	Closed	Fully Fit	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-00151613		Underside of vehicle requires derusting and undersealing	Closed	Fully Fit	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-0026B784	000000-002805C2	Rectify Vehicle Failed Emissions Test.	Closed	Non-Taskworthy	No	Level 2	04 Sep 2008	TUM GS SOFT TOP
000000-00269A45	000000-002805C2	Renew Viscous Coupling	Closed	Fully Fit	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-00269A6B	000000-002805C2	Renew Front Axle Bump Stop R.H.S.	Closed	Fully Fit	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-00269A7F	000000-002805C2	Rectify Diesel Fuel Leak on Tank.	Closed	Non-Taskworthy	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-002699B7	000000-00280410	Remove Masking Tape From Rear Red Reflectors (R.D.I.)	Closed	Non-Taskworthy	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-002699CB	000000-00280410	Secure Passenger/Drivers side mirrors (R.D.I)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-002699DF	000000-00280410	Renew Passenger side Wiper Blade (R.D.I)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-002699E1	000000-00280410	Renew Brake Pedal Rubber (R.D.I)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-00269A09	000000-00280410	Remove Straps FromSun Visors LH/RH Side (R.D.I)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-00269A0C	000000-00280410	Fit Diesel Sign To Filler Cap (R.D.I)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-00269A0D	000000-00280410	Rectify Map light inop (R.D.I)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-00269A1C	000000-00280410	Paint Rear Diff Cover White (Convoy) (R.D.I.)	Closed	Fully Fit	No	Level 1	03 Sep 2008	TUM GS SOFT TOP
000000-00269A32	000000-00280410	Re-Fit Seat belt Plastic Protection Sleeves (R.D.I.)	Closed	Fully Fit	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-00269A43	000000-00280410	Rectify Horn Inop (R.D.I.)	Closed	Non-Taskworthy	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-00269A5A	000000-00280410	Re-Fit Front Propshaft (sliding joint To T/Box End) R.D.I.	Closed	Fully Fit	No	Level 2	03 Sep 2008	TUM GS SOFT TOP
000000-00049272		ENG OIL & FILTER CHANGE NEXT DUE 112184KM (OOPM)	Closed	Fully Fit	No	Level 1	29 Jan 2007	TUM GS SOFT TOP
000000-001FC24F		Respray LH door.	Closed	Fully Fit	No	Level 1	08 Jul 2008	TUM GS SOFT TOP
000000-0019D3BE	000000-0027C4DF	indicators not working	Closed	Non-Taskworthy	No	Level 2	02 Jun 2008	TUM GS SOFT TOP
000000-0015787E		DRAIN AND RENEW BRAKE FLUID (OOPM)	Closed	Fully Fit	No	Level 2	27 Apr 2008	TUM GS SOFT TOP
000000-000FE0CB		renew coolant pump	Closed	Non-Taskworthy	No	Level 2	11 Mar 2008	TUM GS SOFT TOP
000000-000FE107		renew tailboard	Closed	Limited Role	No	Level 2	11 Mar 2008	TUM GS SOFT TOP
000000-000FE12F	000000-0027A873	renew tailboard strap	Closed	Fully Fit	No	Level 2	11 Mar 2008	TUM GS SOFT TOP
000000-001514B7	000000-0027A873	Fit missing rear compartment seat belt or remove rear seats	Closed	Non-Taskworthy	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-001514BC	000000-0027A873	Secure lh side stowage bin locking clips	Closed	Fully Fit	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-001514BE	000000-0027A873	Renew lh mirror	Closed	Non-Taskworthy	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-001514C1	000000-0027A873	Secure battery clamp correctly	Closed	Non-Taskworthy	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-0015160B	000000-0027A873	Renew wiper blades	Closed	Non-Taskworthy	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-0015160E	000000-0027A873	Fit missing rear reflectors	Closed	Non-Taskworthy	No	Level 1	23 Apr 2008	TUM GS SOFT TOP
000000-00151615	000000-0027A873	Resecure handbrake lever rubber boot	Closed	Fully Fit	No	Level 2	23 Apr 2008	TUM GS SOFT TOP
000000-00151644	000000-0027A873	Rectify fuel leak @ FIP	Closed	Non-Taskworthy	No	Level 2	23 Apr 2008	TUM GS SOFT TOP
000000-001518F9	000000-0027A873	Bleed and adjust brakes	Closed	Non-Taskworthy	No	Level 2	24 Apr 2008	TUM GS SOFT TOP
000000-001518FA	000000-0027A873	Adjust handbrake	Closed	Non-Taskworthy	No	Level 2	24 Apr 2008	TUM GS SOFT TOP
000000-001518FB		MEI FAIL, JOBS COMPLETE WITHIN 28 DAYS (932 RECERTIFIED)	Closed	Non-Taskworthy	No	Level 2	23 Apr 2008	TUM GS SOFT TOP
000000-000F132B	000000-00278300	RECTIFY FUEL LEAKE AT FIP (AFB 6534)	Closed	Non-Taskworthy	No	Level 2	06 Mar 2008	TUM GS SOFT TOP
000000-000FE0DF	000000-00278300	renew FIP	Closed	Non-Taskworthy	No	Level 3	11 Mar 2008	TUM GS SOFT TOP
000000-000FE11B		renew tailboard	Closed	Non-Taskworthy	No	Level 2	11 Mar 2008	TUM GS SOFT TOP
000000-000F1305	000000-00277D52	RECTIFY OIL LEAKE AT OIL FILTER HOUSING (AFB 6534)	Closed	Fully Fit	No	Level 2	06 Mar 2008	TUM GS SOFT TOP
000000-000F1353	000000-00277D52	RENEW REAR DIFF INPUT SEAL (AFB 6534)	Closed	Non-Taskworthy	No	Level 2	06 Mar 2008	TUM GS SOFT TOP
000000-0005A9DB	000000-00270885	FIT PICK HEAD SECURING WING NUT (AFB 6534) (demanded UNICOM bid no. 2225)	Closed	Fully Fit	No	Level 1	20 Mar 2007	TUM GS SOFT TOP
000000-0008774C		Fit missing valve caps	Closed	Fully Fit	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-0008774E		Paint rear tow eye red	Closed	Fully Fit	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-000C8AAC	000000-00273849	indicators and hazards inop	Closed	Non-Taskworthy	No	Level 2	31 Jan 2008	TUM GS SOFT TOP
000000-00087746	000000-00276031	Renew rear diff input seal	Closed	Fully Fit	No	Level 2	05 Sep 2007	TUM GS SOFT TOP
000000-000A4D05	000000-00276031	l/h/f indicator inop	Closed	Non-Taskworthy	No	Level 2	12 Dec 2007	TUM GS SOFT TOP
000000-0008774F		Paint convoy plate (rear diff) white	Closed	Fully Fit	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-000996FA	000000-00274F4A	ELECTRICAL PROBLEM WITH FRONT R/H/SIDE HEADLIGHT	Closed	Non-Taskworthy	No	Level 2	01 Nov 2007	TUM GS SOFT TOP
000000-0009BCC0		Fit Tailgate	Closed	Limited Role	No	Level 1	09 Nov 2007	TUM GS SOFT TOP
000000-0008774D		Paint fuel cap yellow	Closed	Fully Fit	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-00087748		Renew R/H wing mirror	Closed	Non-Taskworthy	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-0008774B		Remove spare from bonnet	Closed	Non-Taskworthy	No	Level 1	05 Sep 2007	TUM GS SOFT TOP
000000-00087741	000000-00272287	Renew brake fluid	Closed	Non-Taskworthy	No	Level 2	05 Sep 2007	TUM GS SOFT TOP
000000-00087743	000000-00272287	Strip, clean + examine rear drum brakes	Closed	Non-Taskworthy	No	Level 2	05 Sep 2007	TUM GS SOFT TOP
000000-00087745	000000-00272287	Strip, clean + examine transmission brake	Closed	Non-Taskworthy	No	Level 2	05 Sep 2007	TUM GS SOFT TOP
000000-0005A9DD	000000-0026EF33	RE-PAINT & STENCIL FRONT & REAR DIFF (AFB 6534)	Closed	Fully Fit	No	Level 1	20 Mar 2007	TUM GS SOFT TOP
000000-0005A9EE		FIT REAR CANOPY SECURING LOOPS (AFB 6534)	Closed	Fully Fit	No	Level 1	20 Mar 2007	TUM GS SOFT TOP
000000-0005A9D4	000000-0026D30E	HD/LT DVR SIDE INOP (AFB 6534)	Closed	Non-Taskworthy	No	Level 2	20 Mar 2007	TUM GS SOFT TOP
000000-0005A9E6	000000-0026D30E	FREE OFF FAN LEAVER SIESED (AFB 6534)	Closed	Fully Fit	No	Level 2	20 Mar 2007	TUM GS SOFT TOP

000000-0005A546	000000-0026D119	Rectify R/H Headlamp INOP	Closed	Non-Taskworthy	No	Level 2	19 Mar 2007	TUM GS SOFT TOP
000000-0004E507		INDICATORS INOP (FUSE AND BULBS CHECKED)	Closed	Non-Taskworthy	No	Level 2	13 Feb 2007	TUM GS SOFT TOP
000000-0003B4F2	000000-0026AD31	WIPER MOTOR U/S	Closed	Non-Taskworthy	No	Level 2	21 Nov 2006	TUM GS SOFT TOP
000000-0002C2A8		Initial Usage	Closed	Fully Fit	No	Level 1	08 Sep 2006	TUM GS SOFT TOP
000000-0002C2AE		Initial Maintenance	Closed	Fully Fit	No	Level 1	08 Sep 2006	TUM GS SOFT TOP

Work Objects

Serial Number: 86KE41
 NSN: 2320998937004

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00141C98		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0010F91D		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-001177CD		No	MEI (2)	05 Jan 2012	Level 2			000:00		
000000-00085C57		No	MEI (2)	05 Jan 2012	Level 2		CL	000:00		
000000-0009667D		No	MEI (2)	05 Jan 2012	Level 2		CL	000:00		
000000-000A0F42		No	MEI (2)	05 Jan 2012	Level 2		CL	000:00		
000000-000AB093		No	MEI (2)	05 Jan 2012	Level 2		CL	000:00		
000000-0003827E		No	MEI (2)	05 Jan 2012	Level 2		CL	000:00		
000000-000D2250		No	MEI (2)	05 Jan 2012	Level 2		CL	000:00		

Work Objects

Serial Number: 86KE41
NSN: 2320998937004

Criteria:
Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL
Work Request ID:
Assigned Work Status: ALL
Working Organisation:
Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0001F94E	00026	Wheel Rim Change		No	-/	RTI				Fully Fit	CL				

Work Objects

Serial Number: 86KE41
 NSN: 2320998937004

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-001177C6		No	6 Monthly/10000 Kms	06 Jul 2011	Level 1			000:00		
000000-0010F920		No	80000 Kms (2)	13 May 2032	Level 1			000:00		
000000-0010F912		No	Weekly (AR)(1)		Level 1			000:00		
000000-000763E3		No	6 Monthly/10000 Kms	06 Jul 2011	Level 1		CL	000:00		
000000-0007722A		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000DE279		No	6 Monthly/10000 Kms	06 Jul 2011	Level 1		CL	000:00		
000000-0007F68A		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000835C2		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-00085D4B		No	2 Yearly/40000 Kms	28 Jan 2012	Level 1		CL	000:00		
000000-00085D4C		No	6 Monthly/10000 Kms	06 Jul 2011	Level 1		CL	000:00		
000000-00085D4D		No	Yearly/20000 Kms	05 Jan 2012	Level 1		CL	000:00		
000000-0008C4AA		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000E4E13		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-0008CE65		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000FF32B		No	6 Monthly/10000 Kms	06 Jul 2011	Level 1		CL	000:00		

000000-00097C42	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000D5EA5	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A1A2D	No	Yearly/20000 Kms	05 Jan 2012	Level 1	CL	000:00
000000-000A1A2E	No	6 Monthly/10000 Kms	06 Jul 2011	Level 1	CL	000:00
000000-000763E2	No	Yearly/20000 Kms	05 Jan 2012	Level 1	CL	000:00
000000-00007252	No	6 Monthly/10000 Kms	06 Jul 2011	Level 1	CL	000:00
000000-00011C12	No	36000 Kms (2)	09 Mar 2026	Level 2	CL	000:00
000000-0003623F	No	6 Monthly/10000 Kms	06 Jul 2011	Level 1	CL	000:00
000000-00036278	No	Yearly/20000 Kms	05 Jan 2012	Level 1	CL	000:00
000000-00036195	No	2 Yearly/40000 Kms	28 Jan 2012	Level 1	CL	000:00
000000-0005926E	No	6 Monthly/10000 Kms	06 Jul 2011	Level 1	CL	000:00
000000-00141C97	No	Weekly (AR)(1)		Level 1		000:00
000000-001177CB	No	Yearly/20000 Kms	05 Jan 2012	Level 1		000:00