



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH

LLB(Hons)



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

email: [redacted]

Our Reference:
FOI2021/06510

Date:
24 June 2021

Dear Mr [redacted]

I am writing about your email of 17 June 2021, requesting the following information:

I have recently purchased a Land Rover 110 Wolf XD (TUM) and believe it to have been previously in active service with the army.

Please would you provide me with its in-service history.

It's MOD registration number was KH81AA and its chassis number is SALLDBA67VA124844.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Ownership History
Annex B - Fault History (redacted)
Annex C – Inspection History
Annex D – Modification History
Annex E – Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor

Defence Equipment & Support

information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

[REDACTED]

[REDACTED]

DE&S Policy Secretariat Asst Hd

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
KH81AA	2320998939940	NB50173100	LV2A/088DUM	TRUCK UTY MED (TUM)(HS) 4X4 GS (HARD TOP) LAND ROVER 2.5LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
07/08/1997	SALLDBA67VA124844	25LO2056A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
KH81AA	3	06/08/1997	CA005A	JSCS ASHCHURCH	CAPITA	28225AA	07/08/1997	
KH81AA	4	01/10/1997	A0377A	34 FD SQN (AIR SP)	33891A	427	10/10/1997	
KH81AA	4	08/02/2007	A0388A	39 ENGR REGT 48 SQN	155	1370	08/02/2007	Y17
KH81AA	2	22/11/2010	A0360A	10 FD SQN (AS) 39 ENGR REGT	81798	123824	13/01/2011	B41
KH81AA		03/04/2014		39 ENGR REGT 60 HQ SQN (AS)			30/04/2014	
KH81AA		28/10/2016		35 ENGR REGT LAD			24/11/2016	
KH81AA		19/01/2018		SEF (G) STORED FLEET			24/05/2018	

Work Objects

Serial Number: KH81AA
NSN: 2320998939744

Criteria:
Repair Level: ALL
Work Object Status: Closed
Mission Impact: ALL
Fault State: ALL
Escalate Work: ALL
Work Request ID:
Assigned Work Status: ALL
Working Organisation:
Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A41C96		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451D	28 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A0E3DD		Renew brake light switch	Closed	Fully Fit	No	Level 2		16 Mar 2017	N/A	Failure	TUM HS FFR HARD TOP			
000000-00A5707C		WINDSCREEN WASHER INOP	Closed	Non-Taskworthy	No	Level 2		14 Sep 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E9BBB		Rectify bolt missing at slam panel	Closed	Fully Fit	No	Level 2		30 Nov 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-009E9B85		Secure L/H/F wheel arch eyebrow	Closed	Fully Fit	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E9B54		Secure rear brake lines correctly	Closed	Fully Fit	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E9B7B		Secure wiper motor cowlng	Closed	Fully Fit	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E9B50		Rectify convoy light INOP	Closed	Limited Role	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CFE		INVESTAGATE FREE PLAY AT T-BOX OUTPUT TO FRONT AXLE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-009D7CE1		NUMBER PLATE LIGHT COVER BROKE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-009D7CDE		DASH TRIM INSECURE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A03025	000000-00323870	Investigate loss of oil	Closed	Non-Taskworthy	No	Level 3		17 Feb 2017	N/A	Closed No Action	TUM HS FFR HARD TOP	3 CIV WKSP REME		
000000-00A03DED	000000-00323344	Engine failure	Closed	Fully Fit	No	Level 3		16 Feb 2017	N/A	Failure	TUM HS FFR HARD TOP			
000000-009E9B76	000000-00323344	Weld and paint A pillar at passanger door	Closed	Fully Fit	No	Level 2		29 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	3 CIV WKSP REME	A & G	
000000-009E9B71	000000-00323344	Derust and paint at rear door	Closed	Fully Fit	No	Level 2		29 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	3 CIV WKSP REME	A & G	
000000-009E9B60	000000-00323344	Derust and paint passanger footwell	Closed	Fully Fit	No	Level 2		29 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	3 CIV WKSP REME	A & G	
000000-009E9B5A	000000-00323344	Derust and paint drivers footwell	Closed	Fully Fit	No	Level 2		29 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP	3 CIV WKSP REME	A & G	
000000-009E9BA8		Investigate oil at gearbox bell housing	Closed	Fully Fit	No	Level 2		30 Nov 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-009E9B4B		Renew R/H/F shock housing retaining ring	Closed	Non-Taskworthy	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E9B44		Rectify play at R/H/R wheel bearing	Closed	Non-Taskworthy	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E8B36		Chnage headlights to left hand drive	Closed	Non-Taskworthy	No	Level 2		30 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009E9BAD		Rectify coolant level	Closed	Fully Fit	No	Level 1		30 Nov 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-009D7CFA		REAR ANTI-ROLL BAR BUSHES PERISHED	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CE8		REAR BRAKE LINES INSECURE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CE7		BOTH FRONT SHOCK BUSHES UNSERVICEABLE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CE6		DVR SIDE SEAT BELT UNSERVICEABLE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CCB		EARTH STRAP PAS SIDE DOOR SNAPPED	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CCA		EGR PUG CONNECTION INSECURE	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CC7		COLLANT LEAK	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CC2		REPLACE BOTH FRONT SPRINGS	Closed	Fully Fit	No	Level 2		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009D7CA5		P/S REAR TAIL LIGHT WRONG BULB	Closed	Fully Fit	No	Level 1		26 Oct 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-0099428A		REPLACE FUEL CAP	Closed	Fully Fit	No	Level 1		17 May 2016	N/A	Damage	TUM HS FFR HARD TOP			
000000-009667D4		EXCESSIVE PLAY AT NO. 3 & 4 BALL JOINT	Closed	Fully Fit	No	Level 2		28 Jan 2016	N/A	Servicing	TUM HS FFR HARD TOP			
000000-009751C9		REPLACE WINDSCREEN WASHER SPRAY DIVERTER	Closed	Fully Fit	No	Level 2		29 Feb 2016	N/A	Refurbishment	TUM HS FFR HARD TOP			
000000-009662DA		F/L/H HUB TO AXLE MOUNT LOOSE & LEAKING	Closed	Fully Fit	No	Level 2		27 Jan 2016	N/A	Servicing	TUM HS FFR HARD TOP			
000000-0082069E		RENEW DOOR LOCKS	Closed	Fully Fit	No	Level 2		08 Jul 2014	N/A	Damage	TUM HS FFR HARD TOP		Support Troop 60 Sqn	
000000-00976C15		REPLACE LIFTING HARNESS DUE TO TORN STITCHING	Closed	Fully Fit	No	Level 1		03 Mar 2016	N/A	Refurbishment	TUM HS FFR HARD TOP			
000000-008D4C1E		REPLACE SPARE WHEEL AND TYRE	Closed	Limited Role	No	Level 1		03 Nov 2015	N/A	Refurbishment	TUM HS FFR HARD TOP			
000000-009616C4		Check No2 ball joint torque tightness as per safety notice LE SNve 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003207	19 Jan 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008A9ADB		REPLACE BATTERY BUZZER	Closed	Fully Fit	No	Level 1		08 Jul 2015	N/A	Damage	TUM HS FFR HARD TOP		C3S Troop	
000000-0095CA85		INSPECT NO2 BALL JOINT	Closed	Non-Taskworthy	No	Level 2		12 Jan 2016	N/A	Inspection	TUM HS FFR HARD TOP		60 SQN FTR SECT	
000000-008B9188		REPLACE DOOR HINGES	Closed	Non-Taskworthy	No	Level 2		25 Jun 2015	N/A	Damage	TUM HS FFR HARD TOP			
000000-0089D4A4		REPLACE PASSENGER DOOR HINGE AND BOLTS	Closed	Non-Taskworthy	No	Level 2		04 Jun 2015	N/A	Failure	TUM HS FFR HARD TOP			
000000-0088F037		BRAKE LIGHTS NOT WORKING	Closed	Non-Taskworthy	No	Level 2		28 Apr 2015	N/A	Failure	TUM HS FFR HARD TOP			
000000-008AC24A		REPLACE FIRE EXTINGUISHER	Closed	Limited Role	No	Level 1		15 Jul 2015	N/A	Refurbishment	TUM HS FFR HARD TOP			
000000-0083A70F		RENEW DOOR LOCKS	Closed	Fully Fit	No	Level 1		24 Sep 2014	N/A	Inspection	TUM HS FFR HARD TOP			
000000-0086E3F8		RE-CARRY OUT 6534 INSPECTION DUE TO LOST PAPERWORK.	Closed	Non-Taskworthy	No	Level 1		29 Jan 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00861AA1		CARRY OUT 2YEARLY L2	Closed	Fully Fit	No	Level 2		06 Jan 2015	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00861A6E		CARRY OUT 2YEARLY OOPM L2	Closed	Fully Fit	No	Level 2		06 Jan 2015	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00861A50		CARRY OUT 2YEARLY OOPM L1	Closed	Fully Fit	No	Level 1		06 Jan 2015	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00861A8C		CARRY OUT 2YEARLY L1	Closed	Fully Fit	No	Level 1		06 Jan 2015	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00865B91		CARRY OUT 6534	Closed	Fully Fit	No	Level 1		15 Jan 2015	N/A	Servicing	TUM HS FFR HARD TOP			
000000-0085BCC4		REPLACE ALL 5 TRYES	Closed	Non-Taskworthy	No	Level 1		04 Dec 2014	N/A	Failure	TUM HS FFR HARD TOP			
000000-0084297F		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUM HS FFR HARD TOP			
000000-00835CC0		RENEW TENSIONER PULLEY	Closed	Non-Taskworthy	No	Level 2		10 Sep 2014	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008315ED		COOLANT / WATER PUMP FAILURE	Closed	Non-Taskworthy	No	Level 2		28 Aug 2014	N/A	Failure	TUM HS FFR HARD TOP			
000000-00823719		INVESTIGATE WATER PUMP NOISE	Closed	Fully Fit	No	Level 2		15 Jul 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-0082B6C8		CARRY OUT 6 MONTHLY VM TASKS	Closed	Fully Fit	No	Level 2		06 Aug 2014	N/A	Servicing	TUM HS FFR HARD TOP			
000000-0082B6BD		CARRY OUT 6 MONTHLY SERVICE.	Closed	Fully Fit	No	Level 1		06 Aug 2014	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00815882		CARRY OUT OVERDUE MEI	Closed	Fully Fit	No	Level 2		09 Jun 2014	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00815881		CARRY OUT 6 MONTHLY LEVEL 2 SERVICE	Closed	Non-Taskworthy	No	Level 2		09 Jun 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00815880		CARRY OUT 6 MONTHLY LEVEL 1 SERVICE	Closed	Non-Taskworthy	No	Level 1		09 Jun 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-007C8C9C		RENEW WIPER MOTOR	Closed	Non-Taskworthy	No	Level 2		06 Nov 2013	N/A	Failure	TUM HS FFR HARD TOP			

000000-003D21FA	000000-00287747	WIPER'S DO NOT WORK	Closed	Non-Taskworthy	No	Level 2		16 Feb 2009	TUM HS FFR HARD TOP
000000-0036E678	000000-0026E97E	CARRY OUT LI MAINT IAW AESP 2320-D-128-601 TABLE 7 COL A.	Closed	Non-Taskworthy	No	Level 1		06 Jan 2009	TUM HS FFR HARD TOP
000000-0036E68C	000000-0026E97E	CARRY OUT L2 MAINT IAW AESP 2320-D-128-601 TABLE 7 COL A.	Closed	Non-Taskworthy	No	Level 2		06 Jan 2009	TUM HS FFR HARD TOP
000000-0033F607	000000-00285C20	WIPERS WONT TURN OFF	Closed	Limited Role	No	Level 2		28 Nov 2008	TUM HS FFR HARD TOP
000000-000EB417	000000-00282EF6	FIT EARTH BONDING STRIP TO PASSENGER DOOR	Closed	Fully Fit	No	Level 1		04 Mar 2008	TUM HS FFR HARD TOP
000000-000EB42B	000000-00282EF6	FIT NEW SEAT COVERS	Closed	Fully Fit	No	Level 1		04 Mar 2008	TUM HS FFR HARD TOP
000000-00206DDF		RENEW SPARE WHEEL	Closed	Limited Role	No	Level 1		14 Jul 2008	TUM HS FFR HARD TOP
000000-00206E08		RENEW FUEL FILLER PIPE AT NECK	Closed	Fully Fit	No	Level 2		14 Jul 2008	TUM HS FFR HARD TOP
000000-00206EE3		RENEW DVRS DOOR SEAL	Closed	Fully Fit	No	Level 2		14 Jul 2008	TUM HS FFR HARD TOP
000000-00206E0B	000000-0027E29A	RENEW FUEL FILLER PIPE AT NECK	Closed	Fully Fit	No	Level 2	RENEW DVRS DOOR SEAL	14 Jul 2008	TUM HS FFR HARD TOP
000000-001CDCC4	000000-0027CEB2	CARRY OUT 1 YEARLY SERVICE	Closed	Non-Taskworthy	No	Level 1		18 Jun 2008	TUM HS FFR HARD TOP
000000-001CDCC7	000000-0027CEB2	CARRY OUT 1 YEARLY QT'S	Closed	Non-Taskworthy	No	Level 2		18 Jun 2008	TUM HS FFR HARD TOP
000000-000CF564		Initial Usage	Closed	Fully Fit	No	Level 1		14 Feb 2008	TUM HS FFR HARD TOP
000000-000CF582		Initial Maintenance	Closed	Fully Fit	No	Level 1		14 Feb 2008	TUM HS FFR HARD TOP

Work Objects

Serial Number: KH81AA
 NSN: 2320998939744

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-001DD4E4		No	6 Monthly 6534 Insp	08 May 2018	Level 1			000:00		
000000-008B2EA3		No	MEI (2)	06 Nov 2018	Level 2	Fully Fit	CL	000:00		
000000-004C8D08		No	6 Monthly 6534 Insp	08 May 2018	Level 1			000:00		
000000-00739AA4		No	6 Monthly 6534 Insp	08 May 2018	Level 1	Fully Fit	CL	000:00		
000000-005D9C86		No	MEI (2)	06 Nov 2018	Level 2	Non-Taskworthy	CL	000:00		
000000-001643DB		No	6 Monthly 6534 Insp	08 May 2018	Level 1			000:00		
000000-0087791C	000000-0032BD5A	No	6 Monthly 6534 Insp	08 May 2018	Level 1	Limited Role	CL	000:00		
000000-00420C76		No	MEI (2)	06 Nov 2018	Level 2	Fully Fit	CL	000:00		
000000-00420CF9		No	6 Monthly 6534 Insp	08 May 2018	Level 1			000:00		
000000-008F92A9		No	6 Monthly 6534 Insp	08 May 2018	Level 1	Fully Fit	CL	000:00		
000000-00242DDE		No	6 Monthly 6534 Insp	08 May 2018	Level 1	Fully Fit	CL	000:00		
000000-002B245B		No	6 Monthly 6534 Insp	08 May 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0023DC51		No	MEI (2)	06 Nov 2018	Level 2	Non-Taskworthy	CL	000:00		
000000-000D5EED		No	MEI (2)	06 Nov 2018	Level 2		CL	000:00		
000000-000F6752		No	MEI (2)	06 Nov 2018	Level 2		CL	000:00		
000000-00101A5C		No	MEI (2)	06 Nov 2018	Level 2		CL	000:00		
000000-000FD394		No	MEI (2)	06 Nov 2018	Level 2		CL	000:00		

000000-00067B19	No	MEI (2)	06 Nov 2018	Level 2		CL	000:00
000000-000C2A32	No	First Parade Insp (AR)(1)		Level 1		CL	000:00
000000-007A17E2	No	MEI (2)	06 Nov 2018	Level 2	Fully Fit	CL	000:00
000000-0018978A	No	6 Monthly 6534 Insp	08 May 2018	Level 1			000:00
000000-005D9E4F	No	6 Monthly 6534 Insp	08 May 2018	Level 1			000:00
000000-00189789	No	MEI (2)	06 Nov 2018	Level 2			000:00
000000-0070A273	No	6 Monthly 6534 Insp	08 May 2018	Level 1	Fully Fit	CL	000:00
000000-007CA451	No	6 Monthly 6534 Insp	08 May 2018	Level 1	Non-Taskworthy	CL	000:00
000000-00739A82	No	MEI (2)	06 Nov 2018	Level 2	Fully Fit	CL	000:00

Work Objects

Serial Number: KH81AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-00718B06	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			000:00
000000-00702115	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			000:00
000000-007199E8	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL	Level 2			000:00
000000-00718280	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	-/-	UTI				Fully Fit	CL	Level 2			000:00
000000-00700A65	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			000:00
000000-006F76DD	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-00691C93	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-006F5638	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F71D5	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F4F42	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-0000794E	00002	Roof Mounted Communication Installation (Blanking Plate Only)		No	-/	RTI				Fully Fit	CL				
000000-000219D1	00016	Radio Battery Isolation Switch and Power Import / Export System		No	-/	RTI				Fully Fit	CL				
000000-0000C112	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Fully Fit	CL				
000000-000091A0	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit	CL				
000000-00018430	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL				
000000-000220B1	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL				
000000-0000B7EB	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL				
000000-000221BC	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL				

Work Objects

Serial Number: KH81AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-005F81CF		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System		Level 1	Fully Fit	CL	000:00		Support Troop 60 Sqn
000000-008B2EA0		No	Yearly/20000 Kms		Level 1	Fully Fit	CL	000:00		
000000-0043E455		No	6 Monthly/10000 Kms		Level 1	Fully Fit	CL	000:00		
000000-004C4457		No	Yearly/20000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-00151AC6		No	Weekly (AR)(1)		Level 1			000:00		
000000-001DBA84		No	6 Monthly/10000 Kms		Level 1			000:00		
000000-0058524E		No	Weekly (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-00206F3C		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		Level 2			000:00		
000000-001426B1		No	Yearly/20000 Kms		Level 1			000:00		
000000-0049735D		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-005EBF78		No	Weekly (AR)(1)		Level 1			000:00		
000000-005F81CC		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)		Level 2	Fully Fit	CL	000:00		Support Troop 60 Sqn
000000-004C4250		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		Level 1	Non-Taskworthy	CL	000:00		
000000-0023DC26		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		Level 1	Fully Fit	CL	000:00		
000000-0010F16E		No	5 Yearly/100000 Kms (1)		Level 1			000:00		
000000-00206F2D		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		Level 1			000:00		
000000-002B245C		No	6 Monthly/10000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-00616B58		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00206F1D		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System		Level 1			000:00		
000000-007B6C36		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-004C4226		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		Level 1	Non-Taskworthy	CL	000:00		
000000-001426B2		No	6 Monthly/10000 Kms		Level 1			000:00		
000000-00430EEE		No	Weekly (AR)(1)		Level 1			000:00		
000000-0087791F	000000-0032BD5A	No	6 Monthly/10000 Kms		Level 1	Limited Role	CL	000:00		
000000-004C4458		No	6 Monthly/10000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-00417BDC		No	6 Monthly/10000 Kms		Level 1	Fully Fit	CL	000:00		
000000-007C93C8		No	Yearly/20000 Kms		Level 1	Fully Fit	CL	000:00		
000000-00092D7E		No	2 Yearly/40000 Kms		Level 1		CL	000:00		
000000-0009BE81		No	Yearly/20000 Kms		Level 1		CL	000:00		
000000-000E62B5		No	6 Monthly/10000 Kms		Level 1		CL	000:00		
000000-000A8828		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000AF24A		No	6 Monthly/10000 Kms		Level 1		CL	000:00		

000000-000B0635	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-000AFAFD	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-000C76C9	No	2 Yearly/40000 Kms	Level 1	CL	000:00
000000-00008636	No	Yearly/20000 Kms	Level 1	CL	000:00
000000-000F85A3	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-0000E890	No	2 Yearly/40000 Kms	Level 1	CL	000:00
000000-0000E891	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-0000E892	No	Yearly/20000 Kms	Level 1	CL	000:00
000000-000BF9DB	No	First 1600 Kms (AR)	Level 2	CL	000:00
000000-0000E893	No	Weekly (AR)(1)	Level 1	CL	000:00
000000-00028687	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-000420E2	No	6 Yearly/120000 Kms (2)	Level 2	CL	000:00
000000-000420E3	No	Yearly/20000 Kms	Level 1	CL	000:00
000000-00042121	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-000FB6B8	No	First 1600 Kms (AR)	Level 2	CL	000:00
000000-00042122	No	Weekly (AR)(1)	Level 1	CL	000:00
000000-000F313A	No	6 Monthly/10000 Kms	Level 1	CL	000:00
000000-0023DC52	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	Level 1 Fully Fit	CL	000:00
000000-00242D13	No	6 Monthly/10000 Kms	Level 1	CW	000:00
000000-004C4225	No	2 Yearly/40000 Kms	Level 1 Non-Taskworthy	CL	000:00
000000-001426B0	No	2 Yearly/40000 Kms	Level 1		000:00
000000-0079A41D	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	Level 1 Fully Fit	CL	000:00
000000-0057EF2D	No	6 Monthly/10000 Kms	Level 1 Fully Fit	CL	000:00
000000-0079A4A0	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	Level 1 Non-Taskworthy	CL	000:00
000000-001DBA83	No	Yearly/20000 Kms	Level 1		000:00
000000-005F8229	No	Yearly/20000 Kms	Level 1 Fully Fit	CL	000:00
000000-0010B5AA	No	2 Yearly/40000 Kms	Level 1	CW	000:00
000000-00242D14	No	Yearly/20000 Kms	Level 1	CW	000:00
000000-006D251B	No	6 Monthly/10000 Kms	Level 1 Fully Fit	CL	000:00
000000-008BD38A	No	6 Monthly/10000 Kms	Level 1 Fully Fit	CL	000:00
000000-0079A41A	No	2 Yearly/40000 Kms	Level 1 Fully Fit	CL	000:00
000000-00616EE3	No	Weekly (AR)(1)	Level 1 Fully Fit	CL	000:00
000000-007B6C38	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	Level 1 Non-Taskworthy	CL	000:00
000000-0018979A	No	6 Monthly/10000 Kms	Level 1		000:00
000000-00206F32	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	Level 2		000:00
000000-0023DC68	No	6 Monthly/10000 Kms	Level 1 Fully Fit	CL	000:00
000000-007B6C61	No	Weekly (AR)(1)	Level 1 Non-Taskworthy	CL	000:00
000000-00636836	No	6 Monthly/10000 Kms	Level 1 Non-Taskworthy	CL	000:00
000000-0039A4B0	No	Yearly/20000 Kms	Level 1 Fully Fit	CL	000:00
000000-00206F30	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	Level 1		000:00
000000-007C93C7	No	6 Monthly/10000 Kms	Level 1 Fully Fit	CL	000:00

Support Troop 60 Sqn