



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]
[REDACTED]

Our Reference:
FOI2021/02936
Date:
23 March 2021

Dear [REDACTED],

I am writing about your email of 12 March 2021, requesting the following information:

Could you give me the history of my land rover LEFOP -1308 MB 74AA TUM HSGS SOFT TOP please

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

- Annex A - Ownership History
- Annex B - Fault History (redacted)
- Annex C - Inspection History
- Annex D - Modification History
- Annex E - Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Defence Equipment & Support

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MB74AA	2320998939963	NB50103101	LV2A/088DUM	TRUCK UTY MED (TUM HS) 4X4 SOFT TOP LANDROVER 2.5LTR TURBO DSL (WITH EEGR)	Civilian Trade Finish

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
28/04/1998	SALLDBA67WA143257	25L05613B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MB74AA	3		CA005A	JSCS ASHCHURCH		34113AA	28/04/1998	
MB74AA	3	10/02/1998	CA301C	JSU CYPRUS VEH SECTION	44188A	2703TT	10/02/1999	
MB74AA	4	23/02/1999	A0560A	2 ANG	2283T	4189	24/02/1999	
MB74AA	4	03/02/2000	A0571A	1 MERCIAN	759	1	09/03/2000	H/T
MB74AA	4	09/02/2002	A2265A	3 RIFLES	486	1	14/02/2002	H/T
MB74AA	4	26/02/2004	A0590A	1 LANCS	728	7	01/03/2004	H/T
MB74AA	4	28/11/2005	A0556A	2 RRF	249	2530	29/11/2005	H/T
MB74AA	4	13/05/2010	A1259A	2 PWRR	999	37255	13/05/2010	H/T
MB74AA	2	14/09/2010	A0560A	2 R ANGLIAN	MCR11	MCR11	14/09/2010	MCR
MB74AA		17/08/2012	A0556A	2 RRF			17/08/2012	
MB74AA		26/08/2014	A1259G	2 PWRR MT			26/08/2014	

MB74AA		11/08/2017	A0560A	2 R ANGLIAN			11/08/2017	
MB74AA		12/03/2019	A1038A	ASHCHURCH MT			12/03/2019	
MB74AA		07/05/2019	A5969A	SEF (UK) ASHCHURCH			07/05/2019	

Work Objects

Serial Number: MB74AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A9DAF8		6.4 - SPARE WHEEL MISSING	Closed	Limited Role	No	Level 1		12 Mar 2018	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00A9DAF3		8.2 - OFFSIDE WIPER BLADE DAMAGED	Closed	Non-Taskworthy	No	Level 1		12 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A9DAF5	000000-003328A3	RE-CERTIFY ALL NON TASKWORTHY JOBS BY 10/04/2018	Closed	Non-Taskworthy	No	Level 2		12 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A9DB11	000000-003328A3	2 - NO SIDE LIGHTS WHEN CONVOY AND SIDE SELECTED	Closed	Non-Taskworthy	No	Level 2		12 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A9DAF6	000000-003328A3	6.2 - PASSENGER SEAT TORN	Closed	Fully Fit	No	Level 2		12 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A9DAF1	000000-003328A3	1.8 - NEARSIDE HEADLIGHT NOT FITTED CORRECTLY	Closed	Non-Taskworthy	No	Level 2		12 Mar 2018	N/A	Inspection	TUM HS GS SOFT TOP			000:00
000000-00A396FD	000000-00329795	PLEASE DEMAND AND FIT TYRE	Closed	Non-Taskworthy	No	Level 2		10 Jul 2017	N/A	Servicing	TUM HS GS SOFT TOP			
000000-00A396F7	000000-00329795	PLEASE INVESTIGATE AGGRESSIVE SHAKING AFTER 40 KPH	Closed	Non-Taskworthy	No	Level 2		10 Jul 2017	N/A	Servicing	TUM HS GS SOFT TOP			
000000-00A0B12A	000000-003244F7	RENEW EXPANTION TANK	Closed	Fully Fit	No	Level 2		02 Mar 2017	N/A	Damage	TUM HS GS SOFT TOP			
000000-009FD97A		RENEW CLUTCH	Closed	Fully Fit	No	Level 2		05 Feb 2017	N/A	Servicing	TUM HS GS SOFT TOP			
000000-00A0ED39		MAP LIGHT INOPERATIVE	Closed	Fully Fit	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A1050D		PLEASE REPAIR ALL NON-TASKWORTHY FAULTS WITHIN 28 DAYS ON PRESENT TO INSPECTIONS FOR RE-MEI.	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ED3B		DRIVERS SEAT BELT PROTECTOR MOD FITTED INCORRECTLY	Closed	Fully Fit	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ED2B		2.7 OFFSIDE STEERING DAMPER BUSHES PERISHED	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ED3F		6.1 ASSESS AND REPAIR VARIOUS CORROSION PATCHES AT DRIVER AND PASSENGER FOOTWELLS	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ED19		2.4 OFFSIDE FRONT RADIUS ARM BUSH SPLIT	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ED13		2.4 NEARSIDE FRONT RADIUS ARM BUSH SPLIT	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ED07		2.4 OFF-SIDE FRONT ANTI ROLL BAR BUSH PERISHED	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ECF7		2.4 BOTH FRONT ANTI ROLL BAR BALL JOINT BOOT BUSHES SPLIT	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0ECF7		OBSERVE OIL LEAK AT SUMP	Closed	Fully Fit	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0EC71		2.4 OFFSIDE REAR LINK ARM BOTTOM BUSH SPLIT	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0EC66		2.4 A FRAME BALL JOINT BOOT COMPLETELY PERISHED	Closed	Non-Taskworthy	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0EC60		SMALL HOLE IN REAR PORTION OF EXHAUST	Closed	Fully Fit	No	Level 2		19 Mar 2017	N/A	Inspection	TUM HS GS SOFT TOP			
000000-00A0A0F6	000000-003244F7	RENEW BOTH FRONT TYRES	Closed	Non-Taskworthy	No	Level 2		08 Mar 2017	N/A	Failure	TUM HS GS SOFT TOP			
000000-009DFE9F	000000-0031F52A	RENEW F.I.P.	Closed	Fully Fit	No	Level 2		13 Nov 2016	N/A	Damage	TUM HS GS SOFT TOP			
000000-009E3B8D	000000-0031F52A	PLEASE FIT MOD 39 NEW SEATBELTS AS REQUIRED	Closed	Non-Taskworthy	No	Level 2		20 Nov 2016	N/A	Modification	TUM HS GS SOFT TOP			
000000-009DD150	000000-0031F52A	oil leak	Closed	Non-Taskworthy	No	Level 2		02 Nov 2016	N/A	Closed No Action	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-009ACB3D		please check vehicle starter mortor	Closed	Fully Fit	No	Level 2		06 Jul 2016	N/A	Servicing	TUM HS GS SOFT TOP			
000000-00992769	000000-003170D5	indicator lights stay on permanant	Closed	Limited Role	No	Level 2		12 May 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0099A96B	000000-003182AF	INDECAORS DONT FLASH	Closed	Non-Taskworthy	No	Level 2		05 Jun 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0099B37E	000000-003182AF	INVESTEGATE DRAG LINK BALL JOINTS	Closed	Non-Taskworthy	No	Level 2		05 Jun 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00990EED	000000-00316EFA	STEERING SHAKES	Closed	Non-Taskworthy	No	Level 2		03 May 2016	N/A	Damage	TUM HS GS SOFT TOP			
000000-0096D5CF		TOP RUBBER PAD FROM WEAPON RACK MISSING	Closed	Fully Fit	No	Level 1		10 Feb 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0098ADFC	000000-003155D8	please replace two front wheel due to below legal requirement	Closed	Non-Taskworthy	No	Level 2		24 Apr 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00984A85	000000-003155D8	oil leak from engine bay	Closed	Non-Taskworthy	No	Level 2		06 Apr 2016	N/A	Inspection	TUM HS GS SOFT TOP			
000000-0096D5D4	000000-00313146	RECERTIFY MEI BY 10/03/16	Closed	Non-Taskworthy	No	Level 2		10 Feb 2016	N/A	Inspection	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0096D5D3	000000-00313146	REAR BACK BUSH ON RIGHT LINK ARM HAS PLAY	Closed	Non-Taskworthy	No	Level 2		10 Feb 2016	N/A	Inspection	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0096D5D1	000000-00313146	RENEW DVRS SEAT BELT	Closed	Non-Taskworthy	No	Level 2		10 Feb 2016	N/A	Inspection	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0096D5D0	000000-00313146	RENEW DVRS SEAT BACK REST DUE TO POOR CONDITION.	Closed	Fully Fit	No	Level 2		10 Feb 2016	N/A	Inspection	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0096D5CE	000000-00313146	DVRS DOOR HANDLE MISSING	Closed	Fully Fit	No	Level 2		10 Feb 2016	N/A	Inspection	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0096A335		RENEW 6 WAY SWITCH TO 7WAY	Closed	Fully Fit	No	Level 2		31 Jan 2016	N/A	Modification	TUM HS GS SOFT TOP			
000000-0096A334		REPAIR BRAKE LIGHT SWITCH	Closed	Non-Taskworthy	No	Level 2		31 Jan 2016	N/A	Failure	TUM HS GS SOFT TOP			
000000-008E0D4C		RENEW STARTER MOTOR	Closed	Non-Taskworthy	No	Level 2		01 Dec 2015	N/A	Failure	TUM HS GS SOFT TOP			
000000-00960C82		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-000031EE	19 Jan 2016	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-008D5C57		REMOVE SNORKEL AND FIT STANDARD AIR INTAKE	Closed	Fully Fit	No	Level 2		04 Nov 2015	N/A	Modification	TUM HS GS SOFT TOP			
000000-008B61B0		spare tyre punched	Closed	Non-Taskworthy	No	Level 2		10 Aug 2015	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-008E5D9C		REPLACE BALL JOINTS 2, 3 & 4 (CASTELLATED NUTS)	Closed	Non-Taskworthy	No	Level 2		15 Dec 2015	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-008B61AA	000000-0030A93E	drivers side door fails to shut	Closed	Non-Taskworthy	No	Level 2		11 Aug 2015	N/A	Closed No Action	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-008B61A9	000000-0030A93E	fuel gaudge inop	Closed	Non-Taskworthy	No	Level 2		11 Aug 2015	N/A	Closed No Action	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0085DF9D	000000-003002C9	PRESENT FIRE EXT AND JACK TO INSPECTIONS	Closed	Limited Role	No	Level 1		09 Dec 2014	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-00895E4C	000000-003069A3	BOTH FRONT TYRES INSP	Closed	Non-Taskworthy	Yes	Level 2		17 May 2015	No Effect	Inspection	TUM HS GS SOFT TOP	COSU JMETS DI VRS		
000000-0084D4F5	000000-003002C9	RENEW TOWING PINTLE	Closed	Limited Role	No	Level 2		29 Oct 2014	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-0084493E	000000-002FE399	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	08 Oct 2014	Degraded	Inspection	TUM HS GS SOFT TOP			
000000-008420DA		Towing Pintle Assembly	Closed	Limited Role	No	Level 2		06 Oct 2014	N/A	Closed No Action	TUM HS GS SOFT TOP			
000000-007BFD53		Please rectify canopy and renew	Closed	Limited Role	No	Level 1		12 Oct 2013	N/A	Failure	TUM HS GS SOFT TOP			
000000-00800159	000000-002F5855	PLEASE CARRY OUT 6MTHLY L2	Closed	Fully Fit	No	Level 2		08 Apr 2014	N/A	Servicing	TUM HS GS SOFT TOP			
000000-00800158	000000-002F5855	PLEASE CARRY OUT 6MTHLY L1	Closed	Fully Fit	No	Level 1		08 Apr 2014	N/A	Servicing	TUM HS GS SOFT TOP			

000000-00803226	000000-002F5855	PLEASE RECTIFY FRONT LEFT SIDE TYRES RENEW	Closed	Non-Taskworthy	No	Level 2	21 Apr 2014	No Effect Servicing	TUM HS GS SOFT TOP
000000-00803224	000000-002F5855	PLEASE RECTIFY STEERING WHEEL IN OP	Closed	Non-Taskworthy	No	Level 2	21 Apr 2014	No Effect Servicing	TUM HS GS SOFT TOP
000000-00803213	000000-002F5855	PLEASE RECTIFY LHS MAIN HEAD LIGHT IN OP	Closed	Non-Taskworthy	No	Level 2	21 Apr 2014	No Effect Servicing	TUM HS GS SOFT TOP
000000-00802A8E	000000-002F5855	PLEASE CARRY OUT ENGINE CHECKS FOR LEAKS	Closed	Non-Taskworthy	No	Level 2	16 Apr 2014	N/A Inspection	TUM HS GS SOFT TOP
000000-0080015A	000000-002F5855	PLEASE CARRY OUT 6534	Closed	Fully Fit	No	Level 1	08 Apr 2014	N/A Inspection	TUM HS GS SOFT TOP
000000-007F4AC9	000000-002F4253	PLEASE REPLACE WING MIRROR	Closed	Non-Taskworthy	No	Level 1	12 Mar 2014	N/A Damage	TUM HS GS SOFT TOP
000000-007F4AC5	000000-002F4253	PLEASE CARRY OUT 25 POINT CHECK	Closed	Fully Fit	No	Level 2	12 Mar 2014	N/A Servicing	TUM HS GS SOFT TOP
000000-007F4BDF	000000-002F4253	PLEASE RECTIFY HORN IN OP	Closed	Limited Role	No	Level 2	12 Mar 2014	No Effect Inspection	TUM HS GS SOFT TOP
000000-007CC05B	000000-002ECA73	RE-CERTIFY BY 11/12/13	Closed	Non-Taskworthy	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC056	000000-002ECA73	INV HIGH EMISSIONS - APPROCHING INSPECTION LIMIT	Closed	Fully Fit	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC059	000000-002ECA73	RENEW No 2, 3 AND 4 BALL JOINT BOOTS - PERISHING	Closed	Fully Fit	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC057	000000-002ECA73	INV HEAVY SEEPAGE AT STEERING BOX	Closed	Fully Fit	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC05A	000000-002ECA73	RENEW 1 X BONNET CES STRAP	Closed	Fully Fit	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC055	000000-002ECA73	DRAIN, FLUSH AND REPLENISH ENGINE LUBRICATION SYSTEM	Closed	Non-Taskworthy	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC054	000000-002ECA73	RENEW RHR REAR LINK ARM BUSH	Closed	Non-Taskworthy	No	Level 2	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007CC053	000000-002ECA73	RENEW DRIVERS WIPER BLADE	Closed	Non-Taskworthy	No	Level 1	13 Nov 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007C27DD	000000-002ECA73	PLEASE CARRY OUT MEI	Closed	Non-Taskworthy	No	Level 2	19 Oct 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-007AA879		PLEASE REPLACE CANOPY	Closed	Fully Fit	No	Level 1	07 Aug 2013	N/A Closed No Action	TUM HS GS SOFT TOP
000000-007B5BA0	000000-002EB502	R/H WING MIRROR NEEDS TIGHTENING	Closed	Fully Fit	No	Level 2	07 Sep 2013	N/A Failure	TUM HS GS SOFT TOP
000000-007B5B96	000000-002EB502	PLEASE RECTIFY BOLT ON BONNET SNAPPED	Closed	Fully Fit	No	Level 2	07 Sep 2013	N/A Failure	TUM HS GS SOFT TOP
000000-007BFD81	000000-002ECA73	please rectify number plate light	Closed	Limited Role	No	Level 2	12 Oct 2013	N/A Failure	TUM HS GS SOFT TOP
000000-007BFD78	000000-002ECA73	please rectify tailgate retaining cadle	Closed	Limited Role	No	Level 2	13 Oct 2013	N/A Closed No Action	TUM HS GS SOFT TOP
000000-007B5BA4	000000-002EB502	REAR CABLE DOOR MISSING	Closed	Fully Fit	No	Level 1	07 Sep 2013	N/A Failure	TUM HS GS SOFT TOP
000000-007C1F6D	000000-002ECA73	PLEASE CARRY OUT BRAKE FLUID CHANGE IAW 2 YEARLY SERVICE	Closed	Non-Taskworthy	No	Level 2	16 Oct 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-007BF8C9	000000-002ECA73	PLEASE CARRY OUT OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (2)	Closed	Non-Taskworthy	No	Level 2	12 Oct 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-007BF8C3	000000-002ECA73	PLEASE CARRY OUT OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	Closed	Non-Taskworthy	No	Level 1	12 Oct 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-007BF8C1	000000-002ECA73	PLEASE CARRY OUT 2 YEARLY L2	Closed	Non-Taskworthy	No	Level 2	12 Oct 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-007BF8BE	000000-002ECA73	PLEASE CARRY OUT 2YEARLY L1	Closed	Non-Taskworthy	No	Level 1	12 Oct 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-0079D0E3	000000-002E7CE7	PLEASE CARRY OUT REMUS MOD FIT	Closed	Fully Fit	No	Level 2	27 Jun 2013	N/A Closed No Action	TUM HS GS SOFT TOP
000000-0079C1B6		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835 25 Jun 2013	N/A Closed No Action	TUM HS GS SOFT TOP
000000-00799210		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A 23 Jun 2013	N/A Closed No Action	TUM HS GS SOFT TOP
000000-00781A6F	000000-002E4D9C	6 Monthly 6534 Insp	Closed	Fully Fit	No	Level 1	22 Apr 2013	N/A Inspection	TUM HS GS SOFT TOP
000000-00781A63	000000-002E4D9C	6 Monthly/10000 Kms L2	Closed	Fully Fit	No	Level 2	22 Apr 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-00781A5D	000000-002E4D9C	6 Monthly/10000 Kms L1	Closed	Fully Fit	No	Level 1	22 Apr 2013	N/A Servicing	TUM HS GS SOFT TOP
000000-0076FC2A	000000-002E2798	CARRY OUT MOD 39	Closed	Fully Fit	No	Level 2	28 Feb 2013	N/A Modification	TUM HS GS SOFT TOP
000000-00767701	000000-002E15A0	PLEASE INSP/RECTIFY TRACK ROD	Closed	Non-Taskworthy	No	Level 2	10 Feb 2013	N/A Failure	TUM HS GS SOFT TOP
000000-00755C52	000000-002DF6D4	Rear seats damaged	Closed	Fully Fit	No	Level 2	05 Dec 2012	N/A Damage	TUM HS GS SOFT TOP
000000-00755C4F	000000-002DF6D4	Fit tailgate lower seal	Closed	Fully Fit	No	Level 2	05 Dec 2012	N/A Damage	TUM HS GS SOFT TOP
000000-00755C4D	000000-002DF6D4	Renew bonnet bump stops	Closed	Fully Fit	No	Level 1	05 Dec 2012	N/A Failure	TUM HS GS SOFT TOP
000000-00748AA8	000000-002DE2E4	RE-INSPECT BEFORE 29 NOV 12	Closed	Non-Taskworthy	No	Level 2	29 Oct 2012	N/A Inspection	TUM HS GS SOFT TOP
000000-00748AA6	000000-002DE2E4	INVESTIGATE POWER STEERING FLUID LEAK	Closed	Non-Taskworthy	No	Level 2	29 Oct 2012	N/A Inspection	TUM HS GS SOFT TOP
000000-00748AA1	000000-002DE2E4	RE-AIM HEAD LIGHTS	Closed	Non-Taskworthy	No	Level 2	29 Oct 2012	N/A Inspection	TUM HS GS SOFT TOP
000000-00738DDD	000000-002DDD71	PLEASE CARRY OUT MEI	Closed	Fully Fit	No	Level 2	14 Sep 2012	N/A Inspection	TUM HS GS SOFT TOP
000000-00746F43	000000-002DDD71	Carry out 12 m L2 tasks IAW AESP 2320 D 128 601 table 7 col B	Closed	Non-Taskworthy	No	Level 2	12 Oct 2012	N/A Closed No Action	TUM HS GS SOFT TOP
000000-00746F42	000000-002DDD71	Carry out 12 m L1tasks IAW AESP 2320 D 128 601 table 7 col B	Closed	Non-Taskworthy	No	Level 1	12 Oct 2012	N/A Closed No Action	TUM HS GS SOFT TOP
000000-007433C9	000000-002DDD71	FRONT TYRE'S BOTH BOLD	Closed	Non-Taskworthy	No	Level 2	15 Oct 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-007433C7	000000-002DDD71	PLEASE FIT BONNET TIE DOWN STRAP	Closed	Non-Taskworthy	No	Level 2	15 Oct 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-007433C6	000000-002DDD71	PLEASE RECTIFY STEERING WHEEL (ALING MENT)	Closed	Non-Taskworthy	No	Level 2	15 Oct 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-007433C5	000000-002DDD71	PLEASE RECTIFY FRONT LEFT HAND BEAM (NOT WORKING)	Closed	Non-Taskworthy	No	Level 1	15 Oct 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-007433C4	000000-002DDD71	PLEASE RECTIFY DRIVER MIRROR (LOOSE)	Closed	Non-Taskworthy	No	Level 1	15 Oct 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-00738DDF	000000-002DDD71	PLEASE CARRY OUT 12M L2 IAW AS PER AESP	Closed	Fully Fit	No	Level 2	15 Sep 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-00738DDE	000000-002DDD71	PLEASE CARRY OUT 12M L1 IAW AS PER AESP	Closed	Fully Fit	No	Level 1	15 Sep 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-00742B6A		PLEASE CARRY OUT 12 M L1 AS PER AESP	Closed	Non-Taskworthy	No	Level 1	14 Oct 2012	N/A Closed No Action	TUM HS GS SOFT TOP
000000-00742B6B		PLEASE CARRY OUT 12 M L2 AS PER AESP	Closed	Non-Taskworthy	No	Level 2	14 Oct 2012	N/A Closed No Action	TUM HS GS SOFT TOP
000000-007280A8	000000-002DB9AE	PLEASE INSPECT AND REPAIR ENGINE CUTTING OFF	Closed	Non-Taskworthy	No	Level 2	19 Jul 2012	N/A Closed No Action	TUM HS GS SOFT TOP
000000-0072603E	000000-002DB9FE	FAULTY FUEL GUAGE	Closed	Non-Taskworthy	No	Level 2	12 Jul 2012	N/A Closed No Action	TUM HS GS SOFT TOP
000000-0071E498	000000-002DABFF	PLEASE INSPECT AND REPAIR LEAKING FUEL TANK	Closed	Non-Taskworthy	No	Level 2	18 Jun 2012	N/A Failure	TUM HS GS SOFT TOP
000000-0070A52D	000000-002D9222	PLEASE CARRY OUT L1 AND L2 TASKS IAW AESP 2320-D-128-601 TABBLE 7 COLUMN A	Closed	Non-Taskworthy	No	Level 2	16 Apr 2012	N/A Servicing	TUM HS GS SOFT TOP
000000-0070A531	000000-002D9222	PLEASE CARRY OUT AF B6534 IAW AESP 2300-A-050-013	Closed	Non-Taskworthy	No	Level 2	16 Apr 2012	N/A Inspection	TUM HS GS SOFT TOP
000000-0070A535	000000-002D9222	PLEASE INSPC ENGINE AS IT WILL NOT START	Closed	Non-Taskworthy	No	Level 2	16 Apr 2012	N/A Failure	TUM HS GS SOFT TOP
000000-00718435	000000-002D9222	RENEW FRONT & REAR SHOCKS	Closed	Fully Fit	Yes	Level 2	06 May 2012	N/A Failure	TUM HS GS SOFT TOP
000000-00718437	000000-002D9222	RENEW REAR BRAKE CALIPERS	Closed	Non-Taskworthy	Yes	Level 2	06 May 2012	N/A Failure	TUM HS GS SOFT TOP
000000-006F582B	000000-002D7744	FUEL LEAK FROM THE TANK	Closed	Non-Taskworthy	No	Level 2	12 Feb 2012	N/A Failure	TUM HS GS SOFT TOP
000000-006F06F4	000000-002D7256	PLEASE INSPECT AND REPAIR FUEL TANK LEAK	Closed	Non-Taskworthy	No	Level 2	29 Jan 2012	N/A Servicing	TUM HS GS SOFT TOP

000:00

Work Objects

Serial Number: MB74AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0022477B		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1			000:00		
000000-007DF3C1	000000-00322DD6	No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Non-Taskworthy	CL	000:00	COSU JMETS DHK	INSP
000000-00224779		No	MEI (2)	13 Mar 2019	Level 2			000:00		
000000-00471A62		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1			000:00		
000000-0032D57F		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0063B93B	000000-0030FEA9	No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-007537FE	000000-00322DD6	No	MEI (2)	13 Mar 2019	Level 2	Non-Taskworthy	CL	000:00	COSU JMETS DHK	INSP
000000-0032D57E		No	MEI (2)	13 Mar 2019	Level 2	Non-Taskworthy	CL	000:00		
000000-00948634		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00948631		No	MEI (2)	13 Mar 2019	Level 2	Non-Taskworthy	CL	000:00		
000000-0022477A		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-0027877D		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-006E8E9E		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Non-Taskworthy	WiP	000:00		
000000-00271539		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00519429		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1			000:00		
000000-003FF9C9		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1			000:00		
000000-005F3067	000000-0030FEA9	No	MEI (2)	13 Mar 2019	Level 2	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-00499B86		No	MEI (2)	13 Mar 2019	Level 2	Limited Role	CL	000:00		
000000-001E2ACF		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1			000:00		
000000-0087D2AA		No	6 Monthly 6534 Insp	11 Sep 2018	Level 1			000:00		

Work Objects

Serial Number: MB74AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0069E645	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00678246	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit					
000000-00639F3D	00038	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit					
000000-00639F3B	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL				
000000-00639F2C	00017	Introduction of Battery Retentior		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00639F2F	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installior		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00639F3C	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00639F3A	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00639F2D	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00639F25	00006	Fitting of Spare Wheel Tyre Inflation Valve Extensior		No	-/	RTI				Limited Role	CL	Level 2			
000000-00639F30	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-00639F2E	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0060DC42	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			

Work Objects

Serial Number: MB74AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate	Maintenance Event Name	Next Due Date	Repair	Fault State	Work	Estimated	Working	Repair
		Work			Level		Status	Repair Time	Organisation	Section
000000-00271538		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-005F307F	000000-0030FEA9	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	30 Nov 2020	Level 2	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-0076F46B	000000-0031F52A	No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-0090F51B	000000-0032EF2D	No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00317379		No	2 Yearly/40000 Kms	07 Feb 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-005D0089	000000-0030E00B	No	2 Yearly/40000 Kms	07 Feb 2020	Level 1	Fully Fit	CL	000:00	COSU JMETS DHK	VRS
000000-002224FC		No	Yearly/20000 Kms	07 Feb 2019	Level 1			000:00		
000000-00827C03	000000-0032855B	No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00317408		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	02 Feb 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-001E2AEA		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1			000:00		
000000-001FFF6B		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	30 Nov 2020	Level 2			000:00		
000000-001FFF29		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	30 Nov 2020	Level 1			000:00		
000000-008CA85E	000000-0032EF2D	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	02 Feb 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-005D008A	000000-0030E00C	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	02 Feb 2020	Level 1	Fully Fit	CL	000:00	COSU JMETS DHK	VRS
000000-0090F51A	000000-0032EF2D	No	Yearly/20000 Kms	07 Feb 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-006A4F06		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Limited Role	CL	000:00		
000000-005F3068	000000-0030FEA9	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	30 Nov 2020	Level 1	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-00471A73	000000-002FE399	No	Yearly/20000 Kms	07 Feb 2019	Level 1	Fully Fit	CL	000:00		
000000-001FFF8C		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	02 Feb 2022	Level 2			000:00		
000000-0031740B		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	02 Feb 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-001FFEEE		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	02 Feb 2020	Level 1			000:00		
000000-0031740A		No	Yearly/20000 Kms	07 Feb 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-001FFEA1		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	02 Feb 2020	Level 1			000:00		
000000-005FE3A6	000000-0030E00B	No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Fully Fit	CL	000:00	COSU JMETS DHK	VRS
000000-00401C1E		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-005FE3A5	000000-0030E00B	No	Yearly/20000 Kms	07 Feb 2019	Level 1	Fully Fit	CL	000:00	COSU JMETS DHK	VRS
000000-005F3086	000000-0030FEA9	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	02 Feb 2022	Level 2	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-0049E9D6		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Fully Fit	CL	000:00		
000000-005D008B	000000-0030E00C	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	02 Feb 2020	Level 1	Fully Fit	CL	000:00	COSU JMETS DHK	VRS
000000-00549DF0	000000-0030772B	No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Fully Fit	CL	000:00	COSU JMETS DHK	VRS
000000-008CA875	000000-0032EF2D	No	2 Yearly/40000 Kms	07 Feb 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-00317409		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		

000000-00749FEA	000000-0031F52A	No	Yearly/20000 Kms	07 Feb 2019	Level 1	Non-Taskworthy	CL	000:00	COSU JMETS DHK	VRS
000000-008CA862	000000-0032EF2C	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	02 Feb 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-002224FD		No	6 Monthly/10000 Kms	08 Aug 2018	Level 1			000:00		