



Ministry
of Defence

[REDACTED] LLB (Hons)

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]

Our Reference:
FOI2021/03420
Date:
31 March 2021

Dear [REDACTED],

I am writing about your email of 25 March 2021, requesting the following information:

I've recently acquired an ex-MOD TUM HS FFR Hard Top with the following details:-

EAC/MAC = NB50203100

ERM = MU24AA

Chassis Number = SALLDBA67WA150587

Under the Freedom Of Information Act, I'm requesting MERLIN Report details pertaining to this vehicle's service within the MOD. I would be grateful if you could forward details at your earliest convenience.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

- Annex A - Ownership History
- Annex B - Fault History (redacted)
- Annex C - Inspection History
- Annex D - Modification History (redacted)
- Annex E - Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B) and Modification History (Annex D), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment

Defence Equipment & Support

to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault and modification reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

[Redacted Signature]

[Redacted Name]

DE&S Policy Secretariat 2 Asst Hd

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MU24AA	2320998939744	NB50203100	LV2A/088DUM	TRUCK UTY MED (TUM) (HS) 4X4 FFR HARD TOP LAND ROVER 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
02/07/1998	SALLDBA67WA150587	25L068861B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MU24AA	3		CA005A	JSCS ASHCHURCH		36030AA	02/07/1998	
MU24AA	3	03/12/1998	CA301C	JSU CYPRUS VEH SECTION	44256A	2780TT	01/03/1999	
MU24AA	4	15/04/1999	A0659A	259 SIG SQN	2402T	562	19/04/1999	
MU24AA	4	30/03/2004	A3441A	CYPRUS COMMUNICATIONS UNIT	MCR04	MCR04	30/03/2004	MCR
MU24AA	4	05/07/2005	N5382H	ISS SVC OPS CYPRUS	H/T	142&17	05/07/2005	H/T
MU24AA	2	28/11/2008	F7828A	LOGISTICS UNIT CYPRUS (AKROTIRI)	41	238	28/11/2008	A59
MU24AA		22/09/2016	A3967A	106 BN REME			22/09/2016	
MU24AA		05/10/2016	CA301C	COSU JMETS VSS			05/10/2016	
MU24AA		09/01/2017	A3712B	10 QOGLR 36 HQ SQN			09/01/2017	
MU24AA		25/01/2017	CA301C	COSU JMETS VSS			25/01/2017	
MU24AA		08/02/2017	A0222D	32 REGT RA 18 BTY			08/02/2017	

MU24AA		06/03/2017	CA301C	COSU JMETS VSS			06/03/2017	
MU24AA		31/03/2017	A3849A	NWOTR			31/03/2017	
MU24AA		13/04/2017	CA301C	COSU JMETS VSS			13/04/2017	
MU24AA		13/06/2017	A3720D	3 RLC 32 CS SQN			13/06/2017	
MU24AA		13/07/2017	CA301C	COSU JMETS VSS			13/07/2017	
MU24AA		07/09/2017	A6052A	3 R ANGLIAN			07/09/2017	
MU24AA		25/09/2017	CA301C	COSU JMETS VSS			25/09/2017	
MU24AA		10/01/2018	A1095A	7 REGT RLC			10/01/2018	
MU24AA		10/01/2018	A1095K	7 REGT RLC 9 SQN			10/01/2018	
MU24AA		07/02/2018	CA301C	COSU JMETS VSS			07/02/2018	
MU24AA		12/04/2018	A6054A	2 R IRISH			12/04/2018	
MU24AA		26/04/2018	CA301C	COSU JMETS VSS			26/04/2018	
MU24AA		12/06/2018	A4062A	4 RMP			12/06/2018	
MU24AA		25/06/2018	CA301C	COSU JMETS VSS			25/06/2018	
MU24AA		26/06/2018	A0820G	27 REGT RLC 8 FUEL SP SQN			26/06/2018	
MU24AA		24/07/2018	CA301C	COSU JMETS VSS			24/07/2018	
MU24AA		29/08/2018	A6044A	6 RIFLES (V)			29/08/2018	
MU24AA		13/09/2018	CA301C	COSU JMETS VSS			13/09/2018	
MU24AA		21/09/2018	A3431A	39 SIG REGT (V)			21/09/2018	
MU24AA		02/10/2018	CA301C	COSU JMETS VSS			02/10/2018	
MU24AA		10/10/2018	A6461A	6 REGT AAC			10/10/2018	
MU24AA		25/10/2018	CA301C	COSU JMETS VSS			25/10/2018	
MU24AA		07/08/2019	CA005A	BABCOCK ASHCHURCH			07/08/2019	
MU24AA		08/08/2019	D1832A	OSVP HOLDINGS			08/08/2019	


Work Objects

Serial Number: MU24AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B227E9		SNvE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B	29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00B1FBDE		SNvE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A	29 Mar 2019	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00AF701F		Chip on windscreen - Passengers Side	Closed	Fully Fit	No	Level 2		19 Nov 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00B084C0		SWITCH PANEL BROKEN	Closed	Fully Fit	No	Level 2		24 Jan 2019	N/A	Damage	TUM HS FFR HARD TOP			000:00
000000-00AF701E	000000-0033B465	REAR R/H CAB CRACKED	Closed	Fully Fit	No	Level 2		19 Nov 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AFC255		POWER STEERING LEAK	Closed	Non-Taskworthy	No	Level 2		03 Dec 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AFA91C		CRACK IN PASSENGER SIDE WINDSCREEN (INFORMED SGT HARRISON)	Closed	Fully Fit	No	Level 2		03 Dec 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00ADB51C		NO SEAT BELTS IN REAR	Closed	Limited Role	No	Level 2		11 Sep 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AFA917		TOW STROP AWAITING INSPECTION	Closed	Fully Fit	No	Level 2		03 Dec 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AFA8F6		NOT CHECKED SEE FMT 933	Closed	Limited Role	No	Level 1		03 Dec 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AFA8F3		BOWMAN NOT FITTED	Closed	Limited Role	No	Level 1		03 Dec 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AACDBB		VEHICLE OVERHAUL	Closed	Fully Fit	No	Level 2		30 Apr 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00ADB517		RE/R BODY CORNER DAMAGED	Closed	Fully Fit	No	Level 2		11 Sep 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A90714		A POST/ FLOOR PLATES STARTING TO CORRODE	Closed	Fully Fit	No	Level 2		06 Feb 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F9C		REAR DOOR LOWER SEAL U/S	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F99		FAN COWL IN CORRECTLY FITTED	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F94		NSF BRAKE PIPE COVER SPLIT	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F8C		FFR ALT POS CABLE SHEETH SPLIT	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F84		FFR ALT CLIP U/S	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F79		RADIATOR GRILL SPLIT	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC109F		BATT NEG TERM COVER MISSING	Closed	Fully Fit	No	Level 1		25 Jun 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00AC0F91		OSR POLE MOUNT BENT	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00AC0F80		FFR ALT BELT NEEDS ADJUSTING	Closed	Fully Fit	No	Level 2		25 Jun 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A59C91	000000-0032C484	STEERING DAMPER BUSHES PERISHED	Closed	Non-Taskworthy	No	Level 2		03 Jun 2018	N/A	Non Specific	TUM HS FFR HARD TOP			000:00
000000-00A94CB9		Renew Radiator	Closed	Fully Fit	No	Level 2		18 Feb 2018	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A8156B		REPLACE REAR DOOR SEAL	Closed	Fully Fit	No	Level 1		13 Dec 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A8156A		OIL SEEPAGE AT T/BOX -O-	Closed	Fully Fit	No	Level 2		13 Dec 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A81566		OIL SEEPAGE AT REAR DIFF	Closed	Fully Fit	No	Level 2		12 Dec 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A8156C	000000-0032C484	PLAY IN DRIVERS AND PASSENGER DOORS	Closed	Fully Fit	No	Level 2		13 Dec 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A98547		Rust on Right Hand A Post	Closed	Fully Fit	No	Level 2		27 Feb 2018	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A8A95F	000000-0032C484	dash spares	Closed	Fully Fit	No	Level 2		22 Jan 2018	N/A	Failure	TUM HS FFR HARD TOP			000:00
000000-00A71CBF	000000-0032C484	renew engine	Closed	Non-Taskworthy	No	Level 2		11 Nov 2017	N/A	Failure	TUM HS FFR HARD TOP			000:00
000000-00A59C61		RECTIFY LIFTIN STEERING COLUMN	Closed	Limited Role	No	Level 2		21 Sep 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A64F03	000000-0032C484	TIMING BELT	Closed	Non-Taskworthy	No	Level 2		16 Oct 2017	N/A	Inspection	TUM HS FFR HARD TOP			000:00
000000-00A5ADB0	000000-0032C484	RENEW TIMING BELT IAW 6 YRLY OOP MAINTENANCE	Closed	Non-Taskworthy	No	Level 2		24 Sep 2017	N/A	Servicing	TUM HS FFR HARD TOP			000:00
000000-00A41C6D		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451D	28 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00A3ED51	000000-0032A0E4	INJECTOR LEAK OFF PIPES LEAKING DIESEL	Closed	Non-Taskworthy	No	Level 2		23 Jul 2017	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008BD3FE		FIT MISIING BLACKOUT SCREEN PRESS STUDS	Closed	Fully Fit	No	Level 1		06 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008BD3A5		OBS SEEPAGE AT BOTH LOWER SWIVEL HOUSING	Closed	Fully Fit	No	Level 2		01 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A082D8	000000-00324215	ALTERNATOR CRACKED	Closed	Fully Fit	No	Level 2		05 Mar 2017	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00A082D4	000000-00324215	BOTH SHOCK ABSORBERS TURNING	Closed	Non-Taskworthy	No	Level 2		05 Mar 2017	N/A	Failure	TUM HS FFR HARD TOP			
000000-008BD3F3		REPLACE DIESEL DECAL FUEL CAP	Closed	Fully Fit	No	Level 1		06 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008BD3DB		ANTI VIBRATION RUBBERS FOR BONNET MISSING	Closed	Fully Fit	No	Level 1		06 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-0087D087		FIT MISSING HUB GREASE CAP	Closed	Fully Fit	No	Level 1		08 Mar 2015	N/A	Failure	TUM HS FFR HARD TOP			
000000-00836D9C		DVRS SEAT ADJUSTING MECH. INOP	Closed	Fully Fit	No	Level 1		10 Sep 2014	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00832333		REAR SOCK COVER	Closed	Fully Fit	No	Level 1		30 Aug 2014	N/A	Refurbishment	TUM HS FFR HARD TOP			
000000-00832331		RIFLE RACK FOAM MISSING	Closed	Fully Fit	No	Level 1		30 Aug 2014	N/A	Non Specific	TUM HS FFR HARD TOP			
000000-009DD9F9	000000-0031F2E2	RE-CERT BY 06/12/2016	Closed	Non-Taskworthy	No	Level 2		08 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009DD9F5	000000-0031F2E2	RENEW REAR STABILAISER BOTH B/JOINTS	Closed	Fully Fit	No	Level 2		08 Nov 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-009CE3D7	000000-0031D993	NS/OS TRACK SEALS LEAKING	Closed	Fully Fit	No	Level 2		04 Oct 2016	N/A	Non Specific	TUM HS FFR HARD TOP			
000000-009CE3D0	000000-0031D993	NO1 BALL JOINT BOOT SPLIT	Closed	Fully Fit	No	Level 2		04 Oct 2016	N/A	Non Specific	TUM HS FFR HARD TOP			
000000-009C50E6	000000-0031C8D5	renew x2 rear hub seals iaw maint sch	Closed	Non-Taskworthy	No	Level 2		13 Sep 2016	N/A	Servicing	TUM HS FFR HARD TOP			
000000-009C4FD0	000000-0031C8D5	RENEW NO1 AND NO2 BALL JOINTS	Closed	Non-Taskworthy	No	Level 2		13 Sep 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-0098FFCA	000000-003178DD	AIR FILTER BASE MOUNTINGS -O-	Closed	Fully Fit	No	Level 2		08 May 2016	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-008BD3B9		AIR FILTER MOUNTS PERISHED	Closed	Fully Fit	No	Level 2		05 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008BD3ED		FIRE EXT PASSED IT'S SHELF LIFE	Closed	Limited Role	No	Level 1		06 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-0098BFD3	000000-003163C2	6534 due 10/05/2016	Closed	Limited Role	No	Level 1		26 Apr 2016	N/A	Inspection	TUM HS FFR HARD TOP	COSU JMETS ENGCON	Inspection Cell	
000000-0095E9FA		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-000031C1	13 Jan 2016	N/A	Inspection	TUM HS FFR HARD TOP			
000000-008D685A	000000-0030ABBF	CARRY OUT FULL MEI	Closed	Non-Taskworthy	No	Level 2		05 Nov 2015	N/A	Inspection	TUM HS FFR HARD TOP			

000000-008BD3B0	000000-0030ABBF	No 1 BALLJOINT BOOT NOT SECURED CORRECTLY	Closed	Non-Taskworthy	No	Level 2	05 Sep 2015	N/A	Inspection	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-008BD7E5	000000-0030ABBF	RE-CERT NT FAULTS BY 05/10/15 OR VEH WILL REQ RE-MEI	Closed	Fully Fit	No	Level 2	06 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	Inspection Cell	
000000-008BD769	000000-0030ABBF	CARRYOUT MODS 2, 3, 40, 42 & 44	Closed	Fully Fit	No	Level 2	06 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-008BD545		NO CES PRESENTED ON MEI	Closed	Limited Role	No	Level 1	06 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-008BD401	000000-0030ABBF	INV LACK OF POWER POSSIBLE TURBO	Closed	Non-Taskworthy	No	Level 2	06 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-008BD3CC	000000-0030ABBF	DRIVERSEAT BELT FRAYED	Closed	Non-Taskworthy	No	Level 2	06 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-008BD3C8		RH COVER NEXT TO BONNET BROKE	Closed	Fully Fit	No	Level 1	06 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-008BD3AB		NO REAR SEAT BELTS FITTED	Closed	Limited Role	No	Level 1	01 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-008BD3AA	000000-0030ABBF	FREEPLAY IN No 1 & 2 BALLJOINTS	Closed	Non-Taskworthy	No	Level 2	01 Sep 2015	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-008BD399	000000-0030ABBF	OIL LEAK AT ENGINE PRESSURE SWITCH	Closed	Fully Fit	No	Level 2	31 Aug 2015	N/A	Inspection	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-00836DAA	000000-0030ABBF	RE-CERT.WITHIN 28 DAYS	Closed	Fully Fit	No	Level 2	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	Inspection Cell	
000000-00836DAC	000000-0030ABBF	CARRY OUT MOD INSTR. NO 38	Closed	Fully Fit	No	Level 2	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-00836D9E	000000-0030ABBF	CARRY OUT MOD INSTR.NO 33	Closed	Fully Fit	No	Level 2	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-0083232E	000000-0030ABBF	REAR DOOR GRAB HANDLE	Closed	Fully Fit	No	Level 2	30 Aug 2014	N/A	Modification	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-0083232D	000000-0030ABBF	REAR DOOR SEAL PERISHED	Closed	Fully Fit	No	Level 2	30 Aug 2014	N/A	Refurbishment	TUM HS FFR HARD TOP	COSU JMETS ENGCON	COSU VRS	
000000-0087D086	000000-0030ABBF	RENEW FANBELT	Closed	Fully Fit	No	Level 2	08 Mar 2015	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-0083232F	000000-0030ABBF	HOLES IN BONNET	Closed	Fully Fit	No	Level 2	31 Aug 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-0087D089		FIT MISSING WHEEL BRACE	Closed	Limited Role	No	Level 1	09 Mar 2015	N/A	No Fault Found	TUM HS FFR HARD TOP			
000000-0087D088		FIT MISSING REAR SAFETY BELT	Closed	Limited Role	No	Level 2	09 Mar 2015	N/A	Damage	TUM HS FFR HARD TOP			
000000-00874FB2		6534 INSPECTION	Closed	Fully Fit	No	Level 1	16 Feb 2015	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00836D8F		CLUTCH SLAVE CYLINDER WRONG WAY FITTED	Closed	Fully Fit	No	Level 2	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00836D9C		CARRY OUT MOD INSTR NO 20	Closed	Fully Fit	No	Level 2	10 Sep 2014	N/A	Modification	TUM HS FFR HARD TOP			
000000-00836D94		AIR FILTER BASE MOUNTINGS U/S	Closed	Fully Fit	No	Level 3	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00836D96		STRAIGHTEN R/H/R FLAG BKT	Closed	Fully Fit	No	Level 2	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-00836D8C		RECTIFY ENGINE BREATHER HOSE OIL LEAKS	Closed	Fully Fit	No	Level 2	11 Sep 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-0084294D		Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	09 Oct 2014	Degraded	Inspection	TUM HS FFR HARD TOP			
000000-00832335	000000-002FBA78	MODIFICATION INSPECTION	Closed	Non-Taskworthy	No	Level 2	31 Aug 2014	N/A	Modification	TUM HS FFR HARD TOP			
000000-007E84D2	000000-002F27BF	BATTERY BUZZER U/S	Closed	Non-Taskworthy	No	Level 2	11 Feb 2014	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-007AF07F	000000-002EA4D9	ANNUAL MEI	Closed	Non-Taskworthy	No	Level 2	27 Aug 2013	N/A	Inspection	TUM HS FFR HARD TOP			
000000-007AF07D	000000-002EA4D9	OOPM 5 YEARLY SER 3 COOLANT	Closed	Non-Taskworthy	No	Level 2	27 Aug 2013	N/A	Servicing	TUM HS FFR HARD TOP			
000000-007AF07A	000000-002EA4D9	OOPM 5 YEARLY SER 2.1 GEARBOX OIL	Closed	Non-Taskworthy	No	Level 1	27 Aug 2013	N/A	Servicing	TUM HS FFR HARD TOP			
000000-007AF075	000000-002EA4D9	12M VM TASKS	Closed	Non-Taskworthy	No	Level 2	27 Aug 2013	N/A	Servicing	TUM HS FFR HARD TOP			
000000-007AF074	000000-002EA4D9	12M SERVICE	Closed	Non-Taskworthy	No	Level 1	27 Aug 2013	N/A	Servicing	TUM HS FFR HARD TOP			
000000-007AF0F7	000000-002EA4D9	PLEASE INSPECT DIFF LOCK NOT ENGAGING	Closed	Limited Role	No	Level 2	27 Aug 2013	N/A	Inspection	TUM HS FFR HARD TOP			
000000-007A3FCD	000000-002E8C87	REMUS UNDER BODY WAX	Closed	Fully Fit	No	Level 2	18 Jul 2013	N/A	Closed No Action	TUM HS FFR HARD TOP			
000000-007A3FCC	000000-002E8C87	REMUS MOD	Closed	Fully Fit	No	Level 2	18 Jul 2013	N/A	Modification	TUM HS FFR HARD TOP			
000000-0079EC02	000000-002E80CE	REPLACE FAN	Closed	Non-Taskworthy	No	Level 2	03 Jul 2013	N/A	Failure	TUM HS FFR HARD TOP			
000000-0079732E		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	23 Jun 2013	N/A	Failure	TUM HS FFR HARD TOP			
000000-0079A39A		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	25 Jun 2013	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00771718	000000-002E2B40	6534	Closed	Fully Fit	No	Level 1	06 Mar 2013	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00771717	000000-002E2B40	6 MONTHLY VM TASKS	Closed	Fully Fit	No	Level 1	06 Mar 2013	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00771716	000000-002E2B40	6 MONTHLY SERVICE	Closed	Fully Fit	No	Level 1	06 Mar 2013	N/A	Servicing	TUM HS FFR HARD TOP			
000000-0073C23C	000000-002DCBBA	REPAIR BRAKES - FAILED ON IMBALANCE -	Closed	Fully Fit	No	Level 2	23 Sep 2012	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00736FAA	000000-002DCBBA	ANNUAL MEI	Closed	Non-Taskworthy	No	Level 2	10 Sep 2012	N/A	Inspection	TUM HS FFR HARD TOP			
000000-00736FA9	000000-002DCBBA	BRAKE FLUID CHANGE	Closed	Non-Taskworthy	No	Level 2	10 Sep 2012	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00736FA8	000000-002DCBBA	2 YEARLY VM TASK	Closed	Non-Taskworthy	No	Level 2	10 Sep 2012	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00736FA7	000000-002DCBBA	TABLE 5 SER 1 & 4	Closed	Non-Taskworthy	No	Level 1	10 Sep 2012	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00736FA6	000000-002DCBBA	2 YEARLY SERVICE	Closed	Non-Taskworthy	No	Level 1	10 Sep 2012	N/A	Servicing	TUM HS FFR HARD TOP			
000000-0070AD43	000000-002D92B0	REPLACE TYRE	Closed	Fully Fit	No	Level 1	17 Apr 2012	N/A	Damage	TUM HS FFR HARD TOP			
000000-00700769	000000-002D8612	CARRY OUT L2 TASKS IAW AESP 2320-D-128-601 T7 COL A (6 MONTHLY VM TASK)	Closed	Fully Fit	No	Level 2	13 Mar 2012	N/A	Servicing	TUM HS FFR HARD TOP			
000000-0070076D	000000-002D8612	CARRY OUT L1 TASKS IAW AESP 2320-D-128-601 T7 COL A (6 MONTHLY VSERV)	Closed	Fully Fit	No	Level 2	13 Mar 2012	N/A	Servicing	TUM HS FFR HARD TOP			
000000-00700777	000000-002D8612	CARRY OUT AF B6534	Closed	Fully Fit	No	Level 2	13 Mar 2012	N/A	Inspection	TUM HS FFR HARD TOP			
000000-006AEABF		Insp Steering Drop Arm Tab Washer	Closed	Fully Fit	No	Level 2	22 Jun 2011	N/A	Inspection	TUM HS FFR HARD TOP			
000000-006DBE75		CAMBELT	Closed	Non-Taskworthy	No	Level 2	09 Nov 2011	Degraded	Servicing	TUM HS FFR HARD TOP			
000000-003D82EC		6534	Closed	Non-Taskworthy	No	Level 2	26 Feb 2009	N/A	Failure	TUM HS FFR HARD TOP			
000000-003D82EB		6 MNTH SERVICE	Closed	Non-Taskworthy	No	Level 2	26 Feb 2009	N/A	Failure	TUM HS FFR HARD TOP			
000000-00272180		ADJUST TP'S	Closed	Fully Fit	No	Level 1	09 Sep 2008			TUM HS FFR HARD TOP			
000000-00272182		FIT CABLE ENTRY COVER AT REAR DOOR	Closed	Fully Fit	No	Level 1	09 Sep 2008			TUM HS FFR HARD TOP			
000000-0027217F		FIT FUSE BOX COVER (UNDER BONNET)	Closed	Fully Fit	No	Level 1	09 Sep 2008			TUM HS FFR HARD TOP			
000000-00272183		GREASE PROPSHAFTS	Closed	Fully Fit	No	Level 1	09 Sep 2008			TUM HS FFR HARD TOP			
000000-0025F96B	000000-00280046	Complete L1 maintenance IAW AESP 2320-D-128-601, Table 7 column C	Closed	Non-Taskworthy	No	Level 2	01 Sep 2008			TUM HS FFR HARD TOP			
000000-0025F976	000000-00280046	Complete L2 maintenance IAW AESP 2320-D-128-601, Table 7 column C	Closed	Non-Taskworthy	No	Level 2	01 Sep 2008			TUM HS FFR HARD TOP			
000000-0010645F	000000-00278AC4	6 MONTH SERVICE	Closed	Fully Fit	No	Level 1	13 Mar 2008			TUM HS FFR HARD TOP			
000000-00106461	000000-00278AC4	6 MONTH SERVICE	Closed	Fully Fit	No	Level 2	13 Mar 2008			TUM HS FFR HARD TOP			
000000-00106462		6 MONTH SERVICE	Closed	Fully Fit	No	Level 2	13 Mar 2008			TUM HS FFR HARD TOP			
000000-000CC2E8		Initial Usage	Closed	Fully Fit	No	Level 1	07 Feb 2008			TUM HS FFR HARD TOP			
000000-000CC342		Initial Usage	Closed	Fully Fit	No	Level 1	07 Feb 2008			TUM HS FFR HARD TOP			
000000-000CC355		Initial Maintenance	Closed	Fully Fit	No	Level 1	07 Feb 2008			TUM HS FFR HARD TOP			



Work Objects

Serial Number: MU24AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-008E0DFE		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-005133B4		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-008E0EA3		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-007FC780	000000-00326A85	No	6 Monthly 6534 Insp		Level 1	Fully Fit	CL	000:00		
000000-0068F29D		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-002CDFFD		No	MEI (2)		Level 2			000:00		
000000-00741AA9	000000-0031F2E2	No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00452D06		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-002CE012		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-005A02E2		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-009882CF		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-001CC4FB		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00218F23		No	MEI (2)		Level 2			000:00		
000000-00397085	000000-002F2E0E	No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00		
000000-00218F24		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00191473		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-005E2207		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00191472		No	MEI (2)		Level 2			000:00		

000000-000BEDB5		No	MEI (2)		Level 2		CL	000:00
000000-000B9F6B		No	MEI (2)		Level 2		CL	000:00
000000-005E220D		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00
000000-0074652D		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	CL	000:00
000000-0058D602	000000-0030ABBF	No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00
000000-00444109	000000-002FBA18	No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00
000000-00A45A9F		No	FMT931 Comms (2)*	12 Jun 2019	Level 2	Limited Role	CL	000:00
000000-0025BC5A		No	6 Monthly 6534 Insp		Level 1			000:00

Work Objects

Serial Number: MU24AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006919B6	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS Installation of 12/24 volt sockets.(Installation Instruction 8 (2320-D-128-411		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-006919B4	00008	Installations Instructions and Index))		No	3/A	STI				Fully Fit	CL	Level 3			
000000-00642279	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00642278	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-0064228C	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00642268	00006	Fitting of Spare Wheel Tyre Inflation Valve Extensior		No	-/-	RTI				Limited Role	CL	Level 2			
000000-006421A3	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-006421A2	00017	Introduction of Battery Retentior		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0064220F	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00027F73	00037	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-006F5F7B	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			
000000-006F77D9	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			

Work Objects

Serial Number: MU24AA
 NSN: 2320998939744

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-001CC4F9		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1			000:00		
000000-00643C72	000000-0031374F	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Limited Role	CL	000:00	COSU JMETS ENGCON	GEF SMRC
000000-00444115	000000-002FBA18	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Sep 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-0059B614	000000-0030ABBF	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Limited Role	CL	000:00		GEF SMRC
000000-00213420		No	2 Yearly/40000 Kms	19 Sep 2020	Level 1			000:00		
000000-009EE3FF	000000-00338F2D	No	2 Yearly/40000 Kms	19 Sep 2020	Level 1	Fully Fit	CL	000:00		
000000-007047B9		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Sep 2020	Level 1	Fully Fit	CL	000:00		
000000-0070F5B2		No	Yearly/20000 Kms	20 Sep 2019	Level 1	Fully Fit	CL	000:00		
000000-0020305B		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	12 Aug 2023	Level 1			000:00		
000000-0094EB66		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-007047BC		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	19 Sep 2020	Level 1	Fully Fit	CL	000:00		
000000-0021345C		No	Yearly/20000 Kms	20 Sep 2019	Level 1			000:00		
000000-002CDFFA		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	12 Aug 2023	Level 1			000:00		
000000-00191475		No	5 Yearly/100000 Kms (1)		Level 1			000:00		
000000-002CDFFB		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	12 Aug 2023	Level 2			000:00		
000000-00444124	000000-002FBA18	No	2 Yearly/40000 Kms	19 Sep 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-008847F9		No	Yearly/20000 Kms	20 Sep 2019	Level 1	Fully Fit	CL	000:00		
000000-0020305C		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	19 Sep 2020	Level 1			000:00		
000000-0070F616		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1			000:00		
000000-0025BA82		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1			000:00		
000000-007047B7		No	2 Yearly/40000 Kms	19 Sep 2020	Level 1	Fully Fit	CL	000:00		
000000-00213435		No	2 Yearly/40000 Kms	19 Sep 2020	Level 1			000:00		
000000-00191470		No	2 Yearly/40000 Kms	19 Sep 2020	Level 1			000:00		
000000-0058D600	000000-0030ABBF	No	Yearly/20000 Kms	20 Sep 2019	Level 1	Limited Role	CL	000:00		GEF SMRC
000000-00203051		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	09 Dec 2023	Level 2			000:00		
000000-0044DF2F	000000-002FBA18	No	Yearly/20000 Kms	20 Sep 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-009EE40E		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Sep 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-00213463		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1			000:00		
000000-008B8578		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-00091BA4		No	Yearly/20000 Kms	20 Sep 2019	Level 1		CL	000:00		
000000-00091B01		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1		CL	000:00		
000000-00093836		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1		CL	000:00		

000000-000A0B14	No	2 Yearly/40000 Kms	19 Sep 2020	Level 1		CL	000:00
000000-000A0B15	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1		CL	000:00
000000-000A0B16	No	Yearly/20000 Kms	20 Sep 2019	Level 1		CL	000:00
000000-0003F5C3	No	Yearly/20000 Kms	20 Sep 2019	Level 1		CL	000:00
000000-000EAC43	No	Yearly/20000 Kms	20 Sep 2019	Level 1		CL	000:00
000000-0003FA2D	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1		CL	000:00
000000-00051E40	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1		CL	000:00
000000-0019143D	No	Yearly/20000 Kms	20 Sep 2019	Level 1			000:00
000000-0020305D	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Sep 2020	Level 1			000:00
000000-0019143E	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1			000:00
000000-0020305A	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	12 Aug 2023	Level 2			000:00
000000-0021345D	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	19 Sep 2020	Level 1			000:00
000000-00213436	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1			000:00
000000-009F3A42	000000-00338F2D	No	Yearly/20000 Kms	20 Sep 2019	Level 1	Fully Fit	CL 000:00
000000-009F3A43	000000-00338F2D	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Fully Fit	CL 000:00
000000-008847FA	000000-0032C507	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	09 Dec 2023	Level 2	Fully Fit	CL 000:00
000000-00397083	000000-002F2E0E	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Fully Fit	CL 000:00
000000-002CDDFF9		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1		000:00
000000-0044DF2E	000000-002FBA18	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Non-Taskworthy	CL 000:00
000000-00198D87		No	6 Yearly/120000 Kms (2)		Level 2		000:00
000000-0044414B	000000-002FBA18	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	19 Sep 2020	Level 1	Non-Taskworthy	CL 000:00
000000-009CBCD9		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	12 Aug 2023	Level 2	Fully Fit	CL 000:00
000000-009EE3F9		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	19 Sep 2020	Level 1	Fully Fit	CL 000:00
000000-009CBCD8		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	12 Aug 2023	Level 1	Fully Fit	CL 000:00
000000-007CDDFF1		No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Fully Fit	CL 000:00
000000-004DC399	000000-003049E9	No	6 Monthly/10000 Kms	21 Mar 2019	Level 1	Fully Fit	CL 000:00
000000-00213462		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	17 Sep 2020	Level 1		000:00
000000-002CDDFF8		No	Yearly/20000 Kms	20 Sep 2019	Level 1		000:00