



Ministry  
of Defence

██████████ LLB(Hons)

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

██████████

email: ██████████

Our Reference:  
FOI2021/02811  
Date:  
23 March 2021

Dear ██████████,

I am writing about your email of 12 March 2021, requesting the following information:

*I would like to make a Freedom of Information Request to discover if the Ministry of Defence may have an records of service and or maintenance for my Land Rover Defender 90 Wolf, which before I purchased it in 2020 had a Vehicle Registration Number "LT 41 AA". Any information that you could share would be gratefully received.*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Ownership History  
Annex B - Fault History (redacted)  
Annex C - Inspection History  
Annex D - Modification History  
Annex E - Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Defence Equipment & Support

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

[REDACTED]

[REDACTED]

DE&S Policy Secretariat Asst Hd

**VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LT41AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
24/03/1998	SALLDAA67WA143889	N/A		

**VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LT41AA	3		CA005A	JSCS ASHCHURCH		32909AA	24/03/1998	
LT41AA	4	14/04/1998	A0551A	1 SCOTS	38436A	2144	19/06/1998	
LT41AA	4	02/08/2000	A0585A	3 MERCIAN REGIMENT (STAFFORDS)	299	2119	02/08/2000	H/T
LT41AA	4	29/10/2002	A9056A	UK BG 1 (CSAT)	837	5050	07/11/2002	H/T
LT41AA	4	03/04/2003	A0585A	3 MERCIAN REGIMENT (STAFFORDS)	690	6289	11/04/2003	H/T
LT41AA	4	19/03/2004	A0563A	1 RIFLES	33367	MCR04	19/03/2004	MC4
LT41AA	4	17/01/2006	A5314A	QM(T) DEPT 13 AA SP REGT	36024	46	19/01/2006	W82
LT41AA	4	20/03/2006	A8312A	JSU KAF	999	84	13/04/2006	H/T
LT41AA	4	21/02/2007	A5314A	QM(T) DEPT 13 AA SP REGT	999	46301	21/02/2007	Y14
LT41AA	3	28/04/2009	A5969A	TFSU (UK)	50464	799DD	14/05/2009	
LT41AA	4	07/11/2012	CB997C	ABRO CATTERICK PLANNED REPAIR	4954D	7146	20/11/2012	

LT41AA	2	08/07/2013	A0501A	1 GREN GDS	L0002	L0002	08/07/2013	
LT41AA		04/03/2014	CL001A	DSG ALDERSHOT			04/03/2014	
LT41AA		11/04/2014	A0501A	1 GREN GDS			11/04/2014	
LT41AA		27/01/2015	CL001A	DSG ALDERSHOT			27/01/2015	
LT41AA		18/03/2015	A0501A	1 GREN GDS			18/03/2015	
LT41AA		31/01/2018	CA005A	BABCOCK ASHCHURCH			31/01/2018	

Work Objects

Serial Number: LT41AA  
 NSN: 232098939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451A	27 Jul 2017	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00A41475		DEMAND HAZARD SWITCH	Closed	Fully Fit	No	Level 2		18 May 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A252B8		No IMI Certificate Presented At Inspection	Closed	Limited Role	No	Level 1		24 Mar 2017	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00A10E8C		HAZARD WARNING INDICATOR ON SWATCH INOP	Closed	Non-Taskworthy	No	Level 2		11 May 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A2343F		No.1 BALL JOINT BOOT SPLIT	Closed	Non-Taskworthy	No	Level 2		11 May 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A23438		RIGHT FRONT BRAKE PIPE FOULING ON LOCK	Closed	Non-Taskworthy	No	Level 2		11 May 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A23433		BOTH TRACTA SEALS LEAKING	Closed	Fully Fit	No	Level 2		04 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087C0C0		KNOCKING AT TOP OF ST COLUMN WHILE TURNING LEFT OR RIGHT	Closed	Non-Taskworthy	No	Level 2		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F7155		FFR BATTERIES X2 MISSING	Closed	Fully Fit	No	Level 1		05 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087C0DA		REQUIRES IMI FOR RADIO EQUIPMENT	Closed	Fully Fit	No	Level 2		17 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009884F3		WATER JERRY CANS MISSING	Closed	Fully Fit	No	Level 1		27 Apr 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-0098CC85		TRANSMISSION NOISY	Closed	Fully Fit	No	Level 2		05 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0087C0D8		NOISE FROM CLUTCH RELEASE BEARING OR 1ST MOTION SHAFT BEARING	Closed	Fully Fit	No	Level 2		11 Mar 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007F7184		RIP IN REAR OPERATORS SEAT	Closed	Fully Fit	No	Level 1		19 Aug 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-008B89A0		FRONT AND REAR DIFF PINION SEALS STARTING TO LEAK	Closed	Fully Fit	No	Level 2		05 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0087C0D4		SLIGHT OIL LEAK ATT/BOX INPUT SEAL & O RING	Closed	Fully Fit	No	Level 2		05 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0087C0D7		ACCIDENT DAMAGE RH H/LIGHT GD	Closed	Fully Fit	No	Level 1		11 Mar 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007F7168		INVESTIGATE FIP BANJO BOLT NOT SEATING CORRECTLY	Closed	Non-Taskworthy	No	Level 2		10 Apr 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-009858BA		REPLACE INDICATOR STALK	Closed	Non-Taskworthy	No	Level 2		15 Feb 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-0096E2A2		REPLACE WIPER MOTOR	Closed	Non-Taskworthy	No	Level 2		02 Feb 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-00968B78		STARTER SOLENOID PERMANENTLY ENGAGING	Closed	Non-Taskworthy	No	Level 2		07 Dec 2015	N/A	Failure	TUL HS FFR HARD TOP			
000000-008E2CB8		REPLACE FLASHER RELAY	Closed	Non-Taskworthy	No	Level 2		01 Feb 2016	N/A	Failure	TUL HS FFR HARD TOP		LAD VMS	
000000-00967C0E		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-0000321C	20 Jan 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009622FC		Pipe split from left pump to fuel filter.	Closed	Non-Taskworthy	No	Level 2		21 Jan 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-00963D30		NO 2 BALL JOINT FITTED WITH A NYLON NUT	Closed	Fully Fit	No	Level 2		15 Dec 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-008E5C43		TOW PIN REQUIRES PAINTING RED	Closed	Fully Fit	No	Level 1		25 Aug 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-008BA0F2		6 MONTHLY SERVICE	Closed	Non-Taskworthy	No	Level 2		13 Oct 2015	N/A	Servicing	TUL HS FFR HARD TOP			
000000-008CCB58		6 MONTHLY SERVICE	Closed	Fully Fit	No	Level 1		13 Oct 2015	N/A	Servicing	TUL HS FFR HARD TOP			
000000-008CCB55		PAINT FUEL CAP YELLOW	Closed	Fully Fit	No	Level 1		24 Aug 2015	N/A	No Fault Found	TUL HS FFR HARD TOP			
000000-008B9C7A		NO BOWMAN RADIO FITTED	Closed	Fully Fit	No	Level 2		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F718D		HAS NO FIRE EXTINGUISHER	Closed	Fully Fit	No	Level 1		25 May 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0089900D		DRIVERS SEATBACK LEVER KNOB MISSING	Closed	Fully Fit	No	Level 1		04 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087C0D3		DRIVERS SEATBACK TORN	Closed	Fully Fit	No	Level 2		04 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087C0CF		SILENCER REAR HANGER BOLT LOOSE	Closed	Fully Fit	No	Level 2		04 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087C0CD		REAR DAMPER TOP BUSH WASHERS INCORRECTLY FITTED	Closed	Fully Fit	No	Level 2		04 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087C0C4		REAR DAMPER BUSHES WORN	Closed	Non-Taskworthy	No	Level 2		04 Mar 2015	N/A	Failure	TUL HS FFR HARD TOP			
000000-0087C0B9		PANHARD ROD BUSHES WORN	Closed	Non-Taskworthy	No	Level 2		04 Mar 2015	N/A	Failure	TUL HS FFR HARD TOP			
000000-0087C0B7		LHF LOWER LINK BUSHES WORN	Closed	Non-Taskworthy	No	Level 2		04 Mar 2015	N/A	Failure	TUL HS FFR HARD TOP			
000000-0087C0B6		RH HEADLIGHT CONDENSATED UP	Closed	Non-Taskworthy	No	Level 2		04 Mar 2015	N/A	Failure	TUL HS FFR HARD TOP			
000000-0087C0B4		BONNET STAY CLIP BROKE	Closed	Fully Fit	No	Level 1		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F716F		DOOR DO NOT LOCK	Closed	Fully Fit	No	Level 2		26 Feb 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-007EF207		Rectify charging fault	Closed	Non-Taskworthy	No	Level 2		02 Dec 2014	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-0085A5A0		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP			
000000-00844176		FFR ALTERNATOR SEIZED	Closed	Limited Role	No	Level 2		26 May 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-0081034C		BOTH M IRRORS STARTING TO DETERIATE	Closed	Fully Fit	No	Level 1		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F7173		WHEEL WOBBLE AT 50 MPH	Closed	Fully Fit	No	Level 2		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F717C		LH HLIGHT MOTOR CONSTANTLY RUNNING	Closed	Fully Fit	No	Level 2		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F7153		LH & RH SUSPENSION TURRETS BURST	Closed	Fully Fit	No	Level 2		10 Mar 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-007F7147		ALTERNATOR BEARING NOISY	Closed	Fully Fit	No	Level 2		10 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F7181		NO TP MARKINGS ON SPARE TYRE	Closed	Fully Fit	No	Level 1		11 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F718F		REGISTRATION AND CONVOY LIGHTS DON'T WORK	Closed	Fully Fit	No	Level 2		27 Feb 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007EF20C		LH WIPER SPINDLE INSECURE AT BULKHEAD	Closed	Fully Fit	No	Level 2		11 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F716B		NAIL IN TREAD OF RHF TYRE	Closed	Fully Fit	No	Level 1		11 Mar 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007F715A		LHF TYRE INNER SIDEWALL CRACKING	Closed	Non-Taskworthy	No	Level 1		11 Mar 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-007F714D		WINDSCREEN WASH JET DOESN'T WORK	Closed	Fully Fit	No	Level 2		27 Feb 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-007EF20A		MEI (2)	Closed	Fully Fit	No	Level 2		27 Feb 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007EEF21		Yearly/20000 Kms	Closed	Fully Fit	No	Level 2		27 Feb 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007EEF1C		Yearly/20000 Kms	Closed	Fully Fit	No	Level 1		27 Feb 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007EEF18		REPLACE IGNITION SWITCH	Closed	Fully Fit	No	Level 2		21 Nov 2013	N/A	Failure	TUL HS FFR HARD TOP			
000000-007CE5C0			Closed	Fully Fit	No	Level 2			N/A					

000000-007B4616 CARRY OUT 6534 INSPECTION  
 000000-007B4611 CARRY OUT 6 MTH L1 SERVICE IAW AESP 2320-D-128-601 TABLE 7 COLUMN A  
 000000-007B4614 CARRY OUT 6 MTH L2 SERVICE IAW AESP 2320-D-128-601 TABLE 7 COLUMN A  
 000000-00798A73 GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09  
 000000-00798A53 Inspect tyres for damage  
 000000-00789BE8 000000-002E5EE PLEASE CARROUT RECEIPT INSPECTION  
 000000-0060777F Incomplete Equipment Information  
 000000-0046CDC7 Insufficient Data  
 000000-006B06FB Insp Steering Drop Arm Tab Washer  
 000000-00754284 CARRY OUT 24 MTH SERVICE IAW 2320-D-128-601 TAB 7 COL C  
 000000-00754287 CARRY OUT OOPM TAB 5 SER's 1,2,3,4,6  
 000000-00754289 CARRY OUT 932W & 933 INSPECTION  
 000000-0075428C CARRY OUT FULL RE-SPRAY IF REQUIRED  
 000000-0075429C CLEAR ALL FAULTS FROM DSG JOB CARD 8B0048228  
 000000-00386E56 Initial Usage  
 000000-00386FF8 Initial Maintenance

Closed	Non-Taskworthy	No	Level 1		10 Sep 2013	N/A	Inspection	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 1		10 Sep 2013	N/A	Servicing	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2		10 Sep 2013	N/A	Inspection	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 1	000000-0000081A	23 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2		14 May 2013	N/A	Inspection	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 1		19 May 2011	N/A	Closed No Action	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 1		18 Aug 2009	N/A	Failure	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	000000-00000312	22 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2		30 Nov 2012	N/A	Servicing	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2		30 Nov 2012	N/A	Servicing	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2		30 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2		30 Nov 2012	N/A	Refurbishment	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2		30 Nov 2012	N/A	Failure	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 1		15 Jan 2009			TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 1		15 Jan 2009			TUL HS FFR HARD TOP



000:00



Work Objects

Serial Number: LT41AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-003CDB93		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1			000:00		
000000-0094104E		No	MEI (2)	28 Mar 2019	Level 2	Non-Taskworthy	CL	000:00		
000000-002EC806		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-003AA293		No	MEI (2)	28 Mar 2019	Level 2	Fully Fit	CL	000:00		
000000-00679933		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00807B22		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-0045E8C4		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1			000:00		
000000-007D48AB		No	MEI (2)	28 Mar 2019	Level 2	Fully Fit	CL	000:00		
000000-002625AD		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1			000:00		
000000-00678E7D		No	MEI (2)	28 Mar 2019	Level 2	Non-Taskworthy	CL	000:00		
000000-0052FD8B		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1			000:00		
000000-0070C489		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1	Non-Taskworthy	WiP	000:00		
000000-004CBE2F		No	MEI (2)	28 Mar 2019	Level 2	Limited Role	CL	000:00		
000000-00950D1E		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-008B8F3F		No	6 Monthly 6534 Insp	26 Sep 2018	Level 1	Limited Role	CL	000:00		
000000-002625AC		No	MEI (2)	28 Mar 2019	Level 2			000:00		
000000-00678D61		No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	CL	000:00		

Work Objects

Serial Number: LT41AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006F620D	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F7A27	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-0068FB72	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00642718	00040	This instruction details the fitting of additional lashing eyes to the front bumper and to the rear chassis rail. This modification is only applicable to those units who would be considering transporting the equipment as internal load by Air.		No	3/A	Mod				Fully Fit					
000000-0064255F	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Limited Role	CL	Level 2			
000000-0064255A	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-00642559	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00642549	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0062A159	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0064255C	00019	Blackout Cover for Warning Light Panel		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0064255D	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0062A169	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/	RTI				Fully Fit	CL	Level 2			



Work Objects

Serial Number: LT41AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-003B8011		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-00262598		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	06 Mar 2019	Level 1			000:00		
000000-00678E7F		No	Yearly/20000 Kms	28 Mar 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-00262595		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	26 Feb 2019	Level 2			000:00		
000000-00925D0B		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	25 Feb 2023	Level 1	Limited Role	CL	000:00		
000000-003AA2A3		No	Yearly/20000 Kms	28 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-00679939		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0026259A		No	Yearly/20000 Kms	28 Mar 2019	Level 1			000:00		
000000-001D9014		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1			000:00		
000000-00262599		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1			000:00		
000000-00925660		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	25 Feb 2023	Level 2	Limited Role	CL	000:00		
000000-007BC563		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	06 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-005BFDAC		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00262597		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	06 Mar 2019	Level 1			000:00		
000000-007D4955		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-004F28F8		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-0086CBBA		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-0045E8B4		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-009472C6		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-007D4956		No	Yearly/20000 Kms	28 Mar 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-004C8EE5		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	06 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-001D9013		No	Yearly/20000 Kms	28 Mar 2019	Level 1			000:00		
000000-007BC565		No	2 Yearly/40000 Kms	23 Mar 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0070C473		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-00262596		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	25 Feb 2023	Level 2			000:00		
000000-004C8EF7		No	2 Yearly/40000 Kms	23 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-0093BD3F		No	Yearly/20000 Kms	28 Mar 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-00262594		No	2 Yearly/40000 Kms	23 Mar 2019	Level 1			000:00		
000000-002EA48C		No	6 Monthly/10000 Kms	27 Sep 2018	Level 1		CW	000:00		
000000-004F28F7		No	Yearly/20000 Kms	28 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-0026259B		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	25 Feb 2023	Level 1			000:00		
000000-007BC579		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	06 Mar 2019	Level 1	Fully Fit	CL	000:00		
000000-004C8EE6		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	06 Mar 2019	Level 1	Fully Fit	CL	000:00		