



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]

email: [REDACTED]
[REDACTED]

Our Reference:
FOI2021/03442
Date:
13 April 2021

Dear [REDACTED],

I am writing about your email of 26 March 2021, requesting the following information:

Would you please send me all details and history, including maintenance, service reports, Merlin report and any other information on the following vehicle which I have purchased - LAND ROVER DEFENDER XD TUM, VIN: SALLDBA67WA141554, vehicle registration number: MB 13 AA, Contract Number: lv2a/088.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Ownership History
Annex B - Fault History (redacted)
Annex C - Inspection History
Annex D - Modification History (redacted)
Annex E - Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B) and Modification History (Annex D), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault and modification reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Defence Equipment & Support

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of “would” rather than “would be likely to”.

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner’s Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
MB13AA	2320998939963	NB50103101	LV2A/088DUM	TRUCK UTY MED (TUM HS) 4X4 SOFT TOP LANDROVER 2.5LTR TURBO DSL (WITH EEGR)	Civilian Trade Finish

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
29/04/1998	SALLDBA67WA141554	25L05399B		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
MB13AA	3		CA005A	JSCS ASHCHURCH		34178AA	29/04/1998	
MB13AA	3	03/12/1998	CA301C	JSU CYPRUS VEH SECTION	44195A	2695TT	05/02/1999	
MB13AA	4	02/03/1999	A0560A	2 R ANGLIAN	2300T	4260	03/03/1999	
MB13AA	4	03/02/2000	A0571A	1 MERCIAN	759	1	09/03/2000	H/T
MB13AA	4	09/02/2002	A2265A	3 RIFLES	486	1	14/02/2002	H/T
MB13AA	4	26/02/2004	A0590A	1 LANCS	728	7	01/03/2004	H/T
MB13AA	4	28/11/2005	A0556A	2 RRF	249	2530	29/11/2005	H/T
MB13AA	4	13/05/2010	A1259A	2 PWRR	999	37255	13/05/2010	H/T
MB13AA	2	14/09/2010	A0560A	2 R ANGLIAN	MCR11	MCR11	14/09/2010	MCR
MB13AA		13/09/2012	A0556A	2 RRF			13/09/2012	
MB13AA		02/08/2014	A1259A	2 PWRR			02/08/2014	

MB13AA		06/08/2014	A1259G	2 PWRR MT			06/08/2014	
MB13AA		10/08/2017	A0560A	2 R ANGLIAN			10/08/2017	
MB13AA		11/09/2018	A5969A	SEF (UK) ASHCHURCH			11/09/2018	

000000-0078D332	Front grille smashed	Closed	Fully Fit	No	Level 2	26 May 2013	N/A	Accident	TUM HS GS SOFT TOP
000000-0078D331	R/H/F ind lens smashed	Closed	Non-Taskworthy	No	Level 1	26 May 2013	N/A	Accident	TUM HS GS SOFT TOP
000000-0078D32F	Bumper bent	Closed	Fully Fit	No	Level 2	26 May 2013	N/A	Accident	TUM HS GS SOFT TOP
000000-0076104E	Dvr seat belt damaged	Closed	Fully Fit	No	Level 2	27 Jan 2013	N/A	Damage	TUM HS GS SOFT TOP
000000-0076103E	R/H headlight guard damaged	Closed	Fully Fit	No	Level 2	27 Jan 2013	N/A	Damage	TUM HS GS SOFT TOP
000000-0076103B	R/H wing damaged	Closed	Non-Taskworthy	No	Level 2	27 Jan 2013	N/A	Damage	TUM HS GS SOFT TOP
000000-00761039	Spare rim and tyre damaged	Closed	Limited Role	No	Level 2	27 Jan 2013	N/A	Damage	TUM HS GS SOFT TOP
000000-0084493A	Towing Pintle Assembly	Closed	Limited Role	No	Level 2	08 Oct 2014	Degraded	Inspection	TUM HS GS SOFT TOP
000000-0079920C	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/05	Closed	Non-Taskworthy	No	Level 1	000000-00001F58			
000000-0078D330	R/H head light guard bent	Closed	Fully Fit	No	Level 1	000000-0000081A			
000000-0073F4C1	PLEASE INSPEC FOR JORDON EXERCISE	Closed	Fully Fit	No	Level 2	26 May 2013	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-00761043	G/box tunnel cover damaged	Closed	Fully Fit	No	Level 2	04 Oct 2012	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-0076104C	Rear floor rail insecure	Closed	Fully Fit	No	Level 2	27 Jan 2013	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-00761047	Canopy perishing	Closed	Fully Fit	No	Level 1	27 Jan 2013	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-0073F49D	PLEASE CARRY OUT 6534	Closed	Fully Fit	No	Level 1	04 Oct 2012	N/A	Inspection	TUM HS GS SOFT TOP
000000-0073F4A6	PLEASE RECTIFY PROP SHAFT LEAK	Closed	Fully Fit	No	Level 2	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F4A5	PLEASE RECTIFY ENGINE LEAK	Closed	Fully Fit	No	Level 2	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F4A4	PLEASE RECTIFY BROKEN STRAP ON BONNET OF VEH	Closed	Fully Fit	No	Level 2	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F4A3	PLEASE RECTIFY NUMBER PLATE LIGHT	Closed	Fully Fit	No	Level 1	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F4A2	PLEASE RECTIFY BRAKE LIGHTS	Closed	Fully Fit	No	Level 1	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F4A1	PLEASE RECTIFY FRONT LEFT HEAD LIGHT DONT WORK	Closed	Fully Fit	No	Level 1	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F4A0	PLEASE RECTIFY DENTS ALL AROUND THE VEH	Closed	Fully Fit	No	Level 2	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F49F	LPEASE CARRY OUT 6M L2 AS PER AESP	Closed	Fully Fit	No	Level 2	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073F49E	LPEASE CARRY OUT 6M L1 AS PER AESP	Closed	Fully Fit	No	Level 1	04 Oct 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-0073CE11	PLEASE CARRY OUT 6M L2 AS PER AESP	Closed	Fully Fit	No	Level 2	25 Sep 2012	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-0073CE10	PLEASE CARRY OUT 6M L1 AS PER AESP	Closed	Fully Fit	No	Level 1	25 Sep 2012	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-0073CE0F	PLEASE CARRY OUT 6534	Closed	Fully Fit	No	Level 1	25 Sep 2012	N/A	Closed No Action	TUM HS GS SOFT TOP
000000-00735929	Renew front prop	Closed	Fully Fit	No	Level 2	05 Sep 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0071E56C	INSPECT AND REPAIR PASSENGER FOOT WEL	Closed	Non-Taskworthy	No	Level 2	18 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0071E55E	PLEASE INSPEC AND REPAIR ROCKER COVER OIL LEAK	Closed	Non-Taskworthy	No	Level 2	18 Jun 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-00710109	CARRY OUT MEI	Closed	Fully Fit	No	Level 2	02 May 2012	N/A	Inspection	TUM HS GS SOFT TOP
000000-007123B2	RENEW L/H DOOR HINGE	Closed	Fully Fit	No	Level 2	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-007123AC	REPAINT CONVOY MARKER	Closed	Fully Fit	No	Level 1	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-007123A9	RENEW 2 REAR SEATS	Closed	Limited Role	No	Level 1	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-007123A9	STRAIGHTEN BRACKET ON FRONT DIFF	Closed	Fully Fit	No	Level 2	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0071239E	RENEW DRIVER AND REAR PASSENGER SEAT BELT BUCKLES	Closed	Non-Taskworthy	No	Level 1	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0071238D	FIT DIFFY TAIL GATE STRAP	Closed	Fully Fit	No	Level 1	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-00712384	RENEW LEFT HAND SHOCK ABSORBER BUSHES	Closed	Non-Taskworthy	No	Level 2	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0071238C	CONVOY LIGHT INOP	Closed	Limited Role	No	Level 2	09 May 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0071010E	DRAIN AND RENEW COOLENT	Closed	Non-Taskworthy	No	Level 2	02 May 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-00710101	CHANGE FUEL FILTER	Closed	Non-Taskworthy	No	Level 2	02 May 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-007100F4	CARRY OUT OIL AND FILTER CHANGE	Closed	Non-Taskworthy	No	Level 2	02 May 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-007100EC	CARRY OUT 2 YEARLY T7 COL C VMS	Closed	Non-Taskworthy	No	Level 2	02 May 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-007100E4	CARRY OUT 2 YEARLY T7 COL C	Closed	Non-Taskworthy	No	Level 1	02 May 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-00709A4B	RENEW BOTH TRACTA SEALS	Closed	Non-Taskworthy	No	Level 2	11 Apr 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-0070929A	PLEASE INSPEC BONNET CHACH AND REPAIR	Closed	Non-Taskworthy	No	Level 2	10 Apr 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-00709299	PLEASE INSPEC STEERING UNIT AND REPAIR DAMAGE	Closed	Non-Taskworthy	No	Level 2	10 Apr 2012	N/A	Damage	TUM HS GS SOFT TOP
000000-00703CFE	PLEASE INSPECT AND REPAIR ENGINE FAULT (LOOK AT ROCKER COVER GASGET)	Closed	Non-Taskworthy	No	Level 2	21 Mar 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-006EB86D	PLEASE RENEW REAR SEAT BOLT MISSING	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006EB86A	PLEASE RPLACE TOOL SECURING STARPS ON BONET	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-006EB867	PLEASE INSPECT AND REPAIR BONET SHOVEL BRACKETS FITTED THE WRONG WA)	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006EB862	PLEASE INSPECT AND REPAIR BONET CATCH INOP	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-006EB851	PLEASE RENEW BREAK SWITCH NUT MISSING	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006EB84C	PLEASE RENEW SPARE TYRE WORN	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006EB843	PLEASE INSPECT AND REPAIR REAR LEFT WHEEL GRINDING WHEN TURNING SHARP LEFT	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006EB83A	PLEASE INSPECT AND REPAIR STEERING WHEEL NOT ALLIGNED	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006EB835	PLEASE INSPECT AND REPAIR TRACKING	Closed	Non-Taskworthy	Yes	Level 2	12 Jan 2012	N/A	Servicing	TUM HS GS SOFT TOP
000000-006E82DE	RECT FUEL LEAK @ HEAD	Closed	Non-Taskworthy	No	Level 2	02 Jan 2012	N/A	Failure	TUM HS GS SOFT TOP
000000-006DC564	REPLACE GOODYEAR TYRES TO MICHELIN	Closed	Non-Taskworthy	No	Level 2	10 Nov 2011	N/A	Failure	TUM HS GS SOFT TOP
000000-006DAD2A	LEVEL 1 MAINT TASKS	Closed	Non-Taskworthy	No	Level 1	06 Nov 2011	N/A	Servicing	TUM HS GS SOFT TOP
000000-006DA9F7	MB13AA6MONTHLY07/11/11	Closed	Non-Taskworthy	No	Level 2	07 Nov 2011	N/A	Servicing	TUM HS GS SOFT TOP
000000-006DA9EE	MB13AA6MONTHLY07/11/11	Closed	Non-Taskworthy	No	Level 2	07 Nov 2011	N/A	Servicing	TUM HS GS SOFT TOP

Work Objects

Serial Number: MB13AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0052CF42		No	MEI (2)	24 May 2018	Level 2	Limited Role	CL	000:00		
000000-0099315A		No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00		
000000-0052CFB8		No	6 Monthly 6534 Insp	25 May 2018	Level 1	Limited Role	CL	000:00		
000000-008C9A9E		No	6 Monthly 6534 Insp	25 May 2018	Level 1			000:00		
000000-0080EE2D		No	MEI (2)	24 May 2018	Level 2	Non-Taskworthy	CL	000:00		
000000-006978F8		No	6 Monthly 6534 Insp	25 May 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0027FE41		No	MEI (2)	24 May 2018	Level 2	Non-Taskworthy	CL	000:00		
000000-0027FE42		No	6 Monthly 6534 Insp	25 May 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-001E12ED		No	MEI (2)	24 May 2018	Level 2			000:00		
000000-00753719		No	6 Monthly 6534 Insp	25 May 2018	Level 1	Non-Taskworthy	WiP	000:00		
000000-00685CCD		No	MEI (2)	24 May 2018	Level 2	Non-Taskworthy	CL	000:00		
000000-0019A28B		No	6 Monthly 6534 Insp	25 May 2018	Level 1			000:00		
000000-001E1303		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-001E12EE		No	6 Monthly 6534 Insp	25 May 2018	Level 1			000:00		
000000-0075411D		No	6 Monthly 6534 Insp	25 May 2018	Level 1	Non-Taskworthy	WiP	000:00		
000000-00812274		No	6 Monthly 6534 Insp	25 May 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00907B5E		No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00		
000000-0019A28C		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-005DD2B1		No	6 Monthly 6534 Insp	25 May 2018	Level 1			000:00		
000000-0021F830		No	6 Monthly 6534 Insp	25 May 2018	Level 1			000:00		

Work Objects

Serial Number: MB13AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0069E003	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00639DE3	00038	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00678146	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit					
000000-0060DE10	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00639DDD	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00639DDE	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00639DE2	00037	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00639DDB	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00639DDF	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00639DE1	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00639DDA	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00639DE6	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/-	RTI				Limited Role	CL	Level 2			

Work Objects

Serial Number: MB13AA
 NSN: 2320998939963

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-001DA28E		No	OOPS Cooling System (AR)		Level 2			000:00		
000000-001DA287		No	Yearly/20000 Kms	21 May 2019	Level 1			000:00		
000000-001917B3		No	Yearly/20000 Kms	21 May 2019	Level 1			000:00		
000000-0080ECDE		No	Yearly/20000 Kms	21 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0019A288		No	Weekly (AR)(1)		Level 1			000:00		
000000-002003D6		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	04 May 2020	Level 1			000:00		
000000-0052876A		Yes	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	04 May 2020	Level 2	Non-Taskworthy	CL	000:00		
000000-00685CC0		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00738FC6		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0019A287		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1			000:00		
000000-0080B813		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-002003D4		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	04 May 2021	Level 2			000:00		
000000-002003D5		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	04 May 2020	Level 2			000:00		
000000-00685C6F		No	Yearly/20000 Kms	21 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-001917EB		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1			000:00		
000000-008C716B	000000-0032ED79	No	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Limited Role	CL	000:00		
000000-00528769		Yes	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	04 May 2021	Level 2	Non-Taskworthy	CL	000:00		
000000-00200230		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 May 2019	Level 1			000:00		
000000-001DA288		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1			000:00		
000000-0096B80D		No	Yearly/20000 Kms	21 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0052876B		Yes	2 Yearly/40000 Kms	24 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0080ECDD		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-005D599F	000000-0030E575	No	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Fully Fit	CL	000:00		
000000-0021F815		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1			000:00		
000000-0097AD32		No	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-001DA28F		No	OOPS Drain/Replenish Eng Oil And Renew Oil Filter (AR)(2)		Level 2			000:00		
000000-0052876E		Yes	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0052876C		Yes	OOPS 5 Yearly Drain/Flush And Replen Cooling System	04 May 2020	Level 1	Non-Taskworthy	CL	000:00		
000000-001DA286		No	2 Yearly/40000 Kms	24 May 2019	Level 1			000:00		
000000-0080B812		No	2 Yearly/40000 Kms	24 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-00200232		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 May 2019	Level 1			000:00		
000000-001917EA		No	Yearly/20000 Kms	21 May 2019	Level 1			000:00		
000000-00337912		Yes	Yearly/20000 Kms	21 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0052876F		Yes	6 Monthly/10000 Kms	19 Nov 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0080B815		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 May 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-0052876D		Yes	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 May 2019	Level 1	Non-Taskworthy	CL	000:00		