



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

---

[REDACTED]

email: [REDACTED]  
[REDACTED]

Our Reference:  
FOI2021/03664  
Date:  
15 April 2021

---

Dear [REDACTED],

I am writing about your email of 5 April 2021, requesting the following information:

*Can you provide history on the following landrovers I have purchased*

LT28AA

LT06AA

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached for each vehicle, as follows:

Annex A - Ownership History  
Annex B - Fault History (redacted)  
Annex C - Inspection History  
Annex D - Modification History  
Annex E - Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annexes B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor

Defence Equipment & Support

information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

**VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LT06AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
24/03/1998	SALLDAA67WA142151	N/A		

**VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LT06AA	3		CA005A	JSCS ASHCHURCH		32969AA	24/03/1998	
LT06AA	4	14/04/1998	A0551A	1 SCOTS	38438A	2143	19/06/1998	
LT06AA	4	12/08/2000	A0606A	3 PARA	296	1	12/08/2000	H/T
LT06AA	4	26/04/2006	A8313A	CF BURMA - (CSAT OP HERRICK)	25115	46	05/05/2006	H/T
LT06AA	4	12/01/2007	A0606A	3 PARA	999	999	12/01/2007	MCR
LT06AA	3	17/02/2010	A5969A	TFSU (UK)	373532	2344DD	24/02/2010	
LT06AA	4	13/06/2012	CB997C	ABRO CATTERICK PLANNED REPAIR	4364D	750	12/07/2012	
LT06AA	2	26/02/2013	CC242H	WCSP TRIALS UNIT	999	999	14/05/2013	
LT06AA		14/11/2018	D1832A	OSVP HOLDINGS			14/11/2018	

**VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LT28AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
30/03/1998	SALLDAA67WA142793	N/A		

**VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LT28AA	3		CA005A	JSCS ASHCHURCH		33222AA	30/03/1998	
LT28AA	4	24/04/1998	A3720A	3 LOGISTIC SUPPORT REGT RLC	38705A	577	15/05/1998	
LT28AA	4	26/03/2001	A3720D	32 CS SQN RLC	331	1	01/04/2001	H/T
LT28AA	4	08/05/2003	A3720B	35 HQ SQN RLC	24047	35917	13/05/2003	T80
LT28AA	4	07/11/2003	A9108A	QM DEPT UK LOG BN	999	999	07/11/2003	
LT28AA	4	07/11/2003	A3720B	35 HQ SQN RLC	368	44750	16/12/2003	U39
LT28AA	4	02/03/2004	A3720C	21 GS SQN RLC	30759	49015	11/03/2004	U65
LT28AA	4	18/03/2004	A9108A	QM DEPT UK LOG BN	31335	4462	09/05/2004	U89
LT28AA	4	13/10/2004	A3720B	35 HQ SQN RLC	1887	60159	18/01/2005	V69
LT28AA	3	27/10/2009	A5969A	TFSU (UK)	75767	1753DD	28/10/2009	
LT28AA	4	15/09/2010	A0227A	40 REGT RA (THE LOWLAND GUNNERS)	1705D	999	08/11/2010	

LT28AA	2	25/01/2012	A5969D	TFSU CT1 RU (STIRLING)	999	999	25/01/2012	
LT28AA		23/05/2013	A1990A	DSG STIRLING			23/05/2013	
LT28AA		23/05/2013	A5969D	DSG STIRLING TUF			23/05/2013	
LT28AA		09/07/2013	A0551A	1 SCOTS			09/07/2013	
LT28AA		24/10/2013	A1990A	DSG STIRLING			24/10/2013	
LT28AA		25/08/2016	A3726A	154 REGT RLC			25/08/2016	
LT28AA		28/09/2016	A0494A	TFSU (UK) STIRLING			28/09/2016	
LT28AA		05/10/2016	A5969D	DSG STIRLING TUF			05/10/2016	
LT28AA		26/01/2017	A2973A	1 RMP			26/01/2017	
LT28AA		24/02/2017	A5969D	DSG STIRLING TUF			24/02/2017	
LT28AA		11/05/2018	A5969A	SEF (UK) ASHCHURCH			11/05/2018	
LT28AA		23/07/2018	CA005A	BABCOCK ASCHURCH			23/07/2018	

Work Objects

Serial Number: LT06AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00A61D62		Renew Chassis	Closed	Non-Taskworthy	No	Level 3		10 Oct 2017	N/A	Damage	TUL HS FFR HARD TOP			
		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451A	28 Jul 2017	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00A4145C		DRIVERS DOOR WILL NOT CLOSE	Closed	Non-Taskworthy	No	Level 2		28 Jun 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A34D1A		BONNET PANEL BROKEN	Closed	Fully Fit	No	Level 1		20 Jan 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-009F7804		RECTIFY GEAR SELECTOR INOP	Closed	Fully Fit	No	Level 2		18 Oct 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-009D41F0		Rectify Weaping output @ engine oil cooler	Closed	Fully Fit	No	Level 2		24 Feb 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00973CF7		SEEPAGE AT TRANSMISSION HOUSING	Closed	Fully Fit	No	Level 2		09 Aug 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-009BA739		DAMAGED REAR DOOR CARD	Closed	Fully Fit	No	Level 1		09 Aug 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009BA732		CREW - RENEW R/H/R HARD TOP PASS THROUGH PORT	Closed	Fully Fit	No	Level 1		07 May 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00808423		Lubricate fan controls	Closed	Fully Fit	No	Level 1		24 Feb 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00808441		CREW - LUBRICATE FRESH AIR FLAPS	Closed	Fully Fit	No	Level 1		07 May 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00973D15		Renew Heli lift wood above rear door	Closed	Fully Fit	No	Level 1		24 Feb 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0097AE8A		CREW - Fit spare tyre inflation extention	Closed	Fully Fit	No	Level 1		10 Mar 2016	No Effect	Inspection	TUL HS FFR HARD TOP			
000000-00973D0D		Renew all tyres	Closed	Non-Taskworthy	No	Level 1		24 Feb 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00973D03		Fit black out blind mod to rear door	Closed	Fully Fit	No	Level 2		24 Feb 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00973F25		coolant gauge inop	Closed	Fully Fit	No	Level 2		25 Feb 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-00973DDD		STEERING REQUIRES ADJUSTMENT (TIE BAR SIZED)	Closed	Non-Taskworthy	No	Level 2		25 Feb 2016	N/A	Non Specific	TUL HS FFR HARD TOP			
000000-00950318		VEHICLE HEATER FAN NOT FUNCTIONING	Closed	Fully Fit	No	Level 2		06 Jan 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-009622DD		Check No2 ball joint torque tightness as per safety notice LE SNvE 0006	Closed	Non-Taskworthy	No	Level 2	000000-00003210	20 Jan 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0095CD37		INVESTIGATE No.2 BALL JOINT AS PER SAFETY NOTICE	Closed	Fully Fit	No	Level 2		12 Jan 2016	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-008AC992	000000-003096F1	please carry out work as detailed on 880C	Closed	Fully Fit	No	Level 2		16 Jul 2015	N/A	Servicing	TUL HS FFR HARD TOP			
000000-00808411		VM - REPAIR/SECURE BOTH AIR INTAKES ON WINGS	Closed	Fully Fit	No	Level 2		07 May 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-008B1951		OVERHAUL WIPERS	Closed	Fully Fit	No	Level 2		20 Jul 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-008B1955		RECTIFY AXLE 1 FAULTS	Closed	Fully Fit	No	Level 2		20 Jul 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-008B1958		RECTIFY AXLE 2 FAULTS	Closed	Fully Fit	No	Level 2		20 Jul 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00808405	000000-003096F1	VM - RECTIFY OIL SEEPAGE @ ENGINE SUMP	Closed	Fully Fit	No	Level 2		07 May 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00808401		VM - INVESTIGATE PLAY IN STEERING	Closed	Fully Fit	No	Level 2		07 May 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-008083FA		VM - OBS OIL SEAPAGE @ OIL COOLER UPPER HOSE	Closed	Fully Fit	No	Level 2		07 May 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0080841C		VM - FRONT BRAKE DISKS FORMING LIP	Closed	Fully Fit	No	Level 2		07 May 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0079B9FD		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00844119		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP			
000000-00798A1A		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/05	Closed	Limited Role	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP			
000000-007E0422		CARRY OUT A SIX MONTHLY SERVICE	Closed	Fully Fit	No	Level 1		23 Jan 2014	N/A	Servicing	TUL HS FFR HARD TOP			
000000-007DBEDD		INVESTIGATE DIFFICULTY IN SELECTING GEARS	Closed	Non-Taskworthy	No	Level 2		13 Jan 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-007D33B7		CARRY OUT A 6534 INSPECTION	Closed	Fully Fit	No	Level 1		05 Dec 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007D33BB		CARRY OUT A YEARLY SERVICE	Closed	Fully Fit	No	Level 1		05 Dec 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-007AAF5		INVESTIGATE ENGINE OVERHEATING	Closed	Non-Taskworthy	No	Level 2		09 Aug 2013	N/A	Failure	TUL HS FFR HARD TOP			
000000-007C4048		CARRY OUT YEARLY SERVICE	Closed	Fully Fit	No	Level 1		24 Oct 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-007C406A		CARRY OUT 6 MONTHLY SERVICE	Closed	Fully Fit	No	Level 1		24 Oct 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-0076BC7C	000000-002E1EF6	CLEAR ALL FAULTS FROM DSG JOB CARD 8B0053829	Closed	Fully Fit	No	Level 2		21 Feb 2013	N/A	Failure	TUL HS FFR HARD TOP			
000000-0076BC7A	000000-002E1EF6	CARRY OUT 6534 INSPECTION	Closed	Fully Fit	No	Level 2		21 Feb 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0076BC72	000000-002E1EF6	CARRY OUT 6 MTH SERVICE IAW AESP 2320-D-128-601	Closed	Fully Fit	No	Level 2		21 Feb 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-006806DE		Insp Steering Drop Arm Tab Washer	Closed	Fully Fit	No	Level 2	000000-00000312	22 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0072638B		CARRY OUT 24 MTH SERVICE IAW 2320-D-128-601 TAB 7 COL C	Closed	Fully Fit	No	Level 2		14 Jul 2012	N/A	Servicing	TUL HS FFR HARD TOP			
000000-0072638C		CARRY OUT OOPM TAB 5 SERs 1,2,3,4,6	Closed	Fully Fit	No	Level 2		14 Jul 2012	N/A	Servicing	TUL HS FFR HARD TOP			
000000-0072638D		CARRY OUT 932W & 933 INSPECTION	Closed	Fully Fit	No	Level 2		14 Jul 2012	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0072638E		CARRY OUT FULL RE-SPRAY IF REQUIRED	Closed	Fully Fit	No	Level 2		14 Jul 2012	N/A	Refurbishment	TUL HS FFR HARD TOP			
000000-0072638F		CLEAR ALL FAULTS FROM DSG JOB CARD 8B0038174	Closed	Fully Fit	No	Level 2		14 Jul 2012	N/A	Failure	TUL HS FFR HARD TOP			
000000-000CA787		HEATER FAN INOP	Closed	Fully Fit	No	Level 2		05 Feb 2008			TUL HS FFR HARD TOP			
000000-000CA784		MAP LIGHT INOP	Closed	Fully Fit	No	Level 2		05 Feb 2008			TUL HS FFR HARD TOP			

000000-000CA77A		FIT CHECK STRAP TO O/S/F DOOR	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA76D		RENEW O/S/F DISC GUARD BRACKET	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA760		MAIN BEAM FLASH INOP	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA796		REAR TOW PINTLE ROTATION PIN MISSING	Closed	Fully Fit	No	Level 1	05 Feb 2008	TUL HS FFR HARD TOP
000000-004283B6		INVEST INDICATORS/HAZRADS INOP	Closed	Non-Taskworthy	No	Level 2	28 May 2009	TUL HS FFR HARD TOP
000000-003ADAA4		VARIOUS L2 TASKS	Closed	Non-Taskworthy	No	Level 2	29 Jan 2009	TUL HS FFR HARD TOP
000000-000C8382		REAR DOOR LATCH BROKEN	Closed	Fully Fit	No	Level 2	30 Jan 2008	TUL HS FFR HARD TOP
000000-000CA757		RENEW VISCOUS FAN COUPLING	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA75B		RE FIT CORRECT DOWN PIPE	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA75F		O/S/R FOG LIGHT LENS CRACKED	Closed	Fully Fit	No	Level 1	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA765		N/S/F INDICATOR LENS CRACKED	Closed	Fully Fit	No	Level 1	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA768		RENEW DROP ARM	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA76A		RENEW PANHARD BOLTS AND BUSHES	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA773		RENEW REAR DOOR GLASS AND LOCK U/S	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA780		FIT NEW CLUTCH PEDAL RUBBER	Closed	Fully Fit	No	Level 1	05 Feb 2008	TUL HS FFR HARD TOP
000000-000CA794		EXCESS PLAY IN O/S TOP AND BOTTOM DOOR HINGES	Closed	Fully Fit	No	Level 2	05 Feb 2008	TUL HS FFR HARD TOP
000000-000A0B1E	000000-0026F3AE	VEHICLE WILL NOT START AND HAS NO POWER FAULT UNKNOWN	Closed	Non-Taskworthy	No	Level 2	26 Nov 2007	TUL HS FFR HARD TOP
000000-00098583	000000-00274A7D	CLUTCH PEDAL DOES NOT RETURN ONCE DEPRESSED	Closed	Non-Taskworthy	No	Level 2	30 Oct 2007	TUL HS FFR HARD TOP
000000-00092498	000000-0027352D	RENEW INDICATOR SWITCH	Closed	Non-Taskworthy	No	Level 2	10 Oct 2007	TUL HS FFR HARD TOP
000000-0007E8AF		VEHICLE GEARS NOT ENGAGING MAYBE CLUTCH OR GEARBOX FAULT	Closed	Non-Taskworthy	No	Level 2	25 Jul 2007	TUL HS FFR HARD TOP
000000-0007021A		H/LIGHT RELFECTOR U/S	Closed	Fully Fit	No	Level 2	07 Jun 2007	TUL HS FFR HARD TOP
000000-0006990A		Initial Usage	Closed	Fully Fit	No	Level 1	14 May 2007	TUL HS FFR HARD TOP
000000-00069913		Initial Usage	Closed	Fully Fit	No	Level 1	14 May 2007	TUL HS FFR HARD TOP
000000-0006991B		Initial Maintenance	Closed	Fully Fit	No	Level 1	14 May 2007	TUL HS FFR HARD TOP

Work Objects

Serial Number: LT28AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Number	Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work Ban	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00BB6712		Asbestos Decontamination Cleaning Required	Closed	Limited Role	No	Level 1			10 Jun 2020	N/A	Ban	TUL HS FFR HARD TOP			000:00
000000-00A4146A		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000451A		28 Jul 2017	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00A18FOE		CHECK AND REPAIR BRAKE LIGHTS	Closed	Fully Fit	No	Level 1			18 Apr 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009622F1		Check No2 ball joint torque tightness as per safety notice LE SNvE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003210		20 Jan 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00844197		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58		09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP			
000000-004332DD		AESP 2320-D-128-601 Table 5 Ser 6 Camshaft Timing Belt Replace	Closed	Fully Fit	No	Level 2			18 Jun 2009	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-004332DC		AESP 2320-D-128-601 Table 5 Ser 4 Air filter Element Replace	Closed	Fully Fit	No	Level 1			18 Jun 2009	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-004332DB		AESP 2320-D-128-601 Table 5 Ser 3 Coolant Drain and Replenish	Closed	Fully Fit	No	Level 1			18 Jun 2009	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-004332DA		AESP 2320-D-128-601 Table 5 Ser 2 Gearbox Oil Drain and Replenish	Closed	Fully Fit	No	Level 1			18 Jun 2009	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-004332D9		AESP 2320-D-128-601 Table 5 Ser 1 Engine Oil and Filter Change	Closed	Fully Fit	No	Level 1			18 Jun 2009	N/A	Closed No Action	TUL HS FFR HARD TOP			000:00
000000-0079BA72		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835		25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007BE1FF		Carry Out 6 Monthly 6534 Insp	Closed	Fully Fit	No	Level 1			09 Oct 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007BE206		Carry Out 6 Monthly Service and Vm Tasks	Closed	Fully Fit	No	Level 2			09 Oct 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-007BF946		RENEW NO1 BALL JOINT	Closed	Fully Fit	No	Level 2			14 Oct 2013	N/A	Damage	TUL HS FFR HARD TOP			
000000-007BF94D		RENEW BOTH REAR SHOCK ABSORBERS	Closed	Fully Fit	No	Level 2			14 Oct 2013	N/A	Damage	TUL HS FFR HARD TOP			
000000-00798A93		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A		24 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP			
000000-0072453F		Replace Component	Closed	Fully Fit	No	Level 1			09 Jul 2012	N/A	Modification	TUL HS FFR HARD TOP			
000000-006FF330		CHANGE BRAKE FLUID	Closed	Non-Taskworthy	No	Level 4			10 Mar 2012	N/A	Servicing	TUL HS FFR HARD TOP			
000000-006D7CC9		6534 INSP FAULTS DATED 22/03/11	Closed	Fully Fit	No	Level 4			28 Oct 2011	N/A	Inspection	TUL HS FFR HARD TOP			
000000-006B06F0		Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-00000312		22 Jun 2011	N/A	Inspection	TUL HS FFR HARD TOP			
000000-004857BB	000000-0029A485	Observe Front Exhaust Rubber Mount Held By Cable Tie - Fm 6534 Date 08-10-09	Closed	Fully Fit	No	Level 2			08 Oct 2009			TUL HS FFR HARD TOP			
000000-004844AF	000000-00299FDC	Carry Out 6534	Closed	Fully Fit	No	Level 3			07 Oct 2009			TUL HS FFR HARD TOP			
000000-004844AD	000000-00299FDC	Carry Out 6 Monthly VM Tasks	Closed	Fully Fit	No	Level 3			07 Oct 2009			TUL HS FFR HARD TOP			
000000-004844A8	000000-00299FDC	Carry Out 6 Monthly Service	Closed	Fully Fit	No	Level 3			07 Oct 2009			TUL HS FFR HARD TOP			
000000-0042C01E	000000-0028F364	Heater Doesn't Work	Closed	Fully Fit	No	Level 2			03 Jun 2009			TUL HS FFR HARD TOP			
000000-004254A1		Awaiting Brake Certification Validity Check	Closed	Non-Taskworthy	No	Level 1			20 May 2009			TUL HS FFR HARD TOP			
000000-003DBF57		Map Light Bulb Blown	Closed	Fully Fit	No	Level 1			04 Mar 2009			TUL HS FFR HARD TOP			
000000-0040A752	000000-0028A959	Reqs Annual MEI	Closed	Fully Fit	No	Level 2			30 Mar 2009			TUL HS FFR HARD TOP			
000000-0040A750	000000-0028A959	Reqs 1 Yrly VM Tasks	Closed	Fully Fit	No	Level 2			30 Mar 2009			TUL HS FFR HARD TOP			
000000-0040A74F		Reqs 1 Yrly VM Tasks	Closed	Fully Fit	No	Level 1			30 Mar 2009			TUL HS FFR HARD TOP			
000000-0040A74E	000000-0028A959	Reqs 1 Yrly Service	Closed	Fully Fit	No	Level 1			30 Mar 2009			TUL HS FFR HARD TOP			
000000-003DF58B	000000-00289492	AESP 2320-D-128-601 Table 5 Ser 2 Gearbox Oil Drain and replenish	Closed	Non-Taskworthy	No	Level 1			11 Mar 2009			TUL HS FFR HARD TOP			
000000-0011BE0F	000000-0027B775	HEATER LEVER INOP	Closed	Fully Fit	No	Level 2			27 Mar 2008			TUL HS FFR HARD TOP			
000000-002E3D13		Reqs Front Grille	Closed	Fully Fit	No	Level 1			31 Oct 2008			TUL HS FFR HARD TOP			
000000-0029B05C	000000-00281CAC	Reqs 6 Mnthly Service	Closed	Fully Fit	No	Level 1			30 Sep 2008			TUL HS FFR HARD TOP			
000000-0029B070	000000-00281CAC	Reqs 6 Mnthly VM Tasks	Closed	Fully Fit	No	Level 2			30 Sep 2008			TUL HS FFR HARD TOP			
000000-0029B084	000000-00281CAC	Reqs 6534	Closed	Fully Fit	No	Level 1			30 Sep 2008			TUL HS FFR HARD TOP			
000000-0029B09B	000000-00281CAC	AESP 2320-D-128-601 Table 5 Ser 1 Engine Oil and Filter Change	Closed	Fully Fit	No	Level 1			30 Sep 2008			TUL HS FFR HARD TOP			
000000-0020AE1C	000000-0027E3E1	Spare Tyre Valve U/S	Closed	Non-Taskworthy	No	Level 1			15 Jul 2008			TUL HS FFR HARD TOP			
000000-0004C7DE	000000-0026B7B4	ROOF REQUIRES REALIGNING	Closed	Fully Fit	No	Level 2			05 Feb 2007			TUL HS FFR HARD TOP			
000000-00097922	000000-0026B7B4	Repair pass window frame	Closed	Fully Fit	No	Level 2			26 Oct 2007			TUL HS FFR HARD TOP			
000000-0021BF73		AESP 2320-D128-601 Table 5 Ser 4 Air Filter Element Replace	Closed	Non-Taskworthy	No	Level 1			03 Apr 2008			TUL HS FFR HARD TOP			
000000-0021BF9C		AESP 2320-D128-601 Table 7 Ser 51 Col C Brake Fluid Drain and Replenish	Closed	Non-Taskworthy	No	Level 2			03 Apr 2008			TUL HS FFR HARD TOP			
000000-0009FEB	000000-00278350	fit spare wheel inflation mod	Closed	Fully Fit	No	Level 1			22 Nov 2007			TUL HS FFR HARD TOP			
000000-0004E086	000000-0026B7B4	SEAT RECLINER MISSING COVER	Closed	Fully Fit	No	Level 1			12 Feb 2007			TUL HS FFR HARD TOP			
000000-0004E088		WAITING FOR NEW DOOR LOCKS	Closed	Fully Fit	No	Level 1			12 Feb 2007			TUL HS FFR HARD TOP			
000000-0021BF10		AESP 2320-D128-601 Table 5 Ser 1 Engine Oil and Filter Change	Closed	Non-Taskworthy	No	Level 1			11 Jan 2007			TUL HS FFR HARD TOP			
000000-0021BF89		AESP 2320-D128-601 Table 5 Ser 3 Coolant Drain and Replenish	Closed	Non-Taskworthy	No	Level 1			11 Jan 2007			TUL HS FFR HARD TOP			
000000-0002ADD5		Initial Usage	Closed	Fully Fit	No	Level 1			05 Sep 2006			TUL HS FFR HARD TOP			
000000-0002ADEE		Initial Maintenance	Closed	Fully Fit	No	Level 1			05 Sep 2006			TUL HS FFR HARD TOP			
000000-0021BECO		AESP 2320-D128-601 Table 5 Ser 6 Camshaft Timing Belt Replace	Closed	Non-Taskworthy	No	Level 2			20 Jun 2004			TUL HS FFR HARD TOP			
000000-0021BE5B		AESP 2320-D128-601 Table 5 Ser 2 Gearbox Oil Drain and Replenish	Closed	Non-Taskworthy	No	Level 1			27 Jan 2003			TUL HS FFR HARD TOP			



Work Objects

Serial Number: LT06AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-006EB093		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1	Non-Taskworthy	WiP	000:00		
000000-008A2345		No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00		
000000-008A289D		No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00		
000000-002AC763		No	MEI (2)	30 Jan 2018	Level 2			000:00		
000000-003440B4		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00		
000000-00213C10		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00		
000000-00793BBC		No	MEI (2)	30 Jan 2018	Level 2	Fully Fit	CL	000:00		
000000-00793CD1		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1	Fully Fit	CL	000:00		
000000-0058CD54		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00		
000000-00647EC0		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1	Fully Fit	CL	000:00		
000000-00088AED		No	MEI (2)	30 Jan 2018	Level 2		CL	000:00		
000000-00090D39		No	MEI (2)	30 Jan 2018	Level 2		CL	000:00		
000000-00009F82		No	MEI (2)	30 Jan 2018	Level 2		CL	000:00		
000000-000354A3		No	MEI (2)	30 Jan 2018	Level 2		CL	000:00		
000000-00213C0F		No	MEI (2)	30 Jan 2018	Level 2			000:00		
000000-0025FC50		No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00		

000000-00853BF6	No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00
000000-004D2ECD	No	MEI (2)	30 Jan 2018	Level 2	Non-Taskworthy	CL	000:00
000000-008A2938	No	Ad Hoc Insp (AR)		Level 1	Non-Taskworthy	CL	000:00
000000-0054A899	No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00
000000-00647E3A	No	MEI (2)	30 Jan 2018	Level 2	Fully Fit	CL	000:00
000000-002AC764	No	6 Monthly 6534 Insp	30 Jan 2018	Level 1			000:00

Work Objects

Serial Number: LT28AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0034C99C		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-00482A97		No	MEI (2)	24 Oct 2018	Level 2			000:00		
000000-005DE35D		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-001C4AE0		No	MEI (2)	24 Oct 2018	Level 2			000:00		
000000-00144D9A		No	MEI (2)	24 Oct 2018	Level 2			000:00		
000000-003F3BFF		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-0034C99B		No	MEI (2)	24 Oct 2018	Level 2			000:00		
000000-00680165		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-0052DFC1		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-007E69EC		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-00482A98		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-008A91F7		No	MEI (2)	24 Oct 2018	Level 2			000:00		
000000-008A91F8		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-002699B7		No	6 Monthly 6534 Insp	25 Apr 2018	Level 1			000:00		
000000-00094768		No	MEI (2)	24 Oct 2018	Level 2		CL	000:00		

000000-000C5D13	No	First Parade Insp (AR)(1)		Level 1	CL	000:00
000000-000A3AF2	No	First Parade Insp (AR)(1)		Level 1	CL	000:00
000000-000B7433	No	MEI (2)	24 Oct 2018	Level 2	CL	000:00
000000-000E11CF	No	First Parade Insp (AR)(1)		Level 1	CL	000:00
000000-001F147F	No	6 Monthly 6534 Insp	25 Apr 2018	Level 1		000:00
000000-001C4AE1	No	6 Monthly 6534 Insp	25 Apr 2018	Level 1		000:00
000000-005DE35C	No	MEI (2)	24 Oct 2018	Level 2		000:00
000000-007482DE	No	6 Monthly 6534 Insp	25 Apr 2018	Level 1		000:00
000000-002699B6	No	MEI (2)	24 Oct 2018	Level 2		000:00
000000-001942C2	No	6 Monthly 6534 Insp	25 Apr 2018	Level 1		000:00
000000-007482DD	No	MEI (2)	24 Oct 2018	Level 2		000:00
000000-0027A96D	No	6 Monthly 6534 Insp	25 Apr 2018	Level 1		000:00
000000-0001963A	No	First Parade Insp (AR)(1)		Level 1	CL	000:00
000000-00083DOC	No	MEI (2)	24 Oct 2018	Level 2	CL	000:00
000000-00088759	No	MEI (2)	24 Oct 2018	Level 2	CL	000:00
000000-000F671C	No	First Parade Insp (AR)(1)		Level 1	CL	000:00

Work Objects

Serial Number: LT06AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0068DA3F	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00689CE0	00020	8 Metre Mast Mount Installation Kit		No	-/-	UTI				Fully Fit					
000000-00689CA1	00008	Installation of 12/24 volt sockets.(Installation Instruction 8 (2320-D-128-411 Installations Instructions and Index))		No	3/A	STI				Fully Fit					
000000-00689C9F	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit					
000000-00689CB2	00033	Rear Door Blackout Blind (FFR Variants) Only		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00689CB3	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00689CB1	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			
000000-00632381	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00632385	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Limited Role	CL	Level 2			
000000-0063239A	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0062A178	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-00629CF6	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			
000000-00632380	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-00632398	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL	Level 2			
000000-00632399	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0063236E	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			

Work Objects

Serial Number: LT28AA  
 NSN: 2320998939742

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006905BF	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-0061AC51	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit					
000000-0061AC82	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061AC7F	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061AC79	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/	RTI				Fully Fit	CL	Level 2			
000000-0061AC6D	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL	Level 2			
000000-0061AC71	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061AC83	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			
000000-0061AC75	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061AC7E	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Non-Taskworthy	CL	Level 2			
000000-0061AC6E	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL	Level 2			
000000-0061AC70	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL	Level 2			
000000-0061AC81	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061AC74	00019	Blackout Cover for Warning Light Panel		No	-/	UTI				Fully Fit	CL	Level 2			
000000-0061AC6F	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL	Level 2			
000000-0061AC78	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL	Level 2			

Work Objects

Serial Number: LT06AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00213C02		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	11 Sep 2018	Level 2			000:00		
000000-006EB046		No	Yearly/20000 Kms	31 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-00213C05		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	06 Sep 2022	Level 1			000:00		
000000-00213C06		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	01 Aug 2019	Level 1			000:00		
000000-00736647		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	25 Oct 2021	Level 2	Fully Fit	CL	000:00		
000000-0086AAAA		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	30 Aug 2019	Level 1	Fully Fit	CL	000:00		
000000-00213C08		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1			000:00		
000000-008541B5		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	01 Aug 2019	Level 1	Fully Fit	CL	000:00		
000000-00311EAF		No	Yearly/20000 Kms	31 Aug 2018	Level 1			000:00		
000000-0025FC3E		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1			000:00		
000000-00311EAB		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1			000:00		
000000-00779CEF		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1	Fully Fit	CL	000:00		
000000-0054A881		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0058CCE1	000000-003096F1	No	Yearly/20000 Kms	31 Aug 2018	Level 1	Fully Fit	CL	000:00		
000000-00870B68		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	06 Sep 2022	Level 1	Non-Taskworthy	CL	000:00		
000000-00213C03		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	25 Oct 2021	Level 2			000:00		
000000-00213C04		No	Yearly/20000 Kms	31 Aug 2018	Level 1			000:00		
000000-00854111		No	Yearly/20000 Kms	31 Aug 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-004D529A	000000-003096F1	No	2 Yearly/40000 Kms	31 Aug 2019	Level 1	Fully Fit	CL	000:00		
000000-0036F954		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1			000:00		
000000-00574788	000000-003096F1	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	01 Aug 2019	Level 1	Fully Fit	CL	000:00		
000000-00213C07		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	30 Aug 2019	Level 1			000:00		
000000-00081265		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-00085E37		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-00094A2E		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-000E6243		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000AFFED		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-000094DE		No	2 Yearly/40000 Kms	31 Aug 2019	Level 1		CL	000:00		
000000-000F8216		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-00009515		No	Yearly/20000 Kms	31 Aug 2018	Level 1		CL	000:00		
000000-00025960		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-0002856E		No	Weekly (AR)(1)		Level 1		CL	000:00		
000000-000C9F3C		No	Yearly/20000 Kms	31 Aug 2018	Level 1		CL	000:00		
000000-000386B2		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1		CL	000:00		
000000-0083F6C2		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1	Fully Fit	CL	000:00		
000000-006D517E		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0060EC00		No	6 Monthly/10000 Kms	12 Jan 2018	Level 1	Fully Fit	CL	000:00		
000000-008541A8		No	2 Yearly/40000 Kms	31 Aug 2019	Level 1	Non-Taskworthy	CL	000:00		
000000-00213C01		No	2 Yearly/40000 Kms	31 Aug 2019	Level 1			000:00		
000000-0057479E	000000-003096F1	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	30 Aug 2019	Level 1	Fully Fit	CL	000:00		

Work Objects

Serial Number: LT28AA  
 NSN: 2320998939742

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-001C4AD0		No	5 Yearly/100000 Kms (1)		Level 1			000:00		
000000-007E69FB		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-0034C9A8		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-0034C9A9		No	Yearly/20000 Kms	24 Oct 2018	Level 1			000:00		
000000-00205A22		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 Oct 2019	Level 1			000:00		
000000-005DE328		No	Yearly/20000 Kms	24 Oct 2018	Level 1			000:00		
000000-0027A92F		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-002699B5		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-00144DA3		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-00205A1F		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	20 Mar 2022	Level 2			000:00		
000000-008A91E6		No	2 Yearly/40000 Kms	24 Oct 2019	Level 1			000:00		
000000-005DE327		No	2 Yearly/40000 Kms	24 Oct 2019	Level 1			000:00		
000000-00205A1E		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	09 Jul 2018	Level 2			000:00		
000000-00482A95		No	Yearly/20000 Kms	24 Oct 2018	Level 1			000:00		
000000-00144DB3		No	6 Yearly/120000 Kms (2)		Level 2			000:00		
000000-001C4AC8		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (AR)(1)		Level 1			000:00		
000000-007E69FC		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	20 Mar 2022	Level 2			000:00		
000000-00680131		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-007482D6		No	Yearly/20000 Kms	24 Oct 2018	Level 1			000:00		
000000-00482A96		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-007482D7		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-00194293		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-0052DFB9		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-0034C9A7		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 Oct 2019	Level 1			000:00		
000000-003F3BE9		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-008A91E8		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1			000:00		
000000-001C4ACF		No	OOPS Drain/Replenish Eng Oil And Renew Oil Filter (AR)(2)		Level 2			000:00		
000000-008A91E9		No	Yearly/20000 Kms	24 Oct 2018	Level 1			000:00		
000000-0007C026		No	Yearly/20000 Kms	24 Oct 2018	Level 1		CL	000:00		
000000-0007BEF3		No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00		
000000-0007C015		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1		CL	000:00		
000000-00084303		No	6 Monthly/10000 Kms	25 Apr 2018	Level 1		CL	000:00		



000000-000F512D	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	CL	000:00
000000-00094765	No	2 Yearly/40000 Kms	24 Oct 2019	Level 1	CL	000:00
000000-00094766	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	CL	000:00
000000-00094767	No	Yearly/20000 Kms	24 Oct 2018	Level 1	CL	000:00
000000-000B4F52	No	6 Yearly/120000 Kms (2)		Level 2	CL	000:00
000000-0009D378	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A2866	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A590B	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A4447	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A63BE	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A3EB2	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000C5F8F	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A3756	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	CL	000:00
000000-000A7085	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A9CDF	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A574E	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000A78E1	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000AC38E	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000AC4B4	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000AFA10	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000AFB7C	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000E778A	No	Yearly/20000 Kms	24 Oct 2018	Level 1	CL	000:00
000000-00003DB4	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000B6E91	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00006541	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00100C87	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000E02DA	No	Yearly/20000 Kms	24 Oct 2018	Level 1	CL	000:00
000000-00009F07	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	CL	000:00
000000-000F8783	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-0000B605	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-0000FF99	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00010E64	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-0001371F	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000117EB	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000F05D4	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00016168	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-0001B8FA	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00019529	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-000F0AAE	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-0001DFB0	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00022E74	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-00022B41	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	CL	000:00
000000-00028C10	No	Weekly (AR)(1)		Level 1	CL	000:00
000000-0034C9A6	No	2 Yearly/40000 Kms	24 Oct 2019	Level 1		000:00
000000-00144DA2	No	Yearly/20000 Kms	24 Oct 2018	Level 1		000:00
000000-001C4AC9	No	OOPS Cooling System (AR)		Level 2		000:00
000000-005DE353	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1		000:00
000000-001C4AC6	No	Yearly/20000 Kms	24 Oct 2018	Level 1		000:00
000000-001C4AC5	No	2 Yearly/40000 Kms	24 Oct 2019	Level 1		000:00
000000-0034C9AA	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 Oct 2019	Level 1		000:00

000000-008A91E7	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 Oct 2019	Level 1	000:00
000000-008A91EA	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 Oct 2019	Level 1	000:00
000000-002699B4	No	Yearly/20000 Kms	24 Oct 2018	Level 1	000:00
000000-00205A20	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	20 Mar 2022	Level 1	000:00
000000-005DE329	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 Oct 2019	Level 1	000:00
000000-007E69FD	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	20 Mar 2022	Level 1	000:00
000000-00205A21	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	24 Oct 2019	Level 1	000:00
000000-001F14B2	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	000:00
000000-005DE352	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	24 Oct 2019	Level 1	000:00
000000-001C4AC7	No	6 Monthly/10000 Kms	25 Apr 2018	Level 1	000:00
000000-00144DA1	No	2 Yearly/40000 Kms	24 Oct 2019	Level 1	000:00