



Ministry
of Defence

Defence Equipment and Support
Secretariat
#2043 Maple 0a
Ministry of Defence
Abbey Wood
Bristol BS34 8JH



Email: DES SEC-PolSec LE-JSC-WPNS@mod.uk

[REDACTED]
email: [REDACTED]

Our Reference:
FOI2021/05171
Date:
24 May 2021

Dear [REDACTED],

I am writing about your email of 15 May 2021, requesting the following information:

Could you please provide Merlin Report and / or details of vehicle history for my Landrover WOLF TUL, ERM LS22AA, chassis number SALLDAA67WA139215, which was in service on the 4/3/1998. I confirm that I am the registered keeper of this vehicle.

I have looked on Merlin and there is ok information available. If you require further details, or if there is a charge payable, then please let me know. I will be very grateful for any information that you can give me that will help me to restore and maintain this vehicle for the future.

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Ownership History
Annex B - Fault History (redacted)
Annex C – Inspection History
Annex D – Modification History
Annex E – Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD

Defence Equipment & Support

contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail CIO-FOI-IR@mod.gov.uk). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

[Redacted Signature]

[Redacted Name]

DE&S Policy Secretariat Asst Hd

VEHICLE DETAILS

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LS22AA	2320998939742	NB42253100	LV2A/088DUM	TRUCK UTY LIGHT (TUL) (HS) 4X4 LAND ROVER FFR HARD TOP 2.5 LTR TURBO DSL (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
04/03/1998	SALLDAA67WA139215	N/A		

VEHICLE HISTORY

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LS22AA	3		CA005A	JSCS ASHCHURCH		32126AA	04/03/1998	
LS22AA	4	27/03/1998	A0214A	19 REGT RA (AS 90 REGT)	37972A	71	27/04/1998	
LS22AA	4	19/01/2000	A9034A	UK ARTY REGT	090H/T	1707H/T	19/02/2000	H/T
LS22AA	4	10/07/2000	A0214A	19 REGT RA (AS 90 REGT)	483	183	17/07/2000	H/T
LS22AA	4	04/07/2011	A0219A	26 REGT RA	999	999	04/07/2011	C06
LS22AA	3	11/07/2011	A5969A	TFSU (UK)	999999	4669DD	11/07/2011	
LS22AA	4	16/08/2012	CB998C	DSG COLCHESTER PLANNED REPAIR	4702D	999	16/08/2012	
LS22AA	2	12/03/2013	A6205G	DSG VEHICLES LONGMOOR	L0002	30/13	16/05/2013	
LS22AA		25/02/2015		1 R IRISH MT			02/03/2015	
LS22AA		27/09/2016		1 GREN GDS			03/10/2016	
LS22AA		10/05/2018		SEF (UK) ASHCHURCH			11/05/2018	
LS22AA		19/09/2018		BABCOCK DISPOSAL			19/09/2018	

Work Objects

Serial Number: LS22AA
 NSN: 2320998939936

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Number	Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00AAE8BE		LIGHT INDICATOR NOT WORKING ON DASH	Closed	Fully Fit	No	Level 2			04 May 2018	No Effect	Failure	TUL HS FFR SOFT TOP			000:00
J05569-1D3C2002		Drivers heater inoperable	Closed	Fully Fit	No	Level 2			30 Oct 2016	N/A	Failure	TUL HS FFR SOFT TOP			000:00
J05569-1D3C2001		Windscreen wipers intermittent	Closed	Limited Role	No	Level 2			30 Oct 2016	N/A	Failure	TUL HS FFR SOFT TOP			000:00
000000-00A42A9B		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA)	Closed	Fully Fit	No	Level 2	000000-00004529		29 Jul 2017	N/A	Inspection	TUL HS FFR SOFT TOP			000:00
000000-00A3A0DA		post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Fully Fit	No	Level 2			05 Jul 2017	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-00A2249F		rear main oil seal wet	Closed	Non-Taskworthy	No	Level 2			12 May 2017	N/A	Failure	TUL HS FFR SOFT TOP			
J05562-1D600000		RENEW WINDSCREEN	Closed	Fully Fit	No	Level 2			11 Nov 2016	N/A	Closed No Action	TUL HS FFR SOFT TOP			
000000-00A095A5		Renew Windscreen	Closed	Fully Fit	No	Level 2			11 Nov 2016	N/A	Closed No Action	TUL HS FFR SOFT TOP			
000000-00A095A5		LIGHT SWITCH U/S	Closed	Non-Taskworthy	No	Level 2			07 Mar 2017	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-00A09592		HAND BRAKE	Closed	Non-Taskworthy	No	Level 2			07 Mar 2017	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-009F74F9		DRIVERS SIDE REAR BRAKE LIGHT COVER DAMAGED AND BULB NOT WORKING	Closed	Non-Taskworthy	No	Level 1			19 Jan 2017	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6D1F		NO FFR BOWMAN CERTIFICATION	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-009C3FA8		TWO OF FOUR FFR BATTERIES FITTED	Closed	Limited Role	No	Level 1			06 Sep 2016	N/A	Closed No Action	TUL HS FFR SOFT TOP			
000000-009711F1		RENEW HEATER MOTOR	Closed	Non-Taskworthy	No	Level 2			18 Feb 2016	N/A	Failure	TUL HS FFR SOFT TOP			
000000-0096DAF3		6 Monthly/10000 Kms	Closed	Non-Taskworthy	No	Level 2			13 Feb 2016	N/A	Servicing	TUL HS FFR SOFT TOP			
000000-0096DAEE		CARRY OUT 934 IAW JSP930	Closed	Non-Taskworthy	No	Level 1			13 Feb 2016	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0096DAED		6 Monthly/10000 Kms	Closed	Non-Taskworthy	No	Level 1			13 Feb 2016	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-00962294		Check No2 ball joint torque tightness as per safety notice LE SNVE 00063	Closed	Non-Taskworthy	No	Level 2	000000-00003210		20 Jan 2016	N/A	Closed No Action	TUL HS FFR SOFT TOP			
000000-008EA304		CARRY OUT SEFIT INSPECTION IN LINE WITH LE SNVE 00063	Closed	Non-Taskworthy	No	Level 2			17 Dec 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B8322		CARRY OUT FMT932(W1) RE-CERTIFICATION	Closed	Non-Taskworthy	No	Level 2			19 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B6BD9		INV/REC ENGINE OIL LEAK LOWER TIMING COVER AREA	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B5894		CARRY OUT 1 YRLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM B)	Closed	Fully Fit	No	Level 1			10 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B589B		CARRY OUT 1 YRLY (L2 VMS TASKS 2320-D-128-601 T 7 COLM B)	Closed	Fully Fit	No	Level 2			10 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B6BF4		ROUTE & SECURE CORRECTLY P/STEER PIPES AT FRONT X-MEMBER	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6BF4		ADJUST HAND BRAKE CABLE	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B6C1C		RECTIFY N/S & O/S FRONT BRAKE HOSES FOULING ROAD SPRINGS	Closed	Non-Taskworthy	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6C44		RECTIFY INOP BRAKE LIGHTS	Closed	Non-Taskworthy	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6C08		TIGHTEN LOWER REAR DOOR HINGE MTG BOLTS	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6C10		REPLACE STEER DAMPER BUSHES (STUD END)	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6C13		FIT AIR INTAKE SNORKLE CLAMP RUBBERS CORRECTLY	Closed	Fully Fit	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-008B6C3C		RECTIFIED SIEZED CONVOY LAMP SHIELD	Closed	Non-Taskworthy	No	Level 2			13 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B5868		CARRY OUT ANNUAL FMT 932 (W1 INSPECTION)	Closed	Fully Fit	No	Level 2			10 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B587B		CARRY OUT ANNUAL (FMT 933 INSPECTION)	Closed	Fully Fit	No	Level 2			10 Aug 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B6BD5		BEAM SET HEAD LIGHTS (AIM U/S)	Closed	Non-Taskworthy	No	Level 2			13 Aug 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-0087A39C		CARRY OUT AF 6534 INSPECTION	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0087A3A0		CARRY OUT 6 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM A)	Closed	Fully Fit	No	Level 1			03 Mar 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0087A3A5		CARRY OUT 6 MTHLY (L2 VMS TASKS 2320-D-128-601 T 7 COLM A)	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-008B6639		TORQUE WHEEL NUTS	Closed	Fully Fit	No	Level 1			01 Apr 2015	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-00844241		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58		09 Oct 2014	Degraded	Inspection	TUL HS FFR SOFT TOP			
000000-00867266		REPAIR WIRING ON STARTER SOLENOID	Closed	Limited Role	No	Level 2			19 Jan 2015	N/A	Failure	TUL HS FFR SOFT TOP			
000000-007F9ED6		P/S DOOR MAP HOLDER MISSING	Closed	Fully Fit	No	Level 1			26 Mar 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-007FBF7		CARRY OUT ANNUAL FMT 932 (W1 INSPECTION)	Closed	Non-Taskworthy	No	Level 2			01 Apr 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-007FBC00		CARRY OUT ANNUAL (FMT 933 INSPECTION)	Closed	Fully Fit	No	Level 2			01 Apr 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-007FBC12		CARRY OUT 2 YRLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM C)	Closed	Fully Fit	No	Level 2			01 Apr 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0083AE5		CARRY OUT 2 YRLY (L2 VMS TASKS 2320-D-128-601 T7 COLM C)	Closed	Fully Fit	No	Level 2			25 Sep 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0083AE5		CARRY OUT O.O.P.M. T5 SERIAL 1 (RENEW ENGINE OIL & FILTER)	Closed	Fully Fit	No	Level 2			25 Sep 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0083AEF0		CARRY OUT O.O.P.M. T5 SERIAL 4 (RENEW AIR CLEANER)	Closed	Fully Fit	No	Level 2			25 Sep 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0083AEF6		RENEW BRAKE FLUID (2 YRLY VMS TASK)	Closed	Fully Fit	No	Level 2			25 Sep 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0083AEFD		REPACK FRONT & REAR HUB BEARINGS (2 YRLY VMS TASK)	Closed	Fully Fit	No	Level 2			25 Sep 2014	N/A	Inspection	TUL HS FFR SOFT TOP			
000000-0084A267		TORQUE WHEEL NUTS	Closed	Fully Fit	No	Level 1			23 Oct 2014	N/A	Inspection	TUL HS FFR SOFT TOP			000:00

000000-007BB400	Update JAMES systems maintenance forecasting and MOD registers	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BB3C8	Passenger door map box insecure	Closed	Limited Role	No	Level 2	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3E8	Bonnet stay grommet u/s	Closed	Fully Fit	No	Level 1	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3FA	Carry out, out inspection and recertify 932w1 and 933 reports	Closed	Non-Taskworthy	No	Level 2	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BA97D	CARRY OUT 12 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM B;	Closed	Fully Fit	No	Level 1	30 Sep 2013	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-007BA994	CARRY OUT 12 MTHLY (L2 VMS TASKS 2320-D-128-601 T 7 COLM B ;	Closed	Fully Fit	No	Level 2	30 Sep 2013	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-007BB3C1	Engine oil level high	Closed	Fully Fit	No	Level 1	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BB3C6	Drivers door bottom hinge worn	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3C7	Drivers door windows loose in runners	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3D1	Passenger door bottom seal missing	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BB3DA	LH aerial mount door catch missing	Closed	Fully Fit	No	Level 1	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BB3DE	LH demister hose grommet missing	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BB3E4	Headlamp adjusting switch loose in cowl	Closed	Fully Fit	No	Level 1	01 Oct 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BB3E7	Ammeter illumination in-op	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3EE	Drivers seat ripped u/s	Closed	Fully Fit	No	Level 1	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3EF	Oil leak @ crankcase breather	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007BB3F5	Oil pressure warn light in-op	Closed	Fully Fit	No	Level 2	01 Oct 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-007C5551	Torque wheel nuts to 170nm using wrench 495129	Closed	Fully Fit	No	Level 2	28 Oct 2013	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-007BA964	CARRY OUT ANNUAL FMT 932 (W 1 INSPECTION)	Closed	Fully Fit	No	Level 2	30 Sep 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-007BA968	CARRY OUT ANNUAL FMT 933 (INSPECTION)	Closed	Limited Role	No	Level 2	30 Sep 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-0079BB10	Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS FFR SOFT TOP
000000-00798837	GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	24 Jun 2013	N/A	Failure	TUL HS FFR SOFT TOP
000000-0078DE75	CARRY OUT AB 6534 INSPECTION	Closed	Non-Taskworthy	No	Level 2	29 May 2013	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-0078DE7B	CARRY OUT 6 MTHLY SERVICE (L1 TASKS 2320-D-128-601 T7 COLM A)	Closed	Non-Taskworthy	No	Level 1	29 May 2013	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-0078DE81	CARRY OUT 6 MTHLY (L2 VMS TASKS 2320-D-128-601 T 7 COLM A;	Closed	Non-Taskworthy	No	Level 2	29 May 2013	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-0078DE8A	REPLACE SPARE WHEEL U/S (P.R.DRIVERS)	Closed	Non-Taskworthy	No	Level 1	29 May 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-0078DE8F	REPLACE BOTH DOOR MIRRORS U/S	Closed	Non-Taskworthy	No	Level 2	29 May 2013	N/A	Damage	TUL HS FFR SOFT TOP	
000000-0078DE94	ADJUST PARK BRAKE (LEVER POPS UP P.R.DRIVERS)	Closed	Non-Taskworthy	No	Level 2	29 May 2013	N/A	Failure	TUL HS FFR SOFT TOP	
000000-00795AE0	TORQUE WHEEL NUTS (230001)	Closed	Fully Fit	No	Level 1	19 Jun 2013	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-00478196	NEW BARRLES FOR DOORS	Closed	Fully Fit	No	Level 2	14 Sep 2009	N/A	Failure	TUL HS FFR SOFT TOP	
000000-006B3784	CARRY OUT 1 YEARLY SERVICE AS PER 601 TABLE 7 COL B	Closed	Fully Fit	No	Level 1	30 Jun 2011	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-006B3782	CARRY OUT 1 YEARLY VM TASKS AS PER 601 TABLE 7 COL B	Closed	Fully Fit	No	Level 2	30 Jun 2011	N/A	Servicing	TUL HS FFR SOFT TOP	
000000-005EF5B1	SOURCE ENGINE No AND UPDATE JAMES	Closed	Fully Fit	No	Level 1	07 Apr 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-006B0698	Insp Steering Drop Arm Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-00000312	22 Jun 2011	N/A	Inspection	TUL HS FFR SOFT TOP
000000-005EACCO	REPLACE PANHARD ROD	Closed	Non-Taskworthy	No	Level 2	24 Mar 2011	N/A	Failure	TUL HS FFR SOFT TOP	
000000-005EACBA	REPLACE No1 BALLJOINT	Closed	Non-Taskworthy	No	Level 2	24 Mar 2011	N/A	Failure	TUL HS FFR SOFT TOP	
000000-005D9BCC	CARRY OUT 6 MONTHLY L1 TASKS IAW AESP 2320-D-128-601 TBL 7 COL A	Closed	Fully Fit	No	Level 1	07 Feb 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-005D9160	CARRY OUT 12 MONTHLY L1 TASKS IAW AESP 2320-D-128-601 TBL 7 COL E	Closed	Fully Fit	No	Level 1	04 Feb 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-005D98D2	CARRY OUT 6 MONTHLY L2 TASKS IAW AESP 2320-D-128-601 TBL 7 COL A	Closed	Fully Fit	No	Level 2	07 Feb 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-005D9166	CARRY OUT 12 MONTHLY L2 TASKS IAW AESP 2320-D-128-601 TBL 7 COL E	Closed	Fully Fit	No	Level 2	04 Feb 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-005D5793	CARRY OUT 6 MONTHLY L2 TASKS IAW AESP 2320-D-128-601 TBL 7 COL A	Closed	Non-Taskworthy	No	Level 2	25 Jan 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-005D578A	CARRY OUT 6 MONTHLY L1 TASKS IAW AESP 2320-D-128-601 TBL 7 COL A	Closed	Non-Taskworthy	No	Level 1	25 Jan 2011	N/A	Inspection	TUL HS FFR SOFT TOP	
000000-004E90FC	000000-002AD89B RE-CONNECT EARTH STRAP ON PASS DOOR	Closed	Fully Fit	No	Level 1	23 Mar 2010			TUL HS FFR SOFT TOP	
000000-0053A6D3	000000-002BD950 CARRY OUT 6 MONTHLY L2 TASKS IAW AESP 2320-D-128-601 TABLE 7 COL A	Closed	Fully Fit	No	Level 2	22 Jul 2010			TUL HS FFR SOFT TOP	
000000-0053A6D0	000000-002BD950 CARRY OUT 6 MONTHLY L1 TASKS IAW AESP 2320-D-128-601 TABLE 7 COL A	Closed	Fully Fit	No	Level 1	22 Jul 2010			TUL HS FFR SOFT TOP	
000000-0053A6D6	000000-002BD950 CARRY OUT 6534 INSPECTION	Closed	Fully Fit	No	Level 2	22 Jul 2010			TUL HS FFR SOFT TOP	
000000-004E90F8	000000-002AD89B REPLACE FRONT RIGHT TYRE	Closed	Fully Fit	No	Level 1	23 Mar 2010			TUL HS FFR SOFT TOP	
000000-004E90FA	000000-002AD89B STAMP VRN ON JACK	Closed	Fully Fit	No	Level 1	23 Mar 2010			TUL HS FFR SOFT TOP	
000000-004E9993	REPLACE STEERING DAMPER BUSH	Closed	Non-Taskworthy	No	Level 2	24 Mar 2010			TUL HS FFR SOFT TOP	
000000-004E4A4F	000000-002AC249 CARRY OUT TABLE 7 SER 52 DRAIN AND REPLEN BRAKE FLUID.	Closed	Non-Taskworthy	No	Level 2	17 Mar 2010			TUL HS FFR SOFT TOP	
000000-004E4A56	000000-002AC249 CARRY OUT TABLE 5 SER 18 & 4	Closed	Non-Taskworthy	No	Level 2	17 Mar 2010			TUL HS FFR SOFT TOP	
000000-004E4A47	000000-002AC249 CARRY OUT 2 YRLY VM IAW AESP 2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 1	17 Mar 2010			TUL HS FFR SOFT TOP	
000000-004E4A42	000000-002AC249 CARRY OUT 2 YRLY SERVICE IAW AESP 2320-D-128-601 TABLE 7 COL C	Closed	Non-Taskworthy	No	Level 1	17 Mar 2010			TUL HS FFR SOFT TOP	
000000-004D559E	DEMAND AND FIT NEW REAR WINDOW	Closed	Fully Fit	No	Level 2	24 Feb 2010			TUL HS FFR SOFT TOP	
000000-0046F986	000000-00297815 RENEW PASSENGER DOOR STAY BAR BKT	Closed	Fully Fit	No	Level 2	26 Aug 2009			TUL HS FFR SOFT TOP	
000000-0046F15A	000000-00295E2D PLEASE CARRY OUT 6 MONTHLY SERVICE	Closed	Non-Taskworthy	No	Level 1	25 Aug 2009			TUL HS FFR SOFT TOP	
000000-0046F15D	000000-00295E2D PLEASE CARRY OUT 6 MONTHLY VM TASKS	Closed	Fully Fit	No	Level 2	25 Aug 2009			TUL HS FFR SOFT TOP	
000000-0046F15E	000000-00295E2D PLEASE CARRY OUT 6534 INSPECTION	Closed	Non-Taskworthy	No	Level 1	25 Aug 2009			TUL HS FFR SOFT TOP	
000000-00425985	000000-0028E204 CARRY OUT 6 MNTLY VM TASKS	Closed	Non-Taskworthy	No	Level 2	21 May 2009			TUL HS FFR SOFT TOP	
000000-00425983	000000-0028E204 CARRY OUT 6 MNTLY SERVICE	Closed	Non-Taskworthy	No	Level 1	21 May 2009			TUL HS FFR SOFT TOP	
000000-0031CA79	PASSENGER DOOR LOCK INOP	Closed	Fully Fit	No	Level 2	17 Nov 2008			TUL HS FFR SOFT TOP	
000000-0031CAA9	DRIVER DOOR STAY STRAP SNAPPED	Closed	Fully Fit	No	Level 2	17 Nov 2008			TUL HS FFR SOFT TOP	
000000-0022DF95	BONNET BUMP STOP MISSING ON DMD	Closed	Fully Fit	No	Level 1	30 Jul 2008			TUL HS FFR SOFT TOP	
000000-0022DFA7	DVR + PASSENGER SEAT MOULDINGS AT REAR MISSING ON DMD	Closed	Fully Fit	No	Level 1	30 Jul 2008			TUL HS FFR SOFT TOP	
000000-0031CA75	DRIVER SEAT BELT MOD DIFFY	Closed	Non-Taskworthy	No	Level 2	17 Nov 2008			TUL HS FFR SOFT TOP	
000000-00319B51	000000-00284B5F REQ 1 YEARLY SERVICE	Closed	Fully Fit	No	Level 1	17 Nov 2008			TUL HS FFR SOFT TOP	
000000-00319B53	000000-00284B5F REQ 1 YEARLY VM TASKS	Closed	Fully Fit	No	Level 1	17 Nov 2008			TUL HS FFR SOFT TOP	
000000-00319B65	000000-00284B5F REQUIRE 6534 INSPECTION	Closed	Fully Fit	No	Level 2	17 Nov 2008			TUL HS FFR SOFT TOP	

000:00

000:00

000:00

000000-00319C90		REQUIRE 5 YEARLY SERVICE	Closed	Fully Fit	No	Level 2	17 Nov 2008	TUL HS FFR SOFT TOP
000000-0031CA80		EARTH STRAP REQ FITTING PASSENGER DOOR	Closed	Fully Fit	No	Level 2	17 Nov 2008	TUL HS FFR SOFT TOP
000000-00215692	000000-0027E809	REQUIRE 6 MONTHLY SERV	Closed	Fully Fit	No	Level 1	18 Jul 2008	TUL HS FFR SOFT TOP
000000-00215693	000000-0027E809	REQUIRE 6 MONTHLY VM TASKS	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUL HS FFR SOFT TOP
000000-00215698	000000-0027E809	REQUIRE 6534	Closed	Fully Fit	No	Level 2	18 Jul 2008	TUL HS FFR SOFT TOP
000000-00208498	000000-0027E32D	STENCIL TPG ON WHEEL STATIONS	Closed	Fully Fit	No	Level 1	14 Jul 2008	TUL HS FFR SOFT TOP
000000-002084A6	000000-0027E32D	CONVOY LIGHT INOP	Closed	Fully Fit	No	Level 1	14 Jul 2008	TUL HS FFR SOFT TOP
000000-002084E1	000000-0027E32D	DMD BACK PLATE DRIVER DOOR WINDOW	Closed	Fully Fit	No	Level 1	14 Jul 2008	TUL HS FFR SOFT TOP
000000-002084F9	000000-0027E32D	BONNET RELEASE CATCH DOES NOT SECURE	Closed	Fully Fit	No	Level 1	14 Jul 2008	TUL HS FFR SOFT TOP
000000-00096DF8	000000-00274215	REPLACE NS LOWER DOOR ASSY	Closed	Non-Taskworthy	No	Level 2	24 Oct 2007	TUL HS FFR SOFT TOP
000000-00034ABC	000000-0027416B	RENEW NO1 BALL JOINT	Closed	Limited Role	No	Level 2	23 Oct 2006	TUL HS FFR SOFT TOP
000000-00034ABD	000000-0027416B	ADJUST REAR LEFT WHEEL BEARING	Closed	Limited Role	No	Level 2	23 Oct 2006	TUL HS FFR SOFT TOP
000000-00034ABE	000000-0027416B	FIT AIR INTAKE MOD	Closed	Limited Role	No	Level 2	23 Oct 2006	TUL HS FFR SOFT TOP
000000-00034ABF	000000-0027416B	OBSERVE OIL SEEPAGE @ ENGINE SUMP	Closed	Limited Role	No	Level 2	23 Oct 2006	TUL HS FFR SOFT TOP
000000-00034AC0	000000-0027416B	FIT JUBILEE CLIP TO ROCKER COVER BREATHER PIPE TOP UNION	Closed	Limited Role	No	Level 2	23 Oct 2006	TUL HS FFR SOFT TOP
000000-00076953	000000-002741DB	UNDER BONNET HARNESS ROUTING	Closed	Non-Taskworthy	No	Level 2	02 Jul 2007	TUL HS FFR SOFT TOP
000000-0007695D	000000-002741DB	FUEL LEAKING FROM FEED PIPES	Closed	Non-Taskworthy	No	Level 2	02 Jul 2007	TUL HS FFR SOFT TOP
000000-0007695A	000000-002741DB	FUEL LEAKING FROM FUEL TANK STUB PIPE/BREATHER HOSE	Closed	Non-Taskworthy	No	Level 2	02 Jul 2007	TUL HS FFR SOFT TOP
000000-0002C4EB		Initial Usage	Closed	Fully Fit	No	Level 1	08 Sep 2006	TUL HS FFR SOFT TOP
000000-0002C4F6		Initial Maintenance	Closed	Fully Fit	No	Level 1	08 Sep 2006	TUL HS FFR SOFT TOP

Work Objects

Serial Number: LS22AA
 NSN: 2320998939936

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-002F76BF		No	MEI (2)	05 Jul 2018	Level 2			000:00		
000000-0058FD36		No	MEI (2)	05 Jul 2018	Level 2			000:00		
000000-00701DF9		No	MEI (2)	05 Jul 2018	Level 2	Non-Taskworthy	CL	000:00		
000000-004757E4		No	MEI (2)	05 Jul 2018	Level 2			000:00		
000000-0083C008		No	6 Monthly 6534 Insp	08 Jun 2018	Level 1	Fully Fit	CL	000:00		
000000-0024CF03		No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00		
000000-008D81BF		No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00		
000000-00643056		No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00		
000000-0024CF02		No	MEI (2)	05 Jul 2018	Level 2			000:00		
000000-00706372		No	6 Monthly 6534 Insp	08 Jun 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0007638E		No	MEI (2)	05 Jul 2018	Level 2		CL	000:00		
000000-00090E57		No	MEI (2)	05 Jul 2018	Level 2		CL	000:00		
000000-000EFDDC		No	MEI (2)	05 Jul 2018	Level 2		CL	000:00		
000000-00047B12		No	MEI (2)	05 Jul 2018	Level 2		CL	000:00		
000000-0050A289		No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00		

000000-00152C97	No	MEI (2)	05 Jul 2018	Level 2			000:00
000000-004757E5	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00
000000-0058FD37	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00
000000-0016434C	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00
000000-002F76C0	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00
000000-00297AAC	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00
000000-0083BFE7	No	MEI (2)	05 Jul 2018	Level 2	Fully Fit	CL	000:00
000000-007BE5CB	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00
000000-003BE9DE	No	6 Monthly 6534 Insp	08 Jun 2018	Level 1			000:00

Work Objects

Serial Number: LS22AA
 NSN: 2320998939936

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/in Service Classification	Modification Type	Apply When Usage Equals	Embodiment by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0069413F	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-0060FED0	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-000128C9	00024	Fitting of Trailer Breakaway Attachment Plate		No	-/	UTI				Fully Fit	CL				
000000-000152BA	00017	Introduction of Battery Retention		No	1/A	UTI				Fully Fit	CL				
000000-00012F97	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL				
000000-0000DB52	00037	Fitting Glow Plug Timer Interface Harness		No	-/	UTI				Fully Fit	CL				
000000-0001A344	00030	Front Belt Protection Sleeves		No	1/A	UTI				Fully Fit	CL				
000000-000140F8	00027	Input/Output Porthole for Communication Cables, Cover Modification		No	-/	UTI				Fully Fit	CL				
000000-00018E74	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Fully Fit	CL				
000000-00019BA8	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants		No	-/-	UTI				Fully Fit	CL				
000000-000190D2	00014	Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit	CL				
000000-0001AAA5	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit	CL				
000000-00021684	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit	CL				
000000-0000A332	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL				
000000-00018D99	00007	TJAAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL				
000000-0002147E	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL				
000000-0000A9A2	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL				
000000-0000BFD7	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Fully Fit	CL				

Work Objects

Serial Number: LS22AA
 NSN: 2320998939936

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-0083BFE8		No	Yearly/20000 Kms	05 Jul 2018	Level 1	Fully Fit	CL	000:00		
000000-00706386		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-001443CC		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-00475801		No	2 Yearly/40000 Kms	06 Sep 2018	Level 1			000:00		
000000-00706385		No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00		
000000-006EA5AE		No	2 Yearly/40000 Kms	06 Sep 2018	Level 1	Fully Fit	CL	000:00		
000000-007D36C2		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1	Non-Taskworthy	CL	000:00		
000000-0083C010		No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	04 Jul 2022	Level 1	Fully Fit	CL	000:00		
000000-00475804		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	07 Sep 2018	Level 1			000:00		
000000-0024CED3		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-0016D69B		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-0083C00E		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	04 Jul 2022	Level 2	Fully Fit	CL	000:00		
000000-003BEA07		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-0058FCFA		No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00		
000000-0024CED0		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	04 Jul 2022	Level 2			000:00		
000000-008CFD63		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1	Fully Fit	CL	000:00		
000000-00475802		No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00		
000000-0031481F		No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00		
000000-0024CED2		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	07 Sep 2018	Level 1			000:00		
000000-0024CECE		No	2 Yearly/40000 Kms	06 Sep 2018	Level 1			000:00		
000000-00117495		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-001443CB		No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00		
000000-00475803		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	07 Sep 2018	Level 1			000:00		
000000-0058FCFB		No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00		
000000-000906BD		No	2 Yearly/40000 Kms	06 Sep 2018	Level 1		CL	000:00		
000000-00090F63		No	Yearly/20000 Kms	05 Jul 2018	Level 1		CL	000:00		

000000-00090F64	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-00090F65	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-00090F66	No	6 Yearly/120000 Kms (2)		Level 2		CL	000:00
000000-00090F67	No	2 Yearly/40000 Kms	06 Sep 2018	Level 1		CL	000:00
000000-000BE1CC	No	First 1600 Kms (AR)		Level 2		CL	000:00
000000-00090F68	No	Weekly (AR)(1)		Level 1		CL	000:00
000000-0009EEEE	No	Yearly/20000 Kms	05 Jul 2018	Level 1		CL	000:00
000000-000F6686	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-000A2A2C	No	Yearly/20000 Kms	05 Jul 2018	Level 1		CL	000:00
000000-000A2A2D	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-000A88B6	No	Yearly/20000 Kms	05 Jul 2018	Level 1		CL	000:00
000000-000A8CF4	No	5 Yearly/100000 Kms (1)		Level 1		CL	000:00
000000-000A82CE	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-000ABD91	No	Weekly (AR)(1)		Level 1		CL	000:00
000000-0000C987	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-000E0A5A	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-0001FD9D	No	Yearly/20000 Kms	05 Jul 2018	Level 1		CL	000:00
000000-000BA6DA	No	2 Yearly/40000 Kms	06 Sep 2018	Level 1		CL	000:00
000000-00044806	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-00044807	No	Yearly/20000 Kms	05 Jul 2018	Level 1		CL	000:00
000000-0005D512	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1		CL	000:00
000000-0064307F	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1	Non-Taskworthy	CL	000:00
000000-0024CED1	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	07 Sep 2018	Level 1			000:00
000000-0016D69A	No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00
000000-0024CEE8	No	Yearly/20000 Kms	05 Jul 2018	Level 1			000:00
000000-007043EA	No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)	07 Sep 2018	Level 1	Fully Fit	CL	000:00
000000-0024CECF	No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)	24 Oct 2018	Level 2			000:00
000000-0024CEE9	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	04 Jul 2022	Level 1			000:00
000000-0096561B	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1	Non-Taskworthy	CL	000:00
000000-0083C00F	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1	Fully Fit	CL	000:00
000000-0050A2A8	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00
000000-00297AEF	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00
000000-00475805	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00
000000-00704404	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	07 Sep 2018	Level 1	Fully Fit	CL	000:00
000000-00314820	No	6 Monthly/10000 Kms	07 Nov 2018	Level 1			000:00