



Ministry  
of Defence

Defence Equipment and Support  
Secretariat  
#2043 Maple 0a  
Ministry of Defence  
Abbey Wood  
Bristol BS34 8JH



Email: DES SEC-PoISec LE-JSC-WPNS@mod.uk

---

[REDACTED]

email: [REDACTED]  
[REDACTED]

Our Reference:  
FOI2021/07163

Date:  
7 July 2021

---

Dear [REDACTED],

I am writing about your email of 5 July 2021, requesting the following information:

*I have an ex mod land rover defender 90 wolf hard top, chassis number SALLDAA68WA149551 (in service number LU80AA) and am requesting under the freedom of information act any history for the vehicle and any service records that may be available.*

I am treating your correspondence as a request for information under the Freedom of Information Act 2000 (FOIA).

A search for the information has now been completed within the Ministry of Defence (MOD), and I can confirm that information in scope of your request is held. This is attached, as follows:

Annex A - Ownership History  
Annex B - Fault History (redacted)  
Annex C - Inspection History  
Annex D - Modification History  
Annex E - Service History

It has proved necessary to withhold information related to your request. This is commercially sensitive information in the Fault History (Annex B), relating to contractor repair times, and has been withheld under qualified exemption Section 43(2) (Commercial Interests).

Section 43 concerns information which if disclosed would or would likely prejudice the commercial interests of any person (including defence contractors and the public authority holding it).

As the exemption is qualified, it was necessary to undertake a Public Interest Test to determine whether the balance for withholding the information outweighs that for disclosure. General arguments in favour of release were that full disclosure would demonstrate the MOD's commitment to openness and transparency; and make the UK Government more accountable to the electorate. The FOI Act also contains a presumption for release. However, reporting the time taken by MOD contractors to rectify fault reports could be used, along with already published contractor information, to reveal market sensitive information, such as hourly labour rates, that would likely allow the company's competitors to exploit when bidding for similar work.

Defence Equipment & Support

Given the arguments described above, on balance, it was determined that the information should be withheld under Section 43(2) (Commercial Interests). The level of prejudice against release of this exempted information has been set at the higher level of "would" rather than "would be likely to".

If you have any queries regarding the content of this letter, please contact this office in the first instance. If you wish to complain about the handling of your request, or the content of this response, you can request an independent internal review by contacting the Information Rights Compliance team, Ground Floor, MOD Main Building, Whitehall, SW1A 2HB (e-mail [CIO-FOI-IR@mod.gov.uk](mailto:CIO-FOI-IR@mod.gov.uk)). Please note that any request for an internal review should be made within 40 working days of the date of this response.

If you remain dissatisfied following an internal review, you may raise your complaint directly to the Information Commissioner under the provisions of Section 50 of the Freedom of Information Act. Please note that the Information Commissioner will not normally investigate your case until the MOD internal review process has been completed. The Information Commissioner can be contacted at: Information Commissioner's Office, Wycliffe House, Water Lane, Wilmslow, Cheshire, SK9 5AF. Further details of the role and powers of the Information Commissioner can be found on the Commissioner's website at <https://ico.org.uk/>.

Yours sincerely,

DE&S Policy Secretariat Asst Hd

**VEHICLE DETAILS**

ERM	NATO Stock Number	Asset Code	Contract Number	Description	Colour
(a)	(b)	(c)	(d)	(e)	(f)
LU80AA	2320998939965	NB42258100	LV2A/088DUM	TRUCK UTY LIGHT (TUL HS) 4X4 GS FFR HARD TOP LHD LANDROVER 2.5LTR TD (WITH EEGR)	Army/NATO Green IRR

Date In Service	Chassis Number	Engine No.	Cast	Cast Date
(g)	(h)	(i)	(j)	(k)
28/07/1998	SALLDAA68WA149551	25L06588B		

**VEHICLE HISTORY**

ERM	Key No.	RIV Date	UIN	Unit Title	RIV No.	RCP No.	RCP Date	Batch
(a)	(b)	(c)	(d)	(e)	(f)	(g)	(h)	(i)
LU80AA	3		CA005A	JSCS ASHCHURCH		37089AA	28/07/1998	
LU80AA	4	20/10/1998	A1095A	7 TLR RLC	43309A	555	16/01/1999	
LU80AA	4	07/01/2000	A9046A	UK CSS BN (CSAT)	20	2876	26/01/2000	A96
LU80AA	4	31/03/2000	A1095A	7 TLR RLC	1096	305	05/05/2000	B12
LU80AA	4	22/03/2004	A9108A	QM DEPT UK LOG BN	80	4588	09/05/2004	U89
LU80AA	2	23/04/2005	A1095A	7 TLR RLC	214	1769	03/06/2005	W17
LU80AA		23/04/2013		7 REGT RLC 9 SQN			24/04/2013	
LU80AA		22/10/2013		7 REGT RLC			22/10/2013	
LU80AA		13/03/2019		EQUIPMENT POOL			13/03/2019	

Work Objects

Serial Number: LU80AA  
 NSN: 232098939965

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Number	Fault Group ID	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-00B20C56		SNVE 377 - SWIVEL HOUSING	Closed	Non-Taskworthy	No	Level 1	000000-0000697A		29 Mar 2019	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00B237C2		SNVE377 - SWIVEL HOUSING	Closed	Fully Fit	No	Level 1	000000-0000697B		29 Mar 2019	N/A	Inspection	TUL HS FFR HARD TOP			000:00
000000-00B129F8		CAST	Closed	Non-Taskworthy	No	Level 4			25 Feb 2019	N/A	CAST	TUL HS FFR HARD TOP			
000000-00AF9318		passenger door won't lock	Closed	Fully Fit	No	Level 2			27 Nov 2018	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0099EBCA		JAMES MOD REGISTER NO UP TO DATE	Closed	Fully Fit	No	Level 2			13 Jun 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0099EBD2		REPLACE BLACKOUT BLIND	Closed	Fully Fit	No	Level 1			13 Jun 2016	N/A	Inspection	TUL HS FFR HARD TOP	9 SQUADRON		000:00
000000-00AAB985		Oil Leak at oil filter housing	Closed	Fully Fit	No	Level 2			26 Apr 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-009AE710		REPLACE REAR DOOR CARD AND HANDLE	Closed	Fully Fit	No	Level 1			12 Jul 2016	N/A	Damage	TUL HS FFR HARD TOP			000:00
000000-00AB4C27		JACK NOT PRESENTED FOR MEI	Closed	Limited Role	No	Level 1			22 May 2018	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00AB4C26		FIRE EXTINGUISHERS NOT PRESENTED FOR MEI	Closed	Limited Role	No	Level 1			22 May 2018	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00AB4C33		CES DEFICIENCY SHEET NOT PRESENTED FOR MEI	Closed	Limited Role	No	Level 1			22 May 2018	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00A9CE80	000000-00332E5E	Renew Whl studs	Closed	Fully Fit	No	Level 2			12 Mar 2018	N/A	Failure	TUL HS FFR HARD TOP	7 REGT RLC LAD	95QNLADFITRSECT	000:00
000000-00A8D29D		WHEEL NUT INDICATORS	Closed	Non-Taskworthy	No	Level 1			30 Jan 2018	N/A	Modification	TUL HS FFR HARD TOP			000:00
000000-00A92ACA		clutch pedal goes straight to floor and fails to return	Closed	Non-Taskworthy	No	Level 2			13 Feb 2018	N/A	Failure	TUL HS FFR HARD TOP			000:00
000000-00A4341C		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch	Closed	Limited Role	No	Level 2	000000-00004559		31 Jul 2017	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00A18B7E		OIL LEAK AT OIL FILTER HOUSING	Closed	Fully Fit	No	Level 2			26 Apr 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A18B53		VEHICLE REQUIRES 2 NEW FRONT TYRES.	Closed	Fully Fit	No	Level 1			26 Apr 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A18B84		COOLANT LEAK AROUND TOP HOSE	Closed	Non-Taskworthy	No	Level 2			26 Apr 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00A18B75		DUE TU TO UNEVEN WEAR ON BOTH FRONT TYRES STEERING FAULT NEEDS INVESTIGATING	Closed	Non-Taskworthy	No	Level 2			26 Apr 2017	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009AFD56		REPLACE ENGINE	Closed	Non-Taskworthy	No	Level 2			14 Jul 2016	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A09358		AUX BELT TENSIONER DAMAGED	Closed	Non-Taskworthy	No	Level 2			07 Mar 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A0C6A8		WIPERS INOP	Closed	Non-Taskworthy	No	Level 2			15 Mar 2017	N/A	Failure	TUL HS FFR HARD TOP			
000000-00A0ECFF		REPLACE RIFLE HEAD PROTECTION CUSHION	Closed	Fully Fit	No	Level 1			21 Mar 2017	N/A	Damage	TUL HS FFR HARD TOP			
000000-009AF877		REPLACE PASSENGER WIPER BLADE	Closed	Fully Fit	No	Level 1			28 Jun 2016	N/A	Damage	TUL HS FFR HARD TOP			
000000-0099EBC8		N/S HEADLIGHT GUARD INSECURE	Closed	Fully Fit	No	Level 1			14 Jun 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009891F9		RIGHT HAND TOP MOUNT PERISHED	Closed	Limited Role	No	Level 2			19 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009891FC		COMMANDERS SEAT BELT PERISHED	Closed	Non-Taskworthy	No	Level 2			19 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009891F8		REPLACE FRONT LEFT TRACTA SEAL	Closed	Limited Role	No	Level 2			19 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009891F3		REPLACE NO2 BALL JOINT AND FIT CORRECT CASTELLATED NUT	Closed	Non-Taskworthy	No	Level 2			19 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009891FD		ADJUST HANDBRAKE	Closed	Fully Fit	No	Level 2			19 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-009891EA		INVEST OIL LEAK FROM FILTER	Closed	Fully Fit	No	Level 2			19 Apr 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00976C21		Oil / Coolant leak	Closed	Non-Taskworthy	No	Level 2			02 Mar 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0096C3B4		CARRY OUT 2 YEARLY L2 SERV	Closed	Non-Taskworthy	No	Level 2			09 Feb 2016	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0096003D		WEEKLY INSPECTION	Closed	Fully Fit	No	Level 1			18 Jan 2016	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0095F10B		Check No2 ball joint torque tightness as per safety notice LE SNVE 0006:	Closed	Non-Taskworthy	No	Level 2	000000-000031CF		14 Jan 2016	N/A	Closed No Action	TUL HS FFR HARD TOP	9 SQUADRON		
000000-008E5691		WEEKLY	Closed	Fully Fit	No	Level 1			14 Dec 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-008E2F23		NO BIRTH CERTIFICATE FOR JACK, NEEDS INSPECTED	Closed	Limited Role	No	Level 2			07 Dec 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0087A982		MISSING COVER @ ENGINE IDLE	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007CBEDA		FIT MOD 38	Closed	Fully Fit	No	Level 2			14 Nov 2013	N/A	Modification	TUL HS FFR HARD TOP			000:00
000000-008C5E8C		clutch	Closed	Non-Taskworthy	No	Level 1			25 Sep 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0087A98D		LIGHT SWITCH MISSING SCREW	Closed	Fully Fit	No	Level 1			03 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0085A177		SPARE TYRE (LOW TREAD DEPTH)	Closed	Fully Fit	No	Level 1			02 Dec 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A963		FIT BLACKOUT BLIND CORRECTLY	Closed	Fully Fit	No	Level 1			03 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0087A95F		FIT MISSING FOAM PAD @ WEAPON RACK	Closed	Fully Fit	No	Level 1			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A95E		REPLACE SPARE TYRE UNEVEN WEAR	Closed	Non-Taskworthy	No	Level 1			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A97B		INV VEHICLE PULLS TO RIGHT	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A95C		MISSING WASHER @ ROCKER COVER	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A973		REPLACE FRONT R/H TYRE (TYRE CHANGED JOB FULLY FIT, CLOSE DOWN ONCE SPARES RECD	Closed	Fully Fit	No	Level 1			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A9B1		ALL NON-TASKWORTHY JOBS TO BE COMPLETED WITHIN 28 DAYS- A MEMBER OF INSPECTIONS CELL TO REMOVE JOI	Closed	Non-Taskworthy	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81DF		OIL SEEPAGE AT R/H/S ENGINE (MEI 10/02/14)	Closed	Fully Fit	No	Level 2			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81E2		OIL SEEPAGE AT UNDERSIDE T.BOX (MEI 10/02/14)	Closed	Fully Fit	No	Level 2			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A968		PSGR DOOR DOES NOT LOCK	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A991		SMALL HOLE IN REAR OF EXHAUST	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A977		FAILED RBT ON PARKING BRAKE(ALL NON TASKWORTHY JOBS TO BE COMPLETED WITH 28 DAYS	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087A95A		OIL SEEPAGE @ ROCKER COVER	Closed	Fully Fit	No	Level 2			03 Mar 2015	N/A	Inspection	TUL HS FFR HARD TOP			
000000-0087CFDF		DMD 2 X TRYES FOLLOWING RECENT ME	Closed	Non-Taskworthy	No	Level 1			09 Mar 2015	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-007E81CC		SECURE STEERING COLUMN SURROUND (MEI 10/02/14)	Closed	Fully Fit	No	Level 2			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81C0		INVESTIGATE DASHBOARD WARNING LAMPS INOP (MEI 10/02/14)	Closed	Fully Fit	No	Level 2			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81BA		INDICATOR SELF RETURNS EARLY (MEI 10/02/14)	Closed	Fully Fit	No	Level 2			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81CF		SECURE RADIATOR GRILL (MEI 10/02/14)	Closed	Fully Fit	No	Level 2			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81D4		SECURE N/S HEADLAMP GUARD (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00837F53		INSPECT & CLASSIFY SPARE TYRE	Closed	Limited Role	No	Level 2			16 Sep 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-00808F12		DMD AND FIT FOAM PADDING FOR RIFFLE RACK 5340-99-883-5938 A/152/0:	Closed	Fully Fit	No	Level 1			08 May 2014	N/A	Failure	TUL HS FFR HARD TOP			
000000-008442EF		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58		09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP			
000000-008491B7		SECURE FRONT GRILL	Closed	Fully Fit	No	Level 1			21 Oct 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-00828CB5		REPLACE FRONT LAMP GUARD	Closed	Fully Fit	No	Level 1			29 Jul 2014	N/A	Damage	TUL HS FFR HARD TOP			
000000-007E820D		VEH CES INCOMPLETE (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E8208		SECURE REAR DOOR BLACKOUT BLIND (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E8204		RENEW S80 MOUNT CUSHIONING (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00823B91		SECURE CENTRAL COLUM	Closed	Fully Fit	No	Level 1			16 Jul 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E820C		FIT FFR BATTERY COVER (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81FE		RENEW O/S/R FFR COVER (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81FB		SECURE N/S/R FFR ANTENNA MOUNT (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81F8		SECURE N/S/F FFR ANTENNA MOUNT (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81EF		REMOVE GERMAN INSP STICKER (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			10 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81D7		SECURE N/S MIRROR ARM (10/02/14)	Closed	Fully Fit	No	Level 1			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00751C27		RENEW COVERS ON REAR OF WING MIRRORS	Closed	Fully Fit	No	Level 1			20 Nov 2012	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00828C92	000000-002FA7F6	REPLACE FRONT LAMP GUARD	Closed	Fully Fit	No	Level 1			29 Jul 2014	N/A	Closed No Action	TUL HS FFR HARD TOP			
000000-0080CE3B		dmd and fit seat reclining handle nsn 5340-99-771-331C	Closed	Fully Fit	No	Level 1			19 May 2014	N/A	Inspection	TUL HS FFR HARD TOP			
000000-007E81C4		MAP LIGHT INOP (MEI 10/02/14)	Closed	Fully Fit	No	Level 1			11 Feb 2014	N/A	Inspection	TUL HS FFR HARD TOP	</		





000000-00084954	000000-00271EBD	Clean vehicle complete
000000-00058E91	000000-0026F6CF	passenger wiper blade
000000-00092166	000000-00273408	PLEASE CARRY OUT 6M VM TASKS
000000-00092165	000000-00273408	PLEASE CARRY OUT 6M SERV
000000-00067848	000000-0026F6CC	rect vehicle failed emission test (m.e.i.)
000000-00067850	000000-0026F6CC	Rect oil leak at steering box (m.e.i.)
000000-00067853	000000-0026F6CC	Adjust headlights (m.e.i.)
000000-00067869	000000-0026F6CC	Fit correct bolts to front propshaft (m.e.i.)
000000-0006786F	000000-0026F6CC	Change steering u/j bolts as pre signal (m.e.i.)
000000-00067874	000000-0026F6CC	Rect oil leak at front diff. (m.e.i.)
000000-00067879	000000-0026F6CC	Rect oil leak at oil filter housing (m.e.i.)
000000-0006787B	000000-0026F6CC	Rect oil leak at t-box (m.e.i.)
000000-00067880	000000-0026F6CC	Renew drivers seat belt (m.e.i.)
000000-00068005		RENEW CHASSIS
000000-000654A2	000000-0026E242	CARRY OUT ANNUAL MEI
000000-000654A1	000000-0026E23C	CARRY OUT 1 YRLY VM TASKS
000000-0006549B	000000-0026E23C	CARRY OUT 1 YRLY SERVICE
000000-00033599		bent chassis
000000-00058E92		spare tyre unservicable
000000-0002637B		ADJUST TRACKING
000000-00002A66		FRONT NUMBER PLATE DAMAGED
000000-00002A68	000000-0026AA02	BRAKE LIGHTS INOP (FUSE HAS BEEN REPLACED)

Closed	Fully Fit	No	Level 1	28 Aug 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 1	20 Mar 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	10 Oct 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 1	10 Oct 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	08 May 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 3	09 May 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	27 Apr 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	27 Apr 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 1	27 Apr 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 3	17 Oct 2006	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 1	20 Mar 2007	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	19 Jul 2006	TUL HS FFR HARD TOP
Closed	Fully Fit	No	Level 2	11 Nov 2005	TUL HS FFR HARD TOP
Closed	Non-Taskworthy	No	Level 2	11 Nov 2005	TUL HS FFR HARD TOP

Work Objects

Serial Number: LU80AA  
 NSN: 2320998939965

Criteria:

Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate Work	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-00A449F7		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-0059BF8C		No	6 Monthly 6534 Insp		Level 1	Non-Taskworthy	WiP	000:00		
000000-006D3B3C		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-0089726A		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-006D3A23		No	First Parade Insp (AR)(1)		Level 1	Non-Taskworthy	CL	000:00		
000000-006C6262		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-006B4CD6		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-0022FEC1		No	6 Monthly 6534 Insp		Level 1		CW	000:00		
000000-004EBB4E		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		
000000-00163251		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-00990DAE		No	MEI (2)		Level 2	Fully Fit	CL	000:00		
000000-006B6788		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-006C6274		No	First Parade Insp (AR)(1)		Level 1	Fully Fit	CL	000:00		
000000-0089726B		No	First Parade Insp (AR)(1)		Level 1			000:00		
000000-00163205		No	6 Monthly 6534 Insp		Level 1			000:00		
000000-0033E0CF		No	MEI (2)		Level 2	Non-Taskworthy	CL	000:00		



000000-000777C0	No	MEI (2)	Level 2		CL	000:00
000000-000E38E4	No	MEI (2)	Level 2		CL	000:00
000000-00004308	No	MEI (2)	Level 2		CL	000:00
000000-0008943F	No	MEI (2)	Level 2		CL	000:00
000000-0008B199	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-0008F4C3	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-000C510E	No	MEI (2)	Level 2		CL	000:00
000000-000990D9	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-000986FA	No	MEI (2)	Level 2		CL	000:00
000000-00099943	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-000C57E1	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-0009C0AA	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-000AA5A0	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-0000EA2E	No	MEI (2)	Level 2		CL	000:00
000000-000E8ADD	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-000FB2EA	No	MEI (2)	Level 2		CL	000:00
000000-000DACD1	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-000CB152	No	MEI (2)	Level 2		CL	000:00
000000-000CBC4C	No	First Parade Insp (AR)(1)	Level 1		CL	000:00
000000-006500A0	No	6 Monthly 6534 Insp	Level 1			000:00
000000-0059BF98	No	First Parade Insp (AR)(1)	Level 1	Non-Taskworthy	WiP	000:00
000000-0099544F	No	6 Monthly 6534 Insp	Level 1			000:00
000000-0044892E	No	6 Monthly 6534 Insp	Level 1			000:00
000000-007E50A7	No	6 Monthly 6534 Insp	Level 1	Fully Fit	CL	000:00
000000-0097BEFF	No	MEI (2)	Level 2			000:00
000000-0027DE74	No	6 Monthly 6534 Insp	Level 1	Non-Taskworthy	CL	000:00
000000-006C6254	No	First Parade Insp (AR)(1)	Level 1	Fully Fit	CL	000:00
000000-0010B074	No	MEI (2)	Level 2		CW	000:00
000000-006C142C	No	First Parade Insp (AR)(1)	Level 1	Fully Fit	CL	000:00
000000-004EBB5B	No	6 Monthly 6534 Insp	Level 1			000:00
000000-007E4050	No	MEI (2)	Level 2	Fully Fit	CL	000:00
000000-0033E0BB	No	6 Monthly 6534 Insp	Level 1	Non-Taskworthy	CL	000:00

Work Objects

Serial Number: LU80AA  
 NSN: 2320998939965

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embody by Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-006F52A4	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F70DA	00030	Front Belt Protection Sleeves		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F7BEC	00035	Fitting of Emergency Hammer		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-006F4EAA	00017	Introduction of Battery Retention		No	1/A	UTI				Non-Taskworthy	CL	Level 2			000:00
000000-0068E0F5	00046	FITTING OF WHEEL NUT INDICATORS TO LAND ROVER HS PLATFORMS		No	1/A	Mod				Non-Taskworthy	CL	Level 2			000:00
000000-00629C5B	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL	Level 2			
000000-0000B475	00008	Input / Output Porthole for Comms / Power Cable Installation		No	-/	RTI				Fully Fit	CL				
000000-0000CF9E	00016	Radio Battery Isolation Switch and Power Import / Export System		No	-/	RTI				Fully Fit	CL				
000000-000221F1	00001	Radio Rack Fixings		No	-/	RTI				Fully Fit	CL				
000000-0000C120	00012	Fitting Radio Frequency Radiated Hazard (RADHAZ) Protection Kit		No	1/A	RTI				Fully Fit	CL				
000000-0000AE8F	00007	TUAAM Earth Bonding Improvements		No	-/	RTI				Fully Fit	CL				
000000-0001699D	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit	CL				
000000-000154B9	00003	Heli-lift Vehicle Modification (Hard Top Only)		No	-/	RTI				Fully Fit	CL				
000000-0001ECB7	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/	RTI				Fully Fit	CL				

Work Objects

Serial Number: LU80AA  
 NSN: 2320998939965

Criteria:  
 Repair Level: ALL  
 Work Object Status: Closed  
 Mission Impact: ALL  
 Fault State: ALL  
 Escalate Work: ALL  
 Work Request ID:  
 Assigned Work Status: ALL  
 Working Organisation:  
 Repair Section:

Maintenance Event ID	Work Request ID	Escalate	Maintenance Event Name	Next Due Date	Repair Level	Fault State	Work Status	Estimated Repair Time	Working Organisation	Repair Section
000000-001A3C6B		No	2 Yearly/40000 Kms		Level 1			000:00		
000000-00312B2C		No	2 Yearly/40000 Kms		Level 1	Fully Fit	CL	000:00		
000000-0022B833		No	OOPS 6 Yearly/120000 Kms Camshaft Timing Belt (2)		Level 2			000:00		
000000-0057C632		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-00533EEE		No	Weekly (AR)(1)		Level 1			000:00		
000000-00118269		No	Weekly (AR)(1)		Level 1			000:00		
000000-005FF47F		No	Weekly (AR)(1)		Level 1			000:00		
000000-0027DE61		No	6 Monthly/10000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-0056EC67		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-0022CE21		No	Yearly/20000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-00312B2A		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		Level 1	Fully Fit	CL	000:00		
000000-0022FEA5		No	6 Monthly/10000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-004D69A3		No	6 Monthly/10000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-005C02F3		No	Weekly (AR)(1)		Level 1			000:00		
000000-00636326		No	2 Yearly/40000 Kms		Level 1	Non-Taskworthy	CL	000:00		
000000-0056EC3B		No	Weekly (AR)(1)		Level 1			000:00		
000000-006110BF		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-005D4E28		No	Weekly (AR)(1)		Level 1			000:00		
000000-00536C30		No	Weekly (AR)(1)		Level 1			000:00		
000000-005255B4		No	Weekly (AR)(1)		Level 1			000:00		
000000-005F4AC4		No	Weekly (AR)(1)		Level 1			000:00		
000000-005E9173		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-004E1121		No	Weekly (AR)(1)		Level 1			000:00		
000000-0022B830		No	OOPS 2 Yearly/40000 Kms Replace Air Cleaner Element (1)		Level 1			000:00		
000000-0022B834		No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)		Level 2			000:00		
000000-004D2E75		No	Weekly (AR)(1)		Level 1			000:00		
000000-00612F85		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-005EEC1D		No	Weekly (AR)(1)		Level 1	Limited Role	WiP	000:00		
000000-00312B2B		No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)		Level 1	Fully Fit	CL	000:00		
000000-001A3C6C		No	Yearly/20000 Kms		Level 1			000:00		
000000-00536D40		No	Weekly (AR)(1)		Level 1			000:00		
000000-005D6334		No	Weekly (AR)(1)		Level 1			000:00		

000000-00641E61	No	6 Monthly/10000 Kms	Level 1	Non-Taskworthy	CL	000:00
000000-00569436	No	Weekly (AR)(1)	Level 1	Limited Role	WiP	000:00
000000-00641E5E	No	Yearly/20000 Kms	Level 1	Non-Taskworthy	CL	000:00
000000-0052DCD3	No	OOPS 5 Yearly/155000 Kms Drain And Replen Gearbox Oil (2)	Level 2	Non-Taskworthy	CL	000:00
000000-000779A9	No	2 Yearly/40000 Kms	Level 1		CL	000:00
000000-000F3C3C	No	5 Yearly/100000 Kms (1)	Level 1		CL	000:00
000000-000EE03B	No	6 Yearly/120000 Kms (2)	Level 2		CL	000:00
000000-00076FB4	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-000FE751	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-000778C5	No	Equipment Check	Level 1		CL	000:00
000000-000778C6	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-00077794	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-000803E0	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000803DD	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-000803DE	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-000803DF	No	First 1600 Kms (AR)	Level 2		CL	000:00
000000-000346BF	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-000BDC6E	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-000E4AC7	No	First 1600 Kms (AR)	Level 2		CL	000:00
000000-00089196	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000500F2	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-0008B44F	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-00095521	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000D525C	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000FF792	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-000E5935	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-000972D0	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000B4D7A	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-0009ECF8	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-0009D3F3	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000778C4	No	Battery Test	Level 1		CL	000:00
000000-000F7803	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-00076E52	No	2 Yearly/40000 Kms	Level 1		CL	000:00
000000-00012172	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-00012170	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-00012171	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-000D8965	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-0001E10E	No	2 Yearly/40000 Kms	Level 1		CL	000:00
000000-0001E10F	No	5 Yearly/100000 Kms (1)	Level 1		CL	000:00
000000-0001E110	No	First 1600 Kms (AR)	Level 2		CL	000:00
000000-0001E111	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000FA2CE	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-00040C34	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-000FB7D3	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-00049E49	No	Weekly (AR)(1)	Level 1		CL	000:00
000000-0004CC11	No	6 Yearly/120000 Kms (2)	Level 2		CL	000:00
000000-0004D89B	No	2 Yearly/40000 Kms	Level 1		CL	000:00
000000-0004D8DC	No	Yearly/20000 Kms	Level 1		CL	000:00
000000-0004D8DD	No	6 Monthly/10000 Kms	Level 1		CL	000:00
000000-000FC48F	No	Weekly (AR)(1)	Level 1		CL	000:00

000000-000EC2D2	No	Weekly (AR)(1)	Level 1	CL	000:00
000000-001A0F8D	No	Weekly (AR)(1)	Level 1		000:00
000000-004E4F11	No	Weekly (AR)(1)	Level 1		000:00
000000-00575C07	No	Weekly (AR)(1)	Level 1	Limited Role	WiP 000:00
000000-0015E5F8	No	6 Monthly/10000 Kms	Level 1		000:00
000000-0022B835	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	Level 1		000:00
000000-001A3C6E	No	6 Monthly/10000 Kms	Level 1		000:00
000000-0014F873	No	Weekly (AR)(1)	Level 1		000:00
000000-00164424	No	Weekly (AR)(1)	Level 1		000:00
000000-0052DCFE	No	OOPS 5 Yearly Drain/Flush And Replen Cooling System	Level 1	Non-Taskworthy	CL 000:00
000000-00444DBB	No	6 Monthly/10000 Kms	Level 1	Fully Fit	CL 000:00
000000-005893CF	No	6 Monthly/10000 Kms	Level 1	Non-Taskworthy	CL 000:00
000000-0038957E	No	Yearly/20000 Kms	Level 1	Fully Fit	CL 000:00
000000-004D2E8D	No	Yearly/20000 Kms	Level 1	Non-Taskworthy	CL 000:00
000000-00583586	No	Weekly (AR)(1)	Level 1	Limited Role	WiP 000:00
000000-0038957D	No	6 Monthly/10000 Kms	Level 1	Fully Fit	CL 000:00
000000-00157C67	No	Weekly (AR)(1)	Level 1		000:00
000000-0022B831	No	OOPS 2 Yearly/20000 Kms Drain Engine Oil And Filter Change (1)	Level 1		000:00