

Work Objects

Serial Number: PE05AA
 NSN: 2320998939939

Criteria:
 Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Modification Event ID	Modification Number	Modification Description	Work Request ID	Escalate Work	Production Classification/In Service Classification	Modification Type	Apply When Usage Equals	Embodiment Target Date	Usage Counter Units	Fault State	Work Status	Repair Level	Working Organisation	Repair Section	Estimated Repair Time
000000-0001FBC0	00029	Spare Wheel Adaptor Plates; Left and Right Hand Installation		No	-/-	UTI				Fully Fit	CL				
000000-000104A0	00031	Cover for Blue Flashing Beacon (Battlefield Ambulance & RMP TUL/TUM (HS) Variants		No	-/-	UTI				Fully Fit	CL				
000000-000227E2	00014	Fitting of Showerproof Dash Cover		No	-/-	RTI				Fully Fit	CL				
000000-000241DB	00038	Fitting of a New Import/Export Box Mount Bracket		No	-/-	UTI				Fully Fit	CL				
000000-00015E36	00017	Introduction of Battery Retention		No	1/A	UTI				Fully Fit	CL				
000000-000192C0	00025	Fitting of Spare Wheel Lifting Aid Harness		No	1/A	UTI				Fully Fit	CL				
000000-000130F8	00019	Blackout Cover for Warning Light Panel		No	-/-	UTI				Fully Fit	CL				
000000-0001367E	00039	TUM (HS) REMUS 1- SAFETY AND COMPLIANCE PROGRAMME		No	-/-	RTI				Fully Fit	CL				
000000-000199DA	00037	Fitting Glow Plug Timer Interface Harness		No	-/-	UTI				Fully Fit	CL				
000000-0002324A	00030	Front Belt Protection Sleeves		No	1/A	UTI				Fully Fit	CL				
000000-00020447	00010	Winterised / Waterproof Radio Bag		No	-/-	RTI				Fully Fit	CL				
000000-00016A51	00004	Fitting Emergency Lights, Siren and Harness		No	-/-	RTI				Fully Fit	CL				
000000-0000A237	00006	Fitting of Spare Wheel Tyre Inflation Valve Extension		No	-/-	RTI				Fully Fit	CL				