

Work Objects

Serial Number: PN31AA
 NSN: 2320998939940

Criteria:

Repair Level: ALL
 Work Object Status: Closed
 Mission Impact: ALL
 Fault State: ALL
 Escalate Work: ALL
 Work Request ID:
 Assigned Work Status: ALL
 Working Organisation:
 Repair Section:

Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
00000-008B3F85		ASBESTOS DECONTAMINATION CLEANING REQUIRED.	Closed	Non-Taskworthy	No	Level 1		02 Jun 2020	N/A	Ban	TUM HS GS HARD TOP			000:00
00000-00AED457		AUTO- AIR FILTER INTAKE HOSES U/S	Closed	Fully Fit	No	Level 2		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00AED455		AUTO- COOLANT HOSES LEAK ON TOP & LHS OF ENGINE	Closed	Fully Fit	No	Level 2		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00AED443		AUTO- REAR DOOR CENTRAL & LOWER HINGES WORN	Closed	Fully Fit	No	Level 2		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00AED436		AUTO- PICKAXE STOWAGE WINGNUT SEIZED	Closed	Fully Fit	No	Level 1		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00AED42F		AUTO- FRONT TIE DOWN RINGS SEIZED	Closed	Fully Fit	No	Level 1		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00AED42B		AUTO- DATA PLATES DEFICIENT	Closed	Fully Fit	No	Level 1		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00AED423		AUTO- RH FEMALE SEAT BELT CATCH FAULTY	Closed	Fully Fit	No	Level 1		26 Oct 2018	N/A	Inspection	TUM HS GS HARD TOP			
00000-00A42B98		Wiring Loom Fire - Land Rover TUM (HS) all variants, TUL (HS) all variants and Battle Field Ambulance (BFA) post embodiment instruction Mod 41 - Battery Isolation Switch.	Closed	Limited Role	No	Level 2	000000-0000452C	29 Jul 2017	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD74		MODS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Modification	TUM HS GS HARD TOP			000:00
00000-0084FD73		FUEL SYSTEM REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		07 Jul 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD72		TRANSMISSION REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD71		TYRES U/S HXP13-001	Closed	Fully Fit	No	Level 2		07 Jul 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD6C		BODY REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD6A		ENGINE/COMPONENT REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		07 Jul 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD62		CAB INTERIOR REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		07 Jul 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD5F		ELECTRICAL REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		07 Jul 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-0084FD3F		STEERING/SUSPENSION REPAIRS HXP13-001	Closed	Fully Fit	No	Level 2		04 Aug 2014	N/A	Inspection	TUM HS GS HARD TOP			000:00
00000-007AF6 F6		renew indicator stalk	Closed	Fully Fit	No	Level 2		28 Aug 2013	N/A	Closed No Action	TUM HS GS HARD TOP			
00000-007A8CD8		RENEW WASHER PUMP	Closed	Non-Taskworthy	No	Level 2		02 Aug 2013	N/A	Failure	TUM HS GS HARD TOP			
00000-007A228B		RENEW REAR CABLE SLEEVES	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A1FEA		RENEW FRONT GRILLE	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-00781103		WHITE PATCH NOT PAINTED ON DIFF	Closed	Fully Fit	No	Level 1		18 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP			
00000-00842F35		Towing Pintle Assembly	Closed	Limited Role	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUM HS GS HARD TOP			
00000-007810F4		various jobs	Closed	Fully Fit	No	Level 2		17 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2C9A		RENEW BOTH MIRRORS	Closed	Non-Taskworthy	No	Level 2		15 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2464		RENEW DIESEL BADGE	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2272		RENEW FRONT TOW PINTLE	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2103		RENEW REAR VIEW MIRROR	Closed	Non-Taskworthy	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A1FA5		renew fuel cap	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A0FB8	000000-002E85EA	REPAIR	Closed	Non-Taskworthy	No	Level 2		10 Jul 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	INSPECTIONS1	
00000-007A2CEA		RENEW DRIVERS DOOR PANEL	Closed	Fully Fit	No	Level 2		15 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2CD8		RENEW PIPE @ POWER STEERING PUMP	Closed	Non-Taskworthy	No	Level 2		15 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2C84		INVESTIGATE HAZARDS INOP	Closed	Non-Taskworthy	No	Level 2		15 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2C6C		RENEW UPPER CRASH PAD	Closed	Fully Fit	No	Level 2		15 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A237F		RENEW REAR SEAT RAILS	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2259		RENEW ASH TRAY	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2244		RENEW TOP DASH	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2142		RENEW GUN CLIP CUSHIONS	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2019		RENEW HEADLIGHT GUARD LOWER BRACKET	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A1DC6		RENEW REAR DOOR PANEL (DIFFY) HANDLE	Closed	Fully Fit	No	Level 2		13 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-0079384E		PLEASE INVESTIGATE LEFT HAND SIDE BODY DAMAGE	Closed	Fully Fit	No	Level 2		12 Jun 2013	N/A	Damage	TUM HS GS HARD TOP			
00000-0079384C		PLEASE INVESTIGATE BONNET CES STRAPS/BRACKETS U/S	Closed	Fully Fit	No	Level 2		12 Jun 2013	N/A	Damage	TUM HS GS HARD TOP			
00000-0079782A		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Non-Taskworthy	No	Level 1	000000-0000081A	23 Jun 2013	N/A	Quarantine	TUM HS GS HARD TOP			
00000-0079A887		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A23A4		RENEW REAR DOOR LOWER SEAL	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A2CFE		RENEW REAR DOOR SEAL	Closed	Fully Fit	No	Level 2		15 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007A1FC6		RENEW BONNET CLIP	Closed	Fully Fit	No	Level 2		14 Jul 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-0079384D		PLEASE INVESTIGATE MAP LIGHT INOP	Closed	Fully Fit	No	Level 2		12 Jun 2013	N/A	Failure	TUM HS GS HARD TOP			
00000-00793850	000000-002E731B	PLEASE INVESTIGATE LHS LIGHT PANEL DAMAGE/PUNTURE	Closed	Non-Taskworthy	No	Level 2		12 Jun 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-00791DA5	000000-002E702D	PLEASE INVESTIGATE NON STARTER	Closed	Fully Fit	No	Level 2		09 Jun 2013	N/A	Failure	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-006 AF18C		Insp Steering Dr op Ar m Tab Washer	Closed	Non-Taskworthy	No	Level 2	000000-000002C3	22 Jun 2011	N/A	Inspection	TUM HS GS HARD TOP			
00000-0077C3D4	000000-002E4074	6 MONTHLY SERVICE	Closed	Fully Fit	No	Level 2		05 Apr 2013	N/A	Servicing	TUM HS GS HARD TOP	TH ES GP	INSPECTIONS1	
00000-00781101	000000-002E50B5	SEATBELTS NOT FITTED CORRECTLY	Closed	Limited Role	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-00781100	000000-002E50B5	SEATS IN REAR NOT FITTED CORRECTLY	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810FC	000000-002E50B5	PIN MISSING FROM TOWING PIN	Closed	Fully Fit	No	Level 1		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810FA	000000-002E50B5	SPARE WHEEL UNSECURE	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810F8	000000-002E50B5	TYRE PRESSURES NOT DISPLAYED ON ARCHES	Closed	Fully Fit	No	Level 1		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810F4	000000-002E50B5	F/R/H GUARD BENT (LIGHT GUARD)	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810EE	000000-002E50B5	R/R/H BRAKE PIPE NOT MOUNTED TO AXLE	Closed	Fully Fit	No	Level 2		17 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810EC	000000-002E50B5	front anti role bar bushes bent	Closed	Fully Fit	No	Level 2		19 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810E7	000000-002E50B5	free play @ both front shock bushes	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810E1	000000-002E50B5	leak @ rocker gasket	Closed	Fully Fit	No	Level 2		16 Apr 2013	N/A	Servicing	TUM HS GS HARD TOP			
00000-007810DF	000000-002E50B5	leak @ sump	Closed	Fully Fit	No	Level 2		16 Apr 2013	N/A	Servicing	TUM HS GS HARD TOP			
00000-00781104		DENT IN F/R/H WHEEL ARCH	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-00781105		NO PLATE DAMAGED REAR	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810EA		freeplay @ front radius arch bushes	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810F0		CAB SPLIT AT REAR DOOR	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-007810F2		ASH TRAY AND CENTER CONSOLE DAMAGED	Closed	Fully Fit	No	Level 2		18 Apr 2013	N/A	Inspection	TUM HS GS HARD TOP			
00000-0077C485	000000-002E4074	NO PLATE DAMAGED REAR	Closed	Fully Fit	No	Level 2		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C484	000000-002E4074	DENT IN F/R/H WHEEL ARCH	Closed	Fully Fit	No	Level 2		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C483	000000-002E4074	NO WHITE PATCH FOR CONVOY	Closed	Fully Fit	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C482	000000-002E4074	SEATBELTS NOT FITTED CORRECTLY	Closed	Limited Role	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C481	000000-002E4074	SEATS IN REAR NOT FITTED CORRECTLY	Closed	Limited Role	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C480	000000-002E4074	PIN MISSING FROM TOWING EYE	Closed	Non-Taskworthy	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C47F	000000-002E4074	SPARE WHEEL UNSECURE	Closed	Fully Fit	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C47E	000000-002E4074	TYRE PRESSURE NOT DISPLAYED ON ARCHES	Closed	Non-Taskworthy	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C47D	000000-002E4074	F/R/H GUARD BENT (LIGHT GUARD)	Closed	Fully Fit	No	Level 1		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C47C	000000-002E4074	ASH TRAY AND CENTRE CONSOLE DAMAGED	Closed	Fully Fit	No	Level 2		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C47B	000000-002E4074	CAB SPLIT AT REAR DOOR	Closed	Fully Fit	No	Level 2		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C47A	000000-002E4074	R/R/H BRAKE PIPE NOT MOUNTED TO AXLE	Closed	Fully Fit	No	Level 2		06 Apr 2013	N/A	Closed No Action	TUM HS GS HARD TOP	TH ES GP	LAD1	
00000-0077C479	000000-002E4074	FRONT ANTI-ROLE BAR BUSHES BENT	Closed	Non-Taskworthy	No	Level 2		06 Apr 2013						