

Work Objects														
Serial Number:	LS13AA													
NSN:	2320998939742													
Criteria:														
Repair Level:	ALL													
Work Object Status:	Closed													
Mission Impact:	ALL													
Fault State:	ALL													
Escalate Work:	ALL													
Work Request ID:														
Assigned Work Status:	ALL													
Working Organisation:														
Repair Section:														
Fault ID	Work Request ID	Fault Description	Work Status	Fault State	Escalate Work	Repair Level	Batch Fault Group ID Number	Fault Occurrence Date	Mission Impact	Reason For Work	Level 3 Description	Working Organisation	Repair Section	Estimated Repair Time
000000-0087E120		FOG LIGHT GLASS CRACKED	Closed	Fully Fit	No	Level 2		10 Mar 2015	N/A	Damage	TUL HS FFR HARD TOP			
000000-00876441		FLAT TYRE	Closed	Fully Fit	No	Level 2		18 Feb 2015	N/A	Damage	TUL HS FFR HARD TOP			
000000-008442B6		Towing Pintle Assembly	Closed	Fully Fit	No	Level 2	000000-00001F58	09 Oct 2014	Degraded	Inspection	TUL HS FFR HARD TOP			
000000-007BAB08		TYRES FAULTY	Closed	Non-Taskworthy	No	Level 2		28 Sep 2013	N/A	Damage	TUL HS FFR HARD TOP			
000000-0079EF24	000000-002EAFBE	THREE TYRES FOUND TO BE FAULTY SOUTH AFRICAN TYRES	Closed	Fully Fit	No	Level 2		03 Jul 2013	Degraded	Failure	TUL HS FFR HARD TOP			
000000-00798BA1		GOODYEAR G90 tyres manufactured in South Africa cracking File Ref OSVP/64/40/04/09	Closed	Fully Fit	No	Level 1	000000-0000081A	23 Jun 2013	N/A	Failure	TUL HS FFR HARD TOP			
000000-00798B76		Inspect tyres for damage	Closed	Fully Fit	No	Level 2	000000-00000835	25 Jun 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00779CC8		REQUIRES 6 MONTHLY SAFETY INSPECTION (6534)	Closed	Fully Fit	No	Level 1		26 Mar 2013	N/A	Inspection	TUL HS FFR HARD TOP			
000000-00779CC5		REQUIRES 6 MONTHLY SERVICE	Closed	Fully Fit	No	Level 1		26 Mar 2013	N/A	Servicing	TUL HS FFR HARD TOP			
000000-00760E01		REQUIRES RESPRAY	Closed	Fully Fit	No	Level 3		25 Jan 2013	N/A	Refurbishment	TUL HS FFR HARD TOP			