


Little Lopen Pikler Triangle and Ramp	
Aspect	Details
Images	
Alert Number	2106-0227
Product Type	Toys – Climbing frame
Product Identifiers	Item No. 275039
Product Description	Wooden A shape climbing frame and ramp in brown carton
Country of Origin	China
Counterfeit	No
Risk Level	Serious
Risk Type	Injuries
Risk Description	<p>The product presents a serious risk of injuries due to the instability of the toy. When subjected to the stability test the frame tipped over sideways, which could cause serious injuries if the child was to fall if they climbed the toy from the side. Activity toys must be assembled using self-locking mechanisms however the ramp has no means of attachment and the main frame has no means of being locked in the open position. Slides should also consist at least of a starting section, a sliding section and a run-out section, however the slide did not have a starting section (with handles) or a run-out section which poses further risk of injuries. The toy does not meet the requirements of the Toys (Safety) Regulations 2011.</p>
Corrective Measures	Destruction of the product
Online Marketplace	N/A
Notifier	Local Authority Trading Standards